(7-77)	LICENSEE EVENT REPORT
	UPDATED REPORT PREVIOUS REPORT DATE 12-21-79
	CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8	V A S P S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 5 1 1 1 1 1 1 1 1 1 1 1
O 1 7 8	REPORT L 6 0 5 0 0 0 2 8 0 7 1 1 2 7 7 9 8 1 2 2 1 7 9 9 EVENT DATE 68 69 EVENT DATE 74 75 REPORT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	During normal operation, routine surveillance revealed the failure of heat tracing
0 3	circuit 2B (Panel 8), Unit #1 suction piping to Boric Acid Transfer Pump, I-CH-P-2A.
0 4	This is a degraded mode of operation permitted by T.S. 3.3.B.5, and is reportable as
0 5	per T.S. 6.6.2.b.(2). Since the temperature of the affected lines was maintained as
0 6	required, the redundant circuit was operable and two flow paths for boric acid to the
0 7	reactor were available, the health and safety of the public were not affected.
08	9 SYSTEM CAUSE CAUSE COMP. VALVE
0 9	CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE  SUBCODE SUBCODE  SUBCODE SUBCODE  SUBCODE SUBCODE  11
	LER/RO EVENT YEAR SEQUENTIAL REPORT NO.  17 REPORT   7 9   0 3 5   0 3   X   1
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER  ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER  ACTION ON PLANT METHOD 1 0 0 0 0 0 Y 23  N 24 43 25 C 2 6 8 26  33 34 8 34 9 35 36 36 37 40 41 41 41 42 42 43 43 42 44 47
1 0	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  A review of the heat tracing circuit showed that failure was caused by water damage to
1 1	the heat tracing circuit. The corrective action implemented was to replace the heat
1 2	tape and initiate a maintenance request to repair the water leak.
1 3	
1 4	
7 8	9 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32    7   (28)   0   0   (29)   31
7 8	Operator Observation  10 12 13 44 45 46 46 46 46 46 46
1 6 R	ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
1111	$\begin{bmatrix} 2 \\ 9 \end{bmatrix} \begin{bmatrix} 33 \\ 10 \end{bmatrix} \begin{bmatrix} 34 \\ 11 \end{bmatrix} \begin{bmatrix} NA \\ 44 \end{bmatrix} \begin{bmatrix} NA \\ 45 \end{bmatrix} \begin{bmatrix} NA \\ 45 \end{bmatrix}$
L <u>'</u> L'	
7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
7 8	9 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 9 11 12 13 NA 9 PERSONNEL INJURIES
,	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  PERSONNEL INJURIES NUMBER DESCRIPTION (41)  PERSONNEL INJURIES NUMBER DESCRIPTION (41)  NA
1 8 7 8 1 9 7 8	PERSONNEL EXPOSURES NUMBER  PERSONNEL INJURIES NUMBER  DESCRIPTION 41  PERSONNEL INJURIES NUMBER  DESCRIPTION 41  PERSONNEL INJURIES NUMBER  DESCRIPTION 41  LOSS OF OR DAMAGE TO FACILITY 43  TYPE  DESCRIPTION  80  80  80
1 8 7 8 1 9 7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  PERSONNEL INJURIES NUMBER DESCRIPTION (41)  PROPER DESCRIPTION (43)  TYPE DESCRIPTION  SO  DIRECTOR (42)  PARSONNEL INJURIES NUMBER DESCRIPTION (41)  PERSONNEL INJURIES NUMBER DESCRIPTION (41)  SO  SO  DESCRIPTION (43)  SO  SO  SO  SO  SO  SO  SO  SO  SO  S

ATTACHMENT (PAGE 1 OF 1) SURRY POWER STATION, UNIT 1

DOCKET NO: 50-280

REPORT NO: 79-035/03X-1 EVENT DATE: 11/27/79

TITLE OF REPORT: Low Current On Heat Tracing

#### 1. DESCRIPTION OF EVENT:

With the unit in normal operation at rated power, operator surveillance found that Heat Tracing Circuit 2B (Panel 8) was operating at less than the current specified in the surveillance document. Low temperature alarms were indicated.

Investigation for faulty heat tracing tape was initiated on the affected circuit. Faults were found on Circuit 2B (Panel 8) "2A" Boric Acid Transfer Pump suction and were identified as being the result of water penetration of the tape. The tape was replaced. The circuit current was then verified to be within specs. of the surveillance document, and a maintenance report was submitted to repair the leak.

This is a degraded mode of operation permitted by T.S. 3.3.B.5 and is reportable in accordance with Technical Specification 6.6.2.b.(2).

## 2. PROBABLE CONSEQUENCES AND STATUTS OF REDUNDANT SYSTEMS:

At all times during the event, the temperature of the affected lines was maintained as required. The redundant circuit was operable. There were at all times two operable flow paths for boric acid to the reactor. Therefore, the health and safety of the general public were not affected.

## 3. CAUSE:

The reduced currents were due to water penetration damage to the heat tracing tape on the affected circuit.

# 4. IMMEDIATE CORRECTIVE ACTION:

The problem was corrected immediately and no further action is required.

### 6. ACTION TAKEN TO PREVENT RECURRENCE:

Continuous surveillance is maintained on the Heat Tracing System. No additional action is considered necessary. A task force has been assembled to investigate the replacement of existing tape with water resistant tape. This investigation is in progress.

#### 7. GENERIC IMPLICATIONS:

In view of the number of failures of this heat tracing tape, a task force has been established to examine the heat tracing system and determine corrective action.