

REPORT ON THE

**REANALYSIS OF
SAFETY-RELATED
PIPING SYSTEMS**

SURRY POWER STATION-UNIT 2

**VIRGINIA ELECTRIC
AND POWER COMPANY**

REVISION 1

EBASCO SERVICES INCORPORATED_____

JERICO, NEW YORK

8006180253

EBASCO SERVICES

INCORPORATED

ENGINEERS - CONSTRUCTORS - CONSULTANTS

ONE JERICO PLAZA

JERICO, N. Y. 11753

CABLE ADDRESS "EBASCOE"

June 12, 1980

NRC-1

Mr Harold R Denton, Director
Office of Nuclear Reactor Regulation
US Nuclear Regulatory Commission
Washington, DC 20555

Dear Mr Denton:

Subject: SHOW CAUSE ORDER REANALYSIS REPORT
 REVISION NO. 1
 SURRY POWER STATION UNIT 2

References: Serial No.: 138B
 Docket No.: 50-281
 License No.: DPR-37

Ebasco Services, Inc is resubmitting forty-five (45) copies of Revision 1 of the "Report on the Reanalysis of Safety-Related Piping Systems, Surry Power Station Unit 2, Virginia Electric and Power Company," originally hand delivered April 11, 1980.

Please replace the forty-five (45) copies submitted on April 11, 1980 (white cover) with those enclosed (beige cover).

The resubmittal is for two (2) reasons:

- 1) General illegibility of Appendix B flow diagrams
- 2) Errata on Appendix B, Page B-2

Main Steam Drawing No. 11548-FM-14A

Feedwater Drawing No. 11548-FM-18A

are Revision 1 but were not indicated as such.

EBASCO SERVICES
INCORPORATED

Mr Harold R Denton

-2-

June 12, 1980

We apologize for any inconvenience this may have caused.

Very truly yours,



H W Nelson
Project Manager

HWN/JNR/bfl
Enclosures

cc: Mr Victor Stello, Director
Office of Inspection and Enforcement

Mr James P O'Reilly, Director
Office of Inspection and Enforcement, Region II

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

April 11, 1980

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Serial No. 138B
PSE&C/GLS:mac:wang

Docket No. 50-281

License No. DPR-37

Dear Mr. Denton:

SHOW CAUSE ORDER REANALYSIS REPORT
REVISION NO. 1
SURRY POWER STATION UNIT 2


In the letter of February 22, 1980 (Serial No. 138), Vepco requested start-up of Surry Power Station Unit 2 based on the "Report on the Reanalysis of Safety Related Piping Systems, Surry Power Station, Unit 2" of the same date. The report reflected the results of the pipe stress and pipe support analyses subject to final verification and modification installation.

The purpose of this submittal is to update the original report to reflect revisions necessitated during modification installation and to make minor typographical corrections to the text to enhance clarity and consistency. The subject changes, which are noted in the margins, in no way alter our original conclusion that the analytical work completed and the modifications installed at the time of start-up provides a high degree of confidence that the integrity of safety systems for Unit 2 can be assured during the DBE or OBE events.

This revised report also incorporates our recent commitment to the NRC Staff (Vepco letter of March 21, 1980, Serial No. 138A) to complete the installation of all modifications associated with the Order to Show Cause prior to start-up of the unit. The additional commitments to complete certain portions of the work associated with I.E. Bulletins 79-02 and 79-14 are firm as outlined in the February 22 letter.

If you have any questions with regard to this submittal, please contact us.

Very truly yours,



W. C. Spencer
Vice President - Power Station Engineering
and Construction Services

Attachment

cc: Mr. Victor Stello, Director
Office of Inspection & Enforcement

Mr. James P. O'Reilly, Director
Office of Inspection & Enforcement, Region II

REPORT ON THE

**REANALYSIS OF
SAFETY-RELATED
PIPING SYSTEMS**

SURRY POWER STATION-UNIT 2

**VIRGINIA ELECTRIC
AND POWER COMPANY**

REVISION 1

EBASCO SERVICES INCORPORATED_____

JERICO, NEW YORK

SURRY POWER STATION - UNIT 2

REPORT ON THE
REANALYSIS OF SAFETY-RELATED PIPING SYSTEMS
SURRY POWER STATION - UNIT 2
VIRGINIA ELECTRIC AND POWER COMPANY

FEBRUARY 22, 1980

REVISION 1

APRIL 11, 1980

EBASCO SERVICES INCORPORATED
JERICHO, NEW YORK

TABLE OF CONTENTS

<u>Section</u>	<u>Title</u>	<u>Page</u>
1.0	SUMMARY AND CONCLUSIONS.....	1-1
2.0	SCOPE OF REANALYSIS.....	2-1
3.0	PIPE STRESS RESULTS.....	3-1
4.0	PIPE SUPPORT RESULTS.....	4-1
5.0	SCHEDULE FOR COMPLETION.....	5-1
6.0	HIGH ENERGY LINE BREAKS.....	6-1
7.0	CONSERVATISMS.....	7-1
7.1	Field Verification of As-Built Conditions.....	7-1
7.2	Quality Assurance and Engineering Assurance...	7-1
7.3	Use of Amplified Response Spectra.....	7-1
7.4	Conservatisms Applied to Inertial Stress.....	7-2
8.0	SYSTEM OPERABILITY EVALUATION.....	8-1
9.0	BRANCH LINE SUMMARY.....	9-1
10.0	RESPONSE TO THE NUCLEAR REGULATORY COMMISSION'S CONCERNS.....	10-1
10.1	Support Stiffness.....	10-1
10.2	NUPIPE Computer Code.....	10-1
10.3	Problem 2538 - Support H-15.....	10-1
10.4	Benchmark Problems.....	10-2
Appendix		
A	Systems Affected.....	A-1
B	Flow Diagrams - Identification of Problems Analyzed	B-1
C	Response to IE Bulletin 79-04.....	C-1
D	Correspondence with the NRC.....	D-1

LIST OF TABLES

<u>Table</u>	<u>Title</u>
3-1	PIPE STRESS RE-EVALUATION SUMMARY
3-2	NOZZLE AND PENETRATION SUMMARY
3-3	PIPE STRESS HARDWARE MODIFICATION SUMMARY
3-4	HARDWARE MODIFICATION SUMMARY DUE TO NOZZLE AND PENETRATION OVERLOADING
4-1	PIPE SUPPORT ANALYSIS SUMMARY
4-2	PIPE SUPPORT HARDWARE MODIFICATION SUMMARY
5-1	SCHEDULE FOR COMPLETION

SURRY POWER STATION - UNIT 2

SECTION 1

SUMMARY AND CONCLUSIONS

In response to the Nuclear Regulatory Commission's Order to Show Cause, dated March 13, 1979, a reanalysis was conducted of safety related piping systems for Surry Power Station Unit 2 which were originally dynamically analyzed using the SHOCK 2 computer program. The SHOCK 2 program, which used an earlier load combination methodology, is no longer considered acceptable by the NRC.

This report discusses the details of the analysis work and results of the pipe and support analyses within the scope of the reanalysis for Surry Unit 2. Further, this reanalysis is consistent with the methods used on Surry Power Station Unit 1, which were discussed in earlier reports submitted on June 5, 1979 (Vepco Serial No. 453) and on August 1, 1979 (Vepco Serial No. 453A) and on January 15, 1980 (Vepco Serial No. 048). This report summarizes the total reanalysis effort for all aspects of the March 13, 1979 Order to Show Cause for Surry Power Station Unit 2.

All piping systems affected by the Order to Show Cause, both inside and outside the containment, have been reanalyzed using the NUPIPE program, which is acceptable to the NRC. Table 3-3 (Pipe Stress Hardware Modification Summary) and Table 3-4 (Hardware Modification Summary Due to Nozzle and Penetration Overloading) identifies all modifications to the piping systems which have resulted from this reanalysis. While some of these modifications are attributable to the seismic analysis method, the majority of modifications result from differences in the as-built conditions and other miscellaneous reasons. All of these modifications have been or will be made prior to startup of the unit following the steam generator replacement outage. With the installation of these modifications, all Surry Unit 2 piping within the scope of this report will meet the Final Safety Analysis Report (FSAR) allowables for both the Operating Basis Earthquake and Design Basis Earthquakes (OBE and DBE) conditions.

All pipe supports both inside and outside containment affected by the Order to Show Cause have been evaluated for the revised support loads from the pipe stress reanalysis. All of these hardware modifications have been or will be installed prior to start up of the Unit following the steam generator replacement outage. Table 4-2 (Pipe Support Hardware Modification Summary) reports all the modifications resulting from the support reanalysis. As was the case in the piping system reanalysis, most of the modifications are the result of differences between the original design conditions and the actual field as-built condition.

During the reanalysis of Surry Unit 2, 79 stress modifications (22 due to pipe stress, 57 due to nozzle overload) and 258 pipe support modifications were identified; while 63 pipe stress and 66 pipe support modifications were identified on Surry Unit 1. The differences in the number of modifications is not considered significant, due to the conduct of the reanalysis applied to Surry Unit 2. Modifications on Surry Unit 1 were

SURRY POWER STATION - UNIT 2

identified after many analytical iterations; whereas, on Surry Unit 2 modifications were designed based on fewer iterations. The conduct of the reanalysis in this manner served to identify modifications faster so that systems could be upgraded more quickly in order not to substantially interfere with the completion of the Steam Generator Replacement Project. In addition, the Surry Unit 2 reanalysis included the OBE condition. Further, all pipe supports were as-built in the field and QC verified prior to reanalysis. Lastly, to limit the interface problems between the Show Cause scope and other piping, supports were added to facilitate the NUPIPE reanalysis.

SURRY POWER STATION - UNIT 2

SECTION 2

SCOPE OF REANALYSIS

As described in the NRC Order to Show Cause, March 13, 1979, some piping systems in the Surry Power Station, Unit 2 were dynamically analyzed with a SHOCK 2 computer program that is not currently acceptable to the NRC.

All systems or portions of systems that were analyzed by the SHOCK 2 computer program have been identified in Appendix A. These systems were reanalyzed by Stone & Webster Engineering Corporation (Stone & Webster) and Ebasco Services Incorporated (EBASCO) using a NUPIPE computer code. Responsibility for the reanalysis is also identified in Appendix A by system and problem number.

The results of the reanalysis are compared with code allowable pipe stresses, allowable loads for nozzles and penetrations, and are used in the evaluation of pipe supports.

SECTION 3

PIPE STRESS RESULTS

A total of 62 pipe stress problems were originally analyzed by the PSTRESS/SHOCK 2 computer program that used algebraic summation and are therefore specifically addressed by the Show Cause Order. These stress problems are being analyzed by two groups: Stone & Webster Engineering Corporation (Stone & Webster) in Boston, Massachusetts, and Ebasco Services Incorporation (EBASCO) in Jericho, New York, as indicated in the following table:

PIPE STRESS PROBLEMS

<u>Stone & Webster</u>	<u>EBASCO</u>	<u>Total</u>
13	49	62

Responsibility for the reanalysis is identified by system and problem number in Appendix A of this report.

Field-verified piping isometric drawings provide the basis for program inputs for the pipe stress reanalysis. The reanalysis is conducted using the NUPIPE computer program. NUPIPE calculates intra-modal seismic forces using a modified square root of the sum of the squares (SRSS) technique which is always more conservative than the approved SRSS method, and an SRSS technique for inter-modal combination.

Piping is analyzed in most cases utilizing amplified response spectra (ARS) that are developed using soil structure interaction techniques (SSI-ARS). The resultant stresses and loads are used to evaluate piping, supports, nozzles, and penetrations. In accordance with the NRC letters of May 25, 1979 and November 15, 1979 to Virginia Electric and Power Company (VEPCO), the seismic inertial stresses and loads computed using the SSI-ARS have been increased by a factor of 1.5 for the DBE and 1.25 for OBE conditions.

All 62 problems have been reanalyzed. Table 3-1, Pipe Stress Re-Evaluation Summary, presents the results for these 62 stress problems. In Table 3-1, the figures for Original Total Stress, at the point of maximum total stress in the pipe, and Original Seismic Stress, at the same point, are extracted from original design stress isometrics (MSK's).

In Table 3-1, the columns for New Total Stress, at the point of maximum total stress in the pipe, and New Seismic Stress, at the same point, were taken from the NUPIPE computer runs with the seismic inertial stress multiplied by a factor of 1.5 and then added to the Seismic Anchor Movement (SAM) Stress for runs using the SSI-ARS. Even though Table 3-1 reports DBE results, stress analysis is performed for OBE also and modifications designed wherever necessary.

The Original Total and Original Seismic Stresses shown in Table 3-1 were computed using the SHOCK 2 programs for the original design conditions. The New Total and New Seismic stresses were computed by the NUPIPE pro-

SURRY POWER STATION - UNIT 2

gram using different mass models and in most cases different ARS's than the original calculations. More importantly, the reanalyses were based on as-built conditions, field verified in 1979, which in some cases differ from the original design conditions. For these reasons, the new stresses and the original stresses in Table 3-1 are not comparable, as they do not necessarily represent the same physical conditions.

Table 3-2, Nozzle and Penetration Summary, summarizes the nozzles and penetrations evaluated under the reanalysis program. For all the problems in which the SSI-ARS are used, the seismic inertial nozzle loads have been increased by a factor of 1.5 for DBE per the NRC letter of May 25, 1979, and by a factor of 1.25 for OBE per the NRC letter of November 15, 1979.

Table 3-3, Pipe Stress Hardware Modification Summary, lists the hardware modifications necessary to bring the pipe stress analysis to within code allowables. Of the 62 problems reanalyzed, hardware modifications were made to 17 problems due to pipe stress. These modifications consisted of 22 added, modified, or deleted supports. The modifications include those necessary to the flexibility analysis of the branch lines. A branch line (Problem No. 2508B) was rerouted as a result of thermal reanalysis, not as a result of seismic reanalysis.

Table 3-4, Hardware Modification Summary due to Nozzle and Penetration Overloading, lists all modifications to reduce nozzle and penetration loads. Of the 62 problems reanalyzed, hardware modifications were made to 17 problems due to nozzle overload. These modifications consisted of 57 added, modified, or deleted supports.

Those modifications which result from the piping reanalysis are identified in Section 3. Only the modifications which result from the pipe support reanalysis are reported in Table 4-2, Pipe Support Hardware Modification Summary. Final verification of piping and support stresses and Engineering Assurance review has yet to be completed for a few problems. It is expected, however, that the number and type of modifications due to the stress and support analysis are correct and final.

SURRY POWER STATION - UNIT 2

TABLE 3-1

Sheet 1 of 5

PIPE STRESS RE-EVALUATION SUMMARY

System Name and Problem Number ⁺	Reanalysis Responsibility	HKS Number	Line Size NPS (Inches)	Pipe Stress (psi)				
				Original Total	Original Seismic	New Total	New Seismic	Allowable
<u>Low Head Safety Injection</u>								
2555	E	122D1	10,12	12043	NA	7974	2449	30690
2709	E	122L1	12	NA	NA	19173	11427	33750
2537/2540/2540B	E	122A1, 117B1	4,6, 10,12	12350	NA	2739	883	33750
2539	E	122J1 122K1	6	30368	NA	14771	7330	32985
2727	S&W	127C1 127C2	6 8,10	21179	NA	24352	17453	33750
2681	E	127K1	8	1677	307	1220	185	28485
2682	E	127K2	8	1677	307	1174	164	28485
2695	E	127D1	8	21179	NA	2094	1103	28485
2697	E	127D2	8	21179	NA	1981	1022	28485
<u>High Head Safety Injection</u>								
2689	E	127F1	10	24649	NA	11773	9571	33750
2735	E	127G1 127G2	3,4,6, 8,10	NA	NA	26660	17772	33750
<u>Containment and Recirculation Spray</u>								
2521	S&W	123A1	8,10	14904	NA	7790	4276	33561
2523	S&W	123A2	8,10	14904	NA	7977	6013	33561
2547	S&W	123C1	8,10	12713	NA	23532	19739	33561
2546	E	123D1	8,10	3528	1576	8892	7328	28800
2541	E	123D2	8,10	3528	1576	18338	16636	28800
2542	E	123D3	8,10	3528	1576	18931	17252	28800

SURRY POWER STATION - UNIT 2

TABLE 3-1

Sheet 2 of 5

PIPE STRESS RE-EVALUATION SUMMARY

System Name and Problem Number	Reanalysis Responsibility	NKS Number	Line Size NPS (Inches)	Pipe Stress (psi)				Allowable
				Original Total	Original Seismic	New Total	New Seismic	
Containment and Re-circulation Spray (Cont'd)								
2543	E	123D4	8,10	3528	1576	8498	6988	29970
2560	E	123E1	10	7334	NA	12775	10995	29970
2561	E	123E2	10	7334	NA	6587	3576	29970
2544	E	123G1	10	11605	7922	2912	1181	28485
2533	E	123G2	10	11605	7922	5874	3813	28485
2548	E	123H1	10	15785	11241	3904	2437	29970
2545	E	123H2	10	15785	11241	2397	676	29970
2744	E	123J1	8	7966	5118	16143	15187	35820
2745	E	123K1	6	24843	22577	15621	12559	33750
2753	E	123L1	12	6136	2818	1344	394	33750
2754	E	123M1	12	5649	NA	1999	949	33750
2751	E	123N1	10	6010	NA	21234	13842	28485
2752	E	123N2	10	6010	NA	18613	13934	28485
2549	S&W	123C2	8	11955	10125	10081	8397	33561
2755	E	123P1	4,8	10369	6324	14311	7340	33750
2756	E	123Q1	10	NA	NA	5705	2686	28485
2757	E	123Q2	10	5810	NA	3847	2381	28485
Main Steam								
2577	S&W	100D1	30	13824	NA	10763	2883	33750
2588	S&W	101D1	30	18635	NA	12513	3041	33750
2579	S&W	102D2	30	13031	NA	11434	4120	33750
2346*	S&W	103A1 103A2	30	19970	NA	32568	25477	33750

SURRY POWER STATION - UNIT 2

TABLE 3-1

Sheet 3 of 5

PIPE STRESS RE-EVALUATION SUMMARY

System Name and Problem Number	Reanalysis Responsibility	MKS Number	Line Size NPS (Inches)	Pipe Stress (psi)				Allowable
				Original Total	Original Seismic	New Total	New Seismic	
<u>Feedwater</u>								
2569	S&W	100G1	14	14499	NA	13681	9360	27000
2573	S&W	101G1	14	16025	NA	12970	8376	27000
2571	S&W	102G1	14	17927	NA	14230	8443	27000
<u>Auxiliary Feedwater</u>								
2473	E	118A1 118A2	3,6	8568	2407	20963	17736	27000
2683	E	118G1 118G2	4,6	21230	NA	12988	9188	27000
<u>Pressurizer Spray</u>								
2771	E	125A1	4	18560	NA	8013	3088	30690
<u>Pressurizer Safety and Relief</u>								
2000	E	124A1 124A2	3,4 6,12	9093	NA	8824	5421	30636
<u>Residual Heat Removal</u>								
2540/2540B	E	Listed Under Low Head Safety Injection System						
2508A/2508B	E	117A1	10,12,14	NA	NA	13112	8461	24570
2554	E	117C1	6	NA	NA	12008	8824	29970
<u>Service Water</u>								
2465	E	119A1	24	NA	NA	6529	6212	21600
2467	E	119A2	24	NA	NA	6561	6214	21600

SURRY POWER STATION - UNIT 2

TABLE 3-1

Sheet 4 of 5

PIPE STRESS RE-EVALUATION SUMMARY

System Name and Problem Number	Reanalysis Responsibility	MKS Number	Line Size NPS (Inches)	Pipe Stress (psi)				
				Original Total	Original Seismic	New Total	New Seismic	Allowable
Service Water (Cont'd)								
2469	E	119A3	24	NA	NA	14687	13730	21600
2471	E	119A4	24	NA	NA	12459	11614	21600
Component Cooling								
2601/2603	E	112S1 112S2	18	9696	NA	7043	5246	21600
2604/2605	E	112AA1 112AB1	18	9696	NA	7074	5204	21600
Containment Vacuum								
2650	S&W	137A1	8	25,750	NA	13659	13037	21600
HP Steam to Auxiliary Feedwater Pump								
2869/2862/2864	E	131A1 131B1 131C1	3,4	22609	NA	24229	19559	27000

SURRY POWER STATION - UNIT 2

TABLE 3-1

Sheet 5 of 5

PIPE STRESS RE-EVALUATION SUMMARY

Legend:

E = EBASCO

S&W = Stone & Webster

NA = Not Available

Allowable Stress = $1.8 S_h$

New Total Stress (for SSI/ARS) = $S_{LP} + S_{DW} + 1.5 S_{DBEI} + S_{DBEA}$

New Seismic (for SSI/ARS) = $1.5 S_{DBEI} + S_{DBEA}$

New Total Stress (original ARS) = $S_{LP} + S_{DW} + S_{DBEI} + S_{DBEA}$ = Original Total Stress

New Seismic (original ARS) = $S_{DBEI} + S_{DBEA}$ = Original Seismic Stress

Where S_{LP} = Longitudinal Pressure Stress

S_{DW} = Dead Load Stress

S_{DBEI} = Seismic Inertial Stress, Design Basis Earthquake

S_{DBEA} = Seismic Stress due to Anchor Movements, Design Basis Earthquake

S_h = Allowable stress at maximum (hot) temperature

Note:

The original total and original seismic stresses shown in Table 3-1 were computed using SHOCK 2 for the original design conditions. The new total and new seismic stresses were computed by the NUPIPE program using different mass models and, in most cases, different ARS's than the original calculations. More importantly, the reanalyses were based on field-verified, as-built conditions in 1979, which, in some cases, differ significantly from the original design conditions. For this reason, the new stresses and the original stresses in Table 3-1 are not comparable, as they do not necessarily represent the same physical conditions

* Soil Structure Interaction (SSI) Amplified Response Spectras (ARS) were used in the new analysis for all problems except Problem 2346 which utilizes a combination of SSI-ARS and the original ARS.

+ Problems having / are counted as separate problems example: 2869/2862/2864 are counted as three problems. Using this method of counting the total number of pipe stress problems equal 62.

TABLE 3-2

Sheet 1 of 4

NOZZLE AND PENETRATION SUMMARY
SHOCK 2 Problems

<u>System and Problem No.</u>	<u>Responsi- bility For Analysis</u>	<u>Total No. of Nozzles/ Penetrations</u>	<u>No. Acceptable (Evaluation Complete)</u>	<u>Nozzle Modification Required</u>	<u>Vendor Confirmation Being Obtained</u>
<u>Low Head Safety Injection</u>					
2555	E	1/0	1	0	1
2709	E	1/0	1	0	0
2537/2540	E	1/0	1	0	1
2539	E	0/0	NA	NA	NA
2727	S&W	2/0	2	0	2
2681	E	0/0	NA	NA	NA
2682	E	0/0	NA	NA	NA
2695	E	0/0	NA	NA	NA
2697	E	0/0	NA	NA	NA
<u>High Head Safety Injection</u>					
2689	E	0/0	NA	NA	NA
2735	E	3/0	3	0	3
<u>Containment and Recirculation Spray</u>					
2521	S&W	0/0	NA	NA	NA
2523	S&W	0/0	NA	NA	NA
2547	S&W	0/0	NA	NA	NA
2546	E	0/0	NA	NA	NA

NOZZLE AND PENETRATION SUMMARY
SHOCK 2 Problems

<u>System and Problem No.</u>	<u>Responsi- bility For Analysis</u>	<u>Total No. of Nozzles/ Penetrations</u>	<u>No. Acceptable (Evaluation Complete)</u>	<u>Nozzle Modification Required</u>	<u>Vendor Confirmation Being Obtained</u>
<u>Containment and Recirculation Spray (Cont'd)</u>					
2541	E	0/0	NA	NA	NA
2542	E	0/0	NA	NA	NA
2543	E	0/0	NA	NA	NA
2560	E	1/0	1	0	0
2561	E	1/0	1	0	0
2544	E	1/0	1	0	0
2533	E	1/0	1	0	0
2548	E	1/0	1	0	0
2545	E	1/0	1	0	0
2744	E	0/0	NA	NA	NA
2745	E	0/0	NA	NA	NA
2753	E	1/0	1	0	0
2754	E	1/0	1	0	1
2751	E	2/0	2	0	0
2752	E	2/0	2	0	0
2549	S&W	0/0	NA	NA	NA
2755	E	2/0	2	0	2
2756	E	2/0	2	0	0
2757	E	2/0	2	0	0

SURRY POWER STATION - UNIT 2

TABLE 3-2

Sheet 3 of 4

NOZZLE AND PENETRATION SUMMARY
SHOCK 2 Problems

<u>System and Problem No.</u>	<u>Responsi- bility For Analysis</u>	<u>Total No. of Nozzles/ Penetrations</u>	<u>No. Acceptable (Evaluation Complete)</u>	<u>Nozzle Modification Required</u>	<u>Vendor Confirmation Being Obtained</u>
<u>Main Steam</u>					
2577	S&W	1/1	1/1	0/0	0/0
2588	S&W	1/1	1/1	0/0	0/0
2579	S&W	1/1	1/1	0/0	0/0
2346	S&W	0/0	NA	NA	NA
<u>Feedwater</u>					
2569	S&W	1/1	1/1	0/0	0/0
2573	S&W	1/1	1/1	0/0	0/0
2571	S&W	1/1	1/1	0/0	0/0
<u>Auxiliary Feedwater</u>					
2473	E	0/0	NA	NA	NA
2683	E	3/0	3	0	3
<u>Pressurizer Spray</u>					
2771	E	1/0	1	0	1
<u>Pressurizer Safety and Relief</u>					
2000	E	5/0	5	0	1 1
<u>Residual Heat Removal</u>					
2540	E	(Listed under Low Head Safety Injection System)			

SURRY POWER STATION - UNIT 2

TABLE 3-2

Sheet 4 of 4

NOZZLE AND PENETRATION SUMMARY
SHOCK 2 Problems

<u>System and Problem No.</u>	<u>Responsi- bility For Analysis</u>	<u>Total No. of Nozzles/ Penetrations</u>	<u>No. Acceptable (Evaluation Complete)</u>	<u>Nozzle Modification Required</u>	<u>Vendor Confirmation Being Obtained</u>
<u>Residual Heat Removal (Cont'd)</u>					
2540B	E	0/0	NA	NA	NA
2508A/2508B	E	8/0	8	0	8
2554	E	0/0	NA	NA	NA
<u>Service Water</u>					
2465	E	1/0	1	0	0
2467	E	1/0	1	0	0
2469	E	1/0	1	0	0
2471	E	1/0	1	0	0
<u>Component Cooling</u>					
2601/2603	E	2/0	2	0	1
2604/2605	E	2/0	2	0	1
<u>Containment Vacuum</u>					
2650	S&W	0	NA	NA	NA
<u>IP Steam to Auxiliary Feedwater Pump</u>					
2862/2864/2869	E	1/0	1	0	0

NOTES: NA = Not Applicable
E = EBASCO
S&W = Stone & Webster

SURRY POWER STATION - UNIT 2

TABLE 3-3

Sheet 1 of 2

PIPE STRESS HARDWARE MODIFICATION SUMMARY

<u>System Name and Problem No.</u>	<u>Reanalysis Responsibility</u>	<u>MKS No.</u>	<u>Overstressed Condition</u>	<u>Attributed To:</u>	<u>Resolution</u>	<u>No. of Modifications</u>
<u>Low Head Safety Injection</u>						
2709	E	122L1	Seismic overstress	Seismic Reanalysis	Spring hanger replaced by rigid restraint.	1
2537/2540	E	122A1 117B1	Thermal overstress	As-built	Removed a restraint, anchor replaced by restraints and a snubber.	2
2539	E	122J1 122K1	Thermal overstress (Branch Line)	As-built	Removed a restraint	1
<u>Containment and Recirculation Spray</u>						
2549	S&W	123C2	Pipe contacts crane wall during seismic condition.	Seismic Reanalysis	Lateral support added.	1
2544	E	123G1	Thermal overstress	As-built	Removed a restraint.	1
2745	E	123K1	Seismic anchor move- ment overstress	As-built	Vertical restraints replaced by spring hangers at two loca- tions	2
2752	E	123N2	Thermal overstress (Branch Line)	As-built	Removed a restraint.	1
<u>Pressurizer Spray</u>						
2771	E	125A1	Seismic overstress	As-built	Two restraints added.	2
<u>Residual Heat Removal</u>						
2508B	E	117A1	Thermal overstress Branch line	As-built	Rerouting of 1-1/2 in. pipe	1
2540	(Listed under Low Head Safety Injection System)					

SURRY POWER STATION - UNIT 2

TABLE 3-3

Sheet 2 of 2

PIPE STRESS HARDWARE MODIFICATION SUMMARY

<u>System Name and Problem No.</u>	<u>Reanalysis Responsibility</u>	<u>MKS No.</u>	<u>Overstressed Condition</u>	<u>Attributed To:</u>	<u>Resolution</u>	<u>No. of Modifications</u>
<u>Residual Heat Removal (Cont'd)</u>						
2540B	E	117B	Thermal and seismic overstress	As-built	Anchor replaced by vertical restraint, horizontal restraint removed.	2
<u>Component Cooling</u>						
2604/ 2605	E	112AA1 112AB1	Seismic overstress	Seismic Reanalysis	Two restraints added.	2
<u>HP Steam to Auxiliary Feedwater Pump</u>						
2862/ 2864/ 2869	E	131A1 131B1 131C1	Thermal and seismic overstress	As-built/ Seismic Reanalysis	Two anchors replaced by restraints, two snubbers and a spring added.	5
<u>Feedwater</u>						
2569	S&W	100G1	Insufficient branch line flexibility	As-built	Remove existing U-bolt on 3/4 in. line	1

Notes:

E = EBASCO

S&W = Stone & Webster

SURRY POWER STATION - UNIT 2

TABLE 3-4

Sheet 1 of 2

HARDWARE MODIFICATION SUMMARY
DUE TO NOZZLE AND PENETRATION OVERLOADING

<u>System Name and Problem No.</u>	<u>Reanalysis Responsibility</u>	<u>Equipment No.</u>	<u>Attributed To:</u>	<u>Resolution</u>	<u>No. of Modifications</u>
<u>Low Head Safety Injection</u>					
2555	E	2-SI-TK-1B	As-built/ Seismic Reanalysis	One restraint added, One spring hanger replaced by a two direction restraint	2
<u>High Head Safety Injection</u>					
2735	E	2-CH-P-1A 2-CH-P-1B 2-CH-P-1C	Seismic Reanalysis	Ten restraints added, one vertical restraint replaced by spring hanger, two anchors added	13
<u>Containment and Recirculation Spray</u>					
2544	E	2-RS-E-1D	As-built	One restraint removed	1
2533	E	2-RS-E-1C	As-built	Two restraints added	2
2753	E	2-CS-P-1B	As-built/ Seismic Reanalysis	One vertical restraint replaced by spring hanger, two restraints added	3
2754	E	2-CS-P-1A	As-built/ Seismic Reanalysis	One vertical restraint replaced by spring one horizontal restraint added.	2
2751	E	2-RS-P-2A	Seismic Reanalysis	One restraint added	1
2752	E	2-RS-P-2B	Seismic Reanalysis	One restraint added	1
2755	E	2-CS-P-1B 2-CS-P-1A	As-built/ Seismic Reanalysis	One restraint added two vertical restraints removed.	3
2756	E	2-RS-E-1A 2-RS-P-1A	As-built	One anchor and one restraint removed	2

SURRY POWER STATION - UNIT 2

TABLE 3-4

Sheet 2 of 2

HARDWARE MODIFICATION SUMMARY
DUE TO NOZZLE AND PENETRATION OVERLOADING

<u>System Name and Problem No.</u>	<u>Reanalysis Responsibility</u>	<u>Equipment No.</u>	<u>Attributed To</u>	<u>Resolution</u>	<u>No. of Modifications</u>
<u>Containment and Recirculation Spray (Cont'd)</u>					
2757	E	2-RS-E-1B 2-RS-P-1B	As-built	One anchor removed	1
<u>Auxiliary Feedwater</u>					
2683	E	2-FW-P-2 2-FW-P-3B 2-FW-P-3A	Seismic Reanalysis	Three horizontal and two vertical restraints added.	5
<u>Pressurizer Safety & Relief</u>					
2000	E	2-RC-TK-2	As-built	A spring replaced by a rigid hanger and a horizontal snubber, two restraints replaced by snubbers, lateral restraint deleted.	4
<u>Residual Heat Removal</u>					
2508B	E	2-RH-P-1A 2-RH-P-1B	Seismic Reanalysis	Six snubbers added, two springs replaced by restraints, one spring hanger added, one vertical restraint added.	10
<u>Service Water</u>					
2471	E	2-RS-E-1D	As-built	One restraint removed	1
<u>Component Cooling</u>					
2601/2603	E	2-RH-E-1B	As-built Seismic Reanalysis	Four vertical restraints replaced by springs and snubbers, two restraints added.	6

Note: E = EBASCO

SURRY POWER STATION - UNIT 2

SECTION 4

PIPE SUPPORT RESULTS

Table 4-1, Pipe Support Analysis Summary, summarizes the pipe support reanalysis program. Six hundred ninety four (694) supports (467 inside the containment, 218 outside the containment) on lines originally analyzed using Shock 2, were reanalyzed as part of this Show Cause effort. Two hundred fifty eight (258) hardware modifications (175 inside the containment, 83 outside the containment) have been identified. The modifications identified due to the pipe support reanalysis are listed in Table 4-2, Pipe Support Hardware Modification Summary.

Those modifications which result from the piping reanalysis are identified in Section 3. Only the modifications which result from the pipe support reanalysis are reported in Table 4-2. Of the modifications identified, only 109 were the result of seismic reanalysis of the piping systems identified in the Show Cause Order, while 149 were the result of differences identified between the as-built conditions and the original design. These conditions are identified in the table for each problem.

For all the problems in which the SSI-ARS are used, the seismic inertial loads have been increased by a factor of 1.5 for DBE per the NRC letter of May 25, 1979, and by a factor of 1.25 for OBE per the NRC letter of November 15, 1979.

SURRY POWER STATION - UNIT 2

TABLE 4-1

Sheet 1 of 4

PIPE SUPPORT ANALYSIS SUMMARY

<u>System Name and Problem Number</u>	<u>Analysis Responsibility</u>	<u>Location</u>	<u>Total Number of Supports</u>	<u>Evaluation Complete</u>	<u>Modifications or Additions Required</u>
<u>Low Head Safety Injection System</u>					
2537/2540	E	IC	33	33	17
2555	E	IC	17	17	9
2539	E	IC	7	7	5
2681	E	OC	4	4	3
2682	E	OC	4	4	3
2695	E	OC	10	10	4
2697	E	OC	9	9	6
2709	E	IC	9	9	3
2727	S&W	OC	17	17	8
<u>High Head Safety Injection System</u>					
2689	E	OC	5	5	4
2735	E	OC	52	52	23
<u>Containment and Recirculation Spray</u>					
2521	S&W	IC	15	15	4
2523	S&W	IC	16	16	5
2547	S&W	IC	13	13	6
2549	S&W	IC	4	4	1
2546	E	IC	12	12	6

SURRY POWER STATION - UNIT 2

TABLE 4-1

Sheet 2 of 4

PIPE SUPPORT ANALYSIS SUMMARY

<u>System Name and Problem Number</u>	<u>Analysis Responsibility</u>	<u>Location</u>	<u>Total Number of Supports</u>	<u>Evaluation Complete</u>	<u>Modifications or Additions Required</u>	
<u>Containment and Recirculation Spray (Cont'd)</u>						
2541	E	IC	11	11	6	
2542	E	IC	11	11	4	
2543	E	IC	12	12	6	1
2560	E	IC	4	4	1	
2561	E	IC	5	5	3	
2544	E	IC	6	6	2	1
2533	E	IC	5	5	1	
2548	E	IC	15	15	6	1
2545	E	IC	17	17	9	
2744	E	OC	4	4	3	
2745	E	OC	4	4	2	1
2753	E	OC	4	4	1	
2754	E	OC	3	3	1	
2751	E	OC	5	5	1	
2752	E	OC	4	4	0	
2755	E	OC	8	8	4	1
2756	E	IC	7	7	2	
2757	E	IC	9	9	3	

SURRY POWER STATION - UNIT 2

TABLE 4-1

Sheet 3 of 4

PIPE SUPPORT ANALYSIS SUMMARY

<u>System Name and Problem Number</u>	<u>Analysis Responsibility</u>	<u>Location</u>	<u>Total Number of Supports</u>	<u>Evaluation Complete</u>	<u>Modifications or Additions Required</u>	
<u>Main Steam</u>						
2577	S&W	IC	9	9	2	
2588	S&W	IC	2	2	0	
2579	S&W	IC	5	5	3	
2346	S&W	OC	41	41	6	
<u>Feedwater</u>						
2569	S&W	IC	9	9	4	
2573	S&W	IC	3	3	0	
2571	S&W	IC	6	6	1	
<u>Auxiliary Feedwater</u>						
2473	E	IC	34	34	12	1
2683	E	OC	22	22	8	
<u>Pressurizer Spray and Relief</u>						
2771	E	IC	32	32	7	
2000	E	IC	29	29	15	1
<u>Residual Heat Removal</u>						
2508A/B	E	IC	45	45	4	
2540B	E	IC	5	5	4	1
2554	E	OC	1	1	1	

SURRY POWER STATION - UNIT 2

TABLE 4-1

Sheet 4 of 4

PIPE SUPPORT ANALYSIS SUMMARY

<u>System Name and Problem Number</u>	<u>Analysis Responsibility</u>	<u>Location</u>	<u>Total Number of Supports</u>	<u>Evaluation Complete</u>	<u>Modifications or Additions Required</u>	
<u>Service Water</u>						
2465	E	IC	2	2	1	
2467	E	IC	2	2	1	
2469	E	IC	1	1	0	
2471	E	IC	1	1	1	1
<u>Component Cooling</u>						
2601	E	IC	16	16	5	
2603	E	IC	13	13	5	1
2604	E	IC	17	17	7	
2605	E	IC	17	17	4	
<u>Containment Vacuum</u>						
2650	S&W	OC	3	3	3	1
<u>High Pressure Steam to Aux Feedwater Pump</u>						
2862	E	OC	8	8	1	1
2864	E	OC	3	3	0	
2869	E	OC	7	7	1	

Notes: E = EBASCO

S&W = Stone & Webster

IC = Inside Containment

OC = Outside Containment

SURRY POWER STATION - UNIT 2

TABLE 4-2

Sheet 1 of 12

PIPE SUPPORT HARDWARE MODIFICATION SUMMARY

<u>SYSTEM NAME AND PROBLEM NUMBER</u>	<u>ANALYSIS RESPONSIBILITY</u>	<u>LOCATION</u>	<u>MKS SUPPORT NUMBER</u>	<u>REASON FOR MODIFICATION</u>	<u>ATTRIBUTABLE TO</u>	<u>RESOLUTION</u>	
<u>Low Head Safety Injection System</u>							
2537/2540	E	IC					
2537	E	IC	2,4	Local pipe wall stress over allowable	Seismic Reanalysis	Modify support	1
			6	Support member over allowable	As-built	Modify support	
			9	Support does not allow lateral movement	As-built	Modify support	1
2540	E	IC	5	Insufficient clearance	Seismic Reanalysis	Modify support	
			7,8,9,10,13,26	Support member over allowable	As-built	Modify support	1
			12,28	Pipe clamp over allowable	As-built	Modify support	1
			17,19	U-bolt over allowable	As-built	Modify support	
			1	Weld over allowable	As-built	Add weld	1
			8A	Upward vertical restraint required	Seismic Reanalysis	Modify restraint for uplift load	
2555	E	IC	8	Support member over allowable	As-built	Modify support	1
			3	Weld over allowable	As-built	Add weld	
			4,5	Local pipe wall stress over allowable	Seismic Reanalysis	Modify support	1
			9,12	Support member over allowable	Seismic Reanalysis	Modify support	1
			12A	Upward vertical restraint required	Seismic Reanalysis	Modify restraint for uplift load	
			13,14	Insufficient lateral clearance	As-built	Modify support	1
2539	E	IC	2	Upward vertical restraint required	Seismic Reanalysis	Modify restraint for uplift load	
			1	Upward vertical restraint required	Seismic Reanalysis	Modify restraint for uplift load	

SURRY POWER STATION - UNIT 2

TABLE 4-2

Sheet 2 of 12

PIPE SUPPORT HARDWARE MODIFICATION SUMMARY

<u>SYSTEM NAME AND PROBLEM NUMBER</u>	<u>ANALYSIS RESPONSIBILITY</u>	<u>LOCATION</u>	<u>MKS SUPPORT NUMBER</u>	<u>REASON FOR MODIFICATION</u>	<u>ATTRIBUTABLE TO</u>	<u>RESOLUTION</u>	
<u>Low Head Safety Injection System (Cont'd)</u>							
2539 (Cont'd)	E	IC	H-1**	Support member over allowable	As-built	Modify support	1
			3,4	Support member over allowable	As-built	Modify support	
2709	E	IC	7	Support member over allowable	As-built	Modify support	
			2,3	Local pipe wall stresses over allowable	Seismic Reanalysis	Modify support	
2727	S&W	OC	8	Support over allowable	Seismic Reanalysis	Modify Support	
			13	Support and weld over allowable	Seismic Reanalysis	Modify Support	
			11	Loads out of range of spring	As-built	Replace spring	
			14	Loads out of spring range	Seismic Reanalysis	Replace spring	
			15	Loads out of spring range	Seismic Reanalysis	Replace spring	
			16	Loads out of spring range	Seismic Reanalysis	Replace spring	1
			18	Loads out of spring range	Seismic Reanalysis	Replace spring	
2695	E	OC	19	Supports restraint lateral movement	As-built	Modify Support	
			H-50	Support member over allowable	As-built	Modify support	1
			A-16	Support member over allowable	As-built	Modify support	
			C-53	Support member over allowable	As-built	Modify support	
			A-17	Support member over allowable	As-built	Modify support	

SURRY POWER STATION - UNIT 2

TABLE 4-2

Sheet 3 of 12

PIPE SUPPORT HARDWARE MODIFICATION SUMMARY

<u>SYSTEM NAME AND PROBLEM NUMBER</u>	<u>ANALYSIS RESPONSIBILITY</u>	<u>LOCATION</u>	<u>MKS SUPPORT NUMBER</u>	<u>REASON FOR MODIFICATION</u>	<u>ATTRIBUTABLE TO</u>	<u>RESOLUTION</u>	
<u>Low Head Safety Injection System (Cont'd)</u>							
2697	E	OC	H-49	Support member over allowable	As-built	Modify support	
			C-7	Support not acting	As-built	Removed support	
			C-17,C-18	Support member over allowable	As-built	Modify support	
			A-14	Support member over allowable	As-built	Modify support	
			A-15	Support member over allowable	As-built	Modify support	
2681	E	OC	2,4	Support member over allowable	As-built	Modify support	
			5	U-bolt over allowable	As-built	Modify support	
2682	E	OC	4	Support member over allowable	As-built	Modify support	
			2	Support member over allowable	As-built	Modify support	
			5	U-bolt over allowable	As-built	Modify support	
<u>High Head Safety Injection System</u>							
2689	E	OC	C-38,C-39	Support member over allowable	As-built	Modify support	
			C-40,C-41	Support member over allowable	As-built	Modify support	
2735	E	OC	19,34,42 22,37,45,28 36,21,23,44	Support member over allowable	As-built	Modify support	1
			1,3,16,31,39,24	Weld over allowable	As-built	Add weld	
			4,6,18,33,41	U-bolt over allowable	Seismic reanalysis	Modify support	1
			26	Local pipe will stress over allowable	Seismic reanalysis	Modify support	1
<u>Containment and Recirculation Spray</u>							
2521	S&W	IC	2	U-bolt capacity for side- load in insufficient	Seismic Reanalysis	Add members to resist sideload	

SURRY POWER STATION - UNIT 2

TABLE 4-2

Sheet 4 of 12

PIPE SUPPORT HARDWARE MODIFICATION SUMMARY

<u>SYSTEM NAME AND PROBLEM NUMBER</u>	<u>ANALYSIS RESPONSIBILITY</u>	<u>LOCATION</u>	<u>HKS SUPPORT NUMBER</u>	<u>REASON FOR MODIFICATION</u>	<u>ATTRIBUTABLE TO</u>	<u>RESOLUTION</u>
<u>Containment and Recirculation Spray (Cont'd)</u>						
2521 (Cont'd)	S&W	IC	3	Frame overstressed with new loads out of springs range	Seismic Reanalysis	Modify existing frame and replace springs
			4	U-strap has insufficient capacity	Seismic Reanalysis	Replace existing strap with new framing
			5	Local stress	Seismic Reanalysis	Eliminate anchor and add vert/lat restraint
2523	S&W	IC	1	U-bolt capacity for side-load is insufficient	Seismic Reanalysis	Add members to resist sideload
			2	Frame overstressed	Seismic Reanalysis	Replace existing frame
			3	Capacity of springs insufficient	Seismic Reanalysis	Replace springs
			4	U-strap has insufficient capacity	Seismic Reanalysis	Replace existing strap with new framing
			5	Local stress	Seismic Reanalysis	Eliminate anchor and add vert/lat restraint
2547	S&W	IC	2	Lateral load fails U-bolt	As-built	Add lateral restraint
			4	Rod hanger cannot resist upward load	Seismic Reanalysis	Replace with sway strut
			6	Insufficient clearance for thermal movement	As-built	Remove lateral stop
			8	Insufficient lateral clearance for thermal movement	As-built	Remove lateral stops (angle)

SURRY POWER STATION - UNIT 2

TABLE 4-2

Sheet 5 of 12

PIPE SUPPORT HARDWARE MODIFICATION SUMMARY

<u>SYSTEM NAME AND PROBLEM NUMBER</u>	<u>ANALYSIS RESPONSIBILITY</u>	<u>LOCATION</u>	<u>NKS SUPPORT NUMBER</u>	<u>REASON FOR MODIFICATION</u>	<u>ATTRIBUTABLE TO</u>	<u>RESOLUTION</u>	
<u>Containment and Recirculation Spray (Cont'd)</u>							
2547 (Cont'd)	S&W	IC	10	Insufficient lateral clearance for thermal movement	As-built	Remove lateral stops (angle)	1
			11	Local stress and support frame overstressed	As-built	Modify structure	
2549	S&W	IC	2	U-bolt failure	As-built	Add lateral restraint	
2546	E	IC	6	Support member over allowable	As-built	Modify support	
			9	Insufficient lateral & vertical clearance	Seismic Reanalysis	Modify restraint	
			7,8	Insufficient lateral clearance	Seismic Reanalysis	Modify restraint	
			2	U-bolt restricts lateral movement	As-built	Modify support	1
			22A	Anchor stress over allowable	Seismic Reanalysis	Relocate adjacent restraint	
2541	E	IC	6,21	Support member over allowable	As-built	Modify support	
			7,9	Insufficient lateral clearance	Seismic Reanalysis	Modify support	
			2,8	U-bolt restricts lateral movements	As-built	Modify support	1
2542	E	IC	15,23	Support member over allowable	As-built	Modify support	1
			13,17	Insufficient lateral clearance	Seismic Reanalysis	Modify support	

SURRY POWER STATION - UNIT 2

TABLE 4-2

Sheet 6 of 12

PIPE SUPPORT HARDWARE MODIFICATION SUMMARY

<u>SYSTEM NAME AND PROBLEM NUMBER</u>	<u>ANALYSIS RESPONSIBILITY</u>	<u>LOCATION</u>	<u>MKS SUPPORT NUMBER</u>	<u>REASON FOR MODIFICATION</u>	<u>ATTRIBUTABLE TO</u>	<u>RESOLUTION</u>
<u>Containment and Recirculation Spray</u>						
2543	E	IC	15,23	Support member over allowable	As-built	Modify support
			12,13,14	Insufficient lateral clearance	Seismic Reanalysis	Modify restraint
			24A	Support member over allowable	Seismic Reanalysis	Relocate adja- cent restraint
2560	E	IC	H-50	U-bolt over allowable	Seismic Reanalysis	Modify support
2561	E	IC	H-91	Upward vertical restraint required	Seismic Reanalysis	Modify for uplift load
			H-50	U-bolt over allowable	Seismic Reanalysis	Modify support
			H-98A	Support member over allowable	As-built	Remove vertical restraint
2544	E	IC	H-67	Upward vertical restraint required	Seismic Reanalysis	Modify support for uplift load
			H-68	Support member over allowable	As-built	Modify support
2533	E	IC	H-3	Support member over allowable	As-built	Modify support
2548	E	IC	7	Support member over allowable	As-built	Modify support
			10	Support member over allowable	As-built	Modify support
			12	U-bolt over allowable	As-built	Modify support
			9A	Upward vertical restraint required	Seismic Reanalysis	Modify support for uplift load
			11	Support member over allowable	As-built	Modify support

1

1

SURRY POWER STATION - UNIT 2

TABLE 4-2

Sheet 7 of 12

PIPE SUPPORT HARDWARE MODIFICATION SUMMARY

<u>SYSTEM NAME AND PROBLEM NUMBER</u>	<u>ANALYSIS RESPONSIBILITY</u>	<u>LOCATION</u>	<u>MKS SUPPORT NUMBER</u>	<u>REASON FOR MODIFICATION</u>	<u>ATTRIBUTABLE TO</u>	<u>RESOLUTION</u>	
<u>Containment and Recirculation Spray (Cont'd)</u>							
2548 (Cont'd)	E	IC	8	Support member over allowable	As-built	Modify support	1
2545	E	IC	3	Support member over allowable	As-built	Modify support	
			14	Upward vertical restraint required	Seismic Reanalysis	Modify restraint for uplift load	
			2	U-bolt over allowable	As-built	Modify support	
			4	Support member over allowable	As-built	Modify support	
			7	Support member over allowable	As-built	Modify support	
			10,15	Weld over allowable	As-built	Add weld	
			6,8	Support member over allowable	As-built	Modify support	
2744	E	OC	2,3	Loads out of spring range	As-built	Two rigid re- straints re- placed by springs	
			1	Local pipe wall stress over allow- able	Seismic Reanalysis	Modify support	1
2745	E	OC	4	Upward vertical restraint required	Seismic Reanalysis	Modify support	
			3	Support does not al- low lateral movement	As-built	Modify support	1
2751	E	OC	2	Local pipe wall stress over allowable	Seismic Reanalysis	Modify support	
2753	E	OC	1	Support member over allowable	As-built	Modify support	

SURRY POWER STATION - UNIT 2

TABLE 4-2

Sheet 8 of 12

PIPE SUPPORT HARDWARE MODIFICATION SUMMARY

<u>SYSTEM AND PROBLEM NUMBER</u>	<u>ANALYSIS RESPONSIBILITY</u>	<u>LOCATION</u>	<u>MKS SUPPORT NUMBER</u>	<u>REASON FOR MODIFICATION</u>	<u>ATTRIBUTABLE TO</u>	<u>RESOLUTION</u>
<u>Containment and Recirculation Spray (Cont'd)</u>						
2754	E	OC	1	Support member over allowable	As-built	Modify support
2755	E	OC	7,8	Upward vertical restraint required	Seismic Reanalysis	Modify support for uplift load
			9	Upward vertical restraint required	Seismic Reanalysis	Redesign support for uplift load
			11	Weld over allowable	As-built	Add weld
2756	E	IC	54,55	Support member over allowable	As-built	Modify support
2757	E	IC	H-90	Upward vertical restraint required	Seismic Reanalysis	Modify support for uplift load
			H-63, H-88	Support member over allowable	As-built	Modify support
<u>Main Steam</u>						
2577	S&W	IC	1	Local stress ex- ceeds allowable	As-built	Modify lug
			9	Local stress ex- ceeds allowable	As-built	Replace lug with clamp
2579	S&W	IC	1	Spring variability ratio exceeded	Seismic Reanalysis	Replace spring
			4	Loads outside spring range	Seismic Reanalysis	Replace spring
			5	Spring variability ratio exceeded. Local stress over allowable.	Seismic Reanalysis	Replace spring Replace pipe lug with clamp.
2346	S&W	OC	1,2,3	Loads outside spring range, local over- stress in lug	Seismic Reanalysis	Replace springs, modify lug.

SURRY POWER STATION - UNIT 2

TABLE 4-2

Sheet 8a of 12

PIPE SUPPORT HARDWARE MODIFICATION SUMMARY

<u>SYSTEM AND PROBLEM NUMBER</u>	<u>ANALYSIS RESPONSIBILITY</u>	<u>LOCATION</u>	<u>MKS SUPPORT NUMBER</u>	<u>REASON FOR MODIFICATION</u>	<u>ATTRIBUTABLE TO</u>	<u>RESOLUTION</u>
<u>Main Steam (Cont'd)</u>						
2346 (Cont'd)	S&W	OC	5,7,9	Snubbers, local stress, and support members are overstressed	Seismic Reanalysis	Modify snubbers and lugs

SURRY POWER STATION - UNIT 2

TABLE 4-2

Sheet 9 of 12

PIPE SUPPORT HARDWARE MODIFICATION SUMMARY

<u>SYSTEM NAME AND PROBLEM NUMBER</u>	<u>ANALYSIS RESPONSIBILITY</u>	<u>LOCATION</u>	<u>MKS SUPPORT NUMBER</u>	<u>REASON FOR MODIFICATION</u>	<u>ATTRIBUTABLE TO</u>	<u>RESOLUTION</u>
<u>Feedwater</u>						
2569	S&W	IC	2,3	Loads outside spring range	Seismic Reanalysis	Replace springs
			6	Thermal movement	As-built	Reduce pin-to pin dimension
			7	Insufficient clearance for lateral movement	Seismic Reanalysis	Modify support
2571	S&W	IC	5	Loads outside spring range	Seismic Reanalysis	Replace springs
<u>Auxiliary Feedwater</u>						
2473	E	IC	8,18	Lateral clearance insufficient	Seismic Reanalysis	Modify restraint
			14	Upward vertical restraint required	Seismic Reanalysis	Modify restraint for uplift load
			16	Upward vertical restraint required	Seismic Reanalysis	Modify restraint for uplift load
			11,13,26,29,32	Weld over allowable	As-built	Modify support
			22	Support member over allowable	As-built	Modify support
			28,31	Support member over allowable	As-built	Modify support
2683	E	OC	H-8A	U-bolt over allowable	As-built	Modify support
			H-11	U-bolt over allowable	As-built	Modify support
			H-9	Support member over allowable	As-built	Modify support
			H-1(118G1), H-5(118G1)	Local pipe wall stress over allowable	Seismic Reanalysis	Modify support
			H-4	U-bolt over allowable	As-built	Modify support
			H-5(118G2)	Upward vertical restraint required	Seismic Reanalysis	Modify support

SURRY POWER STATION - UNIT 2

TABLE 4-2

Sheet 10 of 12

PIPE SUPPORT HARDWARE MODIFICATION SUMMARY

<u>SYSTEM NAME AND PROBLEM NUMBER</u>	<u>ANALYSIS RESPONSIBILITY</u>	<u>LOCATION</u>	<u>MKS SUPPORT NUMBER</u>	<u>REASON FOR MODIFICATION</u>	<u>ATTRIBUTABLE TO</u>	<u>RESOLUTION</u>	
<u>Auxiliary Feedwater (Cont'd)</u>							
2683 (Cont'd)	E	OC	H-1(118G2)	Support does not allow lateral movement	As-built	Modify support	1
<u>Pressurizer Spray and Relief</u>							
2771	E	IC	33	Upward vertical restraint required	Seismic Reanalysis	Modify support for uplift load	
			5,23	Weld over allowable	As-built	Add weld	
			6,24	Support member over allowable	As-built	Modify support	1
			26,27	Upward vertical restraint required	Seismic Reanalysis	Modify for uplift load	
2000	E	IC	4,12,H-5,8,10,17	Local pipe wall stress over allowables	Seismic Reanalysis	Modify support	1
			15	Insufficient vertical clearance	Seismic Reanalysis	Modify support	
			13	Support restraints lateral movement	As-built	Modify support	
			4A,7,H-1A,11,21A,113	Support member over allowable	As-built	Modify support	
			H-2	Weld over allowable	As-built	Add weld	1
<u>Residual Heat Removal</u>							
2508A/2508B	E	IC	H-36,H-15,H-17	Support member over allowable	As-built	Modify support	
			H-12	Vertical support not required	Seismic Reanalysis	Remove support	
2540B	E	IC	20,21	Upward vertical restraint required	Seismic Reanalysis	Modify for uplift load	1

SURRY POWER STATION - UNIT 2

TABLE 4-2

Sheet 11 of 12

PIPE SUPPORT HARDWARE MODIFICATION SUMMARY

<u>SYSTEM NAME AND PROBLEM NUMBER</u>	<u>ANALYSIS RESPONSIBILITY</u>	<u>LOCATION</u>	<u>MKS SUPPORT NUMBER</u>	<u>REASON FOR MODIFICATION</u>	<u>ATTRIBUTABLE TO</u>	<u>RESOLUTION</u>	
<u>Residual Heat Removal (Cont'd)</u>							
2540B (Cont'd)	E	IC	23	Insufficient lateral clearance	Seismic Reanalysis	Modify support	1
			22	Support member over allowable	As-built	Modify support	
2554	E	OC	H-31	Insufficient lateral clearance	Seismic Reanalysis	Modify support	1
<u>Service Water</u>							
2465	E	IC	1	Support member over allowable	As-built	Modify support	
2467	E	IC	1	Support member over allowable	As-built	Modify support	
2471	E	IC	2	Local pipe wall stress over allowable	Seismic Reanalysis	Modify support	
<u>Component Cooling</u>							
2601	E	IC	H-32A, H-28, H-44	Uplift vertical restraint required	Seismic Reanalysis	Modify support for uplift	
			H-30	Insufficient lateral clearance	Seismic Reanalysis	Modify support	
			H-31	Weld over allowable	As-built	Add weld	
2603	E	IC	4	Insufficient lateral clear- ance	Seismic Reanalysis	Modify support	
			6,8	Support member over allowable	As-built	Modify support	1
			9	Upward vertical restraint required	Seismic Reanalysis	Modify support for uplift load	
			10	Upward vertical restraint required	Seismic Reanalysis	Modify support for uplift load	
2604	E	IC	H-38A	Upward vertical restraint required	Seismic Reanalysis	Modify support for uplift load	

SURRY POWER STATION - UNIT 2

TABLE 4-2

Sheet 12 of 12

PIPE SUPPORT HARDWARE MODIFICATION SUMMARY

SYSTEM NAME AND PROBLEM NUMBER	ANALYSIS RESPONSIBILITY	LOCATION	NKS SUPPORT NUMBER	REASON FOR MODIFICATION	ATTRIBUTABLE TO	RESOLUTION	
<u>Component Cooling (Cont'd)</u>							
2604 (Cont'd)	E	IC	H-38B	Upward vertical restraint required	Seismic Reanalysis	Modify support for uplift load	1
			H-35,H-36,H-38C	Weld over allowable	As-built	Add weld	1
			H-38	Support member over allowable	As-built	Modify support	
			H-38D	Local pipe wall stress over allowable	Seismic Reanalysis	Modify support	1
2605	E	IC	H-25	Support member over allowable	As-built	Modify support	
			H-25B	Upward vertical restraint required	Seismic Reanalysis	Modify support for uplift load	
			H-25A	Upward vertical restraint required	Seismic Reanalysis	Modify support for uplift load	
			H-23	Weld over allowable	As-built	Add weld	1
<u>Containment Vacuum</u>							
2650	S&W	OC	1	Support restraint lateral movement	As-built	Modify support	
			2	Local stress at attachment on pipe exceeds allowable	As-built	Move support above elbow and use trunion	1
			3	Local stress	Seismic Reanalysis	Modify support	1
<u>High Pressure Steam To Aux. Feedwater Pump</u>							
2862	E	OC	3	Support member over allowable	As-built	Modify support	
2869	E	OC	5	Support member over allowable	As-built	Modify support	

Notes:

** Originally Problem No. 2708

SURRY POWER STATION - UNIT 2

TABLE 5-1

SCHEDULE FOR COMPLETION

<u>Location of Problem</u>	<u>Reanalysis Responsibility</u>	<u>Stress Reanalysis</u>	<u>Status</u>	
			<u>Support/Restraint Reanalysis</u>	<u>Modification Installation</u>
Inside Containment Systems	E/S&W	Complete	Complete	Prior to start-up following SGR outage
Outside Containment Systems				
Low Head Safety Injection	E/S&W	Complete	Complete	Prior to start-up following SGR outage
High Head Safety Injection	E	Complete	Complete	Prior to start-up following SGR outage
Containment Recirculation Spray	E	Complete	Complete	Prior to start-up following SGR outage
Auxiliary Feedwater	E	Complete	Complete	Prior to start-up following SGR outage
Balance of Systems	E/S&W	Complete	Complete	Prior to start-up following SGR outage

NOTES: E = EBASCO
S&W = Stone & Webster
SGR = Steam Generator Replacement

SECTION 5

SCHEDULE FOR COMPLETION

The status of the reanalysis of those systems subject to Show Cause and the installation of modifications identified as being required by the reanalysis is shown in Table 5-1, Schedule for Completion.

Reanalysis on all systems is complete pending final review. Required modifications on all lines will be installed prior to start up of the Unit following the Steam Generator Replacement Outage.

1

SURRY POWER STATION - UNIT 2

SECTION 6

HIGH ENERGY LINE BREAKS

For the high energy lines outside the containment addressed in Appendix D of the Final Safety Analysis Report (FSAR), only the main steam lines are included in this stress reanalysis.

Each of the main steam lines has two terminal break locations, one at the containment penetration and the other at the main steam manifold. Each of the risers to the main steam relief valve headers has two terminal break locations, one at the main steam lines, the other at the tee into the main steam header. These terminal breakpoints are predetermined and are not changed as a result of the stress reanalysis.

Two intermediate break locations were originally determined based upon maximum primary plus secondary stresses. Upon reanalysis, two additional breakpoints on each of the steam lines were located. One of these points is located immediately upstream of the check valve (TV-MS201A, TV-MS201B, TV-MS201C) and the other point is at the elbow just downstream of the check valve. All of these points will be included in the augmented inservice inspection program.

1

SURRY POWER STATION - UNIT 2

SECTION 7

CONSERVATISMS

The conservatisms applied to the design of the piping systems for Surry Power Station Units 1 and 2 were extensively delineated in Section 7 of the VEPCO June 5, 1979 submittal (Serial Number 453). The seismic capability of nuclear piping and the seismic event probability at the Surry Power Station were discussed in that submittal. The design of Unit 2 closely follows the design of Unit 1, applying the same conservative criteria with respect to safety systems and system redundancies.

Similiarly, the reanalysis efforts on Surry Power Station Unit 2 closely follows that of Unit 1, applying the same stress limits and soil structure interaction amplified response spectra (SSI-ARS).

Paragraphs 7.1, 7.2, 7.3 and 7.4 describe the differences in the conservatisms applied to the Unit 2 reanalysis.

7.1 FIELD VERIFICATION OF AS-BUILT CONDITIONS

To ensure that the pipe stress and pipe support reanalysis is performed as accurately as possible, field verification of as-built conditions has been performed. The field verification produced detailed piping isometric drawings and pipe support sketches for each support upon which reanalysis is based. All field-verified piping isometrics and pipe support sketches are independently verified by Surry Power Station quality control personnel.

7.2 QUALITY ASSURANCE/ENGINEERING ASSURANCE

7.2.1 EBASCO QUALITY ASSURANCE

The EBASCO QA Topical Report ETR-1001, Revision 7, as approved by the Nuclear Regulatory Commission on December 15, 1978, is being applied to the Surry Unit 2 reanalysis activities.

7.2.2 STONE & WEBSTER QUALITY ASSURANCE/ENGINEERING ASSURANCE

The Stone & Webster Quality Assurance program described in the VEPCO June 5, 1979 submittal to NRC, is being applied to the Surry Unit 2 reanalysis activities.

7.3 USE OF AMPLIFIED RESPONSE SPECTRA

The use of amplified response spectra was extensively discussed in the June 5, 1979 submittal. The soil structure interaction amplified response Spectra (SSI-ARS) are being used in the reanalysis in most cases.

For pipe runs extending over a range of elevations S&W and EBASCO utilized an amplified response spectra enveloping the acceleration of the mass points spanning the elevation of the piping run.

SURRY POWER STATION - UNIT 2

7.4 CONSERVATISMS APPLIED TO INERTIAL STRESSES

In accordance with the NRC letters of May 25, 1979 and November 15, 1979 to VEPCO, the seismic inertial stresses and loads computed using the SSI-ARS have been increased by a factor of 1.5 for the DBE and 1.25 for OBE conditions.

SURRY POWER STATION - UNIT 2

SECTION 8

SYSTEM OPERABILITY EVALUATION

This section has been deleted. Since all modifications will be installed prior to startup following the Steam Generator Replacement Outage, a system operability evaluation is no longer necessary.

1

SECTION 9

BRANCH LINE SUMMARY

Branch lines are evaluated to assure that sufficient flexibility exists between the run pipe and the first few restraints on the branch piping. The flexibility of the branch pipe must be evaluated separately in each of the three translational directions and must be sufficient to prevent overstresses in the branch/run pipe interface due to thermal and seismic displacements imposed on the branch pipe. The procedure is intended to provide a secondary stress check based on run pipe displacements resulting from the current analysis. If a branch line is part of the scope of work under IE Bulletin 79-14, a detailed evaluation is performed as part of the IE 79-14 effort.

S&W has performed evaluation of branch lines in accordance with Section 6 of the August 1, 1979 report for Unit 1 (Vepco Serial No. 453A).

EBASCO has performed evaluation of some of the branch lines by coding for the NUPIPE program and analyzing it for seismic anchor movement and thermal analysis. Engineering judgement is used in qualifying the branch lines with small displacements in the remaining cases. Thermal analysis is conducted by applying the thermal displacements from the run pipe and the operating temperature of the branch line. The seismic anchor movement analysis is performed by applying seismic inertia displacements. The applicable stress intensification factor (SIF) at the branch connection is included in the analysis. The stresses from both analyses are combined by absolute sum. Allowable stress is considered to be S_A .

SURRY POWER STATION - UNIT 2

SECTION 10

RESPONSE TO NRC STAFF CONCERNS

A meeting was held with the Nuclear Regulatory Commission at Ebasco Services, Jericho Offices on October 24, 1979, to review pipe stress analyses within EBASCO's scope of work. As a result of the discussions, four staff concerns were identified as delineated in the NRC Summary of Meeting Notes dated November 13, 1979. These concerns were:

- 1) The validity of support stiffness used in the piping reanalysis when, for example, a vertical trunion is welded onto a horizontal wide flange.
- 2) The pertinence of the version of B31.1 Code implemented in Control Data Corporations' NUPIPE program, which was used in the EBASCO reanalysis program.
- 3) The identification of the original loads on support H-15 in problem 2538.
- 4) The verification of the NUPIPE computer program (benchmark problems).

These concerns are addressed in the following sections.

10.1 SUPPORT STIFFNESS

The original piping analysis of Surry Unit 2 did not consider the actual stiffness of the supports. Representative support stiffness was considered during the current reanalysis.

During the pipe support reanalysis effort it has been observed that certain anchor type supports expose wide flange members to torsional moments. This type of loading condition results in a very flexible support. As a part of the pipe support reanalysis effort, anchors have been reviewed for this type of loading and members modified to resist torsion as required.

10.2 NUPIPE COMPUTER CODE

At EBASCO's request, Nuclear Services Corporation (NSC) conducted a thorough review of the NUPIPE program against the source codes, NSC has determined that all values utilized by the program, but not specified by the user as input, are pertinent to the 1967 and earlier versions of the B31.1 Power Piping Code. The code of record for Surry Unit 2 is B31.1 1955 with code class N-7.

10.3 PROBLEM 2538 - SUPPORT H-15

Problem 2538, a portion of the Low Head Safety Injection System (LHSIS) was originally analyzed as a hand calculation by S&W; SHOCK 2 was not used, therefore, problem 2538 is not within the scope of the Show Cause Order. In the original analysis, decal loads were applied to the restraints in this problem. These decal loads did not include moments.

SURRY POWER STATION - UNIT 2

In the EBASCO NUPIPE analysis of the portion of the LHSIS within problem 2538, the system was not overstressed. However, the loads identified by the NUPIPE analysis as existing at hanger 15 caused local pipe wall and support anchor stresses to exceed allowables by an order of magnitude. Support H-15 has been modified so that it will relieve the local overstress conditions.

10.4 BENCHMARK PROBLEMS

EBASCO has performed four pipe stress problems supplied by the NRC to verify the NUPIPE computer program. The results were submitted to the staff in the EBASCO letter to Dr M Hartzman dated January 3, 1980 (Letter Number VEP/NRC/002).

SURRY POWER STATION - UNIT 2

APPENDIX A
SYSTEMS AFFECTED

SURRY POWER STATION - UNIT 2

The reanalysis included those safety related lines originally computer-analyzed with the SHOCK2 program. The systems line numbers, the associated computer problem numbers, and the flow diagram numbers are listed below. The following table includes all seismically analyzed lines. The figure numbers refer to the FSAR drawings, and the Surry Unit 2, FM and FP drawings included in Appendix B.

<u>System</u>	<u>Line No.</u>	<u>Responsi- bilities for Analysis</u>	<u>Problem No.</u>	<u>MKS No.</u>	<u>Flow Diagram No.</u>
Low Head Safety Injection	8-SI-214-153	E	2695	127D1	FM-106A
	8-SI-292-153	E	2697	127D2	FM-106A
	8-SI-214-153	E	2681	127K1	FM-106A
	8-SI-292-153	E	2682	127K2	FM-106A
	10-SI-284-152	S&W	2727	127C1	FM-106A
	10-SI-216-153	S&W	2727	127C1	FM-106A
	8-SI-292-153	S&W	2727	127C1	FM-106A
	10-SI-351-153	S&W	2727	127C1	FM-106A
	6-SI-249-1502	S&W	2727	127C1	FM-106A
	10-SI-349-153	S&W	2727	127C1	FM-106A
	8-SI-214-152	S&W	2727	127C1	FM-106A
	10-SI-283-152	S&W	2727	127C2	FM-106A
	10-SI-213-153	S&W	2727	127C2	FM-106A
	6-SI-248-1502	S&W	2727	127C2	FM-106A
	10-SI-352-1502	S&W	2727	127C2	FM-106A
	10-SI-350-153	S&W	2727	127C2	FM-106A
	10-SI-349-153	S&W	2727	127C2	FM-106A
	10-SI-348-153	S&W	2727	127C2	FM-106A
	8-SI-214-153	S&W	2727	127C2	FM-106A
	12-SI-247-602	E	2537	122A1	FM-106B
	12-SI-247-1502	E	2537	122A1	FM-106B
	12-RC-324-1502	E	2537	122A1	FM-106B
	10-RH-117-1502	E	2537	122A1,	FM-106B,
				117B1	104A
	12-SI-246-602	E	2555	122D1	FM-106B
	12-SI-246-1502	E	2555	122D1	FM-106B
	12-RC-323-1502	E	2555	122D1	FM-106B
	10-RH-116-1502	E	2555	122D1	FM-106B
	6-SI-248-1502	E	2539	122K1	FM-106B
	6-SI-249-1502	E	2539	122K1	FM-106B
	6-SI-250-1502	E	2539	122J1	FM-106B
	6-RC-321-1502	E	2539	122J1	FM-106B
	6-SI-343-1502	E	2539	122K1	FM-106B
	12-SI-245-602	E	2709	122L1	FM-106B
	12-SI-245-1502	E	2709	122L1	FM-106B
	12-RC-322-1502	E	2709	122L1	FM-106B
High Head Safety Injection	10-SI-206-153	E	2689	127F1	FM-106A
	6-CH-372-152	E	2735	127G1	FM-105B
	4-CH-412-152	E	2735	127G1	FM-105B
	3-CH-373-152	E	2735	127G1	FM-105B
	8-SI-214-153	E	2735	127G2	106A

SURREY POWER STATION - UNIT 2

<u>System</u>	<u>Line No.</u>	<u>Responsi- bilities for Analysis</u>	<u>Problem No.</u>	<u>MKS No.</u>	<u>Flow Diagram No.</u>
High Head Safety Injection (Cont'd)	8-CH-504-152	E	2735	127G1, G2	105B
	8-CH-317-152	E	2735	127G1, G2	105B
	8-SI-217-152	E	2735	127G1, G2	106A
	3-SI-292-153	E	2735	127G1	106A
	6-SI-218-152	E	2735	127G1, G2	105B, 106A
	6-SI-219-152	E	2735	127G1, G2	105B, 106A
	6-SI-278-152	E	2735	127G1, G2	105B, 106A
	6-CH-501-152	E	2735	127G1	105B
	6-CH-502-152	E	2735	127G1	105B
	6-CH-503-152	E	2735	127G1	105B
	8-CH-505-152	E	2735	127G2	105B
	8-CH-506-152	E	2735	127G1, G2	105B
	8-SI-207-152	E	2735	127G2	106A
	8-SI-302-152	E	2735	127G2	106A
	8-SI-170-153	E	2735	127G2	106A
	8-SI-172-153	E	2735	127G2	106A
	10-SI-206-153	E	2735	127G2	106A
	6-CH-318-152	E	2735	127G1	105B
	6-CH-319-152	E	2735	127G1	105B
Residual Heat Removal	14-RH-101-1502	E	2508B	117A1	FM-104A
	14-RH-102-602	E	2508B	117A1	FM-104A
	10-RH-104-602	E	2508B	117A1	FM-104A
	10-RH-105-602	E	2508B	117A1	FM-104A
	12-RH-106-602	E	2508B	117A1	FM-104A
	10-RH-107-602	E	2508B	117A1	FM-104A
	10-RH-108-602	E	2508B	117A1	FM-104A
	10-RH-109-602	E	2508A	117A1	FM-104A
	10-RH-110-602	E	2508A	117A1	FM-104A
	12-RH-112-602	E	2508B	117A1	FM-104A
	14-RH-118-602	E	2508B	117A1	FM-104A
	12-RH-119-602	E	2508A	117A1	FM-104A
	12-RH-112-602	E	2540	117B1	FM-104A
	3-RH-113-602	E	2540B	117B1	FM-104A
	4-RH-115-152	E	2540B	117B1	FM-104A
	10-RH-116-1502	E	2540	117B1	FM-104A
	10-RH-117-1502	E	2540	117B1	FM-104A
	6-RH-120-152	E	2540	117B1	FM-104A
	10-RH-137-602	E	2540	117B1	FM-104A
	6-RH-120-152	E	2554	117C1	FM-104A, 101A

SURREY POWER STATION - UNIT 2

<u>System</u>	<u>Line No.</u>	<u>Responsi- bilities for Analysis</u>	<u>Problem No.</u>	<u>MKS No.</u>	<u>Flow Diagram No.</u>	
Main Steam	30-SHP-101-601	S&W	2577	100D	FM-14A	1
	30-SHP-102-601	S&W	2588	101D	FM-14A	
	30-SHP-103-601	S&W	2579	102D	FM-14A	
	30-SHP-101-601	S&W	2346	103A	FM-14A	
	30-SHP-102-601	S&W	2346	103A	FM-14A	
	30-SHP-103-601	S&W	2346	103A	FM-14A	
	30-SHP-124-601	S&W	2346	103A	FM-14A	
	30-SHP-123-601	S&W	2346	103A	FM-14A	
	30-SHP-122-601	S&W	2346	103A	FM-14A	
Feedwater	14-WFPD-117-601	S&W	2569	100G	FM-18A	
	14-WFPD-113-601	S&W	2573	101G	FM-18A	
	14-WFPD-109-601	S&W	2571	102G	FM-18A	
Auxiliary Feedwater	6-WAPD-101-601	E	2473	118A1, A2	FM-18A, 18B	
	6-WAPD-102-602	E	2473	118A2	FM-18A, 18B	
	3-WAPD-109-601	E	2473	118A1, A2	FM-18A	
	3-WAPD-110-601	E	2473	118A1, A2	FM-18A	
	3-WAPD-111-601	E	2473	118A1, A2	FM-18A	
	3-WAPD-112-601	E	2473	118A1, A2	FM-18A	
	3-WAPD-113-601	E	2473	118A1, A2	FM-18A	
	3-WAPD-114-601	E	2473	118A1, A2	FM-18A	
	6-WAPD-150-601	E	2473	118A1, A2	FM-18A, 18B	
	6-WAPD-151-601	E	2473	118A1, A2	FM-18A, 18B	
	6-WAPD-101-601	E	2683	118G2	FM-18A, 18B	
	6-WAPD-102-601	E	2683	118G1	FM-18A, 18B	
	6-WAPD-103-601	E	2683	118G1, G2	FM-18A	
	6-WAPD-104-601	E	2683	118G1, G2	FM-18A	
	4-WAPD-105-601	E	2683	118G1, G2	FM-18A	
	4-WAPD-106-601	E	2683	118G1, G2	FM-18A	
	4-WAPD-107-601	E	2683	118G1, G2	FM-18A	
	4-WAPD-108-601	E	2683	118G1, G2	FM-18A	
	6-WAPD-50-601	E	2683	118G1, G2	FM-18A, 18B	
	6-WAPD-52-601	E	2683	118G1, G2	FM-18A, 18B	
Service Water	24-WS-126-10	E	2465	119A1	FM-21A	
	24-WS-128-10	E	2467	119A2	FM-21A	
	24-WS-130-10	E	2469	119A3	FM-21A	
	24-WS-132-10	E	2471	119A4	FM-21A	

SURRY POWER STATION - UNIT 2

<u>System</u>	<u>Line No.</u>	<u>Responsi- bilities for Analysis</u>	<u>Problem No.</u>	<u>MKS No.</u>	<u>Flow Diagram No.</u>
Pressurizer Safety and Relief	4-RC-334-1502	E	2000	124A1	FM-103B
	3-RC-335-1502	E	2000	124A1	FM-103B
	3-RC-361-1502	E	2000	124A1	FM-103B
	6-RC-320-602	E	2000	124A1, A2	FM-103B
	6-RC-362-602	E	2000	124A1, A2	FM-103B
	12-RC-336-602	E	2000	124A1, A2	FM-103B
	6-RC-337-1502	E	2000	124A1, A2	FM-103B
	6-RC-338-1502	E	2000	124A1	FM-103B
	6-RC-339-1502	E	2000	124A1	FM-103B
	6-RC-340-602	E	2000	124A1, A2	FM-103B
	6-RC-341-602	E	2000	124A1, A2	FM-103B
	6-RC-342-602	E	2000	124A1, A2	FM-103B
	Pressurizer Spray	4-RC-314-1502	E	2771	125A1
4-RC-315-1502		E	2771	125A1	FM-103B
2-CH-368-1502		E	2771	125A1	FM-103B
HP Steam to Auxiliary Feedwater Pump	4-SHP-125-601	E	2862	131A1	FM-14A
	3-SHP-132-601	E	2862	131A1	FM-14A
	3-SHP-128-601	E	2862	131A1	FM-14A
	3-SHP-131-601	E	2862	131A1	FM-14A
	3-SHP-157-601	E	2862	131A1	FM-14A
	4-SHP-126-601	E	2864	131B1	FM-14A
	3-SHP-129-601	E	2864	131B1	FM-14A
	4-SHP-127-601	E	2869	131C1	FM-14A
	3-SHP-130-601	E	2869	131C1	FM-14A
	3-SHP-135-601	E	2869	131C1	FM-14A
Containment and Recir- culation Spray	10-CS-104-153	S&W	2521	123A1	FM-101A
	8-CS-123-153	S&W	2521	123A1	FM-101A
	10-CS-103-153	S&W	2523	123A1	FM-101A
	8-CS-122-153	S&W	2523	123A1	FM-101A
	10-CS-103-153	S&W	2547	123C1	FM-101A
	8-CS-133-153	S&W	2547	123C1	FM-101A
	10-CS-104-153	S&W	2549	123C2	FM-101A
	8-CS-134-153	S&W	2549	123C2	FM-101A
	10-RS-112-153	E	2546	123D1	FM-101A
	8-RS-123-153	E	2546	123D1	FM-101A
	10-RS-104-153	E	2541	123D2	FM-101A
	8-RS-121-153	E	2541	123D2	FM-101A
	10-RS-103-153	E	2542	123D3	FM-101A
	8-RS-120-153	E	2542	123D3	FM-101A
	10-RS-111-153	E	2543	123D4	FM-101A
	8-RS-122-153	E	2543	123D4	FM-101A

1

SURREY POWER STATION - UNIT 2

<u>System</u>	<u>Line No.</u>	<u>Responsi- bilities for Analysis</u>	<u>Problem No.</u>	<u>MKS No.</u>	<u>Flow Diagram No.</u>
Containment and Recir- culation Spray (Cont'd)	10-RS-112-153	E	2560	123E1	FM-101A
	10-RS-104-153	E	2561	123E2	FM-101A
	10-RS-110-153	E	2544	123G1	FM-101A
	10-RS-109-153	E	2533	123G2	FM-101A
	10-RS-103-153	E	2548	123H1	FM-101A
	10-RS-111-153	E	2545	123H2	FM-101A
	8-CS-134-153	E	2744	123J1	FM-101A
	8-CS-133-153	E	2745	123K1	FM-101A
	12-CS-102-153	E	2753	123L1	FM-101A
	12-CS-101-153	E	2754	123M1	FM-101A
	10-RS-109-153	E	2751	123N1	FM-101A
	4-RS-114-153	E	2751	123N1	FM-101A
	10-RS-110-153	E	2752	123N2	FM-101A
	4-RS-115-153	E	2752	123N2	FM-101A
	8-CS-133-153	E	2755	123P1	FM-101A
	8-CS-134-153	E	2755	123P1	FM-101A
	4-CS-135-153	E	2755	123P1	FM-101A
	4-CS-136-153	E	2755	123P1	FM-101A
	4-CS-105-152	E	2755	123P1	FM-101A
	1/2-CS-108-153	E	2755	123P1	FM-101A
	4-CS-106-152	E	2755	123P1	FM-101A
	10-RS-101-153	E	2756	123Q1	FM-101A
	10-RS-102-153	E	2757	123Q2	FM-101A
Component Cooling	18-CC-15-121	E	2604	112AA1	FM-22A
	18-CC-9-121	E	2605	112AB1	FM-22A
	18-CC-7-121	E	2601	112S1	FM-22A
	18-CC-14-121	E	2603	112S2	FM-22A
Containment Vacuum	8-CV-108-151	S&W	2650	137A	FM-102A

Note: E = EBASCO
S&W = Stone & Webster

SURRY POWER STATION - UNIT 2

APPENDIX B

FLOW DIAGRAMS -
IDENTIFICATION OF PROBLEMS
REANALYZED


SURRY POWER STATION - UNIT 2

APPENDIX B

FLOW DIAGRAMS - IDENTIFICATION
OF PROBLEMS REANALYZED

<u>Title</u>	<u>Drawing No.</u>
Main Steam	11548-FM-14A
Feedwater	11548-FM-18A
Cross-Connects for Auxiliary Feed	11448-FM-18B
Circulating and Service Water	11548-FM-21A
Component Cooling	11548-FM-22A
Containment and Recirculating Spray	11548-FM-101A
Containment Vacuum and Leakage Monitor	11548-FM-102A
Reactor Coolant Sheet 1	11548-FM-103A
Reactor Coolant Sheet 2	11548-FM-103B
Residual Heat Removal	11548-FM-104A
Chemical and Volume Control Sheet 2	11548-FM-105B
Safety Injection Sheet 1	11548-FM-106A
Safety Injection Sheet 2	11548-FM-106B
Refueling Water Storage Tank Crosstie	11448-FM-106C

1








**FLOW DIAGRAM
MAIN STEAM**

1572 EXTENSION-SURRY POWER STATION
VIRGINIA ELECTRIC AND POWER COMPANY

DESIGNED & ENGINEERED BY
11548-FM-14A

REV. 1





NOTES:
 _____ NEW
 _____ EXISTING

REFERENCE DRAWINGS:

FLOW DIAGRAM - FEEDWATER FM-18A
FLOW DIAGRAM - FEEDWATER 11548-FM-18A
VALVE OPERATING NUMBERS-CROSS-
CONNECTS FOR AUXILIARY FEED FM-68B

APPROVED W. A. S. [Signature]
CERTIFIED PROFESSIONAL INSURER, NO. 04692
COMMONWEALTH OF VIRGINIA


FLOW DIAGRAM
CROSS-CONNECTS FOR
AUXILIARY FEED
SUNNY POWER STATION
VIRGINIA ELECTRIC AND POWER COMPANY
STONE & WEBSTER ENGINEERING CORPORATION
BOSTON, MASS.

 DRAWING NUMBER 11448-FM-18B

"THE INFORMATION ON THIS DRAWING MAY NOT BE COPIED OR USED FOR OTHER THAN THE CONSTRUCTION MAINTENANCE OR REPAIR OF THE PLANT FACILITY DESCRIBED IN THE TITLE BLOCK."


[illegible]

①	ARCH.	CONC.	STEEL	MESH	VESSEL	BS	ELEC.	②	ARCH.	CONC.	STEEL	MESH	VESSEL	BS	ELEC.	③	ARCH.	CONC.	STEEL	MESH	VESSEL	BS	ELEC.	④	ARCH.	CONC.	STEEL	MESH	VESSEL	BS	ELEC.	⑤	ARCH.	CONC.	STEEL	MESH	VESSEL	BS	ELEC.



11548-FM-22A

MKS-112AB1



DETAIL A
TYPICAL ORIFICE FLANGE

LOCAL SAMPLE DETAIL

NOTES:
ALL TEMPERATURE CONNECTIONS TO BE 1" EXCEPT AS NOTED
NUMBER SHOWN AT REACTOR CONTAINMENT LINE
INDICATES PIPING PENETRATION NUMBER
ALL PRESSURE, SAMPLE, DRAIN & VENT CONNECTIONS TO
BE 3/4" WITH VOS-60C EXCEPT AS NOTED.
FURNISHED BY EQUIPMENT MANUFACTURER
MCB - MAIN CONTROL BOARD
COMPUTER
LMC - LEAKAGE MONITORING TEST CONNECTIONS
PROVIDE ROOT VALVES AT ALL FLOW ORIFICES DETAIL A

REFERENCE DWGS:
FLOW DIAG - COMPONENT COOLING WATER SH. 2 FM-22B
FLOW DIAG - COMPONENT COOLING WATER SH. 6 11448-FM-22F
FLOW DIAG - SAMPLING SYSTEM FM-32A
FLOW DIAG - VENT & DRAIN SYSTEM FM-100A
REACTOR CONTAINMENT PENETRATIONS FV-1A

MKS-112AA1





APPROVED: *H. A. Sinner, Jr.*
CERTIFIED PROFESSIONAL ENGINEER, No. 04323
COMMONWEALTH OF VIRGINIA

FLOW DIAGRAM
COMPONENT COOLING WATER SH. 1


1972 EXTENSION - SURRY POWER STATION
VIRGINIA ELECTRIC AND POWER COMPANY
STONE & WEBSTER ENGINEERING CORPORATION
BOSTON, MASS.
DRAWING NUMBER 11548-FM-22A

OUTSIDE REACTOR CONTAINMENT UNIT										INSIDE REACTOR CONTAINMENT UNIT									
1	REVIEW ANY SIZES CHANGED	2	ADDED CHECK VALVES	3	REMOVED NEUTRON SHIELD TANK	4	GENERAL REVISION	5	ADDED VENTS (DRAINS, REMOVED LINES)	6	ADDED VENTS (DRAINS, REMOVED LINES)	7	ADDED VENTS (DRAINS, REMOVED LINES)	8	ADDED VENTS (DRAINS, REMOVED LINES)	9	ADDED VENTS (DRAINS, REMOVED LINES)	10	ADDED VENTS (DRAINS, REMOVED LINES)
11	ADDED CHECK VALVES	12	ADDED CHECK VALVES	13	ADDED CHECK VALVES	14	ADDED CHECK VALVES	15	ADDED CHECK VALVES	16	ADDED CHECK VALVES	17	ADDED CHECK VALVES	18	ADDED CHECK VALVES	19	ADDED CHECK VALVES	20	ADDED CHECK VALVES
21	ADDED CHECK VALVES	22	ADDED CHECK VALVES	23	ADDED CHECK VALVES	24	ADDED CHECK VALVES	25	ADDED CHECK VALVES	26	ADDED CHECK VALVES	27	ADDED CHECK VALVES	28	ADDED CHECK VALVES	29	ADDED CHECK VALVES	30	ADDED CHECK VALVES
31	ADDED CHECK VALVES	32	ADDED CHECK VALVES	33	ADDED CHECK VALVES	34	ADDED CHECK VALVES	35	ADDED CHECK VALVES	36	ADDED CHECK VALVES	37	ADDED CHECK VALVES	38	ADDED CHECK VALVES	39	ADDED CHECK VALVES	40	ADDED CHECK VALVES
41	ADDED CHECK VALVES	42	ADDED CHECK VALVES	43	ADDED CHECK VALVES	44	ADDED CHECK VALVES	45	ADDED CHECK VALVES	46	ADDED CHECK VALVES	47	ADDED CHECK VALVES	48	ADDED CHECK VALVES	49	ADDED CHECK VALVES	50	ADDED CHECK VALVES
51	ADDED CHECK VALVES	52	ADDED CHECK VALVES	53	ADDED CHECK VALVES	54	ADDED CHECK VALVES	55	ADDED CHECK VALVES	56	ADDED CHECK VALVES	57	ADDED CHECK VALVES	58	ADDED CHECK VALVES	59	ADDED CHECK VALVES	60	ADDED CHECK VALVES
61	ADDED CHECK VALVES	62	ADDED CHECK VALVES	63	ADDED CHECK VALVES	64	ADDED CHECK VALVES	65	ADDED CHECK VALVES	66	ADDED CHECK VALVES	67	ADDED CHECK VALVES	68	ADDED CHECK VALVES	69	ADDED CHECK VALVES	70	ADDED CHECK VALVES
71	ADDED CHECK VALVES	72	ADDED CHECK VALVES	73	ADDED CHECK VALVES	74	ADDED CHECK VALVES	75	ADDED CHECK VALVES	76	ADDED CHECK VALVES	77	ADDED CHECK VALVES	78	ADDED CHECK VALVES	79	ADDED CHECK VALVES	80	ADDED CHECK VALVES
81	ADDED CHECK VALVES	82	ADDED CHECK VALVES	83	ADDED CHECK VALVES	84	ADDED CHECK VALVES	85	ADDED CHECK VALVES	86	ADDED CHECK VALVES	87	ADDED CHECK VALVES	88	ADDED CHECK VALVES	89	ADDED CHECK VALVES	90	ADDED CHECK VALVES
91	ADDED CHECK VALVES	92	ADDED CHECK VALVES	93	ADDED CHECK VALVES	94	ADDED CHECK VALVES	95	ADDED CHECK VALVES	96	ADDED CHECK VALVES	97	ADDED CHECK VALVES	98	ADDED CHECK VALVES	99	ADDED CHECK VALVES	100	ADDED CHECK VALVES





11548-FM-103B



1. 27 1/2" and 31" INCHES TO BE BLANKED OFF.
2. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
3. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
4. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
5. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
6. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
7. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
8. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
9. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
10. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
11. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
12. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
13. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
14. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
15. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
16. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
17. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
18. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
19. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
20. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
21. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
22. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
23. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
24. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
25. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
26. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
27. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
28. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
29. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.
30. ALL VALVES SHALL BE BLANKED OFF BY THE OPERATOR FOR THE REASON OF THE VALVE BEING BLANKED OFF.

- LEGEND
- A.C. - INDICATED MANUAL VALVE POSITION MAINTAINED BY ADMINISTRATIVE CONTROL WHICH IS CONSIDERED EQUIVALENT TO A LOCKED VALVE
- IMR - INSIDE MISSILE BARRIER AND/OR SECONDARY SHIELD
- OMR - OUTSIDE MISSILE BARRIER AND/OR SECONDARY SHIELD
- EO - FAIL OPEN
- EC - FAIL CLOSED
- D - LOCAL DRAIN
- V - LOCAL VENT
- S - TRIPPED BY SAFEGUARDS INITIATION SYSTEM
- DS - NEEDLE VALVE
- DA - DIAPHRAGM VALVE WITH AIR OPERATOR
- LMC - LEAKAGE MONITORING CONNECTION
- REFERENCE DWGS:
- | | |
|--------------------------|----------------|
| COMPONENT COOLING SYSTEM | FM-22A/B |
| SAMPLING SYSTEM | FM-32A |
| VENT/RAIN SYSTEM | FM-100B |
| REACTOR COOLANT SYSTEM | FM-103A |
| RESIDUAL HEAT REMOVAL | FM-104A |
| CHEM/VOLUME CONTROL | FM-105B/C |
| SAFETY INJECTION SYSTEM | FM-106B |
| BORON RECOVERY SYSTEM | 11448-FM-29A/D |




FLOW DIAGRAM
REACTOR COOLANT SYSTEM
SHEET 2


1972 EXTENSION-SURRY POWER STATION
VIRGINIA ELECTRIC AND POWER COMPANY
STONE & WEBSTER ENGINEERING CORPORATION
BOSTON, MASS.

DRAWING NUMBER 11548-FM-103B

NO.	DESCRIPTION	CHD	CON	APP	DATE	ISSUE
1	ADDED: 2-RC-100-152 VALVE IN 2-RC-100-152 LINE AT PT 2472 & DWG COORDINATES					
2	OLD REMOVED, LINE NOS ADDED & VALVE NOS CHGD					

11548-FM-104A





11548-FM-105B

TCV-CC 203
(11448-FM-22E)

NONREGENERATIVE
HEAT EXCHANGER

HEAD SAFETY INJECTION
(FM-106A) 2-CH-372-1503

OUTSIDE REACTOR
CONTAINMENT

INSIDE REACTOR
CONTAINMENT (FM-105)

HYDRO TEST
CONN

SEAL WATER
INJECTION FILTERS

CHARGING PUMPS

MKS-127G1

NOTE:
DEVELOPED FROM 6684303
GENERAL NOTES & REF. DNG. SEE FM-105A
THE VALVES LISTED BELOW ARE SUPPLIED BY SEW
ALL OTHER VALVES ARE SUPPLIED BY WESTINGHOUSE
1. VDS-15V
2. VDS-15V
3. VDS-15V



APPROVED: *[Signature]*
DATE: 11/15/72

FLOW DIAGRAM
CHEM & VOLUME CONTROL SYS
SHEET-2

1972 EXTENSION - SURRY POWER STATION
VIRGINIA ELECTRIC AND POWER COMPANY
RTONK & WEBSTER ENGINEERING CORPORATION
BOSTON, MASS.


DRAWING NUMBER 11548-FM-105B

REVISED INSTRUMENTATION FILTER & PUMPING ADDED MINOR CHANGES															SYN. DESIGNATIONS REMOVED FROM WINDST. NOS. 1001 UP MINOR CHANGES ADDED OR REMOVED															GENERAL REVISION															REDRAWN (LINE NO. CHG.)															ORIGINAL ISSUE														
DESCRIPTION															DESCRIPTION															DESCRIPTION															DESCRIPTION															DESCRIPTION														
CHG. CORR. APPR. DATE REGR.															CHG. CORR. APPR. DATE REGR.															CHG. CORR. APPR. DATE REGR.															CHG. CORR. APPR. DATE REGR.															CHG. CORR. APPR. DATE REGR.														

THE INFORMATION ON THIS DRAWING MAY NOT BE
COPIED OR USED FOR OTHER THAN THE CONSTRUCTION,
MAINTENANCE OR REPAIR OF THE PLANT FACILITY
DESCRIBED IN THE TITLE BLOCK.

12

Designed by
Dwg. Chg'd by



NOTES:

- A LOCATE CONNECTION CLOSE TO BOREON INJECTION TANK
- B FV - 2293 TO BE GAGGED DURING IN-DRY TESTING
- C LOCATE CONNECTION CLOSE TO VALVE MOV-19, 7C & D
- D THIS IS A SPECIAL VALVE - FUNCTIONS BOTH AS A CONTROL AND A RELIEF VALVE
- E TAPS MUST BE 2'-0" APART
- F SAMPLE CONNECTION SHALL BE BROUGHT INTO THE ANNULUS REGION BEHIND A COLUMN WHICH SHIELDS AWAY FROM ACCUMULATOR
- G ALL VALVE CONNECTIONS MUST BE MADE TO THE MAIN PIPE LINE
- H ELECTROMAGNETIC ACTION IN MAIN PIPE LINE


SYMBOL FC DENOTES FAIL CLOSED VALVE
SYMBOL AC DENOTES ADMINISTRATIVE CONTROL VALVE
SYMBOL W DENOTES WELD END PREPARATION FOR SCHED. 10S INSTALL 10S TO 40S TRANSITION PIECE.
H. VALVE A - 4" TAP


REFERENCE DRAWINGS

FLOW DIAG. BOREON RECOVERY SYS	11448-FM-29A-D
FLOW DIAG. CHEM & VOL. CONT. SYS	11448-FM-105A
FLOW DIAG. VENT & DRAIN SYS	FM-102A-C
FLOW DIAG. CONTAINMENT & REGR. SPRAY SYS	FM-101A
FLOW DIAG. REACTOR COOLANT SYS	FM-103A-E
FLOW DIAG. RESIDUAL HEAT REMOVAL SYS	FM-104A
FLOW DIAG. CHEM & VOLUME CONTROL SYS	FM-105A-E
FLOW DIAG. SAFETY INJECTION SYS SH 2	FM-106B
FLOW DIAG. SAFETY INJECTION SYS	11448-FM-106A-B
FLOOR DRAINAGE AUXILIARY BLDG	11448-FE-2A
VALVE OPERATING NUMBERS - SAFETY NO. SYSTEM	FM-106A-E

FLOW DIAGRAM
SAFETY INJECTION SYSTEM
SHEET 1
1972 EXTENSION SURRY POWER STATION
VIRGINIA ELECTRIC AND POWER COMPANY
STONE & WEBSTER ENGINEERING CORPORATION
BOSTON, MASS.
DRAWING NUMBER 11548-FM-106A

NO.	DESCRIPTION	DATE	BY	CHKD.	APPD.	DATE	NO.	DESCRIPTION	DATE	BY	CHKD.	APPD.	DATE
14	ADD NOTE FOR TRUCK CONN (D-4)	11/28/72	J.M. GENTNER	D. CHIDLEY			15	ADD NOTE FOR TRUCK CONN (D-4)	11/28/72	J.M. GENTNER	D. CHIDLEY		
16	ADD NOTE FOR TRUCK CONN (D-4)	11/28/72	J.M. GENTNER	D. CHIDLEY			17	ADD NOTE FOR TRUCK CONN (D-4)	11/28/72	J.M. GENTNER	D. CHIDLEY		





11448-FM-106C

SURRY POWER STATION - UNIT 2

APPENDIX C

RESPONSE TO
IE BULLETIN 79-04

SURRY POWER STATION - UNIT 2

APPENDIX C

RESPONSE TO IE BULLETIN 79-04

Velan swing check valves, sized 3 and 6 inches, are installed in the following seismic Category I piping systems:

- a) Chemical and volume control system
- b) Safety injection systems

A detailed listing by line number is contained in the following table.

Lines with 6 inch check valves were originally seismically analyzed by computer program or hand calculations. The re-evaluation of these systems using the correct valve weight is currently being done under the NUPIPE program. The results have shown that the pipe stress is within the allowable for all lines.

Lines with 3 inch check valves were analyzed originally by hand calculations. An estimated weight, overly conservative, was used instead of actual valve weights. The incorrect valve weight has no effect on these calculations and re-evaluation is not required, however, these valves and the related pipe lines are included in the scope of IE Bulletin 79-14.

SURRY POWER STATION - UNIT 2

LISTING OF VELAN SWING CHECK VALVES

COVERED BY IE BULLETIN NO. 79-04

SAFETY INJECTION SYSTEMS - UNIT 2

6 Inch	2-SI-79	6-RC-317-1502
	2-SI-82	6-RC-319-1502
	2-SI-85	6-RC-320-1502
	2-SI-88	6-RC-318-1502
	2-SI-91	6-RC-316-1502
	2-SI-94	6-RC-321-1502
	2-SI-228	6-SI-249-1502
	2-SI-229	6-SI-249-1502
	2-SI-238	6-SI-248-1502
	2-SI-239	6-SI-249-1502
	2-SI-240	6-SI-250-1502
	2-SI-241	6-SI-345-1502
	2-SI-242	6-SI-344-1502
	2-SI-243	6-SI-353-1502
	3 Inch	2-SI-224
2-SI-225		3-SI-270-1503
2-SI-226		3-SI-347-1503
2-SI-227		3-SI-272-1503

CHEMICAL AND VOLUME CONTROL SYSTEM - UNIT 2

3 Inch	2-CH-196	3-CH-500-1502
	2-CH-258	3-CH-381-1503
	2-CH-267	3-CH-302-1503
	2-CH-276	3-CH-303-1503
	2-CH-309	3-CH-379-1503
	2-CH-312	3-CH-301-1502

SURRY POWER STATION - UNIT 2

APPENDIX D
CORRESPONDENCE
WITH THE
NRC

SURRY POWER STATION - UNIT 2

APPENDIX D

CORRESPONDENCE WITH NRC

The following is a listing of correspondence with the NRC related to the reanalysis effort.

<u>Item No.</u>	<u>Date</u>	<u>Signature</u>	<u>Addressee</u>	<u>Letter No./Subject</u>
<u>NRC TO VEPCO</u>				
1	3/13/79	Denton	Proffitt	Show Cause Order
2	4/2/79	Stello	Proffitt	Addendum to Show Cause Order
3	4/13/79	Stello	Proffitt	Use of Soil Structure Interaction Techniques
4	5/18/79	Stello	Proffitt	Request for Further SSI Information
5	5/25/79	Eisenhut	Proffitt	Factor Adjustment to SSI Calculated Stresses
6	7/18/79	O'Reilly	Proffitt	Information Pertaining to IE Bulletin No. 79-14, Revision 1
7	8/15/79	O'Reilly	Proffitt	Letter of Guidance on IE Bulletin No. 79-14
8	8/27/79	Denton	Proffitt	Lifting of Suspension Required by the Order to Show Cause
9	10/5/79	O'Reilly	Proffitt	Confirmation of Concurrence
10	10/23/79	Murphy	Proffitt	Refers to NRC Inspection of Sept. 10-13 and Sept. 19-21, 1979
11	10/24/79	Murphy	Proffitt	Refers to NRC Inspection of Sept. 13-14, 1979
12	10/25/79	Murphy	Proffitt	Refers to NRC Inspection of Sept. 26-28, 1979
13	11/15/79	Eisenhut	Proffitt	Refers to Soil Structure Interaction

SURRY POWER STATION - UNIT 2

APPENDIX D (Cont'd)

CORRESPONDENCE WITH NRC

<u>Item No.</u>	<u>Date</u>	<u>Signature</u>	<u>Addressee</u>	<u>Letter No./Subject</u>
			<u>VEPCO TO NRC</u>	
14	3/30/79	Spencer	Denton/ Stello	198/Initial Response to Show Cause Order
15	4/19/79	Stallings	O'Reilly	270/LER 79-010/013L-0
16	4/23/79	Spencer	O'Reilly	289/Response to IE Bulletin No. 79-07
17	4/24/79	Spencer	O'Reilly	288/Response to IE Bulletin No. 79-07
18	4/27/79	Spencer	Denton/ Stello	311/Transmittal to Two Sample Problems to EG&G
19	5/2/79	Stallings	Denton	Observations on Reanalysis Effort
20	5/2/79	Spencer	Stello	260/Submittal of SSI Information
21	5/22/79	Ragone	Hendrie	Comments on Moratorium/ Surry Reanalysis
22	5/24/79	Spencer	Stello	Response to NRC Letter of 4/2/79
23	5/24/79	Spencer	Stello	Response to NRC Letter of 5/18/79
24	6/5/79	Spencer	Denton	Submittal of Report on Reanalysis
25	6/8/79	Spencer	Denton	Additional Information, Report on Reanalysis of Piping
26	6/8/79	Spencer	Stello	Soil Structure Interac- tion Report
27	6/12/79	Spencer	Denton	Modification Informa- tion, Reanalysis of Piping Systems

1

SURRY POWER STATION - UNIT 2

APPENDIX D (Cont'd)

CORRESPONDENCE WITH NRC

<u>Item No.</u>	<u>Date</u>	<u>Signature</u>	<u>Addressee</u>	<u>Letter No./Subject</u>
28	6/15/79	Spencer	Denton	Schedule and Support Information
29	6/19/79	Spencer	Denton	Support Modifications
30	6/25/79	Spencer	Denton	Support Information, Reanalysis of Piping Systems
31	8/1/79	Spencer	Denton	Submittal of Revised Report on Analysis
32	8/21/79	Spencer	Denton	Analysis Completion of Designated Supports - Outside Containment
33	8/31/79	Spencer	Denton	Reanalysis of Piping Systems
34	8/31/79	Spencer	O'Reilly	60-Day Response for IE 79-14
35	9/13/79	Spencer	Eisenhut	Response to NRC Letter of 5/25/79
36	10/3/79	Proffitt	Denton	Seismic Analysis of Piping Systems
37	10/4/79	Spencer	O'Reilly	Response to NRC Letter of 7/2/79
38	10/4/79	Spencer	O'Reilly	Response to IE Letter Dated 9/7/79
39	10/15/79	Spencer	O'Reilly	Extension of IE Bulletin 79-14 Deadline
40	10/23/79	Spencer	O'Reilly	Extension of IE Bulletin 79-14 Deadline, Unit 2
41	10/30/79	Spencer	O'Reilly	120-Day Response to IE 79-14
42	11/28/79	Spencer	Denton	Seismic Analysis of Piping Systems

SURRY POWER STATION - UNIT 2

APPENDIX D (Cont'd)

CORRESPONDENCE WITH NRC

<u>Item No.</u>	<u>Date</u>	<u>Signature</u>	<u>Addressee</u>	<u>Letter No./Subject</u>
43	12/7/79	Spencer	O'Reilly	Response to NRC Letter of 11/8/79
44	12/13/79	Spencer	Denton	Show Cause Order Reanalysis
45	12/21/79	Spencer	O'Reilly	Show Cause 60 Days Analysis Completion
46	2/1/80	Spencer	Denton	Show Cause Modification Schedule Revision
47	2/22/80	Spencer	Denton	Start-up Request for Surry Unit 2
48	3/21/80	Spencer	Denton	Amended Start-up Request for Surry Unit 2
49	3/28/80	Spencer	Denton	Show Cause Report Errata for Surry Unit 1
<u>S&W to NRC</u>				
50	3/22/79	Kennedy	Denton	Transmittal of S&W Computer Programs
51	3/30/79	Jacobs	Herring	Submittal of Computer Outputs
52	4/3/79	Jacobs	Bezler	Submittal of Benchmark Problem to Brookhaven National Laboratory
53	4/6/79	Kennedy	Denton	Transmittal of S&W Computer Programs
54	4/6/79	Jacobs	Stello	Plan for Verification of Dynamic Analysis Codes
55	4/11/79	Jacobs	Bezler	Submittal of Computer Outputs
56	4/13/79	Jacobs	Stello	Update and Status of Verification Plan for Dynamic Analysis Codes

SURRY POWER STATION - UNIT 2

APPENDIX D (Cont'd)

CORRESPONDENCE WITH NRC

<u>Item No.</u>	<u>Date</u>	<u>Signature</u>	<u>Addressee</u>	<u>Letter No./Subject</u>
57	4/18/79	Jacobs	Hartman	Submittal of Computer Outputs
58	4/27/79	Jacobs	Bezler	Submittal of Benchmark Problems
59	4/27/79	Jacobs	Stello	Status of Verification Plan for Dynamic Analysis Codes
60	5/8/79	Rossier	Neighbors	Draft Outline of SSI-ARS Report
61	5/9/79	Kennedy	Stello	Reference SHOCK 0 Program
62	5/11/79	Kennedy	Stello	Reference SHOCK 0 Program
63	5/14/79	Kennedy	Denton	Proprietary Computer Codes
64	6/4/79	Jacobs	Bezler	Submittal of Benchmark Problems
65	6/12/79	Jacobs	Bezler	Submittal of Benchmark Problems
66	9/6/79	Allen	Stello	Response to NRC Letter of 8/10/79
<u>Ebasco to NRC</u>				
67	9/7/79	Nelson	Hartzman	Benchmark Problem VEP/NRC/001
68	1/3/90	Nelson	Hartzman	Benchmark Problem VEP/NRC/002