

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | V | A | S | P | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

01 | L | E | 0 | 5 | 0 | 0 | 0 | 2 | 8 | 0 | 7 | 0 | 6 | 0 | 3 | 8 | 0 | 8 | 0 | 6 | 2 | 3 | 8 | 0 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) With Unit #1 critical at 0% power PT-27A revealed that the amp readings for circuit 22A

012 | (Boron Injection Tank Inlet) Panel 2 was below the acceptance criteria stipulated in the PT. Repair of the defective circuit was initiated immediately. This is a degraded mode of operation as specified in T.S. 3.3.(B)5 and is reportable in accordance with T.S. 6.6.2.b.2. Because the redundant circuit was operable, the health and safety of the public were not affected.

09 | SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP. SUBCODE | VALVE SUBCODE

09 | S | H | 11 | E | 12 | A | 13 | H | E | A | T | E | R | 14 | Z | 15 | Z | 16

17 | LE/RD REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO.

17 | 8 | 0 | 0 | 3 | 5 | 0 | 3 | L | 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The heat tracing rafe for this circuit was completely replaced. No

10 | additional actions were deemed necessary. 11 | 12 | 13 | 14 |

15 | FACILITY STATUS | % POWER | OTHER STATUS | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION

15 | G | 28 | 0 | 0 | 0 | 29 | NA | B | 31 | Electrician

16 | ACTIVITY CONTENT | AMOUNT OF ACTIVITY | LOCATION OF RELEASE

16 | Z | 33 | Z | 34 | NA | NA | 36

17 | PERSONNEL EXPOSURES | PERSONNEL INJURIES

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 0 | 0 | 0 | 40 | NA | 41

18 | LOSS OF OR DAMAGE TO FACILITY | PUBLICITY ISSUED

18 | Z | 42 | NA | 43 | N | 44 | NA | 45 | NAME OF PREPARER: J. L. Wilson PHONE: (804) 357-3184

8006270 294