

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | V | A | S | P | S | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 5  
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 29 57 CAT 58

CON'T  
0 1 | L | 0 | 5 | 0 | 0 | 0 | 2 | 8 | 1 | 0 | 8 | 2 | 6 | 8 | 0 | 0 | 9 | 2 | 5 | 8 | 0 | \_\_\_\_\_ | 5  
8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While attempting to pressurize "B" Accumulator using normal Nitrogen supply, the  
0 3 | pressure on "B" Accumulator was reduced below allowable limits. This event is contrary  
0 4 | to Technical Specifications 3.3.A.2 and is reportable as per Technical Specifications  
0 5 | 6.6.2.b (2)  
0 6 |  
0 7 |  
0 8 |

0 9 | \_\_\_\_\_ | 80  
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
A D (11) E (12) B (13) P I P E X X (14) X (15) Z (16)

(17) LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
8 0 0 2 1 / 0 3 L 0

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
B (18) Z (19) Z (20) Z (21) 0 0 0 0 Y (23) N (24) L (25) Z 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The Low Accumulator Pressure was caused by a leak and low pressure in the  
1 1 | Nitrogen fill header. "B" accumulator was declared inoperable in accordance with  
1 2 | T.S. Additional nitrogen supply pressure was added to the fill system and the  
1 3 | Accumulator was pressurized and declared operable. Repairs to the leaking fittings  
1 4 | on the fill header were made.

1 5 | FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
C (28) 0 5 4 (29) NA A (31) Observation

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
Z (33) Z (34) NA NA

1 7 | PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
0 0 0 (37) Z (38) NA

1 8 | PERSONNEL INJURIES NUMBER DESCRIPTION  
0 0 0 (40) NA

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
Z (42) NA

2 0 | ISSUED DESCRIPTION PUBLICITY NRC USE ONLY  
N (44) NA

ATTACHMENT 1  
SURRY POWER STATION, UNIT 2  
DOCKET NO: 50-281  
REPORT NO: 80-021/03L-0  
EVENT DATE: 08-26-80

TITLE OF REPORT: LOW NITROGEN PRESSURE ON "B" ACCUMULATOR

1. Description of Event:

While attempting to pressurize "B" Accumulator using normal Nitrogen supply to the accumulators, the pressure on "B" Accumulator was reduced below the allowable limits. This event is contrary to Technical Specifications 3.3.A.2 and is reportable as per Technical Specifications 6.6.2.b.(2)

2. Probable Consequences and Status of Redundant System:

Technical Specification allows for the isolation of one accumulator for a period not to exceed 4 hours. The other two accumulators remained operable. The pressure in 'B' accumulator was returned to required specification within the four hours limitation. Therefore the health and safety of the public was not affected.

3. Cause:

The low accumulator pressure was caused by a leak and low pressure in the nitrogen fill header.

4. Immediate Corrective Action:

"B" accumulator was declared inoperable. Additional nitrogen supply pressure was added to the fill system and "B" accumulator was pressurized and declared operable. The accumulator was inoperable for 95 minutes.

5. Subsequent Corrective Action:

Repairs were made to the leaking fittings on the fill header.

6. Action to Prevent Recurrence:

The above corrective action will prevent recurrence.

7. Generic Implications:

None