CONTECT BLOCK: ](ı) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 
 0
 0
 0
 0
 0
 0
 3
 4
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1
 1</t 1 P S 1 LICENSE NUMBER DN'T 1 

 REPCAT
 L
 6
 0
 5
 0
 0
 2
 8
 0
 7
 2
 2
 8
 0
 8
 2
 0
 8
 0
 9

 SCUPECE
 50
 60
 61
 DOCKET NUMBER
 68
 69
 EVENT DATE
 74
 75
 REPORT DATE
 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) With Unit #1 at 100% power PT-27D revealed that the amp readings for circuit 13A Boron 2 Injection recirc to the Boric Acid Tanks Panels 8 & 9 were below the Acceptance Criteria 13 Stipulated in the PT. Repair of the defective circuits was initiated immediately. This 4 event is a degraded mode of operation as specified in T.S. 3.3.b.10 and is reportable 5 in accordance with T.S.6.6.2.b(2) Recirculation flow from the Boron Injection Tank was 6 verified, therefore the health and safety of the public were not affected. 17 8 8 9 80 SYSTEM CAUSE CAUSE COMP. VALVE SUBCODE CODE CODE SUBCODE COMPONENT CODE SUBCODE S F (11 9 E | A | T | E | R (14)Έ (12 A (13) H Z (16 Z (15 REVISION SEQUENTIAL OCCURRENCE REPORT EVENT YEAR LER/FO REPORT NO. CODE TYPE NO. REPORT 8 0 0 4 9 0 3 L 0 77 EFFECT ON PLANT ATTACHMENT SUBMITTED NPRD-PRIME COMP COMPONENT METHOD HOURS (22) FORM SUB. VUFACTURER Z [2] C (1E) 3 Z (20) 0 0 0 0 (19) N (24) 1 8 5 L (25) (26) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The East Tracing Tape failed because of excessive heat. A design change has been 0 initiated to change the manner by which these borated lines are heat traced. The failei tape was replaced. 2] 3 4 80 METHOD OF DISCOVERY OTHER STATUS (30) % POWER DISCOVERY DESCRIPTION (32) 1 0 0 NA Electrican B (31) 80 ACTIVITY RELEASED\_OF FELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE NA Z (33) Z (34 NA 45 80 XPOSURES DESCRIPTION (29) YPE NA Z (38) PERSONNEL INJURIES 80 DESCRIPTION (41) NA 8 12 LOSS OF OF DAMAGE TO FACILITY (43) 80 DESCRIPTION NA 80 PUBLICI DESCRIPTION (45) NRC USE ONLY ISSUED NA I N 1 | | | | 68 69 (804) 800826591 357-3184 J. L. Wilson MANE OF PREPARER PHONE -

ATTACHMENT 1 SURRY POWER STATION, UNIT DOCKET NO: 50-280 REPORT NO: 80-049/03L-0 EVENT DATE: 7-22-80

### TITLE OF REPORT:

#### HEAT TRACING FAILURE

## 1. Description of Event:

With Unit #1 at 100 percent power PT-27D revealed that the ap readings for circuit 13A (Boron Injection Recirculation to the Boric Acid Tanks) Panels 8 & 9 were below the Acceptance Criteria Stipulated in the PT. Repair of the defective circuit was initiated immediately. This event is a degraded mode of operation as specified in T.S.3.3.E.10 and is reportable in accordance with T.S.6.6.2.b(2)

## 2. Probable Consequences & Status of Redundant Systems:

flow from the Boron Injection Tank was verified. Tech. Spec. 3.3.B.10 permits operation with the recirculation between a Unit's Boron Injection Tank and it's Boric Acid Storage Tank to be inoperable for a period not to exceed two hours. The heat tracing circuit was returned to service in one hour and ten minutes therefore, the health and safety of the public were mot affected.

# 3. <u>Cause:</u>

• .v. --

The Heat Tracing Tape failed due to excessive heat.

4. Immediate Corrective Action:

The immediate corrective action was to replace the defective Heat Tracing Tape, and verify the operability of the affected Heat Tracing Circuit.

## 5. Subsequent Corrective Action:

A Design Change has been initiated to change the Heat Tracing Circuit 13A to prevent over heating.

## 6. Action Taken to Prevent Recurrence:

No additional actions were deemed necessary.

## 7. Generic Implications:

A task force has been established to study the total spectrum of the heat tracing system in an attempt to discern present problems and recommend solutions which will eliminate sporadic failures experienced.