RC FO	LICENSEE EVENT REPORT	DRY COMMISSION
	CONTROL BLOCK: 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ATION)
1 1	V A S P S 1 2 0 0 - 0 0 0 0 0 0 0 3 4 1 1 1 1 1 4 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30	57 CAT 58 5
ON'T	REPORT SOURCE L 6 0 5 0 0 0 2 8 0 7 1 0 1 9 8 0 8 1 1 1 1 7 60 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
) 3	points to be greater than twice background. This reduces the sensitivity to	
) 4	This is contrary to Tech. Spec. Table 3, 7-5, and is reportable as per T.S	. 6.6.2.b.
) [5]	(1). The health and safety of the public were not affected.	J·
) 6		
7		
18		BO
9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE R M 11 X 12 Z 13 I N S T R U 14 X 15 Z 16 SEQUENTIAL OCCURRENCE REPORT	REVISION
	Type Code Code Type Code Code Code Type Code	NO. 32 COMPONENT MANUFACTURER V 1 1 5 26
0	With Unit 1 shutdown and defueled, background radiation decreased as shown b	y PT-26.1.
T	Both RM-CC-105 and RM-CC-106 Setpoints were reset to a value less than twice	background.
2		
3		· ·
T 4		
	H 22 10 10 10 12 13 Inservice Inspection	32)
6 RE	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) Z (33) Z (34) N/A PERSONNEL EXPOSURES AMOUNT OF ACTIVITY (35) DESCRIPTION OF RELEASE (36) AMOUNT OF ACTIVITY (35) DESCRIPTION OF RELEASE (36) AMOUNT OF ACTIVITY (35) AMOUNT OF ACTIVITY (80
7 8	NUMBER TYPE DESCRIPTION (39) 11 12 13 N/A	80
S	PERSONNEL INJURIES NUMBER DESCRIPTION 41 O O O O O N/A	80
9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A	80
0	PUBLICITY SSUED DESCRIPTION 45 N/A 10 801121050 NRC N/A 66 69	USE ONLY

ATTACHMENT 1

SURRY POWER STATION, UNIT 1

DOCKET NO: 50-280

REPORT NO: 80-062/03L-0 EVENT DATE: 10-19-80

TITLE of EVENT: RM-CC-105/106 SEIPOINIS out of SPEC.

1. DESCRIPTION of EVENT:

With Unit 1 at cold shutdown and defueled, PT 26.1 showed RM-CC-105/106 alarm setpoints to be greater than twice background. This is contrary to Tech. Spec. Table 3.7-5 and is reportable as per T.S. 6.6.2.b.(1).

2. PROBABLE CONSEQUENCES and STATUS of REDUNDANT SYSTEMS:

Component cooling water radiation monitors (RM-CC-105/106) provide for the automatic closure of CC surge tank vent valve HCV-CC-100. With the reduced background radiation resulting from Unit 1 defueling, the setpoint of RM-CC-105/106 must be lowered. The setpoints being less conservative than those required by T.S. does not prevent the fulfillment of the functional requirements of this system. Therefore the health and safety of the public were not affected.

3. CAUSE:

This event was due to the decrease in background radiation levels.

4. IMMEDIATE CORRECTIVE ACTION:

Reduce the alarm setpoints to less than twice background by use of procedure CAL-RM-004.

5. SUBSEQUENT CORRECTIVE ACTION:

None required.

6. ACTIONS TAKEN to PREVENT RECURRENCE:

None.

7. GENERIC IMPLICATIONS:

None.