

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	V	A	S	P	S	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
8	LICENSEE CODE					14	LICENSE NUMBER										25	LICENSE TYPE					30	57 CAT		58

01	L	0	5	0	0	0	2	8	1	1	1	0	5	8	0	1	2	0	5	8	0
8	REPORT SOURCE		DOCKET NUMBER						EVENT DATE				REPORT DATE								

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With the unit at 100%, a high temperature on 'A' Chg. Pump (2-CH-P-1A) revealed a low

03 Service Water flow to the pump. The low discharge pressure alarm failed to annunciate.

04 This is contrary to T.S. 3.3.A.8.b, and is reportable per T.S. 6.6.2.b.(2). The redun-

05 dant pump was started and the Chg Pump temperatures returned to normal. Therefore, the

06 health and safety of the public were not affected.

07

08

09	W	A	X	Z	P	U	M	P	S	X	B	Z			
7	SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE		
17	80		037		03		L		0						
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
18	F	Z	Z	0000	Y	N	A	A	4	8	5				
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 A clogged pump inlet strainer caused the low discharge pressure and a clogged pressure

11 switch sensing line prevented the alarm from annunciating. The strainer was cleaned and

12 the sensing line was purged. Both were tested and returned to service.

13

14

15	E	1	0	0	N/A	A	Operator observation			
FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
16	Z	Z	N/A		N/A		N/A		N/A	
ACTIVITY CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE						
17	0	0	0	N/A		N/A				
PERSONNEL EXPOSURES		DESCRIPTION								
18	0	0	0	N/A		N/A				
PERSONNEL INJURIES		DESCRIPTION								
19	Z	N/A		N/A		N/A				
LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION								
20	N	N/A		N/A		N/A				
PUBLICITY ISSUED		DESCRIPTION								

8012110393

J. L. Wilson

(804) 357-3184

NRC USE ONLY

9237-16 02

ATTACHMENT 1 (PAGE 1 OF 1)
SURREY POWER STATION, UNIT 2
DOCKET NO: 50-281
REPORT NO: 80-037/03L-0
EVENT DATE: 11-05-80

TITLE OF REPORT: LOW DISCHARGE PRESSURE ON 2-SW-P-10B

1. EVENT DESCRIPTION

Upon investigation of a high temperature on charging pump 2-CH-P-1A, FI-SW-201A (charging pump lube oil cooler flow indicator) and FI-SW-201B (charging pump intermediate seal cooler flow indicator) indicated a reduced flow. Service Water Pump 2-SW-P-10B indicated a low discharge pressure of 10 PSIG. The low discharge pressure switch sensing line was clogged. This is contrary to T.S. 3.3.B.8.b and is reportable per T.S. 6.6.2.b.(2).

2. PROBABLE CONSEQUENCES AND STATUS OF REDUNDANT SYSTEMS:

The Charging Pump Service Water Subsystem provides cooling for the charging pump lube oil and intermediate seal coolers. The redundant pump, 2-SW-P-10A, was operable and performed its intended function. The charging pump temperatures returned to normal. Therefore, the health and safety of the public were not affected.

3. CAUSE:

The cause of the low discharge pressure was a clogged pump suction strainer. The cause of the failure of low discharge pressure alarm to annunciate was a clogged sensing line.

4. IMMEDIATE CORRECTIVE ACTION:

The redundant pump, 2-SW-P-10A, was started and verified, providing the required pressure and flow.

5. SUBSEQUENT CORRECTIVE ACTION:

Cleaned suction strainer in inlet to pump 2-SW-P-10B. Restarted the pump, and verified that it was operable. Also, cleaned the sensing line for the discharge pressure switch.

6. ACTIONS TAKEN TO PREVENT RECURRENCE:

A design change is in progress, as a result of the pipe stress analysis program. Piping rearrangement and system changes specified in the design change will improve the flow capabilities of the system.

7. GENERIC IMPLICATIONS:

Any changes would be applicable to both units.