

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 VA SP S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

1 REPORT SOURCE L 6 0 5 0 0 0 2 8 1 7 0 1 1 9 8 1 8 0 2 1 3 8 1 9

8 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

2 A fire watch had been established when the Fuel Oil Pump House CO₂ system was made inop-
 3 erable for Design Change modifications. At 0700 it was discovered that a fire watch was
 4 not being maintained. Operations personnel had made periodic inspections of the area;
 5 The position was unmanned for only 1½ hours. Manual fire suppression was available, A
 6 fire watch was immediately re-established. Therefore, the health and safety of the public
 7 were not affected. This event is contrary to T.S. 3.21.D.3.a and is reportable per T.S.
 8 6.6.2.b.(2). 80

9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 0 9 A B 11 A 12 C 13 Z Z Z Z Z Z 14 Z 15 Z 16
 8
 17 LER/RO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT REVISION
 REPORT NUMBER YEAR REPORT NO. CODE TYPE NO.
 8 1 8 1 - 0 1 1 / 0 3 L - 0
 21 22 23 24 25 26 27 28 29 30 31 32
 ACTION FUTURE EFFECT SHUTDOWN HOURS ATTACHMENT NPRD-4 PRIME COMP. COMPONENT
 TAKEN ACTION ON PLANT METHOD METHOD SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
 X 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 Z 25 Z 9 9 9 9 26
 33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The assigned fire watch had left their post without being properly relieved. A fire watch
 1 1 was immediately re-established, and appropriate disciplinary action was taken against the
 1 2 missing fire watch.
 1 3
 1 4

9 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32
 1 5 E 28 1 0 0 29 N/A B 31 Operator inspection 80

8 9 ACTIVITY CONTENT RELEAED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
 1 6 Z 33 Z 34 N/A N/A 80

8 9 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
 1 7 0 0 0 37 Z 38 N/A 80

8 9 PERSONNEL INJURIES NUMBER DESCRIPTION 41
 1 8 0 0 0 40 N/A 80

8 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
 1 9 Z 42 N/A 80

8 9 PUBLICITY ISSUED DESCRIPTION 45 8102190595 N/A 80
 2 0 N 44
 8 9 J. L. Wilson (804) 357-3184 68 69 NRC USE ONLY 917-926

ATTACHMENT I
SURRY POWER STATION, UNIT 2
DOCKET NO: 50-281
REPORT NO: 81-011/03L-0
EVENT DATE: 01-19-81

TITLE OF EVENT: FIRE WATCH NOT MAINTAINED

1. EVENT DESCRIPTION:

With Unit 1 defueled and Unit 2 at 100% power, the Fuel Oil Pump House High Pressure CO₂ fire system had been made inoperable for Design Change modifications. A fire watch had been established as required by Tech. Specs. At 0700 hours on 1-19-81, it was discovered that the fire watch was not being maintained. This is contrary to Technical Specifications 3.21.D.3.a and is reportable per Technical Specification 6.6.2.b.(2).

2. PROBABLE CONSEQUENCES AND STATUS OF REDUNDANT SYSTEMS:

The automatic initiation system for the Fuel Oil Pump House CO₂ fire protection system was inoperable; however, manual initiation capabilities were still available. Operations personnel had been making periodic inspections of the area, therefore, the position was unmanned for only 1½ hours. The health and safety of the public were not affected.

3. CAUSE:

The assigned fire watch left without being properly relieved. The fire watch had gone home at 0530 hours.

4. IMMEDIATE CORRECTIVE ACTIONS:

The immediate corrective action was to establish a fire watch and attempt to locate the missing fire watch.

5. SUBSEQUENT CORRECTIVE ACTION:

Appropriate disciplinary action was taken against the fire watch.

6. ACTION TAKEN TO PREVENT RECURRENCE:

The importance of maintaining a fire watch has been emphasized to all fire watches.

7. GENERIC IMPLICATIONS:

None.