

LER 76-15/3L
LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--	--

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME:

01	N	Y	R	E	G	1
----	---	---	---	---	---	---

 LICENSE NUMBER:

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE:

4	1	1	1	1
---	---	---	---	---

 EVENT TYPE:

0	3
---	---

CATEGORY:

01	CONT
----	------

 REPORT TYPE:

L

 REPORT SOURCE:

L

 DOCKET NUMBER:

0	5	0	-	0	2	4	4
---	---	---	---	---	---	---	---

 EVENT DATE:

0	4	2	4	7	6
---	---	---	---	---	---

 REPORT DATE:

0	5	2	4	7	6
---	---	---	---	---	---

EVENT DESCRIPTION

02

 During normal operation air ejector and blowdown radiation monitors alarmed. Analysis

03

 of "B" SG blowdown showed iodine activity from a calculated leak rate of 0.06-gpm.

04

 Eddy current (ec) testing verified the leaking tube. Twelve others in adjacent area which

05

 appeared to have similar ID type indications at approx. 2½ to 3" above the tube sheet

06

 were all plugged. Additional ec testing was conducted (cont'd. on attached sheet)

SYSTEM CODE:

C	B
---	---

 CAUSE CODE:

E

 COMPONENT CODE:

H	T	E	X	C	H
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER:

N

 COMPONENT MANUFACTURER:

W	1	2	0
---	---	---	---

 VIOLATION:

N

CAUSE DESCRIPTION

08

 The investigation of steam generator tube failures is continuing. The steam generator

09

 is a Westinghouse Series 44, using inconel tubes size 0.875 OD with 0.050 inch walls.

10

FACILITY STATUS:

E

 % POWER:

0	9	9
---	---	---

 OTHER STATUS:

NA

 METHOD OF DISCOVERY:

c

 DISCOVERY DESCRIPTION:

Rad monitors and sample analysis

FORM OF ACTIVITY RELEASED:

Z

 CONTENT OF RELEASE:

Z

 AMOUNT OF ACTIVITY:

NA

 LOCATION OF RELEASE:

NA

PERSONNEL EXPOSURES

NUMBER:

0	0	0
---	---	---

 TYPE:

Z

 DESCRIPTION:

NA

PERSONNEL INJURIES

NUMBER:

0	0	0
---	---	---

 DESCRIPTION:

NA

OFFSITE CONSEQUENCES

15

NA

LOSS OR DAMAGE TO FACILITY

TYPE:

Z

 DESCRIPTION:

NA

PUBLICITY

17

 Press release was made.

ADDITIONAL FACTORS

18

NA

19

NAME: Leon D. White, Jr.

PHONE: 716-546-2700, ext. 2420



11

12

13

14


15

16

Licensee Event Report
Reportable Occurrence 50-244/76-15

Event Description (cont'd.)

(approximately 1,000 tubes) to determine if the pattern of degradation existed in other peripheral tubes beyond the locality of the leak. One additional tube, not in the periphery, was indicated to require plugging. (Reportable Occurrence 76-15, 30-day).



50-244

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: Mr O'Reilly

FROM Rochester Gas & Elec Co
Rochester, NY
L D White

DATE OF DOCUMENT
5-12-76

DATE RECEIVED 5-14-76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
none signed

DESCRIPTION

Ltr furnishing a supplemental rpt on Reportable Occurrence #76-07, which concerning failure of relay for train "A" containment isolation & containment ventilation isolation to latch
.....

ENCLOSURE

**ACKNOWLEDGED
DO NOT REMOVE**

PLANT NAME: Ginna

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO 5-20-76 ehf

BRANCH CHIEF:	<i>Purple</i>
W/3 CYS FOR ACTION	
LIC. ASST:	<i>Shippard</i>
W/1 CYS	
ACRS 16 CYS HOLDING/SENT TO LA	

INTERNAL DISTRIBUTION

<u>REG FILE</u>	
NRC PDR	
I & E (2)	
MIPC (3)	
SCHROEDER/IPPOLITO	
HOUSTON	
NOVAK/CHECK	
GRIMES/SCHWENCER	
CASE	
F. WILLIAMS	
HANAUER	
TEDESCO/MACCARY	
EISENHUT	
BAER	
SHAO	
VOLLMER/BUNCH	
KREGER/J. COLLINS	

EXTERNAL DISTRIBUTION

LPDR: Lyons + Rochester NY	
TIC	
NSIC	

CONTROL NUMBER

4918



Handwritten mark or signature.

.....