



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT


Regulatory

NEW YORK STATE
File-Cy

TELEPHONE
AREA CODE 716 546-2700

February 6, 1976

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406



Subject: Reportable Occurrence 76-01 (30-day report), Containment
Purge Supply and Exhaust Valves excessive leak rates
during testing.
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. O'Reilly:


In accordance with Technical Specifications, Article 6.9.2b, the attached report of Reportable Occurrence 76-01, 30-day, is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,


L. D. White, Jr.

Attachment

cc: Mr. John G. Davis (30)
Mr. William G. McDonald (3)



1362



LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME	LICENSE NUMBER	LICENSE TYPE	EVENT TYPE
01 NYREG 1	00-000000-00	41111	03
CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER
01 CONT	L	L	050-0244
EVENT DATE	REPORT DATE		
011176	020676		

EVENT DESCRIPTION

02	During surveillance test prior to heatup CV purge supply and exhaust valves leaked
03	excessively. Rubber seat adjustment shoes were realigned and leak rates returned to
04	acceptable levels. Excessive leakage from between the purge exhaust valves was
05	reported on February 14, 1974 and November 19, 1974. (Reportable Occurrence 76-01,
06	30-day).

SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
SD	F	VALVEX	A	P340	N

CAUSE DESCRIPTION

08	Possible cause is low ambient temperature during shutdown. It has been found that leak-
09	age checks and adjustments have been necessary after extended operation of purge
10	system; the valves have always performed satisfactorily (cont'd. under Additional Factors)

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
G	000	NA	b	NA

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
Z	Z	NA	NA

PERSONNEL EXPOSURES

13	NUMBER	TYPE	DESCRIPTION
000	Z	NA	

PERSONNEL INJURIES

14	NUMBER	DESCRIPTION
000		NA

OFFSITE CONSEQUENCES

15	NA
----	----

LOSS OR DAMAGE TO FACILITY

16	TYPE	DESCRIPTION
Z		NA

PUBLICITY

17	NA
----	----

ADDITIONAL FACTORS

18	(cont'd. from Cause Description) during power operation. An investigation for replace-
19	ment seat material has been initiated. These are Henry Pratt 48" butterfly valves.

NAME: I. C. Noon PHONE: 716/546-2700, ext. 291-215