•									PO	W 28-06-01
NRC Form 366 19-831			LIC	ENSE	E EVEN	IT REI	PORT	(LER)	U.S. NU	CLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/88
FACILITY NAME (1)	Surry P ial For A	ower Stat An Inadec	tion, Ur quate Se	nit 1 ervice	e Wate	er Suj	oply I	During A	DOCKET NUMBER 0 15 0 0 LOCA WI	(2) PAGE (3) 0 2 8 0 1 OF 0 5 th A Loss of
Offsite EVENT DATE (5) MONTH DAY YEA	R YEAR	LER NUMBER (6) REVISION	REF MONTH	DAY	(7) YEAR		OTHER FACILITY NAM	FACILITIES INVO	LVED (8) DOCKET NUMBER(S)
	8 8 8 -				1 2					
OPERATING MODE (9)	THIS REPO	RT IS SUBMITTED		20.405		NTS OF 10	CFR §: (0	Check one or more (50,73(s)(2)(iv)	of the following) (1	1) 73.71(b)
POWER LEVEL (10) 1 1 0	0 20.408 20.408 20.408	5(#)(1)(i) 5(#)(1)(ii) 5(#)(1)(iii)		50.36(c) 50.36(c) 50.73(a))(1))(2))(2)(i)			50.73(a)(2)(v) 50.73(a)(2)(vii) 50.73(a)(2)(viii)(A)	73.71(c) OTHER (Specify in Abstract below and in Text, NRC Form 366A)
	20.40	5(a)(1)(iv) 5(a)(1)(v)		50.73(a) 50.73(a) ICENSEE)(2)(ii))(2)(iii) CONTACT	FOR THIS	LER (12)	50,73(s)(2)(viii)((50,73(s)(2)(x)	8)	
D. L.	Benson,	Station	Manage	r					AREA CODE 81014	TELEPHONE NUMBER
		COMPLETE C	DNE LINE FOR	EACH CO	MPONENT	FAILURE	DESCRIBE	D IN THIS REPOP	 IT (13)	
CAUSE SYSTEM CO	MPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS			CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS
	I									
<u> </u>			NTAL REPORT	EXPECTE	D (14)	8				MONTH DAY YEAR
YES (If yes, comple	& EXPECTED SL	IBMISSION DATE		x	NO		-		SUBMISS DATE (1	
ABSTRACT (Limit to 1400 upace, i.e. approximately fifteen single days of the power (LOCA) and the power (LOCA), it was determined that an adequate supply of service water may not be available to provide sufficient flow to the Recirculation Spray Heat Exchangers (RSHX), in the event that a large break Loss Of Coolant Accident (LOCA), on one unit, and a Loss of Offsite Power (LOOP) occurred, in coincidence with the additional failure of either an emergency service water pump, condenser isolation signal, an emergency diesel generator, a service water isolation valve, or the intake vacuum priming breakers. The potentially inadequate SW supply following a LOCA with a LOOP is the result of a design deficiency and an inconsistency between T. S. and the Final Safety Analysis Report (FSAR). Prior to startup of either unit, actions will be taken to address each scenario. These will include, changes to plant Emergency Procedures, a requirement that three emergency service water pumps be operable during certain plant conditions, and a design change to provide a safety related circulating water (CW) isolation signal to ensure satisfactory CW isolation.										
NRC Form 386	8810 PDR S	0170460 ADOCK	88101: 05000: Pl	2 280 DC						IE22

• •

•

3P

•

-...

1					_	
NRC Form 366A (9-83)	LICENSEE EVENT REP	ORT (LER) TEXT CONTI	NUATION	U.S. NUCLEAR REC APPROVED O EXPIRES: 8/31	ULATORY COMMISSIO MB NO. 3150-0104 /88	NC
FACILITY NAME (1)		DOCKET NUMBER (2)	LER NUMBE	R (6)	PAGE (3)	
			YEAR SEQUENT	R REVISION		7
Surry Power S	tation, Unit 1	0 15 10 10 10 1 2 18 1	0 81 8 - 0131	1 - 010	0 20 0 1	5

POW 28-06-01

TEXT (If more space is required, use additional NRC Form 366A's) (17)

1.0 Description of the Event

On September 12, 1988 at 0945 hours, with Unit 1 at 100% power and Unit 2 at cold shutdown (CSD), it was determined that an adequate supply of service water may not be available to provide sufficient flow to the Recirculation Spray Heat Exchangers (RSHX) {EIIS-BE, HX}, in the event that a large break Loss Of Coolant Accident (LOCA), on one unit, and a Loss of Offsite Power (LOOP) occurred, in coincidence with the additional failures described in the scenarios below.

- 1) At present, Technical Specifications (T. S.) require two Emergency Service Water (ESW) {EIIS-BI} pumps to be operable when a unit is above 350 degrees Fahrenheit/450 psig. This scenario postulates that during a LOCA and LOOP, a failure of one of the two operable ESW pumps could result in a canal inventory loss of 21,000 gpm, since the RSHXs would use 36,000 gpm and one ESW pump is designed to supply 15,000 gpm.
- 2) Non safety grade equipment is used to detect either a low canal level or a loss of two reserve station service transformers coincident with a hi hi CLS. The low canal level signal will automatically isolate circulating water to the condenser, component cooling, bearing cooling and other non essential service water subsystems. The other signal will automatically isolate circulating water to the condenser. This scenario assumes that the equipment used to detect the conditions stated above could fail, and consequently, the required isolation of service water would not occur.
- 3)
- A LOCA with a LOOP and one unit's Residual Heat Removal system (RHR) {EIIS-BP} in operation, and the failure of one of the two required ESW pumps, would also result in an inadequate service water supply.

NRC Form 366A (9-83) LICENSEE EVENT	REPORT (LER) TEXT CONTI	NUATION	U.S. NUCLEAR REG APPROVED O EXPIRES: 8/31	ULATORY COM MB NO, 3150-01 /88	MISSION	
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER	LER NUMBER (6)		PAGE (3)	
		YEAR SEQUENT	AL AEVISION			
Surry Power Station, Unit 1	0 5 0 0 0 2 8	0 8 8 - 0 3	1 _0 10	0 3 OF	0 5	

Subsequent reviews, with both units at cold shutdown, identified the following related scenarios.

A LOCA and LOOP with a failure of the non (4) accident unit's Emergency Diesel Generator {EIIS-DG} (EDG) would result in an excessive drawdown of the intake canal due to the loss of power to the non accident unit's condenser isolation valves. In addition, a LOCA with either a LOOP or low canal level and a single failure of one of the BC or CC valves, could result in a drawdown of the canal level.

POW 28-06-01

5) The potential exists for the Circulating Water (CW) pumps discharge lines to siphon water out of the canal, if the non safety grade vacuum breakers on the discharge lines fail. However, this is only a concern if canal level is required to be greater than 18 feet, since the discharge lines are designed to allow sufficient air intake to break the siphon when canal level drops to 18 feet.

2.0 Safety Consequences and Implications

The scenarios described above would require as a minimum, the occurrence of three highly unlikely events to result in an inadequate supply of service water. The events are a LOCA, a LOOP, and a failure of one of the following: An emergency service water pump, condenser isolation signal, an EDG, a service water isolation valve, or the intake vacuum priming breakers. Both units are currently in cold shutdown and will remain shutdown until corrective actions are implemented. Therefore, the health and safety of the public will not be affected.

3.0 Cause

The potentially inadequate SW supply following a LOCA with a LOOP is the result of a design deficiency and an inconsistency between T. S. and the Final Safety Analysis Report (FSAR). The original design for condenser isolation did not account for a potential failure of the non-LOCA units' emergency diesel. generator. The present T. S. requirements for two

NRC Form 366A (9-83)	LICENSEE EVENT REF	ORT (LER) TEXT CONTINU	U.S. NUCLEAR REC JATION APPROVED O EXPIRES: 8/31	GULATORY COMMISSION DMB NO. 3150-0104 /88
FACILITY NAME (1)	-	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)
			YEAR SEQUENTIAL REVISION NUMBER NUMBER	
	Surry Power Station, Unit	1 0 5 0 0 0 28 0		0 4 OF 0 5
TEXT (If more space is	required, use additional NRC Form 366A's) (17)			

operable ESW pumps does not account for the SW requirements for a LOCA on one unit with the other unit on RHR. Also, the original design did not require that all of the components required to achieve condenser isolation be qualified as safety grade.

POW 28-06-01

4.0 Immediate Corrective Action(s)

Operator standing orders were issued that instructed the operators to maintain greater than 27 feet of water in the canal and provided guidance on how to minimize depletion of service water from the canal and maximize the supply in the event the above scenarios occurred.

In addition, instructions were issued to maintain three emergency service water pumps operable while either unit is on the residual heat removal system and the other unit is above 350 degrees Fahrenheit/450 psig.

5.0 Additional Corrective Action(s)

Prior to startup of either unit, actions will be taken to address each scenario described above. These actions will include the following:

- 1) Changes to plant Emergency Procedures.
- 2) Operations requirement that three emergency service water pumps be operable prior to placing a unit on RHR with the other unit above 350 degrees Fahrenheit/450 psig and submission of a T. S. change request to that effect.
- 3) Design changes will be implemented that will provide a safety related CW isolation signal and make the necessary modifications to ensure satisfactory CW isolation.

6.0 Action(s) Taken to Prevent Recurrence

The current design change program requires that the change be analyzed for effect on any of the accident analyses. In addition, a thorough review of the UFSAR will be performed as part of a planned design basis development program.

	-	POW 28-06-01	
NRC Form 366A (9-83) LICENSEE EVENT REPC)RT (LER) TEXT CONTINU	U.S. NUCLEAR REC JATION APPROVED C EXPIRES: 8/31	SULATORY COMMISSION DMB NO. 3150-0104 I/88
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)
		YEAR SEQUENTIAL REVISION NUMBER NUMBER	
Surry Power Station, Unit 1	0 5 0 0 0 2 8 0	8 8 - 0 3 1 - 0 0	0 5 OF 0 5
TEXT (If more space is required, use additional NRC Form 366A's) (17)	· · · · · · · · · · · · · · · · · · ·	<u></u>	<u> </u>

7.0 Similar Events

None.

8.0 Manufacturer/Model Number

N/A

VIRGINIA ELECTRIC AND POWER COMPANY

Surry Power Station P. O. Box 315 Surry, Virginia 23883

October 12, 1988

U.S. Nuclear Regulatory Commission Document Control Desk Ol6 Phillips Building Washington, D.C. 20555
 Serial No.:
 88-053

 Docket No.:
 50-280

 Licensee No.:
 DPR-32

Gentlemen:

Pursuant to Surry Power Station Technical Specifications, Virginia Electric and Power Company hereby submits the following Licensee Event Report for Surry Unit 1.

REPORT NUMBER

88-031-00

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be reviewed by Safety Evaluation and Control.

Very truly yours fn

David L. Benson Station Manager

Enclosure

cc: Dr. J. Nelson Grace Regional Administrator Suite 2900 101 Marietta Street, NW Atlanta, Georgia 30323