								_	POW 28-	-06-01	
(9-33) U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/88							DN				
FACILITY NAME (1	Surry	Power Stat	tion, Ur	nit 1				1		(2) PAGE (3)	3
TITLE (4) Pote	TITLE (4) Potential For Overload Of EDGs During LOCA With Loop Due To Design Deficiency										
	EVENT DATE (5) LER NUMBER (6) REPORT DATE (7) OTHER FACILITIES INVOLVED (8)										
	VONTH DAY YEAR YEAR SECURITIAL HEVISION MONTH DAY YEAR FACILITY NAMES DOCKET NUMBER O 15 0 0 0									1	
0 9 1 3	8 8 8 8	0 3 2	00	1 0	1 3	8 8				0 5 0 0 0	
OPERATING MODE (9) NI 20 402(h) 73 71(h) 73 71(h) 73 71(h) 73 71(h)											
POWER	20.	405(a)(1)(i)		50.36(c)(1)			50.73(a)(2)(v)	73.71(c)		
(10) 1	0 0 20.	405(s)(1)(ii)		50,38(c)(2))(2)(1)			50.73(a)(2)(vii)	•)	OTHER (Specify in Abstract below and in Text, NRC For	rm
	20.	405(a)(1)(iv)		50.73(a))(2)(ii)			50,73(e)(2)(viii)(B)	3004/	
	20.	405(a)(1)(v)		50,73(a)) (2) (iii)			50.73(a)(2)(x)			
NAME		· ·	L	ICENSEE	CONTACT	FOR THIS	LER (12)			TELEPHONE NUMBER	
									AREA CODE		_
D.	L. Bensor	<u>Station</u>	Managei	EACH CO	MPONENT	FAILURE	DESCRIBE	D IN THIS REPOR	8 0 4	3 5 7 - 3 1 8	4
CAUSE SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS			CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS	
	SUPPLEMENTAL REPORT EXPECTED (14) EXPECTED SUBMISSION MONTH DAY YEAR								AR		
YES (If yes, c	YES (If yes, complete EXPECTED SUBMISSION DATE) NO								Ц		
On September 13, 1988, at 2320 hours, with Unit 1 at 100% and Unit 2 at cold shutdown (CSD), all 3 Emergency Diesel Generators (EDGs) {EIIS-DG} were declared inoperable due to a design deficiency. The deficiency involved the absence of load sequencing onto the emergency busses following a hi hi Consequence Limiting Safeguards (CLS) actuation and a subsequent Loss Of Offsite Power (LOOP). A unit 1 rampdown was commenced per Technical Specification (T. S.) 3.0.1 and a Notification of an Unusual Event was declared at 2341 hours. However, the unit was not placed in hot shutdown (HSD) until September 14, at 0610 hours, 50 minutes greater than the six hours allowed. The cause of design deficiency was due to the incorrect design assumption that the worst case scenario, for emergency power requirements, was a hi hi CLS actuation with a simultaneous loss of offsite power. The cause of exceeding the 6 hour time to HSD was due to personnel error. Tests will be performed to determine the capability of the EDGs to accept large loads, simulating a hi hi CLS with a LOOP. A design change will be generated to modify the load sequencing to account for a LOCA and subsequent LOOP. The personnel responsible for exceeding the six hour to HSD limit, were reprimanded.											

4

	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION							
ACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBE	3 (6)	PAGE (3)				
		YEAR SEQUENT	R NUMBER					
Surry Power Station, Unit 1	0 5 0 0 0 2 8 0		2 - 0 0	0 2 OF 0 3				

1.0 <u>Description of the Event</u>

On September 13, 1988, at 2320 hours, with Unit 1 at 100% and Unit 2 at cold shutdown (CSD), all 3 Emergency Diesel Generators (EDGs) {EIIS-DG} were declared inoperable due to a design deficiency. The deficiency involved the absence of load sequencing onto the emergency busses {EIIS-EK} following a hi hi Consequence Limiting Safeguards (CLS) {EIIS-JE} actuation and a subsequent Loss Of Offsite Power (LOOP).

POW 28-06-01

Presently, all safeguards pumps do not start immediately upon the actuation of a hi hi Consequence Limiting Safeguards (CLS) signal. Specifically, the Inside Recirculation Spray (IRS) pumps {EIIS-BE, P} and Outside Recirculation Spray (ORS) pumps do not start until two minutes and five minutes, respectively, after the hi hi CLS signal. A LOOP occurring simultaneously with a hi hi CLS actuation would not overload the EDGs with this pump starting scheme. However, if a LOOP were to occur five minutes or more after a hi hi CLS actuation, when all safeguards loads were operating, a potential exists for overloading the EDGs. A unit 1 rampdown was commenced per Technical Specification (T. S.) 3.0.1 and a Notification of an Unusual Event was declared at 2341 hours. However, the unit was not placed in hot shutdown (HSD) until September 14, at 0610 hours, 50 minutes greater than the six hours allowed.

2.0 <u>Safety Consequences and Implications</u>

The present emergency power system is designed to satisfy the requirements of the original plant design basis. Although the above postulated event was not considered, a complete loss of AC power is addressed in the UFSAR, in that a highly reliable DC power supply is provided to maintain vital plant instrumentation functional. Also, procedures exist that guide operators in the restoration of AC power. Therefore, the health and safety of the public were not affected.

		POW 28-06-01
IS BOLLICENSEE	REPORT (LER) TEXT CONTINU	U.S. NUCLEAR REGULATORY COMMISSIO APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/88
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6) PAGE (3)
·		YEAR SEQUENTIAL REVISION NUMBER NUMBER
Surry Powre Station, Unit 1	0 5 0 0 2 8 0	8 8 - 0 3 2 - 0 0 0 3 ^{OF} 0 3
TEXT (If more space is required, use additional NRC Form 366A's) (17)		

3.0 Cause

The cause of design deficiency was due to the incorrect design assumption that the worst case scenario, for emergency power requirements, was a hi hi CLS actuation with a simultaneous loss of offsite power.

The cause of exceeding the 6 hour time to HSD was due to personnel error.

4.0 Immediate Corrective Action(s)

Unit 1 was ramped to hot shutdown and subsequently placed in cold shutdown on September 15, at 0552 hours, within the required 30 hours.

5.0 Additional Corrective Action(s)

Tests will be performed to determine the capability of the EDGs to accept large loads, simulating a hi hi CLS with a LOOP.

6.0 Action(s) Taken to Prevent Recurrence

A design change will be generated to modify the load sequencing to account for a LOCA and subsequent LOOP. The personnel responsible for exceeding the six hour to HSD limit, were reprimanded.

7.0 Similar Events

None.

8.0 Manufacturer/Model Number

N/A

VIRGINIA ELECTRIC AND POWER COMPANY

Surry Power Station P. O. Box 315 Surry, Virginia 23883

October 13, 1988

U.S. Nuclear Regulatory Commission Document Control Desk Ol6 Phillips Building Washington, D.C. 20555
 Serial No.:
 88-055

 Docket No.:
 50-280

 Licensee No.:
 DPR-32

Gentlemen:

Pursuant to Surry Power Station Technical Specifications, Virginia Electric and Power Company hereby submits the following Licensee Event Report for Surry Unit 1.

REPORT NUMBER

88-032-00

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be reviewed by Safety Evaluation and Control.

Very truly yours,

Benson

Station Manager

Enclosure

cc: Dr. J. Nelson Grace Regional Administrator Suite 2900 101 Marietta Street, NW Atlanta, Georgia 30323