

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

October 8, 1993

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555

Serial No. 93-451A
NL&P/ETS R0
Docket Nos. 50-280
50-281
License Nos. DPR-32
DPR-37

Gentlemen:

VIRGINIA ELECTRIC AND POWER COMPANY
SURRY POWER STATION UNITS 1 AND 2
INSERVICE INSPECTION PROGRAM
PRESSURIZER WELD EXAMINATIONS

Inservice Inspection Program relief requests SR-005 were submitted for Surry Power Station Units 1 and 2 on April 16, 1987 and supplemented on February 15, 1989. These requests identified a support structure obstruction which prevented complete examination of the shell-to-top head weld and intersecting longitudinal weld on the pressurizers (1-RC-E-2 and 2-RC-E-2). Specifically, relief was requested from the full volumetric examinations requirements of Section XI, 1980 Edition, Winter 1980 Addenda, Category B-B. As an alternative, we proposed to examine the welds to the extent practical, and delay removing the support structure to perform a complete examination of the identified welds until later in the second ten year interval. These requests were evaluated and approved by the staff in a SER dated March 14, 1991.

We reassessed the pressurizer welds and conclude that removal of the support structure from the pressurizer to perform a complete examination is not practical. Our evaluation estimated that the removal activities and examination of the obstructed portion of the welds will require an expenditure of 18.4 man-rem per unit to accomplish. Based on the large man-rem expenditure, we believe that a complete examination requiring support structure removal is not commensurate with the gain in assurance of component integrity. As such, on August 11, 1993, we requested withdrawal of the original relief requests, with the intention of completing the weld examinations to the extent practical for both units. In a subsequent telephone conversation with your staff to discuss the pressurizer weld examination coverage, it was determined that submitting revised relief requests for the examinations would be necessary. Accordingly, we have reassessed the extent of examination coverage for each weld using the applicable Code requirements, and are providing the details in revised relief requests (SR-005) for both Surry Unit 1 and Unit 2, included as Attachments 1 and 2 to this letter. This letter supersedes our August 11, 1993 request (Serial No. 93-451).

We propose to perform the remaining third period Category B-B examinations on the

9310150173 931008
PDR ADDOCK 05000280
Q PDR


140013

A047
11

pressurizer without removing the support interferences during the 1994 refueling outages for both units. The Code required examination will be completed to the extent practical. If the examination coverage attained for these welds is significantly less than what is proposed by the relief requests, we will submit actual weld examination coverage results following each refueling outage for your review.

These relief requests have been reviewed by the Surry Station Nuclear Safety and Operating Committee. In order to support the Unit 1 refueling outage, we request your review and concurrence of the revised relief request for Unit 1 by November 1, 1993, to support detailed outage planning for the Unit 1 refueling outage currently scheduled to begin in February 1994. If you have any questions concerning these requests please contact us.

Very truly yours,



W. L. Stewart

Attachments

cc: U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, N. W.
Suite 2900
Atlanta, Georgia 30323

Mr. M. W. Branch
NRC Senior Resident Inspector
Surry Power Station

Attachment 1
Surry Power Station Unit 1
Pressurizer Weld Examinations

RELIEF REQUEST NO. SR-005 (Revised)

I. IDENTIFICATION OF COMPONENTS

<u>Weld#</u>	<u>Component ID#</u>	<u>Description</u>	<u>Class</u>
1-07	1-RC-E-2	shell to head	1
1-15	1-RC-E-2	longitudinal	1

II. IMPRACTICAL CODE REQUIREMENTS

The 1980 Edition of ASME Section XI, Category B-B, items B2.11 and B2.12 requires a volumetric examination of 100% of the circumferential shell to head weld and 1 foot of the intersecting longitudinal weld.

III. BASIS FOR RELIEF

The pressurizer is covered with an insulation support ring (attachment 1). The insulation support ring is 6 inches wide, where it interferes with the examination. This ring prevents complete volumetric coverage of both the upper shell to head weld and intersecting longitudinal weld. Total removal of the insulation support ring is considered impractical due to high anticipated exposure levels estimated at 18.4 man-rem. Partial removal of the support ring at the mechanical connection would allow some increase in coverage near the mechanical connection, where the support ring could be spread apart. However, the actual area of weld made accessible to this increased coverage is estimated to be very small in relation to the overall weld length, because the insulation support structure is rigid, interconnected with cross supports, and welded to the supports for the safety valves and power operated relief valves. The intersection of the circumferential shell to head and longitudinal welds is physically located behind one of these supports. Examination coverage of this area would not be improved by partial removal at the mechanical connection.

Any removal of the mechanical connection and spreading apart of the insulation support structure would increase the risk of misalignment problems, and warping of the structure. This risk coupled with the marginal increase in examination coverage, makes partial removal of the insulation support structure also impractical.


IV. ALTERNATE PROVISIONS

A volumetric examination will be performed to the extent practical on welds 1-07 and 1-15. No extended beam path examinations can be performed, since the pressurizer is a clad

vessel. The estimated coverage in the perpendicular beam path directions are detailed in attachment 2. The parallel beam path estimates are as follows:

<u>Weld #</u>	<u>45° (7&8)</u>	<u>60° (7&8)</u>
1-07	79%	79%
1-15 (accessible length only approx. 5")	26%	26%


ATTACHMENT 1



INSULATION SUPPORT ISO
 (FOR STUDY OF INTERFERENCES
 WITH ISI NDE OF PRESSURIZER
 WELDS # 7 & 15)

DESIGNED BY:	JWB
ENGINEER:	<i>[Signature]</i>
DATE:	

PRESSURIZER INSULATION SUPPORT




SECTION A-A
N.T.S.

DRAWN BY:
JWB

ENGINEER:
R. C. Miller

PRESSURIZER INSULATION
SUPPORT





SECTION B - B
N.T.S

AWN BY:
JWB

ENGINEER:
Richard L. Miller

DATE:

PRESSURIZER INSULATION
SUPPORT



PLAN


9 DISC SPRINGS FACING INWARD
9 DISC SPRINGS FACING OUTWARD

EXISTING STRAP

NOTES:

1. SCALE: NONE
2. STUDS SHALL BE PRELOADED TO PRODUCE A MEASURED STRAIN OF .028"-.002"; THIS TO BE DONE WHILE THE FOLLOWING CONDITIONS EXIST:
PRESSURIZER SHELL AT AMBIENT TEMP & ATMOS. PRESSURE AND STRAP AT AMBIENT TEMP ± 15°F
3. INSULATION ON SUPPORT COLUMNS TO BE IN ACCORDANCE W/DC - 84-69
4. AT FINAL INSTALLATION THIS DIMENSION TO BE 1 1/4 ± 1/2
5. SPECIFIC WELDING & NDT PROCEDURES SHALL BE DEVELOPED FOR THIS JOINT IN ACCORDANCE WITH SITE SPECIFIC EQUIPMENT AND CONDITIONS
6. SEE SK.738955/8471-M-40
7. REFERENCE DWG. 11448-FP-9D-7
8. DESIGN BASED ON CALC.NO.14937.03-MN(B)-263-JC REV.0
9. DISCARD JOINT SPACER (SEE REF. DWG.)
10. SEE SK.738955/8471-M-41; 43 & 45

FINAL DRAFT



NUTS AND SPRING WASHERS NOT SHOWN FOR CLARITY

SWEC 14937.03

DC - 84 - 71

O. A. CAT. I
NUCLEAR SAFETY RELATED

6								PRESSURIZER (SAFETY RELIEF VALVE) (BSP)
5								
4								
3								
2								EXPANSION JOINT
1	ORIGINAL ISSUE APYD FOR CONSTR	DIP	11/6	11/6	11/6	11/6	11/6	SURRY POWER STATION UNIT 1
ISSUE	DESCRIPTION	DATE	BY	CHKD	APPD	DATE		VIRGINIA ELECTRIC & POWER CO.
STONE & WEBSTER ENGINEERING CORP BOSTON, MASS								SK. 738955/8471-M-39-1

THE INFORMATION ON THIS DRAWING MAY NOT BE COPIED OR USED FOR OTHER THAN THE CONSTRUCTION MAINTENANCE OR REPAIR OF THE PLANT FACILITY DESCRIBED IN THE TITLE BLOCK

AREAS	LEVELS	WORK PKG

PRINTS
APP CARD
①


ATTACHMENT 2

Surry Unit 1
Pressurizer
Weld 7 Partial Examination Evaluation
(Hatched areas represent no examination coverage)

Weld 7
5 Scan
45° 1/2" Transducer

Vessel Side

Head Side




38.53 Sq. In. Exam. Volume
4.81 Sq. In. not examined
33.72 Sq. In. Examined
88% Examined

Required Examination Boundary
A-B-C-D

Weld 7
2 Scan
45° 1/2" Transducer

Vessel Side

Head Side




38.53 Sq. In. Exam. Volume
18.70 Sq. In. not examined
19.83 Sq. In. Examined
51% Examined

Required Examination Boundary
A-B-C-D

Weld 7
5 Scan
60° 1/2" Transducer

Vessel Side

Head Side




38.53 Sq. In. Exam. Volume
2.68 Sq. In. not examined
35.85 Sq. In. Examined
93% Examined

Required Examination Boundary
A-B-C-D

Weld 7
2 Scan
60° 1/2" Transducer

Vessel Side


Head Side




38.53 Sq. In. Exam. Volume
25.17 Sq. In. not examined
13.36 Sq. In. Examined
35% Examined

Required Examination Boundary
A-B-C-D



Surry Unit 1
Pressurizer
Weld 15 Partial Examination Evaluation
(Hatched areas represent no examination coverage)



Clockwise



Counterclockwise



NOTE: Weld 15 coverage estimate applies only to the area of the weld not covered and made inaccessible by the insulation support ring. Of the Code required examination area, the insulation support ring covers 6 inches of weld 15, allowing approximately 3 inches above the ring to be accessible, and 3 inches below the ring to be accessible.

SURRY UNIT 2

Attachment 2
Surry Power Station Unit 2
Pressurizer Weld Examinations

RELIEF REQUEST NO. SR-005 (Revised)

I. IDENTIFICATION OF COMPONENTS

<u>Weld#</u>	<u>Component ID#</u>	<u>Description</u>	<u>Class</u>
1-07	2-RC-E-2	shell to head	1
1-02	2-RC-E-2	longitudinal	1

II. IMPRACTICAL CODE REQUIREMENTS

The 1980 Edition of ASME Section XI, Category B-B, items B2.11 and B2.12 requires a volumetric examination of 100% of the circumferential shell to head weld and 1 foot of the intersecting longitudinal weld.

III. BASIS FOR RELIEF

The pressurizer is covered with an insulation support ring (attachment 1). The insulation support ring is 6 inches wide, where it interferes with the examination. This ring prevents complete volumetric coverage of both the upper shell to head weld and intersecting longitudinal weld. Total removal of the insulation support ring is considered impractical due to high anticipated exposure levels estimated at 18.4 man-rem. Partial removal of the support ring at the mechanical connection would allow some increase in coverage near the mechanical connection, where the support ring could be spread apart. However, the actual area of weld made accessible to this increased coverage is estimated to be very small in relation to the overall weld length, because the insulation support structure is rigid, interconnected with cross supports, and welded to the supports for the safety valves and power operated relief valves. The intersection of the circumferential shell to head and longitudinal welds is physically located behind one of these supports. Examination coverage of this area would not be improved by partial removal at the mechanical connection.

Any removal of the mechanical connection and spreading apart of the insulation support structure would increase the risk of misalignment problems, and warping of the structure. This risk coupled with the marginal increase in examination coverage, makes partial removal of the insulation support structure also impractical.


IV. ALTERNATE PROVISIONS

A volumetric examination will be performed to the extent practical on welds 1-07 and 1-02. No extended beam path examinations can be performed, since the pressurizer is a clad

vessel. The estimated coverage in the perpendicular beam path directions are detailed in attachment 2. The parallel beam path estimates are as follows:

<u>Weld #</u>	<u>45° (7&8)</u>	<u>60° (7&8)</u>
1-07	26%	26%
1-02 (accessible length only approx. 7.5")	100%	100%


ATTACHMENT 1



VIRGINIA POWER
NORTH CAROLINA POWER
NUCLEAR ENGINEERING SERVICES
RICHMOND, VIRGINIA

INSERVICE INSPECTION DETAIL DRAWING
PRESSURIZER: 2-RC-E-2
SURRY POWER STATION UNIT 2
VIRGINIA POWER


DESIGN	DESIGN SUPV	CAD NO.	PCED000201
DRWN GTW	DIPLO ENGR WFM	DRAWING NO.	11548-VMKS-RC-E-002
CHKD MBL	LEAD ENGR ARF	REV.	2
DATE 12/04/85	SCALE NONE	UNLESS OTHERWISE NOTED 04 OF 2	




INSULATION SUPPORT 150
 (FOR STUDY OF INTERFERENCES
 WITH 151 NDE OF PRESSURIZER
 WELDS #7 & 2)

SURRY POWER STATION

PRESSURIZER WELD UT INTERFERENCE UNIT 2		
DRAWN BY: MM	ENGINEER: R.C. Miller	DATE: 10-20-86



SECTION A-A



SECTION B-B

SURRY POWER STATION

PRESSURIZER WELD
UT INTERFERENCE
UNIT 2

DRAWN BY:

MM

ENGINEER:

R.L. Miller


DATE:

10-20-86

ATTACHMENT 2

Surry Unit 2
Pressurizer
Weld 7 Partial Examination Evaluation
(Hatched areas represent no examination coverage)


Weld 7
5 Scan
45° 1/2" Transducer



38.53 Sq. In. Exam. Volume
24.83 Sq. In. not examined
13.70 Sq. In. Examined
36% Examined

Required Examination Boundary
A-B-C-D


Weld 7
2 Scan
45° 1/2" Transducer



38.53 Sq. In. Exam. Volume
32.29 Sq. In. not examined
6.24 Sq. In. Examined
16% Examined

Required Examination Boundary
A-B-C-D


Weld 7
5 Scan
60° 1/2" Transducer



38.53 Sq. In. Exam. Volume
20.47 Sq. In. not examined
18.06 Sq. In. Examined
47% Examined

Required Examination Boundary
A-B-C-D


Weld 7
2 Scan
60° 1/2" Transducer




38.53 Sq. In. Exam. Volume
27.91 Sq. In. not examined
10.62 Sq. In. Examined
28% Examined

Required Examination Boundary
A-B-C-D



Surry Unit 2
Pressurizer
Weld 2 Partial Examination Evaluation
(Hatched areas represent no examination coverage)



Clockwise



Counterclockwise



NOTE: Weld 2 coverage estimate applies only to the area of the weld not covered and made inaccessible by the insulation support ring. If the Code required examination area, the insulation support ring covers the top 4 inches of weld 2, allowing approximately 8 inches to be accessible.