

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8910260034      DOC. DATE: 89/10/18      NOTARIZED: NO      DOCKET #  
 FACIL: 50-281 Surry Power Station, Unit 2, Virginia Electric & Power      05000281  
 AUTH. NAME      AUTHOR AFFILIATION  
 KANSLER, M. R.      Virginia Power (Virginia Electric & Power Co.)  
 RECIP. NAME      RECIPIENT AFFILIATION

SUBJECT: LER 89-012-00: on 890919, individual rod position indicators  
 out of spec for greater than 60 min in 24 h period.  
W/8      ltr.

DISTRIBUTION CODE: IE22T      COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: lcy NMSS/FCAF/PM. 05000281 S

	RECIPIENT ID CODE/NAME	COPIES	LTR	ENCL	RECIPIENT ID CODE/NAME	COPIES	LTR	ENCL
	PD2-2 LA	1		1	PD2-2 PD	1		1
	BUCKLEY, B	1		1				
INTERNAL:	ACRS MICHELSON	1		1	ACRS MOELLER	2		2
	ACRS WYLIE	1		1	AEOD/DOA	1		1
	AEOD/DSP/TPAB	1		1	AEOD/ROAB/DSP	2		2
	DEDRO	1		1	NRR/DEST/ESB 8D	1		1
	NRR/DEST/ICSB 7	1		1	NRR/DEST/MEB 9H	1		1
	NRR/DEST/MTB 9H	1		1	NRR/DEST/PSB 8D	1		1
	NRR/DEST/RSB 8E	1		1	NRR/DEST/SGB 8D	1		1
	NRR/DLPQ/HFB 10	1		1	NRR/DLPQ/PEB 10	1		1
	NRR/DOEA/EAB 11	1		1	NRR/DREP/RPB 10	2		2
	NUDOCS-ABSTRACT	1		1	<u>REG FILE 02</u>	1		1
	RES/DSIR/EIB	1		1	<u>RGN2 FILE 01</u>	1		1
EXTERNAL:	EG&G WILLIAMS, S	4		4	L ST LOBBY WARD	1		1
	LPDR	1		1	NRC PDR	1		1
	NSIC MAYS, G	1		1	NSIC MURPHY, G. A	1		1
	NUDOCS FULL TXT	1		1				
NOTES:		1		1				

A0-4

R  
I  
D  
S  
/  
A  
D  
D  
S

VIRGINIA ELECTRIC AND POWER COMPANY  
Surry Power Station  
P.O. Box 315  
Surry, Virginia 23883

October 18, 1989

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Serial No.: 89-049  
Docket Nos.: 50-281  
License Nos.: DPR-37

Gentlemen:


Pursuant to Surry Power Station Technical Specifications, Virginia Electric and Power Company hereby submits the following Licensee Event Report for Unit 2.

REPORT NUMBER

89-012-00

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be reviewed by Safety Evaluation and Control.

Very truly yours,



for

M. R. Kansler  
Station Manager

Enclosure

cc: Regional Administrator  
Suite 2900  
101 Marietta Street, NW  
Atlanta, Georgia 30323

IE22  
11

**LICENSEE EVENT REPORT (LER)**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Surry Power Station, Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 2 8 1	PAGE (3) 1 OF 0 4
--	--------------------------------------	----------------------

TITLE (4) Individual Rod Position Indicators Out of Specification For Greater Than 60 Minutes in a 24 Hour Period

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0 9	1 9	8 9	8 9	0 1 2	0 0	1 0	1 8	8 9			0 5 0 0 0
											0 5 0 0 0

OPERATING MODE (9) N	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)									
POWER LEVEL (10) 0 0 2	20.402(b)	20.405(c)	50.73(e)(2)(iv)	73.71(b)						
	20.405(a)(1)(i)	50.38(c)(1)	50.73(e)(2)(v)	73.71(c)						
	20.405(a)(1)(ii)	50.38(c)(2)	50.73(e)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)						
	20.405(a)(1)(iii)	X 50.73(e)(2)(ii)	50.73(e)(2)(viii)(A)							
	20.405(a)(1)(iv)	50.73(e)(2)(iii)	50.73(e)(2)(viii)(B)							
20.405(a)(1)(v)	50.73(e)(2)(iii)	50.73(e)(2)(x)								

LICENSEE CONTACT FOR THIS LER (12)

NAME M. R. Kansler, Station Manager	TELEPHONE NUMBER
	AREA CODE: 8 1 0 4      3 1 5 7 1 - 3 1 1 8 4

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
X	A A	Z I I	M 0 3 5	N					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	X NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
---	------	-------------------------------	-------	-----	------

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On September 19, 1989 at 0815 hours during a unit startup with the reactor critical and less than 2% power, it was discovered that two Individual Rod Position Indicators (IRPI) in control bank "A", group two, had differed in indicated position from the bank's step demand counter by more than 12 steps for 63 and 64 minutes within the last 24 hours. This occurrence is contrary to Technical Specification (T.S.) 3.12.E, which allows this condition to exist for a maximum of 60 minutes in any 24 hour period. This event was due to an inadequate method used to log accumulated times for IRPI differences in excess of 12 steps. The procedure used to log these accumulated times will be modified and the plant computer will be reprogrammed to monitor accumulated times and alarm to alert the operator prior to exceeding the 60 minute limit.

**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Surry Power Station, Unit 2	DOCKET NUMBER (2)  0   5   0   0   0   2   8   1   8   9   -   0   1   2   -   0   0	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8   9	0   1   2	-   0   0	0   2	OF 0   4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

1.0 Description of the Event

On September 19, 1989 at 0815 hours during a unit startup with the reactor critical and less than 2% power, it was discovered that two Individual Rod Position Indicators (IRPI) (EIIS-ZI) in control bank "A" group two, had differed in indicated position from the bank's step demand counter by more than 12 steps for 63 and 64 minutes within the last 24 hours. This occurrence is contrary to Technical Specification (T.S.) 3.12.E, which allows this condition to exist for a maximum of 60 minutes in any 24 hour period.

The subject IRPIs were adjusted to within 12 steps of their step demand counters approximately 15 minutes prior to reactor criticality, however, the event was not realized until thirty minutes after the adjustment.

2.0 Safety Consequences and Implications

The IRPIs provide control rod position indication in the main control room. The control rod demand counters, which indicate the control rod group position as demanded by the rod control system, (EIIS-AA) remained operable during the time the IRPIs were not within specification.

The inoperable IRPIs did not affect the operation of the control rod assemblies. All rods were capable of being tripped into the core if required. Therefore, the health and safety of the public were not affected.

3.0 Cause

IRPIs associated with Westinghouse PWRs are known to drift as a result of reactor coolant temperature and rod position changes at low reactor power levels. Due to this generic problem, a Technical Specification change was recently approved to allow a greater than 12 step, but less than 24 step difference between IRPIs and bank step demand counters for a maximum of one hour in any 24 hour period.

**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Surry Power Station, Unit 2	DOCKET NUMBER (2)  0 5 0 0 0 2 8 1 8 9 - 0 1 2 - 0 0 0 3	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		

TEXT (If more space is required, use additional NRC Form 366A's) (17)

The event was due to an inadequate method used to log accumulated out of specification time for the IRPIs. The greater than one hour accumulated out of specification time occurred over three separate time periods during rod withdrawal. The three events were recorded on two separate procedures corresponding to two different shifts. The operator performing the last procedure on the later shift had not been informed of the accumulated time recorded on the earlier shift's procedure and was not aware of the additional time that the IRPIs difference had exceeded 12 steps. The event could have been averted by discontinuing rod withdrawal had the on shift operator been aware of this condition.

4.0 Immediate Corrective Action(s)

None required since the IRPIs had been adjusted to within the required T.S. tolerance prior to the discovery of the event.

5.0 Additional Corrective Action(s)

None required.

6.0 Action(s) Taken to Prevent Recurrence

The procedure used to log the accumulated time the IRPIs differ from their respective bank's step demand counter by more than 12 steps will be modified to ensure that these accumulated times are transferred during shift relief.

Additionally, the plant computer will be reprogrammed to monitor these accumulated times and will alarm to alert the operator prior to exceeding the 60 minute limit.

7.0 Similar Events

Although an event in which exceeding the allowed accumulated time for IRPI deviation has not occurred before, past incidents of IRPI deviation have been reported which prompted the T.S. change described above.

**LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION**

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Surry Power Station, Unit 2	DOCKET NUMBER (2)  0   5   0   0   0   2   8   1	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8   9	-   0   1   2	-   0   0	0   4	OF 0   4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

8.0 Manufacturer/Model Number(s)

Magnetics Inc./Project #K9391, K9392.