VIRGINIA ELECTRIC AND POWER COMPANY Surry Power Station P.O. Box 315 Surry, Virginia 23883

January 3, 1990

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Serial No.:	89–06 0
Docket Nos.:	5 0 –280
	5 0–28 1
License Nos.:	DPR-32
	DPR-37

Gentlemen:

Pursuant to Surry Power Station Technical Specifications, Virginia Electric and Power Company hereby submits the following Licensee Event Report for Units 1 and 2.

REPORT NUMBER

89-041-00

This report has been reviewed by the Station Nuclear Safety and Operating Committee and will be reviewed by Corporate Nuclear Safety.

Very truly yours,

ano-

M. R. Kansler Station Manager

Enclosure

cc: Regional Administrator Suite 2900 101 Marietta Street, NW Atlanta, Georgia 30323

> 9001110181 PDR ADOCK

ļ,	~RC	Form	366
•			

POW 28-06-01

U.S. H''JLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104

LICENSEE EVENT REPORT (LER)

EXPIRES: 8/31/88

FACILITY NAME (1) DOCKET NUMBER									CKET NUMBER	1 (2)		PA	GE (3)						
Surry Power Station, Units 1 and 2								5 0 0	10[2	1 ⁸ 0	1 OF	-03							
TITLE (4) Auxiliary Vent Fan Taken Out of Service Without Implementing Techni							Technic	al											
Specification Action Statement Due to Personnel Error																			
EV	ENT DATE	: (5)		LER NUMBER ((6)	RE	PORT DAT	E (7)	OTHER FACILITIES INVOLVED (8)										
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION	MONTH	DAY	YEAR		FACILITY NAME	is	DOCKET NUMBER(S)							
							11					0 15	1010	101_	1_1_				
Ι.		Ι.						. Г				1	-						
1 2	06	89	89	041	0 0	01	03	90				0 5	10 10	101					
· 001	RATING		THIS RE	PORT IS SUBMITTE	D PURSUANT	TO THE R	EQUIREM	ENTS OF 10) CFR §: ((Check one or more of	the following) (11)		, .					
M	DDE (9)	N	20	.402(b)		20.406	(c)			50.73(a)(2)(iv)			73.71(b)	'1(b)					
POWE			20	.406(a)(1)(i)		50.36(c	:)(1)			50.73(s)(2)(v)		73_71(c)							
(10)	՝՝ 1 _լ	0,0	20	.405(a)(1)(8)		50.36(c	:)(2)			50,73(s)(2)(vii)			OTHER (Specify in Abstract						
			20	.405(a)(1)(iii)	X	50.73(a	1)(2)(I)			1 50,73(a)(2)(viii)(A)	1		1640 w and 11 366A)	n Text, ren	IC Form				
			20	.405(a)(1)(iv)		50,73(a	1)(2)(ii)			- 50,73(a)(2)(viii)(8)	(8)								
			20	.405(s)(1)(v)		50.73ta	1)(2)(iii)			50.73(a)(2)(x)			•						
			L				CONTACT	FOR THIS	LER (12)	·									
NAME					. .							TELEPH	TELEPHONE NUMBER						
М	. R. 2	Kans]	er, S	Station Ma	mager						T								
											8 0 4	3 5	3 5 7 - 3 1 8 4						
				COMPLETE	ONE LINE FOR	EACH C	OMPONEN	T FAILURE	DESCRIBE	ED IN THIS REPORT	' (13)								
CALISE	SYSTEM	COMB	ONENT	MANUFAC-	REPORTABLE	CALISE SYSTEM COMPONENT MANUFAC						REPC	REPORTABLE						
0-052	arare			TURER	TO NPRDS			CAUGE	513121	Comrenent	TURER	то	NPRDS						
	[]	· · ·			T				Ī										
								<u> </u>											
	T I	Γ			T				T	· · ·									
								<u> </u>											
				SUPPLEM	ENTAL REPORT	EXPECT	ED (14)				EXPEC	TED	MONTH	DAY	YEAR				
									SION		T	T							
YE	S (If yee, c	ompiete E	XPECTED	SUBMISSION DATI	E)		X NO												
ABSTRA	CT (Limit)	to 1400 m	XOCES, 1.0., 1	approximately fifteen	single-spece typ	ewritten lie	nes) (16)					· ·							
· · · ·																			

On December 6, 1989, the "A" train of auxiliary ventilation was removed from service by placing the fan control switch in the pull-to-lock (PTL) position. This removed the automatic start feature of the fan rendering the fan technically inoperable and the appropriate Technical Specification action statement was not implemented. The cause of the event was personnel error. The shift supervisor involved failed to consider that placing the switch in PTL would render the fan inoperable. The fan was returned to automatic control when the switch was placed in the automatic position 30 minutes after the event. All operations personnel have been directed to consider safety related equipment inoperable whenever placing the controls in the PTL position.

	IS. NUCLEAR REGULATORY COMMISSION	DN APPROVED OMB NO. 3150-0104 EXPIRES: 4/30/92 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH T BFORMATION COLLECTION REQUEST: 50.0 HRS. FORW/ COMMENTS REGARDING BURDEN ESTIMATE TO THE RECO AND REPORTS MANAGEMENT BRANCH (P530). U.S. NUCLI REGULATORY COMMISSION, WASHINGTON, DC 20585. AND THE PAPERWORK REDUCTION PROJECT (3150-0104), OFF OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.							
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)						
Surry Power Station, Units 1 and 2		YEAR SEQUENTIAL REVISION							
TEXT // more space to required use of this will be to serve a server	0 5 0 0 0 2 8 0	8 9 _ 0 4 1 _ 0 0	0 2 OF 0 3						
and a second a revealed, one sourcons NHC Form 3054 2/ (17)									

1.0 Description of the Event

On December 6, 1989, with Unit 1 and Unit 2 at 100% power, the Superintendent of Operations discovered through a review of control room operator's logs that "A" train auxiliary ventilation exhaust (ELLS-VF) the fan (1-VS-F-58A) (ELLS-FAN) had been removed from service earlier that day for approximately 30 minutes. The fan's control switch had been placed in the pull-to-lock position at 1010 hours to support replacement of the fan's oil level sight glass. The shift supervisor had received instructions earlier that the maintenance on the fan was to be performed under operator standby. This is an approved method used to control operation of equipment while maintenance is being performed on it. In this case operator standby was achieved by placing the control switch in the PTL position under the direct control of a control room operator. In the PTL position the fan would not automatically start as designed upon the initiation of a safety injection. Consequently, the fan should have been considered inoperable. Technical Specifications 3.22 requires that when one train of the exhaust filter system is inoperable for any reason, the redundant train shall be demonstrated operable immediately and the inoperable train shall be returned to operable status within seven days or the unit be placed in at least hot shutdown. The seven day action statement was not entered nor was the "B" At 1040 hours, train demonstrated operable. fan control was returned to automatic after maintenance personnel determined that the correct parts were not available.

2.0 Safety Consequences and Implications

The auxiliary ventilation system is designed to remove heat from various areas in the plant to ensure proper operation of safety related equipment in the event of a design basis accident (DBA). In addition, this system is designed to remove particulate and iodine contaminants in the exhaust air from these areas following a DBA. U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104 EXPIRES: 4/30/92

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION					ESTIMATED BURDEN PER RESPONSE TO COMPLY WTH THIS DEFORMATION COLLECTION REQUEST: 50,0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.												
FACILITY NAME (1)		DOCKET NUMBER (2)						LER NUMBER (6)						PAGE (3)			
								YEAR		SEQUENTIAL NUMBER		NUMBER					
Surry Power Station, Units I and 2		15	10	1 0	10			0 10		01411						٦ ک	
TEXT (If more spece is required, use additional NRC Form 3864's) (TT)	<u> </u>	1.	<u> </u>	1.		20	10	0 9						<u>, , , , , , , , , , , , , , , , , , , </u>		-	

During the time that the control switch for the "A" train of filtered exhaust was in the pull-to-lock position, the "B" train was operable and in automatic. In addition, since the maintenance was not performed on the fan, the fan was available for operation at all times during this event. Therefore, the health and safety of the public were not affected.

3.0 Cause

NRC FORM 366A (6-89)

Technical the The cause of failure to enter Specification action statement was due to personnel error. The senior reactor operator (SRO) involved with the event failed to consider that placing the fan's control switch in the PTL position rendered it Consequently, the actions technically inoperable. required by Technical Specification for an inoperable fan were not implemented.

Immediate Corrective Action(s) 4.0

None required since the fan had been returned to automatic control when the event was discovered.

5.0 Additional Corrective Action(s)

None required.

6.0 Action(s) Taken to Prevent Recurrence

A memorandum was issued by the operations coordinator to all operations shift supervisors directing that safety related equipment be considered inoperable controls are placed in the PTL whenever their position. The only exceptions would be if appropriate. approved controls are taken. This memorandum has been placed in required reading for all licensed personnel.

7.0 Similar Events

None.

Manufacturer/Model Number(s) 8.0

N/A.