

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

February 25, 1991

U.S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D.C. 20555

Serial No. 91-077  
NL&P/RBP R0  
Docket Nos. 50-280  
50-281  
License Nos. DPR-32  
DPR-37

Gentlemen:

**VIRGINIA ELECTRIC AND POWER COMPANY**  
**SURRY POWER STATION UNITS 1 AND 2**  
**1990 ANNUAL STEAM GENERATOR INSERVICE INSPECTION REPORT**

In accordance with the requirements of Technical Specifications 4.19.F.b, Virginia Electric and Power Company submits herewith the 1990 Steam Generator Inservice Inspection Report for Surry Power Station Units 1 and 2. There is no information provided for Unit 2 because there were no steam generator tube inspections performed for Unit 2 during the calendar year 1990.

During the 1990 refueling outage for Surry Power Station Unit 1, the tubes in the "A," "B," and "C" steam generators were examined. The information in Attachment 1 is a summary of the results of those examinations. These results include the number and extent of the tubes examined, location and characterization of each indication of an imperfection, and identification of the tubes that were plugged. Attachment 2 provides a glossary of the terms used in the report.

Should you require additional information, please contact us.

Very truly yours,



W. L. Stewart  
Senior Vice President - Nuclear

Attachments

1. 1990 Annual Steam Generator Inservice Inspection Report for Surry Unit 1.
2. Glossary of Terms.

9103040071 910225  
PDR ADOCK 05000280  
Q PDR

A047  
11

cc: U.S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, N.W.  
Suite 2900  
Atlanta, Georgia 30323

Mr. W. E. Holland  
NRC Senior Resident Inspector  
Surry Power Station