

PSEG Nuclear LLC
P.O. Box 236, Hancocks Bridge, New Jersey 08038-0236



JUN 18 2018

10CFR50.73

LR-N18-0068

United States Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-001

Hope Creek Generating Station
Renewed Facility Operating License No. NPF-57
Docket No. 50-354

Subject: Licensee Event Report 2018-003-00, Feedwater Isolation Valve
Leakage Exceeded Technical Specification Limit

In accordance with 10 CFR 50.73(a)(2)(i)(B), PSEG Nuclear LLC is submitting Licensee
Event Report (LER) Number 2018-003-00, "Feedwater Isolation Valve Leakage
Exceeded Technical Specification Limit."

If you have any questions or require additional information, please contact
Mr. Thomas MacEwen at (856) 339-1097.

There are no regulatory commitments contained in this letter.

Sincerely,


John F. Garecht (acting plant manager)

for Edward T. Casulli
Plant Manager
Hope Creek Generating Station

ttm

Attachment: Licensee Event Report 2018-003-00

cc: Mr. Daniel Dorman, Regional Administrator – Region I, NRC
Mr. Jim Kim, Project Manager - US NRC
Mr. Justin Hawkins, NRC Senior Resident Inspector – Hope Creek (X24)
Mr. Patrick Mulligan, Manager IV, NJBNE
Mr. Thomas MacEwen, Hope Creek Commitment Tracking Coordinator (H02)
Mr. Lee Marabella, Corporate Commitment Tracking Coordinator (N21)



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)
(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

| | | |
|--|--------------------------------------|--------------------------|
| 1. Facility Name Hope Creek Generating Station | 2. Docket Number 05000-354 | 3. Page 1 OF 3 |
|--|--------------------------------------|--------------------------|

4. Title
Feedwater Isolation Valve Leakage Exceeded Technical Specification Limit

| 5. Event Date | | | 6. LER Number | | | 7. Report Date | | | 8. Other Facilities Involved | |
|---------------|-----|------|---------------|-------------------|---------|----------------|-----|------|------------------------------|---------------|
| Month | Day | Year | Year | Sequential Number | Rev No. | Month | Day | Year | Facility Name | Docket Number |
| 04 | 18 | 2018 | 2018 | -003 | -00 | 06 | 18 | 2018 | Facility Name | Docket Number |
| | | | | | | | | | | 05000 |
| | | | | | | | | | | 05000 |

| | | | | | | | | | | |
|-----------------------------------|--|---|--|---|--|--|--|--|--|--|
| 9. Operating Mode 5 | 11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply) | | | | | | | | | |
| | <input type="checkbox"/> 20.2201(b) | <input type="checkbox"/> 20.2203(a)(3)(i) | <input type="checkbox"/> 50.73(a)(2)(ii)(A) | <input type="checkbox"/> 50.73(a)(2)(viii)(A) | | | | | | |
| | <input type="checkbox"/> 20.2201(d) | <input type="checkbox"/> 20.2203(a)(3)(ii) | <input type="checkbox"/> 50.73(a)(2)(ii)(B) | <input type="checkbox"/> 50.73(a)(2)(viii)(B) | | | | | | |
| | <input type="checkbox"/> 20.2203(a)(1) | <input type="checkbox"/> 20.2203(a)(4) | <input type="checkbox"/> 50.73(a)(2)(iii) | <input type="checkbox"/> 50.73(a)(2)(ix)(A) | | | | | | |
| | <input type="checkbox"/> 20.2203(a)(2)(i) | <input type="checkbox"/> 50.36(c)(1)(i)(A) | <input type="checkbox"/> 50.73(a)(2)(iv)(A) | <input type="checkbox"/> 50.73(a)(2)(x) | | | | | | |
| | <input type="checkbox"/> 20.2203(a)(2)(ii) | <input type="checkbox"/> 50.36(c)(1)(ii)(A) | <input type="checkbox"/> 50.73(a)(2)(v)(A) | <input type="checkbox"/> 73.71(a)(4) | | | | | | |
| 10. Power Level 0 | <input type="checkbox"/> 20.2203(a)(2)(iii) | <input type="checkbox"/> 50.36(c)(2) | <input type="checkbox"/> 50.73(a)(2)(v)(B) | <input type="checkbox"/> 73.71(a)(5) | | | | | | |
| | <input type="checkbox"/> 20.2203(a)(2)(iv) | <input type="checkbox"/> 50.46(a)(3)(ii) | <input type="checkbox"/> 50.73(a)(2)(v)(C) | <input type="checkbox"/> 73.77(a)(1) | | | | | | |
| | <input type="checkbox"/> 20.2203(a)(2)(v) | <input type="checkbox"/> 50.73(a)(2)(i)(A) | <input type="checkbox"/> 50.73(a)(2)(v)(D) | <input type="checkbox"/> 73.77(a)(2)(ii) | | | | | | |
| | <input type="checkbox"/> 20.2203(a)(2)(vi) | <input checked="" type="checkbox"/> 50.73(a)(2)(i)(B) | <input type="checkbox"/> 50.73(a)(2)(vii) | <input type="checkbox"/> 73.77(a)(2)(iii) | | | | | | |
| | | <input type="checkbox"/> 50.73(a)(2)(i)(C) | <input type="checkbox"/> Other (Specify in Abstract below or in NRC Form 366A) | | | | | | | |

12. Licensee Contact for this LER

| | |
|--|--|
| Licensee Contact Thomas MacEwen, Principal Nuclear Engineer | Telephone Number (Include Area Code) 856-339-1097 |
|--|--|

13. Complete One Line for each Component Failure Described in this Report

| Cause | System | Component | Manufacturer | Reportable To ICES | Cause | System | Component | Manufacturer | Reportable To ICES |
|-------|--------|-----------|--------------|--------------------|-------|--------|-----------|--------------|--------------------|
| X | SJ | ISV | A391 | N | | | | | |

| | |
|--|---|
| 14. Supplemental Report Expected <input checked="" type="checkbox"/> Yes (If yes, complete 15. Expected Submission Date) <input type="checkbox"/> No | 15. Expected Submission Date Month: 08, Day: 31, Year: 2018 |
|--|---|

Abstract (Limit to 1400 spaces, i.e., approximately 14 single-spaced typewritten lines)

On April 18, 2018, with Hope Creek Generating Station (HCGS) in a planned refueling outage, HCGS performed a required surveillance test of the long term seal of the feedwater lines. The test criteria could not be met due to leakage past feedwater isolation valve H1AE -AE-HVF032B. The valve is sealed with a water seal from the High Pressure Reactor Coolant (HPCI) system, or Reactor Core Isolation Cooling (RCIC) system to form a long-term seal boundary of the feedwater lines. The valve is tested per Technical Specification 4.6.1.2.d to verify a maximum leak rate of 10 gpm at a test pressure of 55.7 psig. During the test, a test pressure of 44 psig was the highest pressure that could be obtained, which does not meet the acceptance criterion.

These conditions are being reported in accordance with 10 CFR 50.73(a)(2)(i)(B) as a condition prohibited by plant Technical Specifications.



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOF-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

| 1. FACILITY NAME | 2. DOCKET NUMBER | 3. LER NUMBER | | |
|-------------------------------|------------------|---------------|-------------------|---------|
| | | YEAR | SEQUENTIAL NUMBER | REV NO. |
| Hope Creek Generating Station | 05000-354 | 2018 | - 003 | - 00 |

NARRATIVE

PLANT AND SYSTEM IDENTIFICATION

General Electric – Boiling Water Reactor (BWR/4)*
 Feedwater System (SJ) – EIS Identifier {SJ/ISV}
 High Pressure Coolant Injection (BJ) – EIS Identifier {BJ}
 Reactor Core Isolation Cooling (BN) – EIS Identifier {BN}
 Secondary Containment (NG) – EIS Identifier {NG}
 *Energy Industry Identification System {EIS} codes and component function identifier codes appear as {SS/CCC}

IDENTIFICATION OF OCCURRENCE

Event Dates: April 18, 2018
 Discovery Dates: April 18, 2018

CONDITIONS PRIOR TO OCCURRENCE

Hope Creek was shut down for Refueling Outage H1R21 in Operational Condition (OPCON) 5 – Refueling Operations.

DESCRIPTION OF OCCURRENCE

On April 18, 2018, with Hope Creek Generating Station (HCGS) in a planned refueling outage, HCGS performed a required surveillance test of the long term seal of the feedwater lines. The test criteria could not be met due to leakage past feedwater system {SJ} isolation valve H1AE -AE-HVF032B. The valve is sealed with a water seal from the High Pressure Coolant Injection (HPCI) {BJ} system, or Reactor Core Isolation Cooling (RCIC) {BN} system, to form a long-term seal boundary of the feedwater lines. The valve is tested with water at a test pressure of 55.7 psig to ensure the seal boundary will prevent bypass leakage. During the test, a test pressure of 44 psig was the highest pressure that could be obtained, which does not meet the acceptance criterion.

The H1AE -AE-HV-F032B is 24 inch anchor darling “Y” type swing check valve with a Limitorque SMB-4 motor operator to assist in maintaining the valve closed.

Technical Specification 4.6.1.2.d limits the total combined leakage rate to 10 gpm, or less, for all the containment isolation valves which form the boundary for the long term seal of the feedwater lines, when tested at 55.7 psig. Based on the cause of the failure, and the maintenance history of the valve, it was concluded that the condition is reportable as a condition prohibited by Technical Specifications under 10 CFR 50.73(a)(2)(i)(B).

CAUSE OF EVENT

An internal inspection was performed on the H1AE -AE-HV-F032B under work order 60138581 in H1R21. The following was identified during this inspection:

- One bore on the hinge arm was larger than the acceptance criteria by an average of 0.004 inches. (2.039 inches vs 2.029 - 2.035 inches)
- The hinge pin was worn and undersized by 0.002 inches. (1.997 inches vs 2.000 +/- 0.001 inches)
- The gap between the hinge arm and disc was smaller by 0.0325 inches (0.030 inches vs 0.0625 inches)

The combination of the wear on the hinge arm bores, the wear on the hinge pin, and the smaller gap between the hinge arm and disc prevented the valve disc from properly seating, which resulted in the high leak rate.



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

| 1. FACILITY NAME | 2. DOCKET NUMBER | 3. LER NUMBER | | |
|-------------------------------|------------------|---------------|-------------------|---------|
| | | YEAR | SEQUENTIAL NUMBER | REV NO. |
| Hope Creek Generating Station | 05000-354 | 2018 | - 003 | - 00 |

SAFETY CONSEQUENCES AND IMPLICATIONS

The long term feedwater seal is established following a Loss of Coolant Accident (LOCA) by manually aligning the RCIC and/or HPCI jockey pumps to the feedwater lines between the inboard and outboard containment isolation valves. H1AE -AE-HV-F032B is the outboard containment isolation valve on one of two feedwater supply lines. The purpose of the feedwater seal, as described in the UFSAR, is to establish a water seal of the feedwater penetrations to eliminate bypass leakage. The seal is established following a LOCA, and is to be maintained for a minimum of 30 days.

The purpose of the leak rate testing is to verify that the leakage is within the capability of the system to maintain the seal for the 30 day minimum.

An evaluation is in progress to determine if the as-found leakage would have affected the ability to maintain the feedwater seal for the 30 day minimum. A supplement to this LER will be submitted when the results of the evaluation are available.

PREVIOUS EVENTS

A review of Licensee Event Reports and the corrective action program for the past three years identified no LERs issued for similar conditions.

CORRECTIVE ACTIONS

The F032B check valve was opened and inspected. Corrective maintenance was performed to address the dimensional clearances and deficiencies identified in the Cause of Event section above. A satisfactory leak rate test was performed following the corrective maintenance.

COMMITMENTS

This LER contains no regulatory commitments.