

Carrie T. Dunton Director, Nuclear Site Support Oconee Nuclear Station

Duke Energy ON01VP | 7800 Rochester Hwy Seneca, SC 29672

o. 864.873.3477 f: 864.873.4208 carrie.dunton@duke-energy.com

RA-18-0076

July 5, 2018

10 CFR 50.73

Attn: Document Control Desk U. S. Nuclear Regulatory Commission 11555 Rockville Pike Rockville, MD 20852-2746

Duke Energy Carolinas, LLC Oconee Nuclear Station Unit 3 Docket Numbers: 50-287 Renewed Operating Licenses: DPR-55

Subject: Licensee Event Report 287/2018-002, Revision 00 – Actuation of the Keowee Hydroelectric Station Due to Loss of AC Power to the Unit 3 Main Feeder Buses

Licensee Event Report 287/2018-002, Revision 00, is being submitted pursuant to the requirements of 10 CFR 50.73 to provide notification of the subject event.

There are no regulatory commitments associated with this LER.

If there are questions, or further information is needed, contact Stephen C. Newman, Lead Nuclear Engineer, Regulatory Affairs, at (864) 873-4388.

Sincerely,

In In Count for

Carrie T. Dunton Director, Nuclear Site Support Oconee Nuclear Station

Enclosure

cc (w/Enclosure):

Ms. Catherine Haney, Administrator, Region II U.S. Nuclear Regulatory Commission Marquis One Tower 245 Peachtree Center Ave., NE, Suite 1200 Atlanta, GA 30303-1257

Ms. Audrey L. Klett, Project Manager (by electronic mail only) U.S. Nuclear Regulatory Commission 11555 Rockville Pike Mail Stop O-08B1A Rockville, MD 20852-2738

Mr. Eddy Crowe NRC Senior Resident Inspector Oconee Nuclear Station

NRC FO	RM 366			U.S. NUCLI	EAR REG	ULATORY	COMM	ISSION	APF	PROVED BY	OMB: N	O. 3150-	0104 E	XPIRE	S: 0	3/31/20	)20
NRC FORM 366 (04-2018) U.S. NUCLEAR REGULATORY COMMISSION (04-2018) LICENSEE EVENT REPORT (LER) (See Page 2 for required number of digits/characters for each block) (See NUREG-1022, R.3 for instruction and guidance for completing this form http://www.nrc.gov/reading-m/doc-collections/nuregs/staff/sr1022/r3/)							, this form	APPROVED BY OMB: NO. 3150-0104 EXPIRES: 03/31/2020 Estimated burden per response to comply with this mandalory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (7-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 2055-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.									
1. Facility Name Oconee Nuclear Station Unit 3								2. Docket Number 3. 05000287				3. Page	3. Page 1 OF 4				
4. Title Actuation of the Keowee Hydroelectric Station Due to Loss of AC Power to the Unit 3 Main Feeder Buses																	
	Event D			LER Numbe			Report D						Facilities Ir				
Month	Day	Sequential Box				Docket Number											
05	10	2018	2018	002	00	07	5	2018		acility Name				Docket 0500	Num	ber	
	Operating I	<u>i</u> odo		·	44 This [	Jonant in Cul			- 44-0	Beguinemonto	of 40 CE	E. Char					
5.0		noue	20.2			20.2203		ursuant to the Requirements of 10 CFR §: (Check all that apply) □ 50.73(a)(2)(ii)(A) □ 50.73(a)(2)(v				viii)(A	/iii)(A)				
	6		·			20.2203(a)(3)(ii)			☐ 50.73(a)(2)(ii)(B)		□ 50.73(a)(2)(viii)(B)						
						20.2203(a)(4)			50.73(a)(2)(iii)		□ 50.73(a)(2)(ix)(A)						
						50.36(c)(1)(i)(A)		_	50.73(a)(2)(iv)(A)		50.73(a)(2)(x)						
10. Power Level						50.36(c)	50.36(c)(1)(ii)(A)				v)(A)		73.71(a)(4)				
			20.2203(a)(2)(iii)			50.36(c)	(2)	<u>_</u>	Ľ	] 50.73(a)(2)(	v)(B)		73.71(a)(5)				
000			20.2203(a)(2)(iv)			50.46(a)(3)(ii)			50.73(a)(2)(v)(C)		☐ 73.77(a)(1)						
			20.2203(a)(2)(v)			🔲 50.73(a)	(2)(i)(A)			50.73(a)(2)	v)(D)		☐ 73.77(a)(2)(ii)				
		20.2203(a)(2)(vi)			🗌 50.73(a)	(2)(i)(B)			50.73(a)(2)(vii)		73.77(a)(2)(iii)						
						🗌 50.73(a)	(2)(i)(C)			Other (Spec	rify in Abs	tract belo	w or in NR	C Form	n 366	A	
						12. Lice	ensee Co	ontact for	r this	LER							
Licensee Co Steph		Newma	<u>n, Lea</u>	d Nuclea								(864)	umber (include 873-438		ie)		ſ
				13. Co	omplete O	ne Line for e	ach Con	ponent Fa	ailure	Described in t	his Repor	: 					
Ca.		System	Compo		nufacturer	Reportable	To ICES	Cause	•	System	Compo	onent	Manufactur	rer R	eporta -	able To I	CES
×		EL	RL	Y 9	S440	Ye	es							_			
14. Supplemental Report Expected											Month	Da	/	Yea	r		
Yes (If yes, complete 15. Expected Submission Date			ate) 🛛 N	No	15. Expected Submission Date												
Abstract (L	Abstract (Limit to 1400 spaces, i.e., approximately 14 single-spaced typewritten lines)																
On May 10, 2018, at 16:03, with Unit 3 in MODE 6 (refueling) with the unit's startup transformer (CT-3)																	
	carrying the unit's power loads, a CT-3 lockout occurred. With the transformer locked out, Unit 3 experienced a																
loss c	loss of all alternating current (AC) power to the unit's main feeder buses (MFBs) which subsequently resulted in an																

autostart of both Keowee Hydroelectric Station (KHS) Units. Approximately 18 seconds later, emergency AC power was restored to the MFBs via the KHS Unit 2 underground powerpath and CT-4 transformer. During the 38-second power outage, the Unit 3 decay heat removal and spent fuel cooling systems were unavailable; however, the MFB Monitoring Panel responded as designed to restore AC power.

This event was reportable pursuant to 10 CFR 50.73(a)(2)(iv)(A) as a valid actuation of one of the systems listed in 10 CFR 50.73(a)(2)(iv)(B)(8), i.e., the Keowee Hydroelectric Station.

The cause of the CT-3 lockout was due to transient disturbances from external voltages/currents being impressed upon the direct current (DC) system due to an internal failure of the 62GZ relay concurrent with multiple DC grounds. A Cause Evaluation is ongoing to determine if planned corrective actions are warranted. The overall plant risk due to the event was insignificant and there was no impact on public health and safety.

NRC FORM 366 (02-2018)

NRC FORM 366A U.S. NUCLEAR REGUL	ATORY COMMISSION	APPROVED BY OMB: NO. 3150-010 Estimated burden per response to comply wi		EXPIRES: 3	
	SEE EVENT REPORT (LER) CONTINUATION SHEET Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects. Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office				
(See NUREG-1022, R.3 for instruction and guidance f http://www.nrc.gov/reading-rm/doc-collections/nuregs/		of Management and Budget, Washington, DC a does not display a currently valid OMB contra person is not required to respond to, the inform	ol number, the Ni		
1. FACILITY NAME	2. DOCKET N	UMBER		3. LER NUMBER	
Oconee Nuclear Station Unit 3	05000-287		YEAR	SEQUENTIAL NUMBER	REV NO.
			2018	002	00
EVALUATION:	NARF	RATIVE			
Background					
Dackground		· .			
During start-ups, shutdowns, and outag not available, power is supplied from th Emergency power can be provided to a Hydroelectric Station (KHS)KHS [EIIS:	e Switchyard throu any or all three Oc	ugh the Start-up Transform onee Nuclear Station (ONS	er (CT-3 o ) Units fro	n Ūnit 3).	-
<ol> <li>the overhead path, that includes</li> <li>the underground path, through C</li> </ol>	•	former (CT-1, CT-2, or CT-	3) on eacł	n ONS unit; and	d
In addition, there is an offsite powerpat CT-5. Transformers 3T or CT-3 supply			team Stati	ion via transfor	mer
DESCRIPTION OF EVENT					
On May 10, 2018, at 16:03, with Unit 3 unit's power loads, a CT-3 lockout occu alternating current (AC) power to the un Safeguards (ES) [EIIS: JE] generated s loss of power, it sent a signal to start th was restored to the MFBs via the KHS 38-second power outage, the Unit 3 de unavailable.	urred. With the tra nit's main feeder b signal, approximat le Keowee Units. [EIIS: EK] Unit 2 u	nsformer locked out, Unit 3 uses (MFBs) [EIIS: BU]. Al ely 20 seconds after the MF Approximately 18 seconds underground powerpath and	experience though nc B Moniton later, eme I CT-4 trai	ced a loss of all ot an Engineere ring Panel sens rgency AC pov nsformer. Duri	ed sed a ver ng the
Prior to and at the time of the lockout, of implementation of a protective relaying the lockout; however, the testing did en had existing internal degradation that of degradation is unknown.	upgrade project. nergize the 62GZ r	This testing was determine elay [EIIS: RLY]. Evidence	d not to be indicates	e the direct cau that the 62GZ	
<u>Reportability</u>					
This event was reportable pursuant to 10 CFR 50.73(a)(2)(iv)(B)(8), i.e., the k			of one of	the systems lis	sted in
Pursuant to 10 CFR 50.72 requirement was a valid actuation.	ts and the guidanc	e provided in NUREG-102	2 (R3), the	e KHS start sigi	nal
Additionally, the loss of power to the M 16:25 per Emergency Action Limit CU2 MEB-2 reduced to a single power sour	2.1, "AC power cap	pability, Table C-3, to essen	tial 4160 \	V buses MFB-′	1 and

NRC FORM 366A (04-2017)

3

5

NRC FORM 366A U.S. NUCLEAR REGULA	TORY COMMISSION	APPROVED BY OMB: NO. 3150-010		EXPIRES: 3					
	Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection								
(See NUREG-1022, R.3 for instruction and guidance for http://www.nrc.gov/reading-rm/doc-collections/nuregs/s		does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.							
1. FACILITY NAME	2. DOCKET N	UMBER		3. LER NUMBER					
Oconee Nuclear Station Unit 3	05000-287	X	YEAR	SEQUENTIAL NUMBER	REV NO.				
			2018	002	00				
source failure will result in loss of all AC power to SAFETY SYSTEMS." Oconee Units 1 and 2 were unaffected by this event.									
CAUSAL FACTORS			•						
The cause of the CT-3 lockout was due to transient disturbances from external voltages/currents being impressed upon the DC system due to an internal failure of the 62GZ relay concurrent with multiple DC grounds.									
CORRECTIVE ACTIONS									
Immediate:				t					
<ol> <li>Stopped the relay functional testing and entered the appropriate abnormal operating procedures.</li> <li>Restored decay heat removal and spent fuel cooling capability.</li> <li>Closed the unit 3 equipment hatch.</li> </ol>									
Subsequent:									
<ol> <li>The damaged 62GZ control relay was replaced.</li> <li>DC grounds were isolated and repaired.</li> </ol>									
<u>Planned</u> :									
 1. A Cause Evaluation is ongoing to determine if planned corrective actions are warranted.									
SAFETY ANALYSIS									
A qualitative risk evaluation was perfo	ormed to conside	er the potential impacts of	this even	t on plant safe	ety.				
ONS-3 was in Mode 6 when a CT3 lockout actuation occurred on May 10, 2018, resulting in a loss of AC power to the Unit 3 Main Feeder Busses (MFBs). The MFB Monitor Panel initiated a Keowee start signal. All required KHS equipment responded as designed and power was restored in approximately 38 seconds. The temporary loss of AC power resulted in a loss of decay heat removal that was automatically restored from KHS Unit 2. The Oconee Unit 3 Spent Fuel Pool (SFP) cooling flow was also lost but was manually restored by procedure in approximately 6 minutes.									
As documented on the May 10, 2018 approximately 66 minutes based on t					nis				

approximately 66 minutes based on the expected heat load for the number of days after shutdown. T time available supports that operators could have reliably performed necessary recovery actions if automatic restoration of power or LPI flow had failed. Similarly, the "time to boil" for the SFP was approximately 28 hours.

	P							
NRC FORM 366A	U.S. NUCLEAR REGULA	TORY COMMISSION	APPROVED BY OMB: NO. 3150-0104 EXPIRES: 3/31/2020					
	LICENSEE EVENT R CONTINUATION	SHEET	Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.					
1. FACILITY NAME		2. DOCKET N	OCKETNUMBER		3. LER NUMBER			
Oconee Nuc	ear Station Unit 3	05000-287	,	YEAR	SEQUENTIAL NUMBER	REV NO.		
				2018	002	00		

Procedural actions available to recover from a potential failure of KHS Unit 2 include alignment of backup power from Transformer CT-5, swapping the KHS Unit 1 alignment from overhead path to underground path, alignment of 4160V cross-tie from Unit 2 Startup Transformer CT-2, and alignment of gravity flow from the Borated Water Storage Tank to the core. Although the containment equipment hatch was open at the time of the lockout, containment closure was reestablished in approximately 22 minutes providing significant margin prior to core boiling.

Based the reliability of the Keowee power system, diverse power sources, and redundancy of cooling systems, the impact of this event on plant risk was very low when available recovery actions are considered. Thus, it is concluded that the impact of this event on overall plant risk is insignificant and had no impact on public health and safety.

## ADDITIONAL INFORMATION

A review of Duke Energy's Corrective Action Program and industry Operating Experience (OE) databases was conducted using applicable keyword searches, i.e., "CT-3, KHS, KHU, lockout, actuation," identified one (1) similar Oconee LER that occurred in 2006. LER 287/2006-01, Rev. 0, reported an event involving a KHS actuation because of a CT-3 lockout on Unit 3. In that instance, it was concluded that the differential relays which precipitated the lockout were very sensitive to mechanical impact/jarring. The corrective actions associated with that LER would not have prevented the current lockout event.

Energy Industry Identification System (EIIS) codes are identified in the text as [XX]. This event is considered INPO Consolidated Events System (ICES) Reportable. There were no releases of radioactive materials, radiation exposures or personnel injuries associated with this event.