

Exelon Generation Company, LLC Braidwood Station 35100 South Route 53, Suite 84 Braceville, IL 60407-9619

www.exeloncorp.com

10 CFR 50.73

August 2, 2018 BW180082

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001

> Braidwood Station, Unit 1 Renewed Facility Operating License No. NPF-72 NRC Docket No. STN 50-456

Subject: Licensee Event Report 2018-006-00 – Manual Unit Trip on Low Steam Generator Level Following Trip of a Turbine Feedwater Pump Due to a Design Issue

The enclosed Licensee Event Report (LER) is being submitted in accordance with 10 CFR 50.73, "Licensee Event Report System."

There are no regulatory commitments contained in this letter. Should you have any questions concerning this submittal, please contact Mr. Francis Jordan, Regulatory Assurance Manager, at (815) 417-2800.

Respectfully,

Marri Marchionda Palmer Site Vice President Braidwood Station

Enclosure: LER 2018-006-00

cc: NRR Project Manager – Braidwood Station Illinois Emergency Management Agency – Division of Nuclear Safety US NRC Regional Administrator, Region III US NRC Senior Resident Inspector (Braidwood Station) Illinois Emergency Management Agency – Braidwood Representative

NRC FORM 366 U.S. NUCLEAR REGULATO						JLATORY	Y COMMISSION APPROVED BY OMB: NO. 3150-0104 EXPIRES					RES: 0	3/31/2020				
	Sta Reco.		LICENSEE EVENT REPORT (LER									ated burden per response to comply with this mandatory collection request: 80 hours. ted lessons learned are incorporated into the licensing process and fed back to					
and a second		10 ⁴ 1 (ters for eac	-		industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to						
a star	¥2,		_			-				orm	Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503.						
13 Links	~ & /		NUREG-1022, R.3 for instruction and guidance for completing the state of the state								If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.						
1. Facility Name								2. Docket Number				3. Page					
Braidwood Station, Unit 1					05000456			;	1 OF 3								
4. Title Manual Unit Trip on Low Steam Generator Level Following Trip of a Turbine Feedwater Pump Due to a Design Issue																	
5	Event [Date	6. LER Number 7. Report					Report [Date 8. Other Facilities Involved								
Month	Day	Year	Year	Seque	ential	Rev	Month	Day	Year		acility Name 'A		Docket Num			t Number	
06	04	2018	2018	- 006	-	• No. 00	08	02	201	Fi	N/A N/A Facility Name Docket Numb N/A N/A				t Number		
9. 0	l perating	Mode		11. Tł	is Repo	ort is S	ubmitted	l Pursuai	nt to th	e Req	uirements o	f 10 CFR §:	(Check all	that a	pply)		
			20.2201(b)				20.2203(a)		5	0.73(a)(2)(ii)(A)		50.73(a)(2)(viii)(A)					
			20.2201(d)				20.2203(a)(3)(ii) ·			50.73(a)(2)(ii)()	50.73(a)(2)(viii)(B)				
	1			20.2203(a)(1)			20.2203(a)(4)			5	0.73(a)(2)(iii)	50.73(a)(2)(ix)(A)					
				20.2203(a)(2)(i)			50.36(c)(1)(i)(A)			5	0.73(a)(2)(iv)(A	50.73(a)(2)(x)					
10.	10. Power Level			20.2203(a)(2)(ii)			50.36(c)(1)(ii)(A)			5	50.73(a)(2)(v)(A)		73.71(a)(4)				
			20.2203(a)(2)(iii)				50.36(c)(2)			5	0.73(a)(2)(v)(B)	73.71(a)(5)					
100			20.2203(a)(2)(iv)				50.46(a)(3)(ii)			5	0.73(a)(2)(v)(C	73.77(a)(1)					
			20.2203(a)(2)(v)				50.73(a)(2)(i)(A)			50.73(a)(2)(v)(D))	73.77(a)(2)(i)				
			20.2203(a)(2)(vi)				50.73(a)(2)(i)(B)			50.73(a)(2)(vii)			73.77(a)(2)(ii)				
							50.73(a)(2)(i)(C)						ct below or in NRC Form 366A)				
1 1						1	2. Licens	see Conta	act for	this L	ER	T-1	one Numb	¥ (1	Ide Ar	on Code)	
	Licensee Contact Telephone Number (Include Area Code) Francis Jordan 815-417-2800																
				13. Com	olete On	e Line	for each	n Compoi	nent Fa	ilure	Described in	this Repo	t				
Cause System		Component Manufact		cturer	urer Reportable to I		Саι	ise	System	Component	Manufact	urer	Report	table to ICES			
N//	N/A N/A			N/A N/A			N/A		N	Ά	N/A	N/A	N/A		L,	N/A	
		14. Su	pplemental Report Expected						15. Expected S		ted Submiss	d Submission Date		D	ay	Year	
	Yes (If yes, complete 15. Expected Submission Date) Xo											N/A	N	/A	N/A		
Abstra	ct (Limit	to 1400 sp 2018 at	Daces, i.e.	., approxi	mately 1	4 singl	e-spaced	l typewritt	en lines Ilv trir	s) ned	due to low	erina etee	m denera	tor w	ater la	avels	
follow	ing a ti	rip of the	1C turk	bine driv	en fee	dwat	er pump	o. The	1A an	d 1B	auxiliary fe	edwater	(AF) pump	os au	to sta	rted as	
following a trip of the 1C turbine driven feedwater pump. The 1A and 1B auxiliary feedwater (AF) pumps auto started as expected due to low steam generator levels.																	
The c	ause o	f the eve	ent was	due to	he inc	lusior	n of a di	gital inp	ut mo	dule	in the turbi	ine driven	feedwate	r pun	np coi	ntrol	
The cause of the event was due to the inclusion of a digital input module in the turbine driven feedwater pump control circuitry, which affected only the safeguards testing function of the circuit, and which was not identified as a design input																	
per the design input and configuration change impact screening procedure. Corrective actions planned include implementing the changes to eliminate the design deficiency, and revising the design input and configuration change																	
implementing the changes to eliminate the design deticlency, and revising the design input and configuration change impact screening procedure.																	
This event is reportable in accordance with 10 CFR 50.73(a)(2)(iv)(A) for "Any event or condition that resulted in manual																	
or automatic actuation of any of the systems listed in paragraph (a)(2)(iv)(B) of this section, " Specifically, for																	
1) 10 CFR 50.73(a)(2)(iv)(B)(1) for the "Reactor protection system (RPS) including: reactor scram or reactor trip," and 2) 10 CFR 50.73(a)(2)(iv)(B)(6) for the "PWR auxiliary or emergency feedwater system."																	
2) 10		iu./3(a)(∠/(IV)(B	lo) lot.	ule PV	wh a	ихшагу	or emer	genc)	/ 1660	uwaler sys	lem.					

NRC FORM 366A U.S. NUCLEAR REGULAT	ORY COMMISSION								
(See NUREG-1022, R.3 for instruction and guidance for c http://www.nrc.gov/reading-rm/doc-collections/nuregs/	HEET	Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.							
1. FACILITY NAME	2. DOC	CKET NUMBER 3. LER NUMBER							
			YEAR	SEQUENTIAL NUMBER	REV NO.				
Braidwood	05000456		2018	- 006	- 00				
NARRATIVE									
A. Plant Operating Conditions Before the Event:									
Event Date: June 4, 2018									
Unit: 1 Mode: 1 Reactor Power: 100 percent									
Unit 1 Reactor Coolant System [AB]: Normal operating temperature and pressure									
No structures, systems or components were inoperable at the start of this event that contributed to the event.									
B. Description of Event:									
On June 4, 2018 at 0917 hours, while performing an Engineered Safety Feature actuation relay surveillance test associated with the main feedwater (FW) [SJ] pumps, the 1C main turbine driven FW pump tripped. Operations initiated a main turbine runback. At 0920 hours, Braidwood Unit 1 was manually tripped before reaching the steam generator low water level trip setpoint. The 1A and 1B auxiliary feedwater (AF) [BA] pumps auto started as expected due to low steam generator levels. At 1044 hours, after the startup feedwater pump was placed in service, the 1A and 1B AF pumps were secured.									
Operator response to the trip was proper and all systems and controls performed as expected.									
This event is reportable in accordance with 10 CFR 50.73(a)(2)(iv)(A) for "Any event or condition that resulted in manual or automatic actuation of any of the systems listed in paragraph (a)(2)(iv)(B) of this section," Specifically, for 1) 10 CFR 50.73(a)(2)(iv)(B)(1) for the "Reactor protection system (RPS) including: reactor scram or reactor trip," and 2) 10 CFR 50.73(a)(2)(iv)(B)(6) for the "PWR auxiliary or emergency feedwater system." This LER is being submitted in follow-up to ENS 53443 made on June 4, 2018.									
C. Cause of Event									
The cause of the event was, during a modification of the turbine driven FW pump control circuitry, the inclusion of a digital input module affected only the safeguards testing function of the circuit, and this impact was not identified as a design input per the design input and configuration change impact screening procedure. As a result, the impact of the module on the circuit's electrical impedance was not evaluated and the design error was not discovered during the subsequent evaluation and design change testing. The change to the circuit caused an unexpected loss of a turbine driven feedwater pump during surveillance testing that was performed consistent with past performances.									
D. Safety Consequences:									
There were no safety consequences impacting plant or public safety as a result of this event.									
The operating crew responded appropriately to lowering steam generator levels and manually tripped the reactor prior to automatic actuation. All equipment operated appropriately as designed. There was no loss of any function that would have prevented fulfillment of actions necessary to 1) Shutdown the reactor and maintain it in a safe shutdown condition, 2) Remove residual heat, 3) Control the release of radioactive material, or 4) Mitigate the consequences of an									

accident.

NRC FORM 366A (04-2018)	U.S. NUCLEAR REGULAT	ORY COMMISSION	APPROVED BY OMB: NO. 31	50-0104	EXPIRES	: 03/31/2020					
	LICENSEE EVENT REPO CONTINUATION SP	IEET	Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information and the second sec								
	2, R.3 for instruction and guidance for c gov/reading-rm/doc-collections/nuregs/		sponsor, and a person is not required to	valid OMB control number, the NRC may not conduct or respond to, the information collection.							
1. FACILITY NAME		2. DOC	CKET NUMBER	3. LER NUMBER							
Braidwood		05000456		YEAR	SEQUENTIAL NUMBER	REV NO.					
NARRATIVE				2018	- 006	- 00					
NARRATIVE There was no loss of safety function for this event.											
E. Corrective Actions:											
 Planned Corrective Actions: Implement the changes to eliminate the design deficiency associated with the testing of the FW pump control circuitry. Revise the design input and configuration change impact screening procedure to include consideration of changes to circuits for electrical impacts to the circuit such as impedance. 											
F. Previous Occurrences:											
None											
G. Component Failure Data:											
Mar	nufacturer	Nomenclature	Mode	<u>el</u>	<u>Mfg. Part Number</u>						
	N/A	N/A	N/A		N/A						
	P \										
1											