George A. Lippard Vice President, Nuclear Operations 803.345.4810



August 3, 2018

**Document Control Desk** U.S. Nuclear Regulatory Commission Washington, DC 20555

Dear Sir / Madam:

Subject: VIRGIL C. SUMMER NUCLEAR STATION (VCSNS), UNIT 1 **DOCKET NO. 50-395 OPERATING LICENSE NO. NPF-12** LICENSEE EVENT REPORT (LER) 2017-001-01 C Main Feedwater Failure to Trip Results in Loss of Emergency Feedwater Auto Start Actuation Signal

Attached is revised Licensee Event Report (LER) 2017-001-01, for VCSNS, Unit 1. This revised report provides updated and corrected details regarding the 'C' Main Feedwater Pump's (MFP) failure to trip.

This revision was driven by a review of LER 2017-001-00 that determined that clarification was required regarding MFP oil sampling. This review was captured in CR-18-00485.

Should you have any questions, please call Mr. Michael S. Moore at (803) 345-4752.

Very truly yours,

George A. Lippard

WHK/GAL/bb

Attachment

C: J. E. Addison W. K. Kissam J. B. Archie J. H. Hamilton W. M. Cherry

C. Haney S. A. Williams NRC Resident Inspector L. W. Harris G. J. Lindamood Paulette Ledbetter J. C. Mellette

**ICES** Coordinator K. M. Sutton **INPO Records Center** Marsh USA, Inc. Maintenance Rule Engineer NSRC

RTS (CR-18-00485, CR-17-01611) File (818.07) PRSF (RC-18-0088)

NRC FORM 366			U.S. NUCLEAR REGULATORY COMMI								OMMISSIO	N	N APPROVED BY OMB: NO. 3150-0104 EXPIRES: 03/31/2020 Estimated burden per response to comply with this mandatory collection request: 90 hours								
(U4-2U18)			LICENSEE EVENT REPORT (L (See Page 2 for required number of digits/characters for e (See NUREG-1022, R.3 for instruction and guidance for co http://www.nrc.gov/reading-rm/doc-collections/nuregs/st							for each for com s/stat	LER) each block) ompleting this form staff/sr1022/r3/)			Estimated burgen per response to comply with this mandatory collection request: du hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@mrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.							
1. Faci	lity Nar	ne									2.	Docket Nu	umb	er		3. Page					
VC SUMMER - UNIT 1									<b>05000</b> 395			1	OF 4								
4. Title C MA ACTL	IN FE JATIO	EDWAT N SIGN/	'ER P Al	UMP	FAILU	IRE T	O TRIP	RESU	ILTS II	N LO	SS	OF EME	RG	ENCY F	EE	OWATE	R AUTC	STA	RT		
5. Event Date			6. LER Number					7. Report Date				8. Other Facil			r Facilitie	ties Involved					
Month	Month Day Year Year Sequential Number			Rev No.	Rev No. Month Day		Yea	ar	Facility Name				Docket Number 05000								
04	07	2017	2017 - 001 -			01	01 08 03 2			18	Facility Name Docke 050					Docket Nur 05000	et Number 000				
9. Operating Mode 11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)																					
			20.2201(b)			20	20.2203(a)(3)(i)				50.73(a)(2)(ii)(A)				50.73(a)(2)(viii)(A)						
			20.2201(d)			20	20.2203(a)(3)(ii)				50.73(a)(2)(ii)(B)				50.73(a)(2)(viii)(B)						
	1		20.2203(a)(1)				20	20.2203(a)(4)				50.73(a)(2)(iii)				50.73(a)(2)(ix)(A)					
			20.2203(a)(2)(i) 5				50	50.36(c)(1)(i)(A)				50.73(a)(2)(iv)(A)			[	50.73(a)(2)(x)					
10. Power Level			20.2203(a)(2)(ii) 50.36(c)(1				0.36(c)(1)	36(c)(1)(ii)(A) 50.73(a			a)(2)(v)(A)			73.71(a)(4)							
			20.2203(a)(2)(iii) 50.36(c)(2)					50.73(a)(2)(v)(B)					73.71(a)(5)								
			20.2203(a)(2)(iv) 50.46(a)(3)(				)(ii)	50.73(a)(2)(v)(C)				73.77(a)(1)									
	100		20.2203(a)(2)(v)				50	50.73(a)(2)(i)(A)				50.73(a)(2)(v)(D)					73.77(a)(2)(i)				
			20.2203(a)(2)(vi)				50	50.73(a)(2)(i)(B)			50.73(a)(2)(vii)				73.77(a)(2)(ii)						
							50	50.73(a)(2)(i)(C)				Other (Specify in Abstract belo				ract belov	w or in NRC Form 366A)				
								12. Lice	ensee C	ontac	ct for	this LER									
Licensee Contact Michael S. Moore, Manager Nuclear Licensing							Telephone Number (Include Area (803) 345-4752						ea Code)								
					13. Co	omplet	e One Lir	ne for ea	ach Con	npone	ent Fa	ailure Des	scrib	oed in this	Rep	ort					
Cau B	ise	Systen JK	n F	Compo D	onent	Manu G080	lfacturer	Reporta NO	ble to ICE	S	C	Cause System		Co	mponent	Manufacturer		Reportable to ICES			
		14.	Suppl	ement	al Repo	ort Exp	ected			T							Month		Day	Year	
Yes (If yes, complete 15. Expected Submission Date)				√ N	✓ No			1	15. Expected Submission Date			ite									
Abstra On Ju Actua Condi Emerg This e design steam This c Techr	et (Limi ine 16 tion S itions f gency event v ned. <sup></sup> n leak conditi nical S	t to 1400 s , 2017, f ignal wa for Oper Feedwa was a re Che rem near the near the on is rep pecifica	spaces the sta as inop ation ater P sult o ote tri boote tri bootab tions.	, i.e., a ation perab (LCO ump ( f TPP ip actu Press	pproxim comple le from ) was (MDEF 00022C uating sure (L der 10	nately 1 eted a n Nov enter FWP) C, MA devic .P) be	4 single-s a past op ember 1 ed due t actuatio IN FEEI e not op earing. 50.73(a)	paced ty perabil 2, 201 o havin n per <sup>-</sup> DWATI perating (2)(i)(E	ypewritte ity revi l6 until ng less TS Tak ER PU g as de 3), an c	en line ew a Apri tha ole 3 MP esigr	es) and o il 7, 2 n the .3-3 TUR ned v	determin 2017. To e minimu Functior BINE C, vas a res or cond	ned ech um nal , re sult	that an E nnical Sp number Unit 6.g. mote trip t of oil co n which y	Eme ecifi of ch o act ontar	rgency cation ( nannels uating c ninatior prohibit	Feedwat TS) 3.3.2 operable levice no due to a ted by th	er A 2 Lin e for ot op a gla e pla	uto Sta hiting Motor erating nd sea ant's	art Driven g as al	

U.S. NUCLEAR REGULATORY COMMISSION APPROVED BY OMB: NO. 3150-0104 EXPIRES: 03/31/2020

					_					
NRC FORM 366A U.S. NUCLEAR REGULA	APPROVED BY OMB: NO. 3150-0104 EXPIRES: 03/31/2020									
(See NUREG-1022, R.3 for instruction and guidance for http://www.nrc.gov/reading-rm/doc-collections/nurego	Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.									
1. FACILITY NAME					3. LER NUMBER	2				
		YEAR		SEQUENTIAL NUMBER		REV NO.				
VC SUMMER - UNIT 1	05000-		395	2017	-[	001	-	01 ·		
NARRATIVE										
<ul> <li>1.0 EVENT DESCRIPTION</li> <li>On June 16, 2017, the station completed a past operability review and determined that an Emergency Feedwater Auto Start Actuation Signal was inoperable from November 12, 2016 until April 7, 2017. Technical Specification (TS) 3.3.2 Limiting Conditions for Operation (LCO) was entered due to there being less than the minimum number of channels operable for Motor Driven Emergency Feedwater Pump (MDEFWP) actuation per TS Table 3.3-3 Functional Unit 6.g.</li> <li>MAIN FEEDWATER PUMP TURBINE C (TPP0022C) failed to trip when given a trip signal from the Main Control Board (MCB), Digital Control System (DCS), and the local trip pull handle. Indications did not change when an attempt to trip was made from the MCB. The attempt to trip from DCS resulted in the DCS indicating "tripped" with no change in the 'C' MFP. Indications did not change when attempting to trip 'C' MFP locally. 'C' MFP was tripped by using an alternative method of starting the Emergency Lube Oil Pump and removing power from the Main and Auxiliary Lube Oil Pumps. There was no impact to the station as a result of this condition.</li> <li>There were no issues with the feedwater isolation signal nor were there any issues with securing 'A' and 'B' MFPs during the term of the station as a result of this condition.</li> </ul>										
<ul> <li>There were no issues with the feedwater isolation signal nor were there any issues with securing 'A' and 'B' MFPs during the RF23 downpower.</li> <li>2.0 EVENT ANALYSIS</li> <li>As described in Virgil C. Summer Nuclear Station's Final Safety Analysis Report (FSAR) Section 10.4.7.2, the Feedwater System is designed to pump feedwater from the deaerator storage tank through 2 stages of high pressure heaters to the steam generators during normal operation, startup, and before shutdown. To perform this function, three 50% capacity, non-safety, variable speed, turbine driven feedwater pumps are included in the system. In the event of a loss of one feedwater pump, a power reduction may be necessary to prevent reactor trip, but the MFP turbines can be operated at runout capacity temporarily. There are no further specific criteria described for the MFP turbines in Section 10.4.7.2 of the FSAR.</li> <li>FSAR Section 7.3.2.3 lists the automatic initiations of a MDEFWP. One of the five methods that provides an automatic MDEFWP initiation is a trip of all three MFPs.</li> <li>TS 3/4.3.2 states that the Engineered Safety Feature Actuation System (ESFAS) instrumentation channels and interlocks shown in Table 3.3-3 shall be OPERABLE with their trip setpoints set consistent with the values shown in the Trip Setpoint column of Table 3.3-4 and with RESPONSE TIMES as shown in Table 3.3-5.</li> <li>Action Statement 3.3.2.c states that with an ESFAS instrument channel or interlock inoperable take the ACTION shown in Table 3.3-3.</li> <li>Table 3.3-3 Functional Unit 6.g states that Emergency Feedwater ESFAS instrumentation requires the Trip of MFPs to start Motor-Driven Pumps. In Modes 1 and 2 there must be three total channels (one per pump) of this trip present or Action 19 must be taken.</li> </ul>										
NRC FORM 366A (04-2018)					Pad	ne 2	of	4		

NRC FORM 366A U.S. NUCLEAR REGUL	ATORY COMM	ISSION	APPROVED BY OMB: NO	. 3150-0104	EXPIRES	: 03/31/2020						
(See NUREG-1022, R.3 for instruction and guidance for http://www.nrc.gov/reading-rm/doc-collections/nuregov/reading-rm/do	PORT (LEI SHEET or completing things/staff/sr1022/	Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.										
1. FACILITY NAME 2. DOCKET NUMBER 3. LER NUMBER												
VC SUMMER - UNIT 1	05000-		395	YEAR         3           2017         _	SEQUENTIAL NUMBER 001	REV NO. - 01						
NARRATIVE												
Action 19 states that with the number of OPERABLE channels one less than the Total Number of Channels, STARTUP and/or POWER OPERATION may proceed provided the following conditions are satisfied:												
a. The inoperable channel is placed in the tri	pped conditi	on with	in one hour.									
b. The Minimum Channels OPERABLE requ two hours for surveillance testing of other ch	b. The Minimum Channels OPERABLE requirement is met; however, the inoperable channel may be bypassed for up to two hours for surveillance testing of other channels per Specification 4.3.2.1.											
When the electronic and manual trips were attempted on April 7, 2017, no indication was received that the MFP turbine had tripped (i.e. stop valve closure, speed reduction, local indicator lights). Because the trip system would not actuate, one of three channels for MFP trip under TS 3/4.3.2 was inoperable.												
LCO for TS 3.3.2 was entered at 21:15 on April 7, 2017, requiring the operable channel be placed in the trip condition within an hour. At 22:09, 'C' MFP was secured and LCO for TS 3.3.2 was exited. Therefore, Action 19 under TS 3.3.2 was satisfied as 'C' MFP was able to be placed in the tripped condition by securing the Lube Oil Pumps that supplied high pressure oil to the stop valves ultimately satisfying Emergency Feedwater ESFAS instrumentation requirements.												
An evaluation found that contaminants in the 'C' MFP oil system accumulated in the low flow sections of the oil system such as in the Secondary Operating Cylinder (SOC) and the SV-12 solenoid valve. These contaminants impeded actuation of the SV-12 solenoid valve. The bound condition would not allow the steam inlet valves to close resulting in the inoperable ESFAS.												
The past adverse condition leading to the Emergency Feedwater ESFAS instrumentation channel being inoperable was the inability of the 'C' MFP to trip as a result of the remote trip actuating device, SV-12 solenoid valve, being bound by contaminants in the oil system.												
The first indication that there were contaminants in the oil system of the 'C' MFP was manifested by speed control issues, as documented in CR-16-05720 and CR-17-01268. The SOC actuation, which controls the speed of TPP0022C, was impeded by the contaminants in the oil system.												
Since the SOC was not functioning properly due to the oil contaminants, it is likely that the SV-12 solenoid valve was also adversely affected as they share the same oil system. Additionally, since the SV-12 solenoid valve was not called into service from November 12, 2016 to April 7, 2017, it is conservatively assumed that the TPP0022C trip system was inoperable for that period of time.												
3.0 SAFETY SIGNIFICANCE												
This event has no impact on the Probabilistic Risk Analysis (PRA) model. The PRA model includes start signals for Emergency Feedwater from: Low Steam Generator Level, Manual, Load Sequencer, and Anticipated Transient Without SCRAM Mitigation System Actuation Circuitry (AMSAC). Loss of Feedwater is not modeled as a separate actuation.												

NRC FORM 366A U.S. NUCLEAR REGULA	APPROVED BY OMB: NO. 3150-0104 EXPIRES: 03/31/2020										
(See NUREG-1022, R.3 for instruction and guidance fo http://www.nrc.gov/reading-rm/doc-collections/nuregov/reading-rm/doc	Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, 150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.										
1. FACILITY NAME		2. DOCK	KET NUMBER 3. LER NUMBER								
VC SUMMER - UNIT 1	05000-	<b>05000-</b> 395			- [	NUMBER 001	- [	NO.			
NARRATIVE											
4.0 PREVIOUS OCCURRENCE											
No previous occurrence within the last three years.											
5.0 CORRECTIVE ACTIONS											
MAIN FEEDWATER PUMP TURBINE C was the Main and Auxiliary Lube Oil Pumps.	s tripped by	starting	the Emergency Lube C	il Pump	and	l removing po	we	r from			
MAIN FEEDWATER PUMP TURBINE C was 1603349.	MAIN FEEDWATER PUMP TURBINE C was repaired under Work Orders (WOs) 1704018, 1616104, 1514836, and 1603349.										
The WOs inspected the SV-12 Stem and Cylinder for damage, and replaced parts as appropriate. The front standard trip assembly and other components were also inspected and cleaned as required.											
L											

1