

A 04/17/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)  
DISTRIBUTION FOR INCOMING MATERIAL 50-315

REC: KEPPLER J G  
NRC

ORG: SHALLER D V  
IN & MI PWR

DOC DATE: 04/07/78  
DATE RCVD: 04/14/78

DOCTYPE: LETTER NOTARIZED: NO

COPIES RECEIVED  
LTR 1 ENCL 1

SUBJECT: FORWARDING LICENSEE EVENT REPT (RO 50-315/78-001/031-1) ON 12/17/77  
CONCERNING UNIT 2 C-D EMERGENCY DIESEL GENERATOR TRIPPED ON OVERSPEED DURING  
DIESEL STARTS... W/ATT LER 78-009/03L-1 AND 78-023/03L-0.

PLANT NAME: COOK - UNIT 1

REVIEWER INITIAL: XJM  
DISTRIBUTOR INITIAL: *u*

\*\*\*\*\* DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS \*\*\*\*\*

INCIDENT REPORTS  
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF SCHWENCER\*\*W/4 ENCL

INTERNAL:

- REG FILE\*\*W/ENCL
- I & E\*\*W/2 ENCL
- SCHROEDER/IPPOLITO\*\*W/ENCL
- NOVAK/CHECK\*\*W/ENCL
- KNIGHT\*\*W/ENCL
- HANAUER\*\*W/ENCL
- EISENHUT\*\*W/ENCL
- SHAO\*\*W/ENCL
- KREGER/J. COLLINS\*\*W/ENCL
- K SEYFRIT/IE\*\*W/ENCL

- NRC PDR\*\*W/ENCL
- MIPC\*\*W/3 ENCL
- HOUSTON\*\*W/ENCL
- EEB\*\*W/ENCL
- BUTLER\*\*W/ENCL
- TEDESCO\*\*W/ENCL
- BAER\*\*W/ENCL
- VOLLMER/BUNCH\*\*W/ENCL
- ROSA\*\*W/ENCL

EXTERNAL:

- LPDR'S
- ST. JOSEPH, MI\*\*W/ENCL
- TIC\*\*W/ENCL
- NSIC\*\*W/ENCL
- ACRS CAT B\*\*W/16 ENCL


COPIES NOT SUBMITTED PER  
REGULATORY GUIDE 10.1

DISTRIBUTION: LTR 45 ENCL 45  
SIZE: 1P+1P+4P

CONTROL NBR: 781030109

\*\*\*\*\* THE END \*\*\*\*\*

*51*



*D. Lanham*

FILE COPY



April 7, 1978

Mr. J.G. Keppler, Regional Director  
Office of Inspection and Enforcement  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Operating License DPR-58  
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications the following reports are submitted:

- RO 78-001/03L-1
- RO 78-009/03L-1
- RO 78-023/03L-0.


Sincerely,

D.V. Shaller  
Plant Manager


/bab

- cc: J.E. Dolan  
R.W. Jurgensen  
R.F. Kroeger  
R. Kilburn  
R.J. Vollen BPI  
K.R. Baker RO:III  
R.C. Callen MPSC  
P.W. Steketee, Esq.  
R. Walsh, Esq.  
G. Charnoff, Esq.  
G. Olson  
J.M. Hennigan  
PNSRC  
J.F. Stietzel  
Dir., IE (30 copies)  
Dir., MIPC (3 copies)

APR 10 1978







## SUPPLEMENT TO EVENT

Other previous events include RO-050-0315/76-36;76-55 and 77-42. This RO is a supplement/revision to RO-050-0315/78-01 and RO-050-0315/78-09.

### CAUSE

Investigation revealed that the cause of the Unit 2 CD engine overspeed trips to be a spurious activation of the overspeed trip device, (Dynalco-Model RT-2339 Relay Tachometer), caused by switching noise on the 250 V DC power supply system.

A Design Change (RC-DC-02-1520) was implemented adding capacitors from the power input terminals of RT-2339 to ground, which seemed to attenuate the magnitude of the "glitch" causing the overspeed trips.

After this Design Change was installed and other repair work completed, testing resumed on January 18 and another CD Diesel overspeed trip occurred. Another type of filter scheme was tried without much success. Further investigation revealed that the 250 V DC relay actually causing the trips was the "Upper Valve Gear Lube Oil Failure Alarm Time Delay" (62-VGLQF).

Another design change (RFC-DC-12-1527) was written to replace the 24 V DC supply with an AC input. The AC power source is preferred because of better noise immunity. After this installation was completed on January 26, testing resumed.

The magnitude of the glitch on the diesel tachometer was now approximately 20 RPM, this was a 50-100 RPM reduction from the glitches previously observed. Testing resumed to pin point the ultimate source of the problem. The noise being generated by the 250 V DC relay coils possessed frequency components that were being capacitively coupled to and processed by the signal level electronics of the RT 2339 module.

A modification to the RT 2339 module was added to Design Change 12-1527. This consisted of replacing and re-routing the 100 V DC leads and the magnetic pickup leads inside the module with shielded twisted pair instrument cable. The shielded leads replaced 24 gauge unshielded, untwisted stranded wire.

After this installation was completed, testing resumed. Testing consisted of 12 diesel starts, 5 starts specifically for the Design Change test procedure.

Absolutely no meter deflections were observed and no diesel trips occurred, thus, the noise coming into the module on the 100 V DC relay leads was eliminated.

By February 7, 1978 the shielding and power supply modifications were performed and tested successfully on the Emergency Diesels for both Units. It should be noted that there had never been an overspeed incident resulting from a Blackout start signal or any other signal simulated as part of Preoperational Testing.

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MIDCC1 2000000000000000 3411111 45

CON'T 01 REPORT SOURCE L 605000315 7011878 8040778 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 DURING UNIT 2 PREOPERATIONAL TESTING AND UNIT 1 OPERATION. ON THE DATES OF DEC.17,1978
03 JAN.2,7,18 AND 21,1978, THE UNIT 2 C-D EMERGENCY DIESEL GENERATOR(POWER SUPPLY FOR THE
04 MOTOR DRIVEN AUXILIARY FEED PUMP FOR UNIT 1,T.S. 3.7.1.2a) TRIPPED ON OVERSPEED DURING
05 DIESEL STARTS. IN ALL INSTANCES EXCEPT JAN.21, THE DIESEL WAS RESTARTED AND OPERABLE.
06 ON JAN.21, THE DIESEL WAS DECLARED INOPERABLE AT 1510 HOURS AND DETERMINED TO BE
07 OPERABLE AT 1907 HOURS ON JAN.22 THEREBY, MEETING THE 72 HOUR LIMIT IN T.S.3.7.1.2.

09 EE 11 B 12 A 13 ENGINE 14 Z 15 Z 16
17 LER/RO REPORT NUMBER 78
18 F 19 Z 20 Z 21 Z 22 000 23 009 24 03 25 L 26 1 27
28 03 29 30 L 31 32 1 33
34 Z 35 Z 36 Z 37 000 38 000 39 Y 40 Y 41 Y 42 Y 43 X 44 D 45 2 46 8 47 3 48

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10
11
12
13
14

15 F 28 100 29 NA 30 B 31 TESTING 32

16 Z 33 Z 34 NA 35 NA 36

17 000 37 Z 38 NA 39

18 000 40 NA 41

19 Z 42 NA 43

20 Z 44 NA 45



## SUPPLEMENT TO EVENT

Other previous events include RO-050-0315/76-36,76-55 and 77-42. This RO is a supplement/revision to RO-050-0315/78-01 and RO-050-0315/78-09.

### CAUSE

Investigation revealed that the cause of the Unit 2 CD engine overspeed trips to be a spurious activation of the overspeed trip device, (Dynalco-Model RT-2339 Relay Tachometer), caused by switching noise on the 250 V DC power supply system.

A Design Change (RC-DC-02-1520) was implemented adding capacitors from the power input terminals of RT-2339 to ground, which seemed to attenuate the magnitude of the "glitch" causing the overspeed trips.

After this Design Change was installed and other repair work completed, testing resumed on January 18 and another CD Diesel overspeed trip occurred. Another type of filter scheme was tried without much success. Further investigation revealed that the 250 V DC relay actually causing the trips was the "Upper Valve Gear Lube Oil Failure Alarm Time Delay" (62-VGLQF).

Another design change (RFC-DC-12-1527) was written to replace the 24 V DC supply with an AC input. The AC power source is preferred because of better noise immunity. After this installation was completed on January 26, testing resumed.

The magnitude of the glitch on the diesel tachometer was now approximately 20 RPM, this was a 50-100 RPM reduction from the glitches previously observed. Testing resumed to pin point the ultimate source of the problem. The noise being generated by the 250 V DC relay coils possessed frequency components that were being capacitively coupled to and processed by the signal level electronics of the RT 2339 module.

A modification to the RT 2339 module was added to Design Change 12-1527. This consisted of replacing and re-routing the 100 V DC leads and the magnetic pickup leads inside the module with shielded twisted pair instrument cable. The shielded leads replaced 24 gauge unshielded, untwisted stranded wire.

After this installation was completed, testing resumed. Testing consisted of 12 diesel starts, 5 starts specifically for the Design Change test procedure.

Absolutely no meter deflections were observed and no diesel trips occurred, thus, the noise coming into the module on the 100 V DC relay leads was eliminated.

By February 7, 1978 the shielding and power supply modifications were performed and tested successfully on the Emergency Diesels for both Units. It should be noted that there had never been an overspeed incident resulting from a Blackout start signal or any other signal simulated as part of Preoperational Testing.

THE  
FEDERAL  
BUREAU OF  
INVESTIGATION  
OF THE  
DEPARTMENT OF JUSTICE  
WASHINGTON, D. C.

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MIDCCIT 00000000000000000000 3411111 45  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T  
01 REPORT SOURCE L 650000315 7031378 8040778 9  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
02 DURING PERFORMANCE OF THP STP .204, CONTAINMENT AIR LOCK LEAKAGE TEST ON THE 650 FOOT  
03 ELEVATION INNER DOOR, THE DOOR SEAL LEAKAGE RATE EXCEEDED THE LIMIT IDENTIFIED IN  
04 TECHNICAL SPECIFICATION PARAGRAPH 3.6.1.3. THE TEST WAS STOPPED AND THE SEAL WAS  
05 INSPECTED AND CLEANED. A RETEST WAS SATISFACTORILY PERFORMED IMMEDIATELY FOLLOWING  
06 THE ABOVE INSPECTION.  
07  
08

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
S D 11 X 12 Z 13 P E N E T R 14 A 15 Z 16  
7 8 9 10 11 12 13 18 19 20  
17 LER/RO REPORT NUMBER EVENT YEAR 7 8 21 22 SHUTDOWN METHOD Z 21 36 HOURS 0 0 0 0 22 40 ATTACHMENT SUBMITTED N 23 41 NPRD-4 FORM SUB. Y 24 42 PRIME COMP. SUPPLIER L 25 43 COMPONENT MANUFACTURER W 3 0 2 26 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
10 THE CAUSE WAS DETERMINED TO BE PAINT CHIPS WHICH WERE FOUND ON THE RUBBER SEAL AND  
11 APPEARED TO BE OBSTRUCTING THE PROPER SEAL OF THE DOOR. THE CHIPS WERE CLEANED OFF AND  
12 A RETEST WAS PERFORMED. SIGNS ARE BEING CONSTRUCTED WHICH REMIND PERSONNEL TO  
13 INSPECT THE DOOR SEALS UPON EACH OPENING.  
14

15 FACILITY STATUS E 28 1000 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 SURVEILLANCE TEST 32  
7 8 9 10 12 13 44 45 46 80  
16 ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE 36  
7 8 9 10 11 44 45 80  
17 PERSONNEL EXPOSURES NUMBER TYPE 0 0 0 37 38 DESCRIPTION NA 39  
7 8 9 11 12 13 80  
18 PERSONNEL INJURIES NUMBER DESCRIPTION 0 0 0 40 41 NA  
7 8 9 11 12 80  
19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION Z 42 43 NA  
7 8 9 10 80  
20 PUBLICITY ISSUED DESCRIPTION N 44 45 NA NRC USE ONLY  
7 8 9 10 68 69 80

NAME OF PREPARER T. P. Beilman

PHONE: 616-465-5901