

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

50-315

FILE NUMBER
INCIDENT REPORT

TO:

J.G. Keppler

FROM:
Indiana & Michigan Power Co.
Bridgmena, Michigan
R.W. Jurgen

DATE OF DOCUMENT

2-9-76

DATE RECEIVED

2-12-76

LETTER
 NOTORIZED
 UNCLASSIFIED
 COPY

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

30

DESCRIPTION
Ltr. trans the following.....

PLANT NAME: Cook # 1

ENCLOSURE
Reportable Occurrence # 75-76, on 12-~~11~~-75,
Concerning Pressurizer Level Indicator NLP-
151, exceeding its limits.....

(30 Cys. Received)

**DO NOT REMOVE
ACKNOWLEDGED**

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY FOR ACTION/INFORMATION ENVIRO SAB 2-17-76

BRANCH CHIEF:	Ziemann		
W/3 CYS FOR ACTION			
LIC. ASST:	Diggs		
W/ CYS			
ACRS 16 CYS XXXXXX /SENT TO LA			

INTERNAL DISTRIBUTION

REG FILE			
NRC PDR			
I & E (2)			
MIPC (3)			
SCHROEDEK/IPPOLITO			
HOUSTON			
NOVAK/CHECK			
GRIMES/SCHWENGER			
CASE			
F. WILLIAMS			
HANAUER			
TEDESCO/MACCARY			
EISENHUT			
BAER			
SHAO			
VOLLMER/BUNCH			
KREGER/J. COLLINS			

EXTERNAL DISTRIBUTION CONTROL NUMBER

LPDR: St. Joseph, Mi.			
TIC			
NSIC			

1407



100-100000

RECEIVED
FEDERAL BUREAU OF INVESTIGATION
U. S. DEPARTMENT OF JUSTICE

100-100000

100-100000

TO: SAC, NEW YORK (100-100000)
FROM: SAC, PHOENIX (100-100000)
SUBJECT: [Illegible]

[Illegible]


100-100000



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49706

January 9, 1976



Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of Appendix A Technical Specifications and the United States Nuclear Regulatory Commission Regulatory Guide 7.16, Revision 3, Section 2.b, the following report is submitted:

RO 50-315/75-76

Sincerely,

R.W. Jurgensen
Plant Manager

/bab

- cc: R.S. Hunter
- J.E. Dolan
- G.E. Lien
- R. Kilburn
- R.J. Vollen BPI
- R.C. Callen MPSC
- K.R. Baker RO: III
- P.W. Stekete, Esq.
- R. Walsh, Esq.
- G. Charnoff, Esq.
- G. Olson
- J.M. Hennigan
- PNSRC
- R.S. Keith
- Dir., IE (30 copies)
- Dir., MIPC (3 copies)



Handwritten scribbles or marks in the top right corner.

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME				LICENSE NUMBER										LICENSE TYPE				EVENT TYPE							
01	M	I	D	C	C	1	0	0	-	0	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3
7	8	9	14	15	25	26	30	31	32																

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE											
01	CONT	Z	Z	L	L	0	5	0	-	0	3	1	5	1	2	1	1	7	5	0	1	0	6	7	6
7	8	57	58	59	60	61	68	69	74	75	80														

EVENT DESCRIPTION

02 | WHILE IN MODE 1, AT 81 PERCENT POWER, PRESSURIZER LEVEL INDICATION NLP-151 WAS
 7 8 9 | OBSERVED TO BE GREATER THAN 4 PERCENT HIGHER THAN REDUNDANT CHANNELS. SIMILAR
 7 8 9 | PROBLEMS HAVE BEEN EXPERIENCED 11-30-75 AND 12-2-75. THE STRAIN GAGE AND AMPLIFIER
 7 8 9 | BOARDS HAVE BEEN REPLACED, THE INSTRUMENTS HAVE BEEN FILLED AND VENTED AND RETURNED
 7 8 9 | TO SERVICE. THE SYSTEMS HAVE FUNCTIONED PROPERLY SINCE. (RO 50-315-75-76)
 7 8 9 |

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOATION			
07	I	A	F	I	N	S	T	R	U	N	B	0	8	0	N
7	8	9	10	11	12	17	43	44	47	48					

CAUSE DESCRIPTION

08 | THE CAUSE OF THE PROBLEM APPEARS TO BE GAS ENTRAPMENT IN THE SENSING LINES. FLUSHING
 7 8 9 | AND FILLING THE TRANSMITTERS DURING SHUTDOWN REMOVES THE GAS AND ALLOWS PROPER
 7 8 9 | INSTRUMENT OPERATION. IF FURTHER INSTRUMENT DRIFT IS EXPERIENCED, (SEE SUPPLEMENT)
 7 8 9 |

FACILITY STATUS	% POWER	OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION			
11	E	0	8	1	NA	B	ROUTINE READINGS		
7	8	9	10	12	13	44	45	46	80

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY			LOCATION OF RELEASE			
12	Z	Z	NA			NA		
7	8	9	10	11	44	45	80	

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION				
13	0	0	0	Z	NA	
7	8	9	11	12	13	80

PERSONNEL INJURIES

NUMBER	DESCRIPTION				
14	0	0	0	NA	
7	8	9	11	12	80

OFFSITE CONSEQUENCES

15 | NA
 7 8 9 |

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION			
16	Z	NA		
7	8	9	10	80

PUBLICITY

17 | NA
 7 8 9 |

ADDITIONAL FACTORS

18 | NA
 7 8 9 |

19 |
 7 8 9 |

NAME: G. Swan PHONE: 405-5901 (368)

SUPPLEMENT TO REPORTABLE OCCURRENCE RO 50-315/75-76

CAUSE DESCRIPTION

The transmitters will be flushed, refilled and vented as required. Physical installation of the instrument lines is being studied to determine that lines have been installed with proper slope.



Handwritten scribbles or marks in the top right corner.