

1 09/26/78 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL 50-315

REC: KEPPLER J G
NRC

ORG: SHALLER D V
IN & MI PWR

DOCDATE: 09/18/78
DATE RCVD: 09/22/78

DOCTYPE: LETTER NOTARIZED: NO
SUBJECT:

COPIES RECEIVED
LTR 1 ENCL 1

FORWARDING LICENSEE EVENT REPT (RO 50-315/78-050) ON 06/02/78 CONCERNING THE
BORON INJECTION THROTTLE VALVE POSITIONS WERE CHECKED PURSUANT TO TECH SPEC
4.5.2E2. AND WERE FOUND TO BE OUT OF ADJUSTMENT AND WERE REPOSITIONED,
LEAVING THE VALVES WITH AN UNK

PLANT NAME: COOK -- UNIT 1

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL:

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

NOTES:
I & E -- 3 CYS ALL MATERIAL

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF ORB#1 BC**W/4 ENCL

INTERNAL: REG FILE**W/ENCL
I & E**W/3 ENCL
I & C SYSTEMS BR**W/ENCL
NOVAK/CHECK**W/ENCL
AD FOR ENG**W/ENCL
HANAUER**W/ENCL
AD FOR SYS & PROJ**W/ENCL
ENGINEERING BR**W/ENCL
KREGER/J. COLLINS**W/ENCL
K SEYFRIT/IE**W/ENCL

NRC PDR**W/ENCL
MIPC**W/3 ENCL
EMERGENCY PLAN BR**W/ENCL
EEB**W/ENCL
PLANT SYSTEMS BR**W/ENCL
AD FOR PLANT SYSTEMS**W/ENCL
REACTOR SAFETY BR**W/ENCL
VOLLMER/BUNCH**W/ENCL
POWER SYS BR**W/ENCL


EXTERNAL: LPDR'S
ST. JOSEPH, MI**W/ENCL
NSIC**W/ENCL
ACRS CAT B**W/16 ENCL

DISTRIBUTION: LTR 44 ENCL 44
SIZE: 1P+1P+1P

CONTROL NBR: 780810244

A0.460

***** THE END *****



REGULATORY DOCKET FILE COPY

SS



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

1978 SEP 21 10 45
REGISTRATION
SERVICES

September 18, 1978

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications
the following report is submitted:

RO 78-050/03L-0.

Sincerely,

D.V. Shaller
Plant Manager

/bab

- cc: J.E. Dolan
- R.W. Jurgensen
- R.F. Kroeger
- R. Kilburn
- R.J. Vollen BPI
- K.R. Baker RO:III
- R.C. Callen MPSC
- P.W. Steketee, Esq.
- R. Walsh, Esq.
- G. Charnoff, Esq.
- G. Olson
- J.M. Hennigan
- PNSRC
- J.F. Stietzel
- R.S. Keith
- T.P. Beilman/J.L. Rischling
- Dir., IE (30 copies)
- Dir., MIPC (3 copies)

- bcc: R.L. Dudding
- E.A. Smarrella
- L.J. Matthias
- D.D. Nelson

780810264

A002
5/11

SUPPLEMENT TO LER #

SUPPLEMENT TO CAUSE DESCRIPTION

UPON DISCOVERY OF THE VALVE POSITION ERROR, THE ACTUAL POSITION OF EACH THROTTLE VALVE WAS DOCUMENTED AND FORWARDED TO SERVICE CORPORATION ENGINEERS FOR ANALYSIS. THROUGH CORRESPONDENCE IT HAS BEEN INDICATED BY SERVICE CORPORATION ENGINEERS THAT ALTHOUGH THE VALVE POSITIONS WERE LESS THAN THAT REQUIRED TO FULFILL THE TECHNICAL SPECIFICATION FLOW REQUIREMENTS, THEY WERE CONSISTENT WITH THE SAFETY ANALYSIS.

PREVENTATIVE ACTION

AS THE EVENT WAS CAUSED BY SUPPLYING INCORRECT DATA FOR THE TEST ACCEPTANCE CRITERIA, THE ERROR HAS BEEN DISCUSSED WITH ALL ENGINEERING PERSONNEL RE-EMPHASIZING THE NECESSITY FOR PERFORMING ACCURATE AND THOROUGH RESEARCH PRIOR TO DATA DISTRIBUTION FOR PROCEDURE USE.

ADDITIONALLY, OPERATIONS DEPARTMENT PERSONNEL RESPONSIBLE FOR TEST REVIEW AND ACCEPTANCE HAVE BEEN REINSTRUCTED IN THE IMPORTANCE OF REPORTING UNACCEPTABLE TEST RESULTS FOR INVESTIGATION AND CORRECTION.