

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER  
INCIDENT REPORT

TO:  
Mr. Norman C. Moseley

FROM:  
Florida Power & Light Company  
Miami, Florida  
A. D. Schmidt

DATE OF DOCUMENT  
8/19/76

DATE RECEIVED  
8/31/76

LETTER  
 ORIGINAL  
 COPY

NOTORIZED  
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED  
One signed copy

DESCRIPTION

Ltr. trans the following:

**ACKNOWLEDGED**

**DO NOT REMOVE**

PLANT NAME:  
Turkey Point #4

(1-P)

ENCLOSURE

Licensee Event Report (RO 50-251/76-7) on 8/5/76 concerning the NSSS vendor informing FP&L of recent developments that affect certain safety analyses at Turkey Point.

(4-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION 9/1/76 RJL

BRANCH CHIEF: Lear

W/3 CYS FOR ACTION

LIC. ASST.: Parrish

W/1 CYS

ACRS 16 CYS HOLDING/SENT TO LA

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE				
<input checked="" type="checkbox"/> NRC PDR				
<input checked="" type="checkbox"/> I & E (2)				
<input checked="" type="checkbox"/> MIPC				
<input checked="" type="checkbox"/> SCHROEDER/IPPOLITO				
<input checked="" type="checkbox"/> HOUSTON				
<input checked="" type="checkbox"/> NOVAK/CHECK				
<input checked="" type="checkbox"/> GRIMES				
<input checked="" type="checkbox"/> CASE				
<input checked="" type="checkbox"/> BUTLER				
<input checked="" type="checkbox"/> HANAUER				
<input checked="" type="checkbox"/> TEDESCO/MACCARY				
<input checked="" type="checkbox"/> EISENHUT				
<input checked="" type="checkbox"/> BAER				
<input checked="" type="checkbox"/> SHAO				
<input checked="" type="checkbox"/> VOLLMER/BUNCH				
<input checked="" type="checkbox"/> KREGER/J. COLLINS				

EXTERNAL DISTRIBUTION

LPDR: Miami, Florida.

TIC:

NSIC:

CONTROL NUMBER

8876

The following information was obtained from the records of the  
 Department of the Interior, Bureau of Land Management, on  
 the subject of the above-captioned tract of land.  
 The tract is situated in the County of \_\_\_\_\_  
 State of \_\_\_\_\_ and is more particularly described  
 as follows:

( ) ( )

1917


The above information was obtained from the records of the  
 Department of the Interior, Bureau of Land Management, on  
 the subject of the above-captioned tract of land.



August 19, 1976

PRN-LI-76-221

Mr. Norman C. Moseley, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
230 Peachtree Street, N. W., Suite 818  
Atlanta, Georgia 30303



Dear Mr. Moseley:


REPORTABLE OCCURRENCE 251-76-7  
TURKEY POINT UNIT 4  
DATE OF OCCURRENCE: AUGUST 5, 1976

ECCS ANALYSIS

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide prompt notification of the subject occurrence.

Very truly yours,

*J.R. Bensen*  
for A. D. Schmidt  
Vice President  
Power Resources




MAS/cpc

REGULATORY DOCKET FILE COPY

Attachment

cc: Jack R. Newman, Esquire  
Director, Office of Inspection and Enforcement (40)  
Director, Office of Management Information and  
Program Control (3)

8876



# LICENSEE EVENT REPORT

CONTROL BLOCK:   
1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME <input type="text" value="01"/> <input type="text" value="F"/> <input type="text" value="L"/> <input type="text" value="T"/> <input type="text" value="P"/> <input type="text" value="S"/> <input type="text" value="4"/> <small>7 8 9 14</small>	LICENSE NUMBER <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="-"/> <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="0"/> <small>15 25 26 30</small>	LICENSE TYPE <input type="text" value="4"/> <input type="text" value="1"/> <input type="text" value="1"/> <input type="text" value="1"/> <input type="text" value="1"/> <small>26 30</small>	EVENT TYPE <input type="text" value="0"/> <input type="text" value="1"/> <small>31 32</small>
---	---	--	---

<input type="text" value="01"/> <small>7 8</small>	CATEGORY <input type="text" value="CONT"/> <small>57 58</small>	REPORT TYPE <input type="text" value="T"/> <small>59</small>	REPORT SOURCE <input type="text" value="O"/> <small>60</small>	DOCKET NUMBER <input type="text" value="0"/> <input type="text" value="5"/> <input type="text" value="0"/> <input type="text" value="-"/> <input type="text" value="0"/> <input type="text" value="2"/> <input type="text" value="5"/> <input type="text" value="1"/> <small>61 68</small>	EVENT DATE <input type="text" value="0"/> <input type="text" value="8"/> <input type="text" value="0"/> <input type="text" value="5"/> <input type="text" value="7"/> <input type="text" value="6"/> <small>69 74</small>	REPORT DATE <input type="text" value="0"/> <input type="text" value="8"/> <input type="text" value="1"/> <input type="text" value="9"/> <input type="text" value="7"/> <input type="text" value="6"/> <small>75 80</small>
---	---	--	--	--	---	--

**EVENT DESCRIPTION**

The NSSS vendor has informed FPL of recent developments that affect  
 certain safety analyses at Turkey Point. The consequence has been a  
 reduction in the maximum allowable  $F_Q$  and  $F_{\Delta H}$  as described in the  
 attached report.

SYSTEM CODE <input type="text" value="Z"/> <input type="text" value="Z"/> <small>7 8 9 10</small>	CAUSE CODE <input type="text" value="C"/> <small>11</small>	COMPONENT CODE <input type="text" value="Z"/> <input type="text" value="Z"/> <input type="text" value="Z"/> <input type="text" value="Z"/> <input type="text" value="Z"/> <input type="text" value="Z"/> <small>12 17</small>	PRIME COMPONENT SUPPLIER <input type="text" value="N"/> <small>43</small>	COMPONENT MANUFACTURER <input type="text" value="W"/> <input type="text" value="1"/> <input type="text" value="2"/> <input type="text" value="0"/> <small>44 47</small>	VIOLATION <input type="text" value="N"/> <small>48</small>
---	---	---	---	---	--

**CAUSE DESCRIPTION**

See Event Description.

FACILITY STATUS <input type="text" value="E"/> <small>7 8 9</small>	% POWER <input type="text" value="1"/> <input type="text" value="0"/> <input type="text" value="0"/> <small>10 12 13</small>	OTHER STATUS <input type="text" value="N/A"/> <small>44</small>	METHOD OF DISCOVERY <input type="text" value="d"/> <small>45</small>	DISCOVERY DESCRIPTION <input type="text" value="N/A"/> <small>46 80</small>
---	--	---	--	---

FORM OF ACTIVITY RELEASED <input type="text" value="Z"/> <small>7 8 9</small>	CONTENT OF RELEASE <input type="text" value="Z"/> <small>10 11</small>	AMOUNT OF ACTIVITY <input type="text" value="N/A"/> <small>44</small>	LOCATION OF RELEASE <input type="text" value="N/A"/> <small>45 80</small>
---	--	---	---

**PERSONNEL EXPOSURES**

NUMBER <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="0"/> <small>7 8 9 11</small>	TYPE <input type="text" value="Z"/> <small>12</small>	DESCRIPTION <input type="text" value="N/A"/> <small>13 80</small>
---	---	---

**PERSONNEL INJURIES**

NUMBER <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="0"/> <small>7 8 9 11</small>	DESCRIPTION <input type="text" value="N/A"/> <small>12 80</small>
---	---

**PROBABLE CONSEQUENCES**

7 8 9 80

**LOSS OR DAMAGE TO FACILITY**

TYPE <input type="text" value="Z"/> <small>7 8 9 10</small>	DESCRIPTION <input type="text" value="N/A"/> <small>80</small>
---	--

**PUBLICITY**


7 8 9 80

**ADDITIONAL FACTORS**

7 8 9 80

7 8 9 80

NAME: M. A. Schoppman PHONE: 305/552-3779



FLORIDA POWER &amp; LIGHT COMPANY

August 19, 1976  
L-76-300

Office of Nuclear Reactor Regulation  
 Attn: Victor Stello, Jr., Director  
 Division of Operating Reactors  
 U. S. Nuclear Regulatory Commission  
 Washington, D. C. 20555

Dear Mr. Stello:

Re: Turkey Point Units 3 and 4  
 Docket Nos. 50-250 and 50-251  
Westinghouse Safety Analyses

The Westinghouse Electric Corporation has informed Florida Power & Light Company that recent developments have affected the results of certain safety analyses for Westinghouse plants. The following information regarding this problem is being submitted to you in response to an August 13, 1976 telephone request from your staff.

One development involves the temperature of the fluid in the upper head. Past ECCS analyses assumed that the temperature in the upper head was equal to the vessel inlet temperature ( $T_{cold}$ ). The conservative judgment is to assume that the temperature will be equal to the vessel outlet temperature ( $T_{hot}$ ). The consequence is a reduction in maximum allowable Heat Flux Hot Channel Factor ( $F_Q$ ) to prevent operation at unacceptable local power levels. The resulting  $F_Q$  limit for Turkey Point is conservatively estimated to be 2.165. The new  $F_Q$  limit was derived as shown below:

$$[2.32 - A - B + C] D = 2.165$$

2.32 = previous limit on  $F_Q$


A = .26 = estimated reduction in  $F_Q$  due to increase in upper head temperature from  $T_{cold}$  to  $T_{hot}$ .

B = .04 = estimated reduction in  $F_Q$  due to plugged steam generator tubes.

C = .05 = estimated increase in  $F_Q$  due to the fact that the ECCS analysis peak clad temperature is 50° below the Final Acceptance Criteria.

D =  $\frac{2300}{2200}$  = factor for increasing  $F_Q$  due to operation 100 Mwt below the power level used in the ECCS analysis.

Note: For a 925 ft<sup>3</sup> accumulator volume, A = .16 and  $F_Q = 2.27$ .



To: Victor Stello, Jr.  
Re: Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
Westinghouse Safety Analyses

August 19, 1976  
Page -2-

Another development involves rod bow. Recent test results indicate that the rod bow DNB penalty is higher than previously used. The combination of this penalty with available margins results in an estimated reduction in DNBR on a region-by-region basis. Increasing the rod bow DNB penalty can be offset by a combination of the following:

- a) A reduction in the maximum allowable Nuclear Enthalpy Rise Hot Channel Factor ( $F_{\Delta H}$ ) on a region-by-region basis.
  - i) 0% to 4% reduction for new first cycle fuel applied linearly from Beginning-of-Cycle to End-of-Cycle.
  - ii) 6% constant reduction for fuel which has received 1 cycle of burnup.
  - iii) 7% constant reduction for fuel which has received 2 or more cycles of burnup.
- b) A reduction in  $T_{ave}$  and a corresponding change in the Overtemperature  $\Delta T$  equation. (1° F in  $T_{ave}$  and 1° F in the constant in the temperature difference term in the Overtemperature  $\Delta T$  equation = 1% in DNBR.)
- c) An increase in reactor coolant flow. 1% flow increase = 1% increase in DNBR.)

For the time being, the increased upper head fluid temperature and the increased rod bow penalty are being offset by operationally limiting  $F_0$  and  $F_{\Delta H}$  as described above. In the future, operational considerations may cause us to revise the means by which we accommodate the higher rod bow DNB penalty, in which case we may utilize some other combination of available options.

The revised limits described above represent preliminary estimates. The evaluation of these developments is continuing in






10  
11  
12

To: Victor Stello, Jr.  
Re: Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
Westinghouse Safety Analyses

August 19, 1976  
Page -3-


an effort to quantify the effects on the Turkey Point units more precisely.


Very truly yours,

  
Robert E. Uhrig  
Vice President

REU/MAS/hlc

cc: Norman C. Moseley, Region II  
Jack R. Newman, Esq.





August 19, 1976

PRN-LI-76-221

Mr. Norman C. Moseley, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
230 Peachtree Street, N. W., Suite 818  
Atlanta, Georgia 30303

Dear Mr. Moseley:

REPORTABLE OCCURRENCE 251-76-7  
TURKEY POINT UNIT 4  
DATE OF OCCURRENCE: AUGUST 5, 1976

ECCS ANALYSIS

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide prompt notification of the subject occurrence.


Very truly yours,

*for J.R. Bensen*  
A. D. Schmidt  
Vice President  
Power Resources

MAS/cpc

Attachment

cc: Jack R. Newman, Esquire  
Director, Office of Inspection and Enforcement (40)  
Director, Office of Management Information and  
Program Control (3)



# LICENSEE EVENT REPORT

CONTROL BLOCK: 1         6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME	LICENSE NUMBER	LICENSE TYPE	EVENT TYPE
01   F   L   T   P   S   4	0   0   -   0   0   0   0   0   -   0   0	4   1   1   1   1	0   1
7 8 9 14	15 25	26 30	31 32

01	CONT	CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER	EVENT DATE	REPORT DATE
01	CONT		T	O	0   5   0   -   0   2   5   1	0   8   0   5   7   6	0   8   1   9   7   6
7 8	57 58	59	60	61	68	69 74	75 80

**EVENT DESCRIPTION**

02	The NSSS vendor has informed FPL of recent developments that affect	60
03	certain safety analyses at Turkey Point. The consequence has been a	80
04	reduction in the maximum allowable $F_Q$ and $F_{\Delta H}$ as described in the	80
05	attached report.	80
06		80

07	SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
07	Z   Z	C	Z   Z   Z   Z   Z   Z	N	W   1   2   0	N
7 8 9 10	11	12	17	43	44 47	48

**CAUSE DESCRIPTION**

08	See Event Description.	80
09		80
10		80

11	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11	E	1   0   0	N/A	d	N/A
7 8 9	10	12 13	44	45 46	80

12	FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
12	Z	Z	N/A	N/A
7 8 9	10	11	44	45 80

**PERSONNEL EXPOSURES**

13	NUMBER	TYPE	DESCRIPTION
13	0   0   0	Z	N/A
7 8 9	11	12	13 80

**PERSONNEL INJURIES**

14	NUMBER	DESCRIPTION
14	0   0   0	N/A
7 8 9	11 12	80

**PROBABLE CONSEQUENCES**

15		80
15	N/A	80

**LOSS OR DAMAGE TO FACILITY**

16	TYPE	DESCRIPTION
16	Z	N/A
7 8 9	10	80

**PUBLICITY**


17		80
17	N/A	80


**ADDITIONAL FACTORS**

18		80
18	N/A	80

19		80
19		80

NAME: M. A. Schoppman PHONE: 305/552-3779





August 19, 1976  
L-76-300

Office of Nuclear Reactor Regulation  
Attn: Victor Stello, Jr., Director  
Division of Operating Reactors  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Mr. Stello:

Re: Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
Westinghouse Safety Analyses

The Westinghouse Electric Corporation has informed Florida Power & Light Company that recent developments have affected the results of certain safety analyses for Westinghouse plants. The following information regarding this problem is being submitted to you in response to an August 13, 1976 telephone request from your staff.

One development involves the temperature of the fluid in the upper head. Past ECCS analyses assumed that the temperature in the upper head was equal to the vessel inlet temperature ( $T_{cold}$ ). The conservative judgment is to assume that the temperature will be equal to the vessel outlet temperature ( $T_{hot}$ ). The consequence is a reduction in maximum allowable Heat Flux Hot Channel Factor ( $F_Q$ ) to prevent operation at unacceptable local power levels. The resulting  $F_Q$  limit for Turkey Point is conservatively estimated to be 2.165. The new  $F_Q$  limit was derived as shown below:

$$[2.32 - A - B + C] D = 2.165$$

2.32 = previous limit on  $F_Q$

A = .26 = estimated reduction in  $F_Q$  due to increase in upper head temperature from  $T_{cold}$  to  $T_{hot}$ .


B = .04 = estimated reduction in  $F_Q$  due to plugged steam generator tubes.

C = .05 = estimated increase in  $F_Q$  due to the fact that the ECCS analysis peak clad temperature is 50° below the Final Acceptance Criteria.

D =  $\frac{2300}{2200}$  = factor for increasing  $F_Q$  due to operation 100 Mwt below the power level used in the ECCS analysis.

Note: For a 925 ft<sup>3</sup> accumulator volume, A = .16 and  $F_Q = 2.27$ .





To: Victor Stello, Jr.  
Re: Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
Westinghouse Safety Analyses

August 19, 1976  
Page -2-

Another development involves rod bow. Recent test results indicate that the rod bow DNB penalty is higher than previously used. The combination of this penalty with available margins results in an estimated reduction in DNBR on a region-by-region basis. Increasing the rod bow DNB penalty can be offset by a combination of the following:

- a) A reduction in the maximum allowable Nuclear Enthalpy Rise Hot Channel Factor ( $F_{\Delta H}$ ) on a region-by-region basis.
  - i) 0% to 4% reduction for new first cycle fuel applied linearly from Beginning-of-Cycle to End-of-Cycle.
  - ii) 6% constant reduction for fuel which has received 1 cycle of burnup.
  - iii) 7% constant reduction for fuel which has received 2 or more cycles of burnup.
- b) A reduction in  $T_{ave}$  and a corresponding change in the Overtemperature  $\Delta T$  equation. (1° F in  $T_{ave}$  and 1° F in the constant in the temperature difference term in the Overtemperature  $\Delta T$  equation = 1% in DNBR.)
- c) An increase in reactor coolant flow. 1% flow increase = 1% increase in DNBR.)

For the time being, the increased upper head fluid temperature and the increased rod bow penalty are being offset by operationally limiting  $F_0$  and  $F_{\Delta H}$  as described above. In the future, operational considerations may cause us to revise the means by which we accommodate the higher rod bow DNB penalty, in which case we may utilize some other combination of available options.

The revised limits described above represent preliminary estimates. The evaluation of these developments is continuing in




11-11-11

To: Victor Stello, Jr.  
Re: Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
Westinghouse Safety Analyses

August 19, 1976  
Page -3-

an effort to quantify the effects on the Turkey Point units more precisely.

Very truly yours,

  
Robert E. Uhrig  
Vice President

REU/MAS/hlc

cc: Norman C. Moseley, Region II  
Jack R. Newman, Esq.



11-11-11  
11-11-11  
11-11-11

2

—