

June 25, 1976

PRN-LI-76-162

Mr. Norman C. Moseley, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
230 Peachtree Street, N. W., Suite 818  
Atlanta, Georgia 30303


Dear Mr. Moseley:

REPORTABLE OCCURRENCE 251-76-4  
TURKEY POINT UNIT 4  
DATE OF OCCURRENCE: JUNE 11, 1976

LOW BORON CONCENTRATION

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide prompt notification of the subject occurrence.

Very truly yours,

  
A. D. Schmidt  
Vice President  
Power Resources

MAS/cpc

Attachment

cc: Jack R. Newman, Esquire  
Director, Office of Inspection and Enforcement (40)  
Director, Office of Management Information and  
Program Control (3)

REC'D - CIVIL RIGHTS  
JUN 28 12 59 PM '65

**CONTROL BLOCK:**

**LICENSEE  
NAME**

**LICENSE NUMBER**

**LICENSE  
TYPE**

**EVENT  
TYPE**

0	1		F	L	T	P	S	4		0	0	-	0	0	0	0	-	0	0		4	1	1	1	1		0	1		
7	8	9						14		15										25		26					30		31	32

01		CONT		CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER						EVENT DATE						REPORT DATE					
7	8	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80		
				T	L	0	5	0	-	0	2	5	0	0	6	1	1	7	6	0	6	2	5	7	6		

02	During steady state operation, routine sampling showed that the boron	80
03	concentration of the boron injection tank (BIT) and two of the three	80
04	boric acid storage tanks (BAST) was below the lower Technical Specifica-	80
05	tion limit of 20,000 ppm. Corrective action was to initiate a shutdown	80
06	in accordance with Administrative Procedure 103.8 and to commence	80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION	
07	S H	E	V	A	L	V	E	X	A	D	0	2	5	Y
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21

08 The exact cause of the BIT dilution was not found until the problem had  
7 8 9 80  
09 recurred on June 12. At that time, it was found that dilution of the  
7 8 9 80  
10 Unit 4 BIT was caused by inleakage from the RWST via the BIT inlet and  
7 8 9 80

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	1	0	0	N/A		b	N/A		
7	8	9	10	12	13	44	45	46	80	

		FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
1	2	Z	Z	N/A	N/A
7	8	9	10	11	44
				45	80

NUMBER			TYPE	DESCRIPTION
1	3	0 0 0	Z	N/A

NUMBER				DESCRIPTION	
1	4	0	0	0	N/A

15	N/A	80
----	-----	----

TYPE		DESCRIPTION
16	Z	N/A

17	N/A	80
----	-----	----

18	See Page 2 for continuation of Event Description and Cause Description.
----	---

19 89 80

NAME: M. A. Schoppman

PHONE: 305/552-3779

1000  
1000

REPORTABLE OCCURRENCE 251-76-4  
LICENSEE EVENT REPORT  
PAGE TWO

Event Description (Continued)

adding a concentrated boric acid solution to the tanks. The boron concentration of the tanks was returned to within specification and normal operation was resumed. A similar problem experienced by Unit 3 is reported in Reportable Occurrence 250-76-4. (251-76-4).

Cause Description (Continued)

outlet isolation valves. Since the BIT was being recirculated with the BAST system, two of the three BAST's were also diluted. Maintenance was performed on the inlet isolation valves to stop the leakage. Leakage past the outlet isolation valves was stopped by isolating the leakoff line from those valves. Several cases of BIT dilution have occurred, however, this was the first occurrence attributable directly to significant leakage past the isolation valves. Also, a situation in which cross-dilution occurred between a BIT and a BAST was previously discussed in report 251-75-12.

100-100000  
100-100000