

June 4, 1976

PRN-LI-76-138

Mr. Norman C. Moseley, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
230 Peachtree Street, N.W., Suite 818  
Atlanta, Georgia 30303


Dear Mr. Moseley:

REPORTABLE OCCURRENCE <sup>2</sup>~~8~~51-76-3  
TURKEY POINT UNIT 4  
DATE OF OCCURRENCE: MAY 17, 1976

CORRECTION

A Licensee Event Report for the subject occurrence was sent to you on May 27, 1976. Line 2 of the Event Description contained the words "Steam Generator 4". The correct wording is "Steam Generator 4C". A corrected LER, page 1, is attached.


Very truly yours,

  
A. D. Schmidt  
Vice President  
Power Resources

MAS/ghf

Attachment

cc: Jack R. Newman, Esquire  
Director, Office of Inspection and Enforcement (30)  
Director, Office of Management Information and  
Program Control (3)



# LICENSEE EVENT REPORT

CONTROL BLOCK: 

1	2	3	4	5	6
---	---	---	---	---	---

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 

01	F	L	T	P	S	4
----	---	---	---	---	---	---

 LICENSE NUMBER: 

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE: 

4	1	1	1	1
---	---	---	---	---

 EVENT TYPE: 

0	1
---	---

CATEGORY: 

01	CONT
----	------

 REPORT TYPE: 

T
---

 REPORT SOURCE: 

0
---

 DOCKET NUMBER: 

0	5	0	-	0	2	5	1
---	---	---	---	---	---	---	---

 EVENT DATE: 

0	5	1	7	7	6
---	---	---	---	---	---

 REPORT DATE: 

0	5	2	7	7	6
---	---	---	---	---	---

### EVENT DESCRIPTION

02 | During the current refueling outage, a section of the sixth tube support  
03 | plate was removed from Steam Generator 4C by the manufacturer. The section  
04 | was sent to the manufacturer's Research and Development Laboratory for  
05 | evaluation. Based on preliminary results, some cracking of the tube  
06 | support plate section has been identified. Several observations were

SYSTEM CODE: 

C	C
---	---

 CAUSE CODE: 

F
---

 COMPONENT CODE: 

H	T	E	X	C	H
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER: 

N
---

 COMPONENT MANUFACTURER: 

W	1	2	0
---	---	---	---

 VIOLATION: 

N
---

### CAUSE DESCRIPTION

08 | Laboratory examination results and evaluations have not determined the  
09 | cause of this occurrence. The manufacturer has undertaken a diagnostic  
10 | program to develop an understanding of the observed conditions.

FACILITY STATUS: 

H
---

 % POWER: 

0	0	0
---	---	---

 OTHER STATUS: 

N/A
-----

 METHOD OF DISCOVERY: 

C
---

 DISCOVERY DESCRIPTION: 

Vendor Inspection
-------------------

FORM OF ACTIVITY RELEASED: 

Z
---

 CONTENT OF RELEASE: 

Z
---

 AMOUNT OF ACTIVITY: 

N/A
-----

 LOCATION OF RELEASE: 

N/A
-----

### PERSONNEL EXPOSURES

13 | NUMBER: 

0	0	0
---	---	---

 TYPE: 

Z
---

 DESCRIPTION: 

N/A
-----

### PERSONNEL INJURIES

14 | NUMBER: 

0	0	0
---	---	---

 DESCRIPTION: 

N/A
-----

### PROBABLE CONSEQUENCES

15 | 

N/A
-----

### LOSS OR DAMAGE TO FACILITY

16 | TYPE: 

Z
---

 DESCRIPTION: 

N/A
-----

### PUBLICITY

17 | 

N/A
-----

### ADDITIONAL FACTORS

18 | See Page Two for Continuation of Event Description.

19 |

