



Central File
50-251

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
230 Peachtree Street, N.W., Suite 1217
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE: 251-77-7
TURKEY POINT UNIT 4
DATE OF OCCURRENCE: AUGUST 22, 1977

PRESSURIZER HEATUP RATE

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide prompt notification of the subject occurrence.

Very truly yours,

for J.R. Bensen
A. D. Schmidt
Vice President
Power Resources

MAS/ms

Attachment

cc: Robert Lowenstein, Esquire
Director, Office of Inspection and Enforcement (40)
Director, Office of Management Information and
Program Control (3)

A

CONTROL BLOCK: 1 6

PLEASE PRINT ALL REQUIRED INFORMATION

LICENSEE NAME: [01] [F] [L] [T] [P] [S] [4] | LICENSE NUMBER: [0] [0] [-] [0] [0] [0] [0] [0] [-] [0] [0] | LICENSE TYPE: [4] [1] [1] [1] [1] | EVENT TYPE: [0] [1]

CONT: [01] [8] | CATEGORY: [57] [58] | REPORT TYPE: [T] [59] | REPORT SOURCE: [L] [60] | DOCKET NUMBER: [0] [5] [0] [-] [0] [2] [5] [1] [68] | EVENT DATE: [0] [8] [2] [2] [7] [7] [74] | REPORT DATE: [0] [9] [0] [6] [7] [7] [80]

EVENT DESCRIPTION

[12] [8] [9] Westinghouse notified FPL that the correct maximum allowable heatup rate for the pres-
 [13] [8] [9] surizer is 100° F/hr instead of the currently allowed 200° F/hr (Tech Spec 3.1.2.d).
 [14] [8] [9] There are no safety implications because the pressurizer has never exceeded the 100° F/hr
 [15] [8] [9] heatup rate and can not do so in any normal evolution. Corrective action was discussed
 [16] [8] [9] in the 8/23 and 8/25 memos for Facsimile Transmission from H.E. Yaeger to J.P. O'Reilly,
 (251-77-7)

SYSTEM CODE: [7] [8] [9] [C] [B] [10] | CAUSE CODE: [C] [11] | COMPONENT CODE: [V] [E] [S] [S] [E] [L] [17] | PRIME COMPONENT SUPPLIER: [N] [43] | COMPONENT MANUFACTURER: [W] [1] [2] [0] [44] [47] | VIOLATION: [N] [48]

CAUSE DESCRIPTION

[8] [9] NA
 [9] [8] [9]
 [0] [8] [9]

FACILITY STATUS: [1] [8] [9] [E] | % POWER: [1] [0] [0] [10] [12] [13] | OTHER STATUS: [NA] [44] | METHOD OF DISCOVERY: [D] [45] | DISCOVERY DESCRIPTION: [Westinghouse letter FPL-77-62 (8/18/77)] [46] [80]

FORM OF ACTIVITY RELEASED: [2] [8] [9] | CONTENT OF RELEASE: [Z] [10] [11] | AMOUNT OF ACTIVITY: [NA] [44] | LOCATION OF RELEASE: [NA] [45] [80]

PERSONNEL EXPOSURES

[3] [8] [9] NUMBER: [0] [0] [0] [11] | TYPE: [Z] [12] | DESCRIPTION: [NA] [13] [80]

PERSONNEL INJURIES

[4] [8] [9] NUMBER: [0] [0] [0] [11] | DESCRIPTION: [NA] [12] [80]

PROBABLE CONSEQUENCES

[5] [8] [9] [NA] [80]

LOSS OR DAMAGE TO FACILITY

[6] [8] [9] TYPE: [Z] [10] | DESCRIPTION: [NA] [80]

PUBLICITY

[7] [8] [9] [NA] [80]

ADDITIONAL FACTORS

[8] [8] [9] [NA] [80]

[9] [8] [9]