

● E 03/28/78 ●

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)  
DISTRIBUTION FOR INCOMING MATERIAL 50-251

REC: SCHWENCER A  
NRC

.ORG: UHRIG R E  
FL PWR & LIGHT

DOC DATE: 03/23/78  
DATE RCVD: 03/27/78

DOCTYPE: LETTER NOTARIZED: NO

COPIES RECEIVED  
LTR 3 ENCL 3

SUBJECT:  
FORWARDING EVALUATION ENTITLED: "REPT OF ABNORMAL INDIACTIONS FROM METAL  
IMPACT MONITORING SYSTEM, UNIT NO 4.", PURSUANT TO ORDER FOR MODIFICATION OF  
LIC NO DPR-41 DTD 08/02/77.

PLANT NAME: TURKEY PT #3

REVIEWER INITIAL: XJM  
DISTRIBUTOR INITIAL: *me*

\*\*\*\*\* DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS \*\*\*\*\*

GENERAL DISTRIBUTION FOR AFTER ISSUONCE OF OPERATING LICENSE.  
(DISTRIBUTION CODE A001)

FOR ACTION: . BR CHIEF SCHWENCER\*\*W/7 ENCL

INTERNAL: REG FILE\*\*W/ENCL  
1 & E\*\*W/2 ENCL  
HANAUER\*\*W/ENCL  
EISENHUT\*\*W/ENCL  
BAER\*\*W/ENCL  
GRIMES\*\*W/ENCL  
J. MCGOUGH\*\*W/ENCL

NRC PDR\*\*W/ENCL  
OELD\*\*LTR ONLY  
CHECK\*\*W/ENCL  
SHAO\*\*W/ENCL  
BUTLER\*\*W/ENCL  
J COLLINS\*\*W/ENCL

EXTERNAL: LPDR'S  
MIAMI, FL\*\*W/ENCL  
TIC\*\*W/ENCL  
NSIC\*\*W/ENCL  
ACRS CAT B\*\*W/16 ENCL

DISTRIBUTION: LTR 40 ENCL 39  
@@@2\SIZE: 1P+3P

CONTROL NBR: 780860036 HHHH

\*\*\*\*\* THE END \*\*\*\*\*




1954



1954

1954



REGULATORY DOCKET FILE COPY  
March 23, 1978  
E-78-104

Office of Nuclear Reactor Regulation  
Attention: Mr. A. Schwencer, Chief  
Operating Reactors Branch #1  
Division of Operating Reactors  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555


Dear Mr. Schwencer:

Re: Turkey Point Unit 4  
Docket No. 50-251  
Metal Impact Monitoring System



The Order for Modification of License for Turkey Point Unit No. 4, dated August 2, 1977, amended paragraph 3.D of License DPR-41. Pursuant to the requirements of this Order, Florida Power & Light Company is forwarding the attached evaluation "Report of Abnormal Indications from Metal Impact Monitoring System, Turkey Point Unit No. 4." The indications were first noticed on March 9, 1978 while reviewing the MIMS tapes recorded during the Unit 4 startup.

Very truly yours,

  
Robert E. Uhrig  
Vice President


REU:RJA:dt

Attachment

cc: Mr. James P. O'Reilly, Region II  
Robert Lowenstein, Esquire

780860036

Acc  
5/3



REPORT OF ABNORMAL INDICATIONS  
FROM METAL IMPACT MONITORING SYSTEM

Turkey Point Unit 4  
March 7-8, 1978

---

INTRODUCTION

At the Florida Power and Light Company Turkey Point Plant Unit #4, Metal Impact Monitoring alarms were observed on March 7, 1978. The Metal Impact Monitoring System incorporates three channels, with the transducers all mounted on the in-core moveable detector thimble conduits near the bottom of the reactor vessel.


During heatup of the Reactor Coolant System, magnetic tape recordings of the signals of the Metal Impact Monitoring System were made continuously. With the reactor coolant flow at steady state conditions, metal impacts were detected during two brief periods, one with two reactor coolant pumps running, and one with three pumps operating. Subsequently, a tape for the impacting period was transmitted to the NSSS vendor for analysis.

The tape recordings for two-pump operation, with pumps B and C running, were taken on March 7, 1978, with the reactor coolant temperature of 240°F and pressure of 350 psig. The recording with all three pumps operating was taken on March 8, 1978, with reactor coolant conditions of 540°F and 2235 psig.

ANALYSIS

During the analysis of this tape, the signals were played through a high pass filter to eliminate 60 Hz noise. The output signals were recorded on light sensitive paper of a recording oscillograph. The tape recorder reproduce speed and the paper speed of the oscillograph were set so as to obtain a frequency response of 20 KHz and clear indication of waveform shape of the impacts. The oscillograph charts were examined to determine the rate of impacts over a given time interval, and the amplitude of the impacts. Frequency spectra were also generated for selected impacts as a factor in determining the mass of the object. The results of this analysis are summarized in Table I.

In reviewing these data, consideration was given to the rise time of the signal waveform of the impacts. Techniques



based on the rise time of the signal waveform of the impacts can be used to determine if the impacts are against the vessel wall, or against other surfaces. If the rise times of the signal waveforms seen by all transducers are rapid, on the order of 100 microseconds, this is a fair indication that the impacts are nearby and against the reactor vessel wall. Signals with much longer rise times, up to the order of milliseconds, are an indication that the object is either impacting another surface or is impacting far away.

In performing this analysis, reference was made to Metal Impact Monitoring System data taken during July, 1977 at this plant.

### CONCLUSIONS

The results of the analysis of the data, and a review of the July, 1977 data for two-pump operation indicates that:

1. The waveform of the impact signals were the same as for July, 1977.
2. The rate of impacts were approximately the same for both periods.
3. The amplitude of the impacts were moderately higher in March, 1978 than in July, 1977; however, the plant operating conditions under which the impacts occurred were not identical.
4. The data from both periods shows no sudden  $\Delta$ time changes, i.e., successive impacts always occurred at the same location. No signal overlaps or impacts within 10 milliseconds of each other were found. Therefore, it can be concluded to a high degree of confidence that there is only one loose object impacting in the bottom of the reactor vessel.
5. Based on the relative amounts of the high and low frequency content in the impact signals, the mass of the loose object is estimated to be less than one (1) pound.
6. The impacts were found to be both against the reactor vessel wall and other structures in the bottom of the reactor vessel.
7. The continued safe operation of Turkey Point Unit 4 is not affected by the occurrence of the metal impacts as described in this report.



11-11-55

Dear Mr. [Name],

I have your letter of [Date] regarding [Subject].

[The following text is extremely faint and largely illegible due to the quality of the scan. It appears to be a standard business letter response.]

Sincerely,  
[Signature]



TABLE I  
SUMMARY OF RESULTS

<u>Temp.</u> <u>(°F)</u>	<u>Pressure</u> <u>(psig)</u>	<u>Pumps</u> <u>Running</u>	<u>Maximum</u> <u>Amplitude of</u> <u>Signal (Gp-p)</u>	<u>Rate</u> <u>Impacts/Sec.</u>	<u>Observation</u> <u>Period Sec.</u>	<u>Background</u> <u>Noise Gp-p</u>
240 (3/7/78)	350	B. C. Steady State	1.8-8* (Avg. 2.8**)	2.4	11.0	1.25
540 (3/8/78)	2235	A. B. C. Steady State	0.8-4.7* (Avg. 1.43**)	3.1	9.5	0.67

The following data refer to recordings made during July, 1977.

90	400	A. B. (2 Minute Runs)	0.7-4p-p*** (Avg. 1.5**)	2.6	12.0	0.7
----	-----	-----------------------------	-----------------------------	-----	------	-----

\*Maximum amplitude refers to greatest peak amplitude of any channel for the same impact.

\*\*Average amplitude refers to average of peak amplitude of all three channels for the same impact.

\*\*\*Response limited by Visicorder saturation.

