NRC FORM 591M PART 1 (07-2012) 10 CFR 2.201 SAF	ETY INSPECTION	REPORT AN	U.S. NI D COMPLIANCE IN	UCLEAR REGULATORY COMMISSION
1, LICENSEE/LOCATION INSPEC	TED;		2. NRC/REGIONAL OFFICE	
Acquisition Bell Hospital, LLC d/b/a Bell Hospital 901 Lakeshore Drive Ishpeming, Michigan 49849 REPORT NUMBER(S) 2018001			Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352	
3. DOCKET NUMBER(S)		4. LICENSE NUMBER	₹(S)	5. DATE(S) OF INSPECTION
030-13856		21-02037-03		August 23, 2018
Regulatory Commission (NRC) procedures and representative  1. Based on the inspe  2. Previous violation(s  3. The violations(s), and on-repetitive, and discretion, were sat	rules and regulations and to records, interviews with per action findings, no violations s) closed. pecifically described to you le corrective action was or is be	he conditions of your reonnel, and observat were identified.  by the inspector as no eing taken, and the re	license. The inspection consistents by the inspector. The inspector. The inspector on-cited violations, are not being emaining criteria in the NRC E	fety and to compliance with the Nuclear sted of selective examinations of pection findings are as follows:  og cited because they were self-identified, inforcement Policy, to exercise
				on of NRC requirements and are being nay be subject to posting in accordance

with 10 CFR 19.11.

(Violations and Corrective Actions)

Contrary to License Condition 14.A of NRC License No. 21-02037-03 and Item 3 of the licensee's procedure for preparing, drawing up and injecting radiopharmaceuticals, a member of the licensee's staff failed to wear their whole body dosimeter while performing injections of radiopharmaceuticals. Specifically, a nuclear medicine technologist (NMT) misplaced their whole body dosimeter on or about August 20, 2018 and continued to perform injections of radiopharmaceuticals without it through August 23, 2018.

The root cause of this violation was lack of communication between the NMT and the licensee's radiation safety personnel regarding the lost dosimeter. As corrective action, licensee staff searched for and found the missing dosimeter on August 23, 2018, to use for future administrations within the monitoring period.

Continued on Part 2

## Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps elready taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	RIGNATURE	DATE
LICENSEE'S REPRESENTATIVE	Todd Bostwick	Vidal Brain	9-13-14
NRC INSPECTOR	Edward F. Harvey	Edward Harriey	9/10/2018
BRANCH CHIEF	Aaron T. McCraw	Syl- for ATM	9/10/18

NRC FORM 591M PART 2

U.S. NUCLEAR REGULATORY COMMISSION

(07-2012) 10 CFR 2,261

## SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Acquisition Bell Hospital, LLC d/b/a Bell Hospital 901 Lakeshore Drive Ishpeming, Michigan 49849

REPORT NUMBER(S) 2018001

2. NRC/REGIONAL OFFICE

Region III

U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210

Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

4. LICENSE NUMBER(S)

5. DATE(S) OF INSPECTION

030-13856

21-02037-03

August 23, 2018

(Continued)

Continued from Part 1

In addition, on August 28, 2018, the RSO prepared a dose estimate for the days on which the dosimeter was missing based on the previous dose history for the NMT. The licensee has committed to submitting the dose calculation to their dosimetry service provider at the end of the monitoring period to maintain a more accurate dose of record. As long term corrective action to prevent recurrence, the licensee amended their contract with their dosimetry provider to include a spare dosimeter that may be used in the event of a future lost dosimeter. The inspector reviewed the purchase order and confirmed that the spare dosimeter was ordered and would be sent with the batch of dosimeters to be used during the next monitoring period.

This is a Severity Level IV violation.

NRC FORM 591M PART 3 U.S. NUCLEAR REGULATORY COMMISSION (07-2012) 10 CFR 2:201  SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION						
1. LICENSEE/LOCATION INSPECTI	ED:		2. NRC/REGIONAL OFFICE			
Acquisition Bell Hospital, d/b/a Bell Hospital 901 Lakeshore Drive Ishpeming, Michigan 498-REPORT NUMBER(S) 20180	49		Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352			
3. DOCKET NUMBER(S)		4. LICENSE NUMBER(	S)	5. DATE(S) OF INSPECTION		
030-13856		21-02037-03		August 23, 2018		
6. INSPECTION PROCEDURES USED		7. INSPECTION FOCUS AREAS				
87131		All				
	SUPPLEM	ENTAL INSPECT	ION INFORMATION			
1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTACT		4. TELEPHONE NUMBER		
02120	3	Todd Botswick, MD - RSO (906) 4		(906) 486-4431		
Main Office Inspec		Next Inspection Date: August 23, 2021				
Field Office Inspection						
Temporary Job Site Inspection						

## **PROGRAM SCOPE**

This was an unannounced routine inspection of a hospital authorized to use byproduct material for diagnostic and therapeutic medical procedures permitted by 10 CFR 35.100, 35.200, and 35.300. The nuclear medicine department was staffed with one full time nuclear medicine technologists (NMT) who performed approximately 40 diagnostic administrations per month, Monday through Friday. The licensee received a Mo/Tc-99 generator every two weeks to prepare doses for diagnostic administrations of Tc-99M. Although authorized, the licensee had not performed any therapeutic administrations of radiopharmaceuticals since the last inspection. The licensee retained the services of a medical physicist consultant to perform annual audits of the radiation safety program.

The inspector toured the nuclear medicine department to evaluate the licensee's measures for materials security, hazard communication, and exposure control. The inspector conducted independent and confirmatory surveys of these facilities and found no residual contamination or exposures to members of the public in excess of regulatory limits. The inspector observed both rest and stress administrations of Tc-99M for a cardiac stress test. Licensee staff also demonstrated and discussed procedures for package receipt, area surveys, spill response, and waste handling. Through these observations and discussions, the inspector found the licensee's staff to be knowledgeable of radiation protection principles.

The inspector reviewed a selection of relevant records, including equipment calibrations, consultant audits, source inventories, molybdenum breakthrough tests, and dosimetry reports.

One violation of NRC requirements, described in Parts 1 and 2 of this report, was identified during this inspection.

ów for ATM 9/10/18