

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL 50-260

REC: OREILLY J P
NRC

ORG: FOX H S
TN VALLEY AUTH

DOCDATE: 02/06/78
DATE RCVD: 02/13/78

DOCTYPE: LETTER NOTARIZED: NO
SUBJECT:

COPIES RECEIVED
LTR 0 ENCL 1

LICENSEE EVENT REPT (RO 50-260/78-1) ON 01/13/78 CONCERNING
SURVEILLANCE SAMPLES TAKEN FROM THE CHARCOAL IN THE UNIT 2 PRIMARY
CONTAINMENT PURGE SYSTEM WERE BELOW TECH SPEC LIMIT.

PLANT NAME: BROWNS FERRY - UNIT 2

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL:

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BRANCH CHIEF SCHWENCER**W/4 ENC

INTERNAL:

REG FILE**W/ENCL

I & E**W/2 ENCL

SCHROEDER/IPPOLITO**W/ENCL

NOVAK/CHECK**W/ENCL

KNIGHT**W/ENCL

HANAUER**W/ENCL

EISENHUT**W/ENCL

SHAO**W/ENCL

KREGER/J. COLLINS**W/ENCL

L. CROCKER**W/ENCL

NRC PDR**W/ENCL

MIPC**W/3 ENCL

HOUSTON**W/ENCL

GRIMES**W/ENCL

BUTLER**W/ENCL

TEDESCO**W/ENCL

BAER**W/ENCL

VOLLMER/BUNCH**W/ENCL

ROSA**W/ENCL

K SEYFRIT/IE**W/ENCL

EXTERNAL:

LPDR'S

ATHENS, AL**W/ENCL

TIC**W/ENCL

NSIC**W/ENCL

ACRS CAT B**W/16 ENCL

COPIES NOT SUBMITTED PER
REGULATORY GUIDE 10.1

DISTRIBUTION: LTR 46 ENCL 46
SIZE: 1P+1P

CONTROL NBR: 780460012

***** THE END *****

004



Faint, illegible text at the top of the page, possibly a header or title.

Two lines of faint, illegible text below the header.

Two lines of faint, illegible text.

A block of faint, illegible text, possibly a paragraph or list.

Two lines of faint, illegible text.

Two lines of faint, illegible text.

Two lines of faint, illegible text on the right side.

Two lines of faint, illegible text.

A vertical column of faint, illegible text on the left side.

A vertical column of faint, illegible text in the center.

Two lines of faint, illegible text on the right side.

Two lines of faint, illegible text in the center.

Two lines of faint, illegible text near the bottom.

Two lines of faint, illegible text near the bottom.


1978 FEB 13 11 11 AM '78
RECEIVED
FEB 13 1978
U.S. NUCLEAR REGULATORY
COMMISSION
REG. SECTION

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

FEB 6 1978

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
230 Peachtree Street, NW., Suite 1217
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 -
DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE
OCCURRENCE REPORT BYRO-50-260/781

The enclosed report provides details concerning surveillance samples which were taken from the charcoal in the unit 2 primary containment purge system following a maintenance outage. This report is submitted in accordance with Browns Ferry unit 2 Technical Specifications, Section 6.7.2.b.(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox
Director of Power Production

Enclosure

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

780460012

A002/S *
0/1

131
The following information was received from the
Office of the Inspector General, Department of
Justice, on 11/10/50.
The information was furnished to the
Office of the Inspector General, Department of
Justice, on 11/10/50.

The following information was received from the
Office of the Inspector General, Department of
Justice, on 11/10/50.
The information was furnished to the
Office of the Inspector General, Department of
Justice, on 11/10/50.

The following information was received from the
Office of the Inspector General, Department of
Justice, on 11/10/50.
The information was furnished to the
Office of the Inspector General, Department of
Justice, on 11/10/50.

The following information was received from the
Office of the Inspector General, Department of
Justice, on 11/10/50.
The information was furnished to the
Office of the Inspector General, Department of
Justice, on 11/10/50.

The following information was received from the
Office of the Inspector General, Department of
Justice, on 11/10/50.
The information was furnished to the
Office of the Inspector General, Department of
Justice, on 11/10/50.

* 2/1000
1/10

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 ALBRF2 00000000000000000000 411111 00
9 14 15 25 26 30 37 CAT 58

01 L 050000260 0111378 0020678 0
80 81 88 89 74 75 80

03 Following a maintenance outage, surveillance samples were taken from the
03 charcoal in the unit 2 primary containment purge system. Analysis of the
04 samples revealed the methyl iodine removal efficiency was 5% below the
05 limit of 85% specified in T.S. 3.7.F.2.b. Redundancy was available by
06 the SGTS. There was no effect on the public health or safety.
07
08

09 SC E X FILTER Z Z
9 10 11 12 13 14 15 16
17 78 001 03 L 0
21 22 23 24 26 27 28 29 30 31 32
18 L/R/O REPORT NUMBER 19 EVENT YEAR 20 CAUSE CODE 21 CAUSE SUBCODE 22 SEQUENTIAL REPORT NO. 23 OCCURRENCE CODE 24 REPORT TYPE 25 REVISION NO.
ACTION TAKEN 26 FUTURE ACTION 27 EFFECT ON PLANT 28 SHUTDOWN METHOD 29 HOURS 30 ATTACHMENT SUBMITTED 31 NPRO-4 FORM SUB. 32 PRIME COMP. SUPPLIER 33 COMPONENT MANUFACTURER
C Z Z Z 000 M N L F L 5 0
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48

10 The primary containment purge system was used to ventilate the drywell
11 during the maintenance outage. Material from activities associated with
12 the outage were adsorbed on the charcoal reducing its ability to remove
13 methyl iodine. New charcoal filters were installed in the system.
14

15 E 0000 NA B Surveillance Testing
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

16 Z Z NA NA
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 0000 Z NA
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 0000 NA
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

19 Z NA
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 Z NA
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER _____ PHONE: _____

7
2012
11
11

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | |
|---------------|---|---|---|---|----------------|---|---|---|---|---|---|---|---|---|--------------|---|---|---|---|-----------|---|---|---|---|
| 01 | A | L | B | R | F | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 0 | 0 |
| LICENSEE CODE | | | | | LICENSE NUMBER | | | | | | | | | | LICENSE TYPE | | | | | 57 CAT 58 | | | | |

| | | | | | | | | | | | | | | | | | | | | | | | |
|---------------|---|---------------|---|---|---|---|---|------------|---|---|---|-------------|---|---|---|---|---|---|---|---|---|---|---|
| 01 | L | 0 | 5 | 0 | 0 | 0 | 2 | 6 | 0 | 7 | 0 | 1 | 1 | 3 | 7 | 8 | 8 | 0 | 2 | 0 | 6 | 7 | 8 |
| REPORT SOURCE | | DOCKET NUMBER | | | | | | EVENT DATE | | | | REPORT DATE | | | | | | | | | | | |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 Following a maintenance outage, surveillance samples were taken from the

03 charcoal in the unit 2 primary containment purge system. Analysis of the

04 samples revealed the methyl iodine removal efficiency was 5% below the

05 limit of 85% specified in T.S: 3.7.F.2.b. Redundancy was available by

06 the SGTS. There was no effect on the public health or safety.

07

08

| | | | | | | | | | | | | | | | |
|----------------------|---|-----------------|---|-----------------------|---|-----------------|---|----------------------|---|------------------|---|----------------------|---|------------------------|--|
| 09 | S | C | E | X | F | I | L | T | E | R | Z | Z | | | |
| SYSTEM CODE | | CAUSE CODE | | CAUSE SUBCODE | | COMPONENT CODE | | | | COMP. SUBCODE | | VALVE SUBCODE | | | |
| 17 | 7 | 8 | 0 | 0 | 1 | 0 | 3 | L | 0 | | | | | | |
| LER/RO REPORT NUMBER | | EVENT YEAR | | SEQUENTIAL REPORT NO. | | OCCURRENCE CODE | | REPORT TYPE | | REVISION NO. | | | | | |
| C | Z | Z | Z | 0 | 0 | 0 | M | N | L | F | 1 | 5 | 0 | | |
| ACTION TAKEN | | EFFECT ON PLANT | | SHUTDOWN METHOD | | HOURS | | ATTACHMENT SUBMITTED | | NPRD-4 FORM SUB. | | PRIME COMP. SUPPLIER | | COMPONENT MANUFACTURER | |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The primary containment purge system was used to ventilate the drywell

11 during the maintenance outage. Material from activities associated with

12 the outage were adsorbed on the charcoal reducing its ability to remove

13 methyl iodine. New charcoal filters were installed in the system.

14

| | | | | | | | | |
|------------------------------------|---|--------------------|----|-------------|--------------------|----|----------------------|--|
| 15 | E | 0 | 0 | 0 | NA | B | Surveillance Testing | |
| FACILITY STATUS | | % POWER | | | OTHER STATUS | | METHOD OF DISCOVERY | |
| 16 | Z | Z | NA | NA | NA | NA | NA | |
| ACTIVITY RELEASED | | CONTENT OF RELEASE | | | AMOUNT OF ACTIVITY | | LOCATION OF RELEASE | |
| 17 | 0 | 0 | 0 | Z | NA | NA | NA | |
| PERSONNEL EXPOSURES NUMBER | | TYPE | | DESCRIPTION | | | | |
| 18 | 0 | 0 | 0 | 0 | NA | NA | NA | |
| PERSONNEL INJURIES NUMBER | | TYPE | | DESCRIPTION | | | | |
| 19 | Z | NA | NA | NA | NA | NA | NA | |
| LOSS OF OR DAMAGE TO FACILITY TYPE | | DESCRIPTION | | | | | | |
| 20 | Z | NA | NA | NA | NA | NA | NA | |
| PUBLICITY TYPE | | DESCRIPTION | | | | | | |

NAME OF PREPARER _____ PHONE: _____

1
m. 1000
- 1 -
7

RECEIVED DOCUMENT
CONTROL DESK

1978 FEB 15 PM 12 00

U.S. NRC
DISTRIBUTION SERVICES
BRANCH