

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

TO: N.C. MOSELEY

FROM: TENNESSEE VALLEY AUTHORITY  
CHATTANOOGA, TENN.  
H.S. FOX

DATE OF DOCUMENT  
9-29-76

DATE RECEIVED  
10-4-76

LETTER  
 ORIGINAL  
 COPY

NOTORIZED  
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

1

DESCRIPTION

LTR. TRANS THE FOLLOWING.....

PLANT NAME: BROWNS FERRY # 2

ENCLOSURE

REPORTABLE OCCURRENCE # 7612, ON 9-4-76,  
CONCERNING TWO ALARMS THAT WERE RECEIVED FROM  
A SMOKE DETECTOR IN THE CONTROL ROOM .....

( 1 SIGNED CY. RECEIVED)  
( 2 PAGES)

**ACKNOWLEDGED**

**DO NOT REMOVE**

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED  
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

SAB 10-5-76

<input checked="" type="checkbox"/> BRANCH CHIEF:	SCHWENCER		
<input checked="" type="checkbox"/> W/3 CYS FOR ACTION			
<input checked="" type="checkbox"/> LIC. ASST.:	SHEPPARD		
<input checked="" type="checkbox"/> W/ CYS			
<input checked="" type="checkbox"/> ACRS 16CYS <del>XXXXXX</del> /SENT TO LA			

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE			
<input checked="" type="checkbox"/> NRC PDR			
<input checked="" type="checkbox"/> I & E (2)			
<input checked="" type="checkbox"/> MIPC			
<input checked="" type="checkbox"/> SCHROEDER/IPPOLITO			
<input checked="" type="checkbox"/> HOUSTON			
<input checked="" type="checkbox"/> NOVAK/CHECK			
<input checked="" type="checkbox"/> GRIMES			
<input checked="" type="checkbox"/> CASE			
<input checked="" type="checkbox"/> BUTLER			
<input checked="" type="checkbox"/> HANAUER			
<input checked="" type="checkbox"/> TEDESCO/MACCARY			
<input checked="" type="checkbox"/> EISENHUT			
<input checked="" type="checkbox"/> BAER			
<input checked="" type="checkbox"/> SHAO			
<input checked="" type="checkbox"/> VOLLMER/BUNCH			
<input checked="" type="checkbox"/> KREGER/J. COLLINS			

EXTERNAL DISTRIBUTION

CONTROL NUMBER

<input checked="" type="checkbox"/> LPDR: ATHENS, ALA.			
<input checked="" type="checkbox"/> TIC:			
<input checked="" type="checkbox"/> NSIC:			

10075



... ..  
... ..  
... ..

... ..  
... ..  
... ..

... ..

... ..

... ..

... ..

... ..  
... ..

... ..




Registry

File Copy

# TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

September 29, 1976



Mr. Norman C. Moseley, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
230 Peachtree Street, NW., 8th Floor  
Atlanta, Georgia 30303

Dear Mr. Moseley:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 -  
DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE  
OCCURRENCE REPORT BPRO-50-260/7612

The enclosed report is to provide details concerning two alarms that were received from a smoke detector in the control room due to increased detector sensitivity. This report is submitted in accordance with Browns Ferry Technical Specifications Section 6. This event occurred on Browns Ferry Nuclear Plant unit 2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox  
Director of Power Production

Enclosure (3)

CC (Enclosure):


Director (3)  
Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Director (40)

Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555


10075

1954



1954







TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

September 29, 1976

Mr. Norman C. Moseley, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
230 Peachtree Street, NW., 8th Floor  
Atlanta, Georgia 30303

Dear Mr. Moseley:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 -  
DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE  
OCCURRENCE REPORT BFRO-50-260/7612

The enclosed report is to provide details concerning two alarms that were received from a smoke detector in the control room due to increased detector sensitivity. This report is submitted in accordance with Browns Ferry Technical Specifications Section 6. This event occurred on Browns Ferry Nuclear Plant unit 2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*H. S. Fox*  
for H. S. Fox  
Director of Power Production

Enclosure (3)

CC (Enclosure):

Director (3)  
Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Director (40)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Handwritten marks and scribbles in the top right corner.

Very faint, illegible text at the top of the page.

First block of faint, illegible text in the upper middle section.

Second block of faint, illegible text in the upper middle section.

Third block of faint, illegible text in the upper middle section.

Fourth block of faint, illegible text in the upper middle section.

Fifth block of faint, illegible text in the upper middle section.

Sixth block of faint, illegible text in the upper middle section.

Seventh block of faint, illegible text in the upper middle section.

Eighth block of faint, illegible text in the upper middle section.



# LICENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--	--	--	--	--

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME: 

01	A	L	B	R	F	2
----	---	---	---	---	---	---

 LICENSE NUMBER: 

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE: 

4	1	1	1	1
---	---	---	---	---

 EVENT TYPE: 

0	3
---	---

CON'T: 

01
----

 CATEGORY: 

--	--

 REPORT TYPE: 

L
---

 REPORT SOURCE: 

L
---

 DOCKET NUMBER: 

0	5	0	-	0	2	6	0
---	---	---	---	---	---	---	---

 EVENT DATE: 

0	9	0	4	7	6
---	---	---	---	---	---

 REPORT DATE: 

--	--	--	--	--	--	--	--	--	--

## EVENT DESCRIPTION

02 Two alarms were received from a smoke detector in the control room due to increased  
03 detector sensitivity. The detector was cleaned after the first alarm and then  
04 replaced after the second alarm. (BFRO-50-260/7612)  
05  
06

SYSTEM CODE: 

A	B
---	---

 CAUSE CODE: 

E
---

 COMPONENT CODE: 

I	N	S	T	R	U
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER: 

L
---

 COMPONENT MANUFACTURER: 

K	1	2	0
---	---	---	---

 VIOLATION: 

N
---

## CAUSE DESCRIPTION

08 Detector failed.  
09  
10

FACILITY STATUS: 

G
---

 % POWER: 

0	0	0
---	---	---

 OTHER STATUS: 

NA
----

 METHOD OF DISCOVERY: 

A
---

 DISCOVERY DESCRIPTION: 

Alarm received in control room
--------------------------------

FORM OF ACTIVITY RELEASED: 

Z
---

 CONTENT OF RELEASE: 

Z
---

 AMOUNT OF ACTIVITY: 

NA
----

 LOCATION OF RELEASE: 

NA
----

## PERSONNEL EXPOSURES

NUMBER: 

0	0	0
---	---	---

 TYPE: 

Z
---

 DESCRIPTION: 

NA
----

## PERSONNEL INJURIES

NUMBER: 

0	0	0
---	---	---

 DESCRIPTION: 

NA
----

## OFFSITE CONSEQUENCES

NA

## LOSS OR DAMAGE TO FACILITY

TYPE: 

Z
---

 DESCRIPTION: 

NA
----

## PUBLICITY

NA

## ADDITIONAL FACTORS

NA

NA

NAME: \_\_\_\_\_ PHONE: \_\_\_\_\_

