A 04/06/08

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL 50-296

REC: OREILLY J P

NRC

ORG: FOX H S

TN VALLEY AUTH

DOCDATE: 03/28/78

DATE RCVD: 04/03/78

DOCTYPE: LETTER

NOTARIZED: NO

COPIES RECEIVED LTR 1 ENCL 1

SUBJECT:

ICCT.

LICENSEE EVENT REPT (RO 50-296/78-004) ON 03/15/78 CONCERNING DURING QUALIFICATION TESTING OF BENDIX ELEC CONNECTORS IDENTICAL TO THOSE USED IN

THE PRIMARY CONTAINMENT, THREE OF FIVE TEST SPECIMENS FAILED DURING SIMULATED

LOCA CONDITIONS... W/ENCL.

PLANT NAME: BROWNS FERRY - UNIT 3

REVIEWER INITIAL: XJM

DISTRIBUTOR INITIAL: W

*********** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS ************

INCIDENT REPORTS (DISTRIBUTION CODE A002)

FOR ACTION:

BR CHIEF LEAR**W/4 ENCL

INTERNAL:

REG FILE**W/ENCL

SCHROEDER/IPPOLITO**W/ENCL

NOVAK/CHECK**W/ENCL

KNIGHT**W/ENCL HANAUER**W/ENCL EISENHUT**W/ENCL

SHAO**W/ENCL

KREGER/J. COLLINS**W/ENCL

K SEYFRIT/IE**W/ENCL

EXTERNAL:

LPDR'S

ATHENS, AL**W/ENCL

TIC**W/ENCL NSIC**W/ENCL

ACRS CAT B**W/16 ENCL

- THE COPY

NRC PDR**W/ENCL MIPC**W/3 ENCL HOUSTON**W/ENCL GRIMES**W/ENCL BUTLER**W/ENCL TEDESCO**W/ENCL BAER**W/ENCL

VOLLMER/BUNCH**W/ENCL

ROSA**W/ENCL

COPIES NOT SUBMITTED PER REGULATORY GUIDE 10.1

DISTRIBUTION: SIZE: 1P+2P+1P

LTR 45

ENCL 45

CONTROL NBR:

780950045

THE END *********************

100°

D, $W_{i}^{2}\left(1, 1, 1, \dots, N_{i} \right)$ 1

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

MAR 28 1978

REGULATORY DOCKET FILE COPY

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 230 Peachtree Street, NW., Suite 1217 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE REPORT BFR0-50-296/784

The enclosed report provides details concerning three of five test specimens which failed during simulated LOCA conditions and during qualification testing of Bendix electrical connectors identical to those used in the primary containment. This report is submitted in accordance with Browns Ferry unit 3 Technical Specification 6.7.2.A.(9).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox Director of Power Production

Enclosure

cc (Enclosure):

Director (3)

Office of Management Information and Program Control

U.S. Nuclear Regulatory Commission

Washington, DC 20555

Director (40)

Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission

Washington, DC 20555

100 N

COMMITTED AT A SHIP AND ASSESSED ASSESSED I CALL THE PERSON & THE BY PERSON OF IT WAS A CARE Bearing their north care in well the H. H. Way of the p RISE WELLES IN TRIVING "THE PUBLIC ROUNCES FROM Exist of the way of the Flats

ANT BURN A SACE THE

THE PARTY OF A BUT MANAGER TWO TEACHER AND THE ARREST AND A STREET AND TO BE PROPERTY OF THE STATE OF MELTING TO STATE OF THE ST Compagning that the season of the

The encioned mount proved has shall concerning along the force course of any martialisms and experience makes to the complete one can be expected. go it is an in the time of the affect that the characters is the citaria to ar formation are the presence of their meaning of the compart the second THE STATE OF THE PROPERTY OF STATE STATES AND A STATE OF THE STATES OF T

Jugge + 48 178 1 38

morando de foite fraction

A Thirten I al T

· (orangia II) aa

(B) MODREY!

Prince of Francis is the Information and Francisco Surveyor CORRECT BY THE TO MAN AR BETT SOL MAN OF SORE . TO BE The said and the

Branchos (M)

Office of Laurechton and Thiographically and altered projectings winter will be

the ready no wisss


NAME OF PREPARERL

7.5	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	A L B F R 3 2 0 0 - 0 0 0 0 - 0 0 4-1 A DATE OF THE LOCAL SECOND STATES OF
CON'T	REPORT L 6 0 5 0 0 0 2 9 6 7 0 3 1 5 7 8 8 0 3 2 8 7 8 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	During qualification testing of Bendix electrical connectors
03	identical to those used in the primary containment, three of five
04	test specimens failed during simulated LOCA conditions. There
0 5	was no effect on the public health or safety since this was
06	a laboratory test.
07	<u> </u>
08	
	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC
	COMPONENT COMP
10	$\frac{ F }{33} \frac{ B }{34} \frac{ Z }{49} = \frac{ A }{35} \frac{ Z }{36} = \frac{ A }{36} \frac{ Z }{37} = \frac{ D }{40} \frac{ A }{41} \frac{ Z }{42} = \frac{ A }{42} \frac{ Z }{43} = \frac{ A }{41} \frac{ Z }{43} = \frac{ A }{43} \frac{ Z }{44} = \frac{ A }{47} \frac{ Z }{43} = \frac{ A }{47} = A$
	shorted between pins on the unpotted side. The short was caused by the entry of
12	moisture through the grommet on the rear of the connector. The connectors in the
1 3	primary containment, applicable to the safety systems required to be operational
· 114	during a LOCA, were potted with 3M Scotchcast. The potted connectors were qualified
1 5 7 8	ACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 Z 28 0 9 5 29 N.A. C 31 During special test 9 10 12 13 44 45 46 80
1 6 RE	LEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) N.A. N.A. N.A. SO PERSONNEL EXPOSURES
1 7 7 8	NUMBER TYPE DESCRIPTION (39) 0 0 0 37 Z 38 N.A.
1 8	NUMBER DESCRIPTION (1) O O O (40) N.A.
1 9	9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION LZ 42 N.A. 9 10 80
, , , 20 '	PUBLICITY SSUED DESCRIPTION 45 NRC USE ONLY NRC USE ONLY NRC USE ONLY NRC USE ONLY
7 8	9 10

PHONE:-

Cause Description and Corrective Actions (Continued)

by laboratory test.



BFR0-50-296/784

Report Number : BFRO-50-296/784

Report Date : March 28, 1978

Occurrence Date: March 15, 1978

Facility : Browns Ferry Nuclear Plant Unit 3

Identification of Occurrence

Three Bendix electrical connectors, P/N 10-214036-78p, failed qualification testing at Wyle Laboratories. The test specimens were the same type connectors as those presently used in primary containment.

Conditions Prior to Occurrence

Unit at approximately 95-percent power.

Description of Occurrence

Pin-to-pin shorts occurred in connectors during simulated LOCA conditions.

Designation of Apparent Cause of Occurrence

Moisture entered the rear of the connectors through the grommets. This moisture, combined with impurities, caused pin-to-pin shorts.

Analysis of Occurrence

Test results indicated that identical connectors used in primary containment could possibly fail during a LOCA. The unit was removed from service for corrective action. Since this test was conducted in a laboratory, no effects existed upon public health or safety.

Corrective Action

Connectors in primary containment were potted with 3M Scotchcast to provide an adequate seal against moisture. The potted connectors were qualified by laboratory test.