

Entergy Operations, Inc. 1448 S.R. 333 Russellville, AR 72802 Tel 479-858-4704

Stephenie L. Pyle Manager – Regulatory Assurance Arkansas Nuclear One

10 CFR 50.73

1CAN111805

November 16, 2018

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555-0001

- Subject: Licensee Event Report 50-313/2018-002-01 Arkansas Nuclear One, Unit 1 Docket No. 50-313 License No. DPR-51
- Reference: Entergy letter dated August 10, 2018, "Licensee Event Report 50-313/2018-002-00, "Leak in Class 1 Reactor Coolant System Pressure Boundary Piping due to Cyclic Fatigue Failure on a High Pressure Injection Line Drain Tap Weld" (1CAN081804) (ML18222A210)

Dear Sir or Madam:

Pursuant to the reporting requirements of 10 CFR 50.73, attached is a supplement to Licensee Event Report 50-313/2018-002-00 (reference) concerning a leak in Class 1 Reactor Coolant System Pressure Boundary piping at Arkansas Nuclear One, Unit 1. This supplement is being submitted to update the reportability criteria related to the subject event.

There are no new commitments contained in this submittal.

Should you have any questions concerning this issue, please contact me at 479-858-4704.

Sincerely,

ORIGINAL SIGNED BY STEPHENIE L. PYLE

SLP/dkb

Attachment: Licensee Event Report 50-313/2018-002-01

1CAN111805 Page 2 of 2

cc: Mr. Kriss Kennedy Regional Administrator U. S. Nuclear Regulatory Commission Region IV 1600 East Lamar Boulevard Arlington, TX 76011-4511

> NRC Senior Resident Inspector Arkansas Nuclear One P.O. Box 310 London, AR 72847

Institute of Nuclear Power Operations 700 Galleria Parkway Atlanta, GA 30339-5957 <u>LEREvents@inpo.org</u>

NRC FC	ORM 36	6 U	I.S. NUCL	LEAR REGU	LATORY	СОММІЗ	SION	APPF	OVED	BY OMB: NO. 3	150-0104		EXPIRE	S: 03/31/2020	
(02-2018) (See	NURE	L (Se G-1022, R.3 <u>w.nrc.gov/re</u>	ICENS e Page 2 for for instruc ading-rm/	SEE EVEI	NT REP or of digits/cha ance for c as/nuregs/s	PORT (aracters for ompleting staff/sr10	each block this forr 22/r3/)	Estima Report Send (to Info Affairs numbe inform	ted burd ed lessor comments (T-5 F5 collects.R NEOB-1 used to r, the NF ation colle	en per response to ns learned are incol s regarding burden 3), U.S. Nuclear Reg Resource@nrc.gov, a 0202, (3150-0104), (impose an informal RC may not conduct sction.	o comply with this rporated into the lice estimate to the FC gulatory Commission, ind to the Desk Offin Office of Management ion collection does r or sponsor, and a p	mandatory co nsing process DIA, Privacy a Washington, I cer, Office of t and Budget, not display a person is not	llection re s and fed and Inform DC 20555 Information Washington currently required	equest: 80 hours. back to industry. nation Collections -0001, or by e-mail on and Regulatory on, DC 20503. If a valid OMB control to respond to, the	
1. FACI	LITY N	AME						2. DO	CKET	NUMBER		3	. PAGE		
Arka	ansas	Nuclear	One, l	Jnit 1						05000-	313		1	OF 5	
4. TITLI Le Pr	≡ eak in essu	Class 1 re Injectio	Reacto on Line	or Coolan 9 Drain Ta	t Syste ap Weld	m Pre: ป	ssure	Bounda	ary Pi	iping due to	o Cyclic Fat	igue Fa	ilure	on a High	
5. I	EVENT	DATE	6. L	ER NUMBEI	र	7.	REPOR	T DATE		8. (OTHER FACILI	FIES INVO	LVED		
MONTH	DAY	YEAR	YEAR	SEQUENTIA NUMBER	REV NO.	MONTH	DAY	YEAR	FACIL N/A	ITY NAME			DOCKE	T NUMBER	
06	12	2018	2018	002	01	11	16	2018	FACIL	ITY NAME			DOCKE	T NUMBER	
9. OPERATING MODE 11. THIS REPORT IS SUBMITTED PURSUANT				TO THE F	REQUIR	EMENTS OF 10	CFR §: (Check a	ll that apply)						
3		20.2201(b)			20	.2203(a)	(3)(i)		🖾 50.73(a)(2)(ii)(A)	□ 50.	73(a)(2)(viii)(A)		
		20.2201(d)			20	20.2203(a)(3)(ii)			🗌 50.73(a)(2)(ii)(B)	□ 50.	73(a)(2)(viii)(B)		
			20.2	2203(a)(1)		20	.2203(a)	(4)		🗌 50.73(a)(2)(iii)	□ 50.	73(a)(2)(ix)(A)	
			20.2	2203(a)(2)(i)		50	.36(c)(1)	(i)(A)		🗌 50.73(a)(2)(iv)(A)	□ 50.	73(a)(2)(x)	
10. PO	WER L	EVEL	20.2203(a)(2)(ii)			□ 50	.36(c)(1)	(ii)(A)		🗌 50.73(a)(2)(v)(A)	□ 73.	71(a)(4)	
			20.2	2203(a)(2)(iii)		50	.36(c)(2)			🗌 50.73(a)(2)(v)(B)	□ 73.	71(a)(5)	
	00/	,	□ 20.2203(a)(2)(iv) □ 20.2203(a)(2)(v) □ 20.2203(a)(2)(vi)			□ 50.46(a)(3)(ii) □ 50.73(a)(2)(i)(A) ⊠ 50.73(a)(2)(i)(B)		(ii)		□ 50.73(a)(2)(v)(C)		□ 73.	_ 73.77(a)(1)		
	0%	0						(i)(A)	())(v)(D)	73.		.77(a)(2)(i)	
								(i)(B)		□ 50.73(a)(2)(vii) □ 73		73.	3.77(a)(2)(ii)		
			□ 50.73(a			.73(a)(2)	(i)(C))(C) OTHER Specify in Abstract below or in NRC Form 366A				66A			
		х т			12	LICENS	SEE CON	NTACT FO	OR THI	S LER			uda Arra	Cadal	
Stent		, Pvle M	anader	Regulator	N Assur	ance					(479) S	1100101ER (Incl 158-4704	uae Area	code)	
Otopi		∟. i yi0, ivi	13.		ONE LINE	FOREAC	HCOMP	ONENT F	AILURE	DESCRIBED IN	THIS REPORT				
CAU	SE	SYSTEM	COMF		MANU- CTURER	REPOR TO ICI	TABLE	CAUS	E	SYSTEM	COMPONENT	MANU FACTUR	- I ER	REPORTABLE TO ICES	
В		BQ	١	N/A	N/A	Y	'	N/	A	N/A	N/A	N/A		N/A	
14. SUP	PLEM	ENTAL REP		PECTED		1				15. EX	PECTED	MONTH	DAY	YEAR	
	YES (If	yes, comple	te 15. EXI	PECTED SU	BMISSION	I DATE)		N N	С	SUE	MISSION	N/A	N/A	N/A	

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On June 12, 2018, while in Mode 3 and investigating leakage at Arkansas Nuclear One, Unit 1, a leak was identified on a drain line associated with one of the four High Pressure Injection lines which discharge to the Reactor Coolant System (RCS). The subject leak was identified during a walk down of Reactor Building structures, systems, and components initiated in response to an elevated RCS leak rate. The leak was a result of a cyclic fatigue failure originating from poor weld geometry and grinding marks present on the axial weld toe of the associated field weld. The leak was subsequently repaired and the unit returned to power operation. The corrective action plan addressed the causal factors associated with this event.

Corrective actions completed or planned include 1) similar locations were inspected for weld defects, 2) enhanced training of the specific weld type, and 3) planned mockups for future high risk / high value welds. This event had no effect on the public health and safety. The event was reported to the Nuclear Regulatory Commission on June 12, 2018, via Event Notification 53456.

NRC FORM 366A (04-2017)	U.S. NUCLEAR REGULATO	RY COMMISSION REPORT (LER) SHEET	APPROVED BY OMB: NO. 3150-01 Estimated burden per response to comp Reported lessons learned are incorporated Send comments regarding burden estima Branch (T-5 F53), U.S. Nuclear Regulatory to Infocollects Resource@nrc.gov, and to t	04 Iy with this mar into the licensir te to the FOIA, Commission, Wa be Desk Officer	EXPIRES: 3/ adatory collection request ng process and fed back Privacy and Information shington, DC 20555-0001, Office of Information and	t: 80 hours. to industry. Collections or by e-mail
(See NUREG-1022 http://www.nrc.gov/n	, R.3 for instruction and guidance for reading-rm/doc-collections/nuregs/s	or completing this form staff/sr1022/r3/)	Affairs, NEOB-10202, (3150-0104), Office of means used to impose an information coll number, the NRC may not conduct or spo information collection.	Management an ection does not nsor, and a pers	d Budget, Washington, DC display a currently valid on is not required to res	OMB control
1. FACILITY NAM	E	2. DOCKET NU	JMBER		3. LER NUMBER	
Arkansas	Nuclear One, Unit 1	()5000-313	YEAR	SEQUENTIAL NUMBER	REV NO.

2018

- 002

- 01

NARRATIVE

A. Plant Status

At the time this condition was identified, Arkansas Nuclear One, Unit 1 (ANO-1), was in Mode 3 performing a hot shutdown walkdown on a High Pressure Injection (HPI) [BQ] line to Reactor Coolant System (RCS) [AB] drain line near two HPI drain valves. No structures, systems or components (SSCs) were out of service at the time of this event that contributed to this event.

B. Background

Four separate HPI lines are used to supply makeup and cooling water to the ANO-1 RCS when required. After entering the Reactor Building, each line first contains a stop check valve, followed by a swing check valve, and finally a normally open manual isolation valve before reaching the RCS. Various drain and vent taps are installed in these lines near the two check valves.

The drain tap identified as having a leak in a weld was located on one of the two Loop A HPI lines between the respective stop check valve and swing check valve. The drain line contained two in-series, normally closed drain isolation valves.

Because the swing check valve is downstream of the subject drain tap, any leakage from the drain tap is expected to be HPI fluid. With HPI in operation, HPI pressure would be greater than RCS pressure. With HPI not in operation and given a leak at this drain location, the pressure at the leak point would be less than RCS pressure, causing the downstream swing check valve to seat (effectively isolating the leak path from the RCS).

The subject leak was identified during a walk down of Reactor Building SSCs following a plant shutdown due to elevated RCS leak rate. The leak was located on the drain tap between the main HPI line and the first in-series drain valve. The leak was specifically identified as a through-wall linear indication on the pipe stub and socket weld toe between the sockolet and drain valve MU-1066A.

C. Event Description

To resolve previously identified deficiencies associated with the subject two drain line valves, the valves were replaced in the Spring 2018 refueling outage. The valves were replaced with an equivalent valve and physical configuration. The majority of the welds for this modification package were completed in the fabrication shop, with only the final weld completed in the field. A qualified weld examination and liquid penetrant examination were performed at the completed field weld in the as-welded condition.

NRC FORM 366A (04-2017)	U.S. NUCLEAR REGULATO	RY COMMISSION	APPROVED BY OMB: NO. 3150-01	04 Iv with this mar	EXPIRES: 3	8/31/2020
(See NUREG-1022	LICENSEE EVENT R CONTINUATION	REPORT (LER) SHEET or completing this form staff/sr1022/r3/)	Reported lessons learned are incorporated Send comments regarding burden estima Branch (T-5 F53), U.S. Nuclear Regulatory to Infocollects.Resource@nrc.gov, and to tt Affairs, NEOB-10202, (3150-0104), Office of means used to impose an information coll number, the NRC may not conduct or spo information collection.	into the licensin te to the FOIA, Commission, Wa he Desk Officer, Management an ection does not nsor, and a pers	process and fed back privacy and Informatio shington, DC 20555-0001 Office of Information ar d Budget, Washington, D display a currently valid on is not required to re-	k to industry. n Collections l, or by e-mail d Regulatory C 20503. If a OMB control spond to, the
1. FACILITY NAM	E	2. DOCKET NU	JMBER		3. LER NUMBER	
Arkansas Nuclear One Unit 1			5000.040	YEAR	SEQUENTIAL NUMBER	REV NO.
Arransas		(15000-313	2018	- 002	- 01

NARRATIVE

On May 13, 2018, an elevated RCS leak rate was documented after reaching near operating pressure and temperature during initial plant heat up from the Spring 2018 refueling outage. The leak rate was closely monitored for adverse trends. On June 1, 2018, the RCS leak rate increased. On June 5, 2018, the estimated fill rate of the Reactor Building sump was 0.172 gallons per minute (gpm) and the RCS loss leak rate was calculated to be 0.346 gpm (note that the ANO-1 Technical Specification limit for unidentified leakage is \leq 1 gpm). Chemistry sample results of the Reactor Building sump inventory were inconclusive as to the source of the leak. Multiple Reactor Building entries were performed over a three-day period which identified water leaking to the floor from the "D" Reactor Coolant Pump cavity.

Following the decision by the site to shutdown the unit and locate the source of the leak, the aforementioned drain tap on the Loop A HPI line to the "C" RCS cold leg was found leaking at a welded connection.

The leak was isolated and repaired. The drain valves were permanently removed and the drain stack was replaced with a plug.

D. Event Cause

The direct cause of the event was a cyclic fatigue failure originating from poor weld geometry and grinding marks present on the axial weld toe of the field weld.

Four causal factors of this event were identified:

- 1. The welds were not performed in accordance with the Entergy fleet general weld standard and the welder administrative training provided by the site. The welds were performed by qualified supplemental (contract) personnel.
- 2. The Entergy fleet visual examination procedure for American Society of Mechanical Engineers (ASME) piping weld joints has clear acceptance criteria for weld geometry and the presence of grinding marks on the axial toe of the weld, which should have resulted in the weld being rejected. The examinations were performed by qualified supplemental (contract) personnel.
- 3. Qualified welders and examiners did not follow the Entergy fleet's general welding standard guidance and the examination procedure acceptance criteria. The welds were performed by and inspected by qualified supplemental (contract) personnel.
- 4. While the initiation site for the weld crack was found to be at a weld grinding mark, the system induced vibrations contributed to the through wall growth of the crack.

NRC FORM 366A	U.S. NUCLEAR REGULATO	RY COMMISSION	APPROVED BY OMB: NO. 3150-01	04	EXPIRES: 3	8/31/2020
(See NUREG-1022	LICENSEE EVENT R CONTINUATION	REPORT (LER) SHEET or completing this form staff/sr1022/r3/)	Estimated burden per response to comp Reported lessons learned are incorporated Send comments regarding burden estima Branch (T-5 F53), U.S. Nuclear Regulatory to Infocollects.Resource@nrc.gov, and to t Affairs, NEOB-10202, (3150-0104), Office of means used to impose an information coll number, the NRC may not conduct or spo information collection.	ly with this mar into the licensir te to the FOIA, Commission, Wa he Desk Officer, Management an ection does not nsor, and a pers	datory collection reques g process and fed back Privacy and Information shington, DC 20555-0001 Office of Information and Budget, Washington, D display a currently valid on is not required to res	st: 80 hours. k to industry. n Collections , or by e-mail nd Regulatory C 20503. If a OMB control spond to, the
1. FACILITY NAM	E	2. DOCKET NU	JMBER		3. LER NUMBER	
Arkansas Nuclear One Unit 1				YEAR	SEQUENTIAL NUMBER	REV NO.
Airansas		(15000-313	2018	- 002	- 01

NARRATIVE

E. Corrective Actions

The following actions have been completed:

- The direct cause was addressed by installing a welded plug at the sockolet location and removing the drain valves from the system.
- With respect to the potential extent of condition, the remaining drain/vent valves in the subject area of the HPI injection lines were examined prior to reactor restart.
- Qualifications were suspended for the personnel performing the weld during the Spring 2018 refueling outage.
- Added requirements to perform a proficiency mockup for high risk / high value welds.
- Enhanced the training requirements associated with the weld qualification program.

The following actions associated with the listed contributing causes are currently planned and captured in the corrective action program:

- Senior site management to perform a stand down with site and contract welding organizations and the visual examiners to communicate this failure and the importance of following the guidance in the general welding standard. In addition, management will communicate the requirement and importance of complying with standards, including procedural adherence and quality workmanship.
- Acceptance criteria for weld examination will be reinforced as part of the oversight plan briefing communicated by responsible Non-Destructive Examination (NDE) oversight for contract examiners.
- An Entergy welding supervisor weld inspection hold point will be implemented prior to NDE visual examinations on high risk / high value welds.
- A project plan will be proposed to study "C" HPI system vibrations.
- F. Safety Significance Evaluation

Systems and components required to shutdown the reactor, maintain safe shutdown conditions, remove residual heat, and control the release of radioactive material were available at the time that this condition was discovered.

NKC FURM 366A	U.S. NUCLEAR REGULATO	RY COMMISSION	APPROVED BY OMB: NO. 3150-01	04	EXPIRES: 3	/31/2020		
(See NUREG-1022, http://www.nrc.gov/r	LICENSEE EVENT F CONTINUATION R.3 for instruction and guidance fr eading-rm/doc-collections/nuregs/s	REPORT (LER) SHEET	Estimated burden per response to comply with this mandatory collection request: 80 Reported lessons learned are incorporated into the licensing process and fed back to Send comments regarding burden estimate to the FOIA, Privacy and Information CC Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or to to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Re Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20 means used to impose an information collection does not display a currently valid OME number, the NRC may not conduct or sponsor, and a person is not required to response information collection.					
1. FACILITY NAME		2. DOCKET N	JMBER		3. LER NUMBER			
Arkansas Nuclear One, Unit 1		05000-313		YEAR	SEQUENTIAL NUMBER	REV NO.		
				2018	- 002	- 01		
NARRATIVE								
Four separa signal suppl Flooding Ta were no acti	te HPI lines per train an y cooling water to the A nks are capable of prov ual consequences relate	e automatically a NO-1 RCS. One iding 100 percen ed to the subject	ligned upon receipt of an train of HPI and one train t of the necessary core in event with regards to nuc	Engineer n of LPI a ijection.	red Safeguard long with the Therefore, the ublic safety.	s Core re		

An eight-hour non-emergency notification was reported to the NRC via Event Notification 53456 on June 12, 2018. The basis for that notification was the requirements listed in 10 CFR 50.72(b)(3)(i)(A) and 10 CFR 50.72(b)(3)(v)(A).

The guidance in NUREG 1022 states that an LER is required. This event is reportable pursuant to the following criteria:

10 CFR 50.73(a)(2)(ii)(A) Any event or condition that resulted in:

The condition of the nuclear power plant, including its principle safety barriers, being seriously degraded.

Although the source of the RCS leakage was identified on June 12, 2018, it is assumed that the leak likely began on March 13, 2018, when the RCS leak rate increased. Once the source of the leak was identified, both the RCS and the affected HPI train were declared inoperable. Assuming the leak initiated on March 13, 2018, the unit was not shutdown within a timeframe commensurate with applicable TS requirements. Therefore, this event is also reportable pursuant to the following criteria:

10 CFR 50.73(a)(2)(i)(B) Any operation or condition which was prohibited by the plant's Technical Specifications

H. ADDITIONAL INFORMATION

10 CFR 50.73(b)(5) states that this report shall contain reference to "any previous similar events at the same plant that are known to the licensee." NUREG 1022 reporting guidance states that term "previous occurrences" should include previous events or conditions that involved the same underlying concern or reason as this event, such as the same cause, failure, or sequence of events.

A review of the ANO corrective action program and LERs. No similar events were identified during the previous three years.

Energy Industry Identification System (EIIS) codes and component codes are identified in the text of this report as [XX].