



**Consumers
Power
Company**


ASB

slb

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • (517) 788-0550

January 26, 1981

Mr James G Keppler
Office of Inspection and Enforcement
Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60127



DOCKET 50-255 - DPR-20 - PALISADES PLANT -
LICENSEE EVENT REPORT 81-002 - INADEQUATE
MOUNTING OF DC DISTRIBUTION PANEL

On the reverse side is LER 81-002 which is reportable under Technical Specifications 6.9.2.B(2).

David P Hoffman
Nuclear Licensing Administrator

CC Director, Office of Nuclear Reactor Regulation
Director, Office of Inspection and Enforcement
NRC Resident Inspector, Palisades Plant

*A002
S/11*

JAN 28 1981

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M I P A L L 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 _____ 5

CON'T 01 REPORT SOURCE L 6 0 5 0 0 0 2 5 5 7 0 1 1 0 8 8 1 8 0 1 2 6 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During post installation review of fire protection modifications, it was
03 determined that 125 volt DC distribution panel D21A was not adequately
04 mounted in terms of meeting seismic restraint criteria. The redundant panel
05 D-11A was properly mounted. The loads supplied by the panel (1-2 Diesel
06 Gen. and 2400V Bus 1D) were declared inoperable; repairs were initiated &
07 completed within time required by ICO of TS 3.7.2c. No threat to public
08 health or safety existed.

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
E C 11 B 12 A 13 S U P P O R T 14 X 15 Z 16

17 LER/RO REPORT NUMBER 8 1 0 0 2 0 3 L 0
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
B 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 A 25 N 3 5 5 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The seismically qualified panel was mounted on a field fabricated frame
11 which was insufficiently braced. The apparent cause was incorrect
12 engineering judgement by A/E during project design. To satisfy seismic
13 restraint criteria, frame was modified by addition of braces.

14 _____

15 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
F 28 0 9 8 29 NA 30 D 31 Notification by AE 32

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z 33 Z 34 NA 35 NA 36

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 0 37 Z 38 NA 39

18 PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 0 40 NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z 42 NA 43

20 PUBLICITY ISSUED DESCRIPTION
N 44 NA 45

NRC USE ONLY