
Frederick W. Schneider Vice President Production Public Service Electric and Gas Company 80 Park Place Newark, N.J. 07101 201/622-7000



LICENSE NO. DPR-70 DOCKET NO. 50-272 REPORTABLE OCCURRENCE 77-02/3L

Pursuant to the requirements of Salem Generating Station Unit No. 1 Technical Specifications, Section 6.9.1, we are submitting Licensee Event Report for Reportable Occurrence 77-02/3L. This report is required within thirty (30) days of the occurrence.

Sincerely yours,

CC: Director, Office of Inspection and Enforcement (30 copies) Director, Office of Management Information and Program Control (3 copies)

1033

Report Number: Report Date: Occurrence Date: Facility

Salem Generating Station Public Service Electric & Gas Company Hancocks Bridge, New Jersey 08038

IDENTIFICATION OF OCCURRENCE:

Pipe failure on letdown vent line.

7-02/3L

1/12/77 1/03/77

CONDITIONS PRIOR TO OCCURRENCE:

Mode 3 operation, Plant pressure 2235 psig, Plant temperature 547°F.

DESCRIPTION OF OCCURRENCE:

No. 15 Containment Fan Coil Unit leak detection system alarmed and containment humidity increased. Normal letdown was in service. The containment sump pumps started and makeup to the VCT increased. Letdown flow indicated zero while charging flow was normal. Normal letdown was isolated and excess letdown initiated. All indications of a RCS leak terminated. Investigation revealed a pipe break in the letdown vent line ahead of valve 1CV396. Approximately 2400 gallons of reactor coolant spilled in the 78' elevation of the containment and drained into the containment sump.

DESIGNATION OF APPARENT CAUSE OF OCCURRENCE:

Excessive vibration of the 3/4" vent line caused the pipe to shear downstream of the joint to the main letdown line.

ANALYSIS OF OCCURRENCE:

Airborne activity in the reactor containment was less than the maximum permissible concentration. The spilled coolant drained into the containment sump and was pumped to the waste holdup tanks for processing. The leak rate was reduced to less than the Technical Specification limit of paragraph 3.4.1.2 within the allowed time and all action statements were cancelled. At no time was there any danger to the general public or site personnel.

CORRECTIVE ACTION:

The 3/4" letdown vent line was removed. The remaining socket was plugged and welded. NDE was performed on the new weld and the system was hydrostatically tested. Ten similar vent lines in the CVC System were identified and NDE was performed on the 3/4" to header welds. No indications were identified. Report No. 77-02/3L 1/12/77 Page 2

FAILURE DATA:

Pipe: 3/4" Schedule 40 ASTM A-403 TP-304

Prepared by	Т.	Spencer	
SORC Meeting	No.	8-77	

Manager - Salem Generating Station

LICENSEE EVENT REPORT

