

Frederick W. Schneider
Vice President
Production

Public Service Electric and Gas Company 80 Park Place Newark, N.J. 07101 201/622-7000

May 10, 1977

REGULATORY DOCKET FILE COPY



Mr. James P. O'Reilly
Director of USNRC
Office of Inspections and Enforcements
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

LICENSE NO. DPR-70
DOCKET NO. 50-272
REPORTABLE OCCURRENCE 77-23/3L

Pursuant to the requirements of Salem Generating Station Unit No. 1 Technical Specifications, Section 6.9.1, we are submitting Licensee Event Report for Reportable Occurrence 77-23/3L. This report is required within thirty (30) days of the occurrence.

Sincerely yours,

A handwritten signature in cursive script, appearing to read "F. W. Schneider".

RSS:

CC: Director, Office of Inspection
and Enforcement (30 copies)
Director, Office of Management
Information and Program Control
(3 copies)
Manager - Nuclear Operations
Manager - Salem Gen. Station
Manager - Quality Assurance
Station QA Engineer

771360130

Report Number: 77-23/3L
Report Date: 4/14/77
Occurrence Date: 4/12/77
Facility: Salem Generating Station
Public Service Electric & Gas Company
Hancocks Bridge, New Jersey 08038

IDENTIFICATION OF OCCURRENCE:

Inoperable Boron Injection Tank

CONDITIONS PRIOR TO OCCURRENCE:

Unit in Mode 3, recovering from Reactor Trip/Safety Injection.

DESCRIPTION OF OCCURRENCE:

Following a Reactor Trip/Safety Injection, the Boron Injection Tank was declared inoperable due to the Boron concentration being below the minimum concentration allowed by the Technical Specifications, LCO 3.5.4.1.

DESIGNATION OF APPARENT CAUSE OF OCCURRENCE:

Loss of Boron Concentration was caused by a High Steam line flow coincident with low Tave Safety Injection.

ANALYSIS OF OCCURRENCE:

The Boron Injection Tank was returned to an operable status within the time allowed by Technical Specifications. At no time was there any danger to the general public or site personnel.

CORRECTIVE ACTION:

Emergency Instruction I-4.2 was implemented and the boron concentration in the Boron Injection Tank was returned to within the Technical Specification values. Boron samples confirmed operability.

FAILURE DATA:

Not applicable.

Prepared by T. L. Spencer

SORC Meeting No. 43-77

N. J. Hiller
Manager - Salem Generating Station

LICENSEE EVENT REPORT

CONTROL BLOCK

LICENSEE NAME	LICENSE NUMBER	LICENSE TYPE	EVENT TYPE
01 NJISGISL	00-000000-00	411111	01

REPORT TYPE	REPORT SOURCE	DOCKET NUMBER	EVENT DATE	REPORT DATE
01 CONT	PIO	L	050-0272	041277

EVENT DESCRIPTION

02 During Mode 3, the BIT was declared inoperable due to Boron concentration
 03 being below the required Tech Spec value. The BIT is a passive component
 04 common to both ECCS subsystems, therefore, no redundant component was
 05 available. Boron concentration was re-established and the BIT declared
 06 inoperable. This is the 6th event of this type. (77-23/3L)

SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
07 SF	A	XXXXXX	Z	Z999	N

CAUSE DESCRIPTION

08 The cause of this event was a Safety Injection that diluted the BIT boron
 09 concentration below that allowed by Technical Specifications.

10

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11 G	000	N/A	a	N/A

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
12 Z	Z	N/A	N/A

PERSONNEL EXPOSURES	NUMBER	TYPE	DESCRIPTION
13	000	Z	N/A

PERSONNEL INJURIES	NUMBER	DESCRIPTION
14	000	N/A

15 OFFSITE CONSEQUENCES
N/A

LOSS OR DAMAGE TO FACILITY	TYPE	DESCRIPTION
16	Z	N/A

17 PUBLICITY
N/A

18 ADDITIONAL FACTORS

19

NAME: T. L. Spencer PHONE: (609) 365-7000 Ext. Salem- 528