


REGULATORY DOCKET FILE COPY

VIRGINIA ELECTRIC AND POWER COMPANY

RICHMOND, VIRGINIA 23261

September 15, 1977



Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region II - Suite 818
230 Peachtree Street, Northwest
Atlanta, Georgia 30303

Serial No. 410
PO&M/TAP:dgt
Docket No. 50-280

License No. DPR-32

Dear Mr. O'Reilly:

Pursuant to Surry Power Station Technical Specification 6.6.2, the Virginia Electric and Power Company hereby submits a copy of Reportable Occurrence No. RO-S1-77-15.

The substance of this report has been reviewed by the Station Nuclear Safety and Operating Committee and will be placed on the agenda for the next meeting of the System Nuclear Safety and Operating Committee.

Very truly yours,

A handwritten signature in cursive script that reads "C. M. Stallings".

C. M. Stallings
Vice President-Power Supply
and Production Operations

Enclosures

40 copies RO-S1-77-15

cc: Mr. Robert W. Reid, Chief
Operating Reactors Branch 4

772620115

LICENSEE EVENT REPORT

CONTROL BLOCK: [][][][][][]

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: [0] [1] [V] [A] [S] [P] [S] [1] [14] | LICENSE NUMBER: [0] [0] [-] [0] [0] [0] [0] [0] [-] [0] [0] [25] | LICENSE TYPE: [4] [1] [1] [1] [0] [26] | EVENT TYPE: [0] [1] [32]

CATEGORY: [0] [1] [CONT] [57] | P [P] [58] | Q [Q] [58] | REPORT TYPE: [L] [58] | REPORT SOURCE: [L] [60] | DOCKET NUMBER: [0] [5] [0] [-] [0] [2] [8] [0] [68] | EVENT DATE: [0] [8] [1] [8] [7] [7] [69] | REPORT DATE: [0] [9] [1] [4] [7] [7] [80]

EVENT DESCRIPTION

[0] [2] | During normal operation, while exercising control rods, a flux tilt in excess of 2% occurred when control rod J-13 shutdown Bank A was dropped. Unit power was reduced to a level required by Technical Specification 3.12.B.6 for operation with excessive tilt. Neutron flux setpoints were correspondingly reduced. This condition is reportable per Technical Specification 6.6.2.b.(2). (R0-S1-77-15)

SYSTEM CODE: [Z] [Z] [10] | CAUSE CODE: [E] [11] | COMPONENT CODE: [C] [O] [N] [R] [O] [D] [17] | PRIME COMPONENT SUPPLIER: [N] [43] | COMPONENT MANUFACTURER: [C] [7] [2] [0] [44] | VIOLATION: [N] [48]

CAUSE DESCRIPTION

[0] [8] | The rod dropped due to loss of power to the stationary grip coil of the CRDM. The power loss was traced to a loose pin in the cable-to-CRDM electrical connector.

[1] [0] | With the unit shutdown, the pin was tightened and normal operation of (Continued)

FACILITY STATUS: [E] [9] | % POWER: [1] [0] [0] [10] | OTHER STATUS: [N/A] [13] | METHOD OF DISCOVERY: [A] [44] | DISCOVERY DESCRIPTION: [Observation of Instruments Movement] [46]

FORM OF ACTIVITY RELEASED: [Z] [9] | CONTENT OF RELEASE: [Z] [10] | AMOUNT OF ACTIVITY: [N/A] [44] | LOCATION OF RELEASE: [N/A] [45]

PERSONNEL EXPOSURES

[1] [3] | NUMBER: [0] [0] [0] [11] | TYPE: [Z] [12] | DESCRIPTION: [N/A] [13]

PERSONNEL INJURIES

[1] [4] | NUMBER: [0] [0] [0] [11] | DESCRIPTION: [N/A] [12]

OFFSITE CONSEQUENCES

[1] [5] | [N/A]

LOSS OR DAMAGE TO FACILITY

[1] [8] | TYPE: [Z] [9] | DESCRIPTION: [N/A] [10]

PUBLICITY

[1] [7] | [N/A]

ADDITIONAL FACTORS

[1] [9] | The health and safety of the public were not affected because the unit was at all times operated in a conservative condition with respect to the flux tilt condition.

NAME: J. B. Bouson PHONE: 357-3184

CAUSE DESCRIPTION (CONTINUED)

J-13 restored. Loose connector pins have been an infrequent problem. All connectors are examined upon remating following refuelings.

RECEIVED DOCUMENT
PROCESSING UNIT

1977 SEP 19 AM 9 25