


VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

September 1, 1977



Regulatory

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region II - Suite 818
230 Peachtree Street, Northwest
Atlanta, Georgia 30303

Serial No. 380
PO&M/TAP:das
Docket No. 50-280
License No. DPR-32

Dear Mr. O'Reilly:

Pursuant to Surry Power Station Technical Specification 6.6.2, the Virginia Electric and Power Company hereby submits a copy of Reportable Occurrence No. RO-S1-77-12.

The substance of this report has been reviewed by the Station Nuclear Safety and Operating Committee and will be placed on the agenda for the next meeting of the System Nuclear Safety and Operating Committee.

Very truly yours,

C. M. Stallings

C. M. Stallings
Vice President-Power Supply
and Production Operations

Enclosures

40 copies RO-S1-77-12

cc: Mr. Robert W. Reid, Chief ✓
Operating Reactors Branch 4

772500057

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME:

01	V	A	S	P	S	1
----	---	---	---	---	---	---

 LICENSE NUMBER:

0	0	-	0	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE:

4	1	1	1	0
---	---	---	---	---

 EVENT TYPE:

0	1
---	---

CONT: CATEGORY:

M	I
---	---

 REPORT TYPE:

P

 REPORT SOURCE:

L

 DOCKET NUMBER:

0	5	0	-	0	2	8	0
---	---	---	---	---	---	---	---

 EVENT DATE:

0	8	1	2	7	7
---	---	---	---	---	---

 REPORT DATE:

0	8	3	0	7	7
---	---	---	---	---	---

EVENT DESCRIPTION

02 | The Westinghouse Electric Company informed the station by letter that Technical
03 | Specification 3.1.B.3 is in error as follows: The maximum pressurizer heatup rate
04 | should be 100°F/hour instead of 200°F/hour as presently stated. The cooldown rate
05 | limit remains 200°F/hour. The correct heatup rate restrictions have been promulgated
06 | and permanent changes to Technical Specifications and Operating (Continued)

SYSTEM CODE:

Z	Z
---	---

 CAUSE CODE:

E

 COMPONENT CODE:

Z	Z	Z	Z	Z	Z
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER:

Z

 COMPONENT MANUFACTURER:

Z	9	9	9
---	---	---	---

 VIOLATION:

Y

CAUSE DESCRIPTION

08 | The Technical Specification in error was part of the original set of Specifications
09 | issued in 1972. These specification were based on vendor recommendations.
10 |

FACILITY STATUS:

E

 % POWER:

1	0	0
---	---	---

 OTHER STATUS:

N/A

 METHOD OF DISCOVERY:

D

 DISCOVERY DESCRIPTION:

Letter from Westinghouse

FORM OF ACTIVITY RELEASED:

Z

 CONTENT OF RELEASE:

Z

 AMOUNT OF ACTIVITY:

N/A

 LOCATION OF RELEASE:

N/A

PERSONNEL EXPOSURES

13 | NUMBER:

0	0	0
---	---	---

 TYPE:

Z

 DESCRIPTION:

N/A

PERSONNEL INJURIES

14 | NUMBER:

0	0	0
---	---	---

 DESCRIPTION:

N/A

OFFSITE CONSEQUENCES

15 | N/A

LOSS OR DAMAGE TO FACILITY

16 | TYPE:

Z

 DESCRIPTION:

N/A

PUBLICITY

17 | N/A

ADDITIONAL FACTORS

18 | Calculations have verified that Surry Power Station does not have sufficient installed
19 | pressurizer heater capacity to have exceeded the 100°F/hour (continued)

EVENT DESCRIPTION (CONTINUED)

Procedures have been initiated. (RO-S1-77-12)

ADDITIONAL FACTORS (CONTINUED)

heatup limit.

Since the new Technical Specification has never been violated, the health and safety of the general public were not affected by this event.

RECEIVED DOCUMENT
PROCESSING UNIT

1977 SEP 6 AM 11 15