

*Reactor Facility
Per.*

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

April 19, 1976

Mr. Norman C. Moseley, Director
Office of Inspection & Enforcement
Region II
U. S. Nuclear Regulatory Commission
230 Peachtree Street, Northwest
Atlanta, Georgia 30303

Serial No. 945/031676
LOA/DWSjr:cel
Docket Nos. 50-280
50-281
License Nos. DPR-32
DPR-37

Dear Mr. Moseley:

In response to your letter of March 16, 1976, in which IE Bulletin numbers 76-02 and 76-03 were enclosed, we have made the following findings with respect to Surry Power Station:

1. The types of relays mentioned in IE Bulletin 76-02 (GE type HFA, HCA, HKA, HMA) are installed in various systems at Surry. Review of the failure history of these relays has revealed that no failures of the kind mentioned in the Bulletin have occurred in the nearly four years of station operation. Presently, no action with regard to Bulletin 76-02 is required. If failures of the type mentioned do occur in the future, we would reevaluate the Bulletin at that time.
2. The type of relay mentioned in IE Bulletin 76-03 (GE type 12 STD 15B5A) is not installed at Surry; therefore no further action is required or planned.

If you have further questions, please contact us.

Very truly yours,

C. M. Stallings

C. M. Stallings
Vice President - Power Supply
and Production Operations

cc: Dr. Ernst Volgenau, Director ✓
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555