


VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

July 29, 1976



Mr. Norman C. Moseley, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region II - Suite 818  
230 Peachtree Street, Northwest  
Atlanta, Georgia 30303

Serial No. 160  
PO&M/LJC:jlf

Docket No. 50-280  
License No. DPR-32

Dear Mr. Moseley:

Pursuant to Surry Power Station Technical Specification 6.6.B.2, the Virginia Electric and Power Company hereby submits a copy of Licensee Event Report No. USRE-S1-76-07.


The substance of this report has been reviewed by the Station Nuclear Safety and Operating Committee and will be placed on the agenda for the next meeting of the System Nuclear Safety and Operating Committee.

Very truly yours,

G. M. Stallings  
Vice President-Power Supply  
and Production Operations

Enclosure

cc: Mr. Robert W. Reid, Chief (40 copies)  
Operating Reactors Branch 4



# LICENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 

01	V	A	S	P	S	1
----	---	---	---	---	---	---

 LICENSE NUMBER: 

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE: 

4	1	1	1	0
---	---	---	---	---

 EVENT TYPE: 

0	3
---	---

CON'T: 

0	1
---	---

 CATEGORY: 

M	I
---	---

 REPORT TYPE: 

L
---

 REPORT SOURCE: 

L
---

 DOCKET NUMBER: 

0	5	0	-	0	2	8	0
---	---	---	---	---	---	---	---

 EVENT DATE: 

0	7	0	2	7	6
---	---	---	---	---	---

 REPORT DATE: 

0	7	2	7	7	6
---	---	---	---	---	---

## EVENT DESCRIPTION

02 | During the preparations to run the starting test of #1 emergency diesel generator, water |  
03 | was observed coming out of #19 cylinder. The backup emergency diesel generator was |  
04 | immediately tested satisfactorily and then repairs commenced on #1 emergency diesel |  
05 | generator. The engine was repaired by replacing the cylinder head and head gasket. |  
06 | This is a reportable occurrence in accordance with Technical Specification (Continued) |

SYSTEM CODE: 

E	E
---	---

 CAUSE CODE: 

E
---

 COMPONENT CODE: 

E	N	G	I	N	E
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER: 

A
---

 COMPONENT MANUFACTURER: 

E	1	4	7
---	---	---	---

 VIOLATION: 

N
---

## CAUSE DESCRIPTION

08 | EMD-GM Turbo Vee 20, 3810 Bhp diesel engine was found to have a crack in #19 cylinder |  
09 | head which extended between two exhaust valve seats and into the water jacket. Thus |  
10 | water from the cylinder head water jacket was permitted to drip into the (Continued) |

FACILITY STATUS: 

E
---

 % POWER: 

1	0	0
---	---	---

 OTHER STATUS: 

N/A
-----

 METHOD OF DISCOVERY: 

B
---

 DISCOVERY DESCRIPTION: 

N/A
-----

FORM OF ACTIVITY RELEASED: 

Z
---

 CONTENT OF RELEASE: 

Z
---

 AMOUNT OF ACTIVITY: 

N/A
-----

 LOCATION OF RELEASE: 

N/A
-----

## PERSONNEL EXPOSURES

NUMBER: 

0	0	0
---	---	---

 TYPE: 

Z
---

 DESCRIPTION: 

N/A
-----

## PERSONNEL INJURIES

NUMBER: 

0	0	0
---	---	---

 DESCRIPTION: 

N/A
-----

## OFFSITE CONSEQUENCES

15 | N/A |

## LOSS OR DAMAGE TO FACILITY

TYPE: 

Z
---

 DESCRIPTION: 

N/A
-----

## PUBLICITY

17 | N/A |

## ADDITIONAL FACTORS

18 | The backup emergency diesel generator was demonstrated to be operable. Therefore, the |  
19 | safety systems would have functioned if they had been required. (Continued) |

NAME: T. L. Baucom PHONE: (804) 357-3184

EVENT DESCRIPTION(CONTINUED)

6.6.2b(2). (USRE-S1-76-07).

CAUSE DESCRIPTION (CONTINUED)

cylinder. Rolling the engine with the cylinder test cocks open prior to starting the engine forced the water out of the cylinder. This permitted detection of the problem and prevented further damage to the engine.

This is the fifth cylinder head on this engine to be found with a crack in a time period of approximately three months. Cylinders #1 and #17 were the subject of USRE S1-76-04 and 06. Cylinders #2 and #16 were found during the inspection conducted as a result of USRE S1-76-06. Cylinders #1 and #2 are diametrically opposite of cylinders #16, #17 and #19. This can be indicative of a cylinder head heat stress which is caused by a cylinder heat imbalance or an engine overheat condition.

To ensure the reliability of this engine, the monthly performance test will be conducted on a weekly basis for a period of two months. If no additional cylinder heads are found to be cracked, it will be safe to assume the remaining heads have not been heat stressed to the point of failure. If additional heads are found to be cracked, the determination of the cause of the cracking may be brought to light depending on which head fails.

ADDITIONAL FACTORS (CONTINUED)

Accordingly, no hazard to the safety or health of the general public existed.