



VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

April 22, 1975



Mr. Norman C. Moseley, Director  
Office of Inspection and Enforcement  
United States Nuclear Regulatory Commission  
Region II - Suite 818  
230 Peachtree Street, Northwest  
Atlanta, Georgia 30303

Serial No. 507  
PO&M/JTB:clw

Docket Nos. 50-280  
License Nos. DPR-32

Dear Mr. Moseley:

Pursuant to Surry Power Station Technical Specification 6.6.B.1,  
the Virginia Electric and Power Company hereby submits forty (40) copies  
of Abnormal Occurrence Report No. AO-S1-75-10.

The substance of this report has been reviewed by the Station Nuclear  
Safety and Operating Committee and will be placed on the agenda for the  
next meeting of the System Nuclear Safety and Operating Committee.

Very truly yours,

C. M. Stallings  
Vice President-Power Supply  
and Production Operations

Enclosures

40 copies of AO-S1-75-10

cc: Mr. K. R. Goller

4666

# LICENSEE EVENT REPORT

AO-S1-75-10

CONTROL BLOCK: 

--	--	--	--	--	--

PLEASE PRINT ALL REQUIRED INFORMATION

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE				EVENT TYPE										
01	V	A	S	P	S	1	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	0	0	1		
7	8	9				14	15									25	26							30	31	32

REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE																
01	CONT	P	O	T	L	0	5	0	-	0	2	8	0	0	4	1	2	7	5	0	4	1	8	7	5	
7	8			59	60	61							68	69						74	75					80

## EVENT DESCRIPTION

02 | During normal operation the Process Vent System Particulate Radiation Monitor Alarm | 80

03 | was manually initiated to demonstrate the actuation of automatic shutoff valves in | 80

04 | the system to a trainee. Valve FCV-GW-260 failed to shut as required by Technical | 80

05 | Specification 3.7-2E. AO-S1-75-10 | 80

06 | | 80

SYSTEM CODE	CAUSE CODE	COMPONENT CODE				PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOLATION						
07	8	8	E	R	E	L	A	Y	X	A	W	1	2	0	Y	
7	8	9	10	11	12					43	44				47	48

## CAUSE DESCRIPTION

08 | A Westinghouse Electric Corporation Model MG-6 relay (Latch-Reset) in the control | 80

09 | circuit for valve FCV-GW-260 was found to be stuck in the "operate" position causing | 80

10 | FCV-GW-260 not to shut. | 80

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION						
11	E	1	0	0	N/A	A	N/A			
7	8	9	10	11	12	13	44	45	46	80

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE				
12	Z	N/A	N/A				
7	8	9	10	11	44	45	80

## PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION				
13	0	0	0	Z	N/A	
7	8	9	11	12	13	80

## PERSONNEL INJURIES

NUMBER	DESCRIPTION				
14	0	0	0	N/A	
7	8	9	11	12	80

## OFFSITE CONSEQUENCES

15 | | N/A | 80

## LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION			
16	Z	N/A		
7	8	9	10	80

## PUBLICITY

17 | | N/A | 80

## ADDITIONAL FACTORS

18 | | N/A | 80

19 | | | 80

NAME: E. M. Sweeney, Jr.

PHONE: (804) 357-3184

SUPPLEMENTARY INFORMATION  
FAILURE OF VALVE FCV-FW-260  
TO OPERATE PROPERLY  
AO-S1-75-10

On April 12, 1975 at about 0515 an alarm was manually initiated on the Process Vent System particulate radiation monitor to demonstrate the operation of various trip valves in the system to a trainee. The automatic isolation valve for the Unit No. 2 containment vacuum pump discharge (FCV-GW-260) would not shut as required by Technical Specification 3.7-2E.

Investigation into the problem revealed that the valve was mechanically operable, but was not receiving a "shut" signal from the control circuit. Further troubleshooting revealed that a relay in the control circuit was stuck in the "operate" position preventing FCV-GW-260 from shutting. The affected relay was found to be excessively dirty thus preventing proper operation.

The relay was thoroughly cleaned, adjusted, tested and placed back in operation.