


VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

September 1, 1977



Regulatory

File CV

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region II - Suite 818
230 Peachtree Street, Northwest
Atlanta, Georgia 30303

Serial No. 381
PO&M/TAP:das
Docket No. 50-281
License No. DPR-37

Dear Mr. O'Reilly:

Pursuant to Surry Power Station Technical Specification 6.6.2, the Virginia Electric and Power Company hereby submits a copy of Reportable Occurrence No. RO-S1-77-06.

The substance of this report has been reviewed by the Station Nuclear Safety and Operating Committee and will be placed on the agenda for the next meeting of the System Nuclear Safety and Operating Committee.

Very truly yours,

C. M. Stallings

C. M. Stallings
Vice President-Power Supply
and Production Operations

Enclosures

40 copies RO-S2-77-06

cc: Mr. Robert W. Reid, Chief ✓
Operating Reactors Branch 4

772490115

EVENT DESCRIPTION (CONTINUED)

Corrective action was taken to find and remove the stoppage. This was achieved and the unit was returned to full power. This is not a repetitive occurrence. (RO-S2-77-06)

CAUSE DESCRIPTION (CONTINUED)

pipng, and the other was due to inadequate insulation of a flow transmitter. The elbow insulation and the insulation around the flow transmitter have been increased and the boration lines will be flushed periodically in an attempt to avoid stagnation and solidification of the boric acid.

RECEIVED DOCUMENT
PROCESSING UNIT

1977 SEP 6 AM 9 30