



VIRGINIA ELECTRIC AND POWER COMPANY
 RICHMOND, VIRGINIA 23261

January 22, 1976



Mr. Norman C. Moseley, Director
 Office of Inspection and Enforcement
 United States Nuclear Regulatory Commission
 Region II - Suite 818
 230 Peachtree Street, Northwest
 Atlanta, Georgia 30303

Serial No. 598-S
 PGM/ALH:clw

Docket No. 50-281
 License No. DPR-37

Dear Mr. Moseley:

Pursuant to Surry Power Station Technical Specification 6.6.B.1, the Virginia Electric and Power Company hereby submits forty (40) copies of Supplementary Abnormal Occurrence Report No. AO-S2-75-12.

The substance of this report has been reviewed by the Station Nuclear Safety and Operating Committee and will be placed on the agenda for the next meeting of the System Nuclear Safety and Operating Committee.

Very truly yours,

C. M. Stallings

C. M. Stallings
 Vice President-Power Supply
 and Production Operations

Enclosures

40 copies of AO-S2-75-12

cc: Mr. Robert W. Reid ✓

LICENSEE EVENT REPORT

Supplement to
AO-S2-75-12

CONTROL BLOCK:

--	--	--	--	--	--

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME:

01	V	A	S	P	S	2
----	---	---	---	---	---	---

 LICENSE NUMBER:

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE:

4	1	1	1	0
---	---	---	---	---

 EVENT TYPE:

0	1
---	---

CATEGORY:

01	CONT
----	------

 REPORT TYPE:

P	O
---	---

 REPORT SOURCE:

T	L
---	---

 DOCKET NUMBER:

0	5	0	-	0	2	8	1
---	---	---	---	---	---	---	---

 EVENT DATE:

0	7	0	6	7	5
---	---	---	---	---	---

 REPORT DATE:

0	1	2	0	7	6
---	---	---	---	---	---

EVENT DESCRIPTION

02	See AO-S2-75-12	80
03		80
04		80
05		80
06		80

SYSTEM CODE:

H	B
---	---

 CAUSE CODE:

E

 COMPONENT CODE:

V	A	L	V	E	X
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER:

A

 COMPONENT MANUFACTURER:

S	0	7	5
---	---	---	---

 VIOLATION:

N

CAUSE DESCRIPTION

08	N/A	80
09		80
10		80

FACILITY STATUS:

G

 % POWER:

0	0	0
---	---	---

 OTHER STATUS:

N/A

 METHOD OF DISCOVERY:

C

 DISCOVERY DESCRIPTION:

N/A

FORM OF ACTIVITY RELEASED:

Z

 CONTENT OF RELEASE:

Z

 AMOUNT OF ACTIVITY:

N/A

 LOCATION OF RELEASE:

N/A

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
000	Z	N/A

PERSONNEL INJURIES

NUMBER	DESCRIPTION
000	N/A

OFFSITE CONSEQUENCES

15	N/A	80
----	-----	----

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION
Z	N/A

PUBLICITY

17	N/A	80
----	-----	----

ADDITIONAL FACTORS

18	During the recent 1975 fall outage the following work was accomplished on Unit No. 1	80
----	--	----

19	main steam trip valves (TV-MS-101A,B & C). (con't)	80
----	--	----

NAME: T. L. Baucom

PHONE: (804) 357-3184

ADDITIONAL FACTORS (con't)

1. Disc swing angles were checked and verified to be correct (80±2-0 degrees).
2. Bottom back edge of discs were ground in accordance with Schutte & Koerting instructions to prevent possible sticking of the disc in the open position.
3. Tail link and bushing total end to end clearances were checked and modified as required to provide a total clearance less than 0.106" but greater than 0.042".
4. All gaskets and "O" rings were inspected for wear and replaced as necessary.

Completion of this work eliminated the problems on Unit No. 1 trip valves that had been previously identified and corrected on Unit No. 2 (see AO-S2-75-12). No further work or modifications are considered necessary at this time to insure the proper, safe and reliable operation of the main steam trip valves.