


VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

July 8, 1975



Mr. Norman G. Moseley, Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region II - Suite 818
230 Peachtree Street, Northwest
Atlanta, Georgia 30303

Serial No. 519-S
PO&M/JTB:clw

Docket No. 50-281
License No. DPR-37

Dear Mr. Moseley:

Pursuant to Surry Power Station Technical Specification 6.6.B.1, the Virginia Electric and Power Company hereby submits forty (40) copies of supplementary information to Abnormal Occurrence Report No. AO-S2-75-08. This information was requested by the Principal Inspector, Mr. M. Sinkule.

The substance of this report has been reviewed by the Station Nuclear Safety and Operating Committee and will be placed on the agenda for the next meeting of the System Nuclear Safety and Operating Committee.

Very truly yours,


C. M. Stallings

C. M. Stallings
Vice President-Power Supply
and Production Operations

Enclosures

40 copies of AO-S2-75-08

cc: Mr. K. R. Goller ✓



LICENSEE EVENT REPORT

Supplemental Report
AO-S2-75-08

CONTROL BLOCK:

--	--	--	--	--	--

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE				EVENT TYPE									
01	V	A	S	P	S	2	0	0	-	0	0	0	0	-	0	0	4	1	1	1	0	0	1		
7	8	9	14	15	25	26	30	31	32																
CATEGORY			REPORT TYPE		REPORT SOURCE		DOCKET NUMBER				EVENT DATE			REPORT DATE											
01	CON'T	P	0	T	L	0	5	0	-	0	2	8	1	0	4	2	7	7	5	0	7	0	7	7	5
7	8	57	58	59	60	61	68	69	74	75															

EVENT DESCRIPTION

02	The event previously described occurred because of apparent inadequate implementation																							80
03	of administrative controls during the construction and preoperation of the facility.																							80
04	AO-S2-75-08																							80
05																								80
06																								80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER			VIOLATION		
07	S	P	A	V	A	L	V	E	X	N	V	0	8	5	Y
7	8	9	10	11	12	17	43	44	47	48					

CAUSE DESCRIPTION

08	The administrative control of electrical wire changes has been significantly increased																							80
09	since the apparent time of the occurrence by strengthening the jumper log, establishing																							80
10	operational quality control and by instructing various trades that following (cont'd)																							80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION						
11	G	0	0	0	N/A	B	N/A							
7	8	9	10	12	13	44	45	46						

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE					
12	Z	Z	N/A					N/A					
7	8	9	10	11	44	45							

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION							
13	0	0	0	Z	N/A						
7	8	9	11	12	13						

PERSONNEL INJURIES

NUMBER		DESCRIPTION								
14	0	0	0	N/A						
7	8	9	11	12						

OFFSITE CONSEQUENCES

15	N/A																							80
----	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION							
16	Z	N/A							
7	8	9	10						

PUBLICITY

17	N/A																							80
----	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	CAUSE DESCRIPTION (cont'd): procedural controls is mandatory.																							80
----	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																								80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: E. M. Sweeney, Jr.

PHONE: (804) 357-3184