

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 1600 EAST LAMAR BOULEVARD ARLINGTON, TEXAS 76011-4511

May 8, 2019

Mr. G. T. Powell President and Chief Executive Officer STP Nuclear Operating Co. P.O. Box 330 Wadsworth, TX 77483

SUBJECT: SOUTH TEXAS PROJECT ELECTRIC GENERATING STATION, UNITS 1 AND 2, NRC INTEGRATED INSPECTION REPORT 05000498/2019001; 05000499/2019001, AND INDEPENDENT SPENT FUEL STORAGE INSPECTION 07201041/2019001

Dear Mr. Powell:

On March 31, 2019, the U.S. Nuclear Regulatory Commission (NRC) completed an inspection at your South Texas Project Electric Generating Station, Units 1 and 2. On April 11, 2019, the NRC inspectors discussed the results of this inspection with you and other members of your staff. The results of this inspection are documented in the enclosed report.

NRC inspectors documented two findings of very low safety significance (Green) in this report. One of these findings involved a violation of NRC requirements.

The inspectors documented a licensee-identified violation which was determined to be of very low safety significance in this report. The NRC is treating this violation as a non-cited violation (NCV) consistent with Section 2.3.2.a of the Enforcement Policy.

If you contest the violation or significance or severity of the violation documented in this inspection report, you should provide a response within 30 days of the date of this inspection report, with the basis for your denial, to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555-0001; with copies to the Regional Administrator, Region IV; the Director, Office of Enforcement; and the NRC resident inspector at South Texas Project Electric Generating Station, Units 1 and 2.

If you disagree with a cross-cutting aspect assignment or a finding not associated with a regulatory requirement in this report, you should provide a response within 30 days of the date of this inspection report, with the basis for your disagreement, to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555-0001; with copies to the Regional Administrator, Region IV; and the NRC resident inspector at South Texas Project.

This letter, its enclosure, and your response (if any) will be made available for public inspection and copying at http://www.nrc.gov/reading-rm/adams.html and at the NRC Public Document Room in accordance with 10 CFR 2.390, "Public Inspections, Exemptions, Requests for Withholding."

Sincerely,

/**RA**/

Nicholas H. Taylor, Branch Chief Project Branch B Division of Reactor Projects

Docket Nos. 05000498; 05000499 and 07201041 License Nos. NPF-76 and NPF-80

Enclosure: Inspection Report 05000498/2019001; 05000499/2019001 and 07201041/2019001 w/attachment: NRC Request for Information

U.S. NUCLEAR REGULATORY COMMISSION Inspection Report

| Docket Number(s): | 05000498; 05000499 and 07201041 |
|------------------------|--|
| License Number(s): | NPF-76 and NPF-80 |
| Report Number(s): | 05000498/2019001; 05000499/2019001, and 07201041/2019001 |
| Enterprise Identifier: | I-2019-001-0004 and 1-2019-001-0082 |
| Licensee: | STP Nuclear Operating Co. |
| Facility: | South Texas Project Electric Generating Station, Units 1 and 2 |
| Location: | Wadsworth, TX 77483 |
| Inspection Dates: | January 1, 2019, to March 31, 2019 |
| Inspectors: | B. Baca, Health Physicist J. Choate, Resident Inspector A. Sanchez, Senior Resident Inspector L. Brookhart, Senior ISFSI Inspector, FCDB C. Smith, Reactor Inspector, DRS, EB1 O. Masnyk Bailey, Health Physicist, RI, DIRHB M. Learn, Reactor Engineer, RIII, MCID R. Edwards, Senior Health Physicist, RIII, MCID |
| Approved By: | Nicholas H. Taylor Chief, Project Branch B Division of Reactor Projects |

SUMMARY

The U.S. Nuclear Regulatory Commission (NRC) continued monitoring the licensee's performance by conducting a quarterly inspection at South Texas Project Electric Generating Station, Units 1 and 2, in accordance with the Reactor Oversight Process. The Reactor Oversight Process is the NRC's program for overseeing the safe operation of commercial nuclear power reactors. Refer to <u>https://www.nrc.gov/reactors/operating/oversight.html</u> for more information. NRC and self-revealed findings, violations, and additional items are summarized in the table below. Licensee-identified non-cited violations are documented in report sections: 71153.

List of Findings and Violations

| Failure to Implement the Procedure for Equipment Failures | | | | |
|---|----------------------|----------------|----------------|--|
| Cornerstone | Significance | Cross-cutting | Report | |
| | | Aspect | Section | |
| Initiating Events | Green | [H.12] - Avoid | 71152 | |
| | FIN 05000499/2019-01 | Complacency | Problem | |
| | Closed | | Identification | |
| | | | and | |
| | | | Resolution | |
| The inspectors identified a Green finding for the licensee's failure to implement the procedure | | | | |
| for the failure of a plant generation risk high risk component. Specifically, the licensee failed | | | | |
| to implement and follow Procedure WCG-0008, "Preventing Recurring Equipment | | | | |
| Problems (PREP)," Revision 7, following the failure of the Unit 2 steam generator 2C normal | | | | |
| feedwater regulating control valve, FCV-553. | | | | |

| Failure to Provide Adequate Procedural Guidance for a Surveillance Test | | | |
|---|----------------------|----------------|----------------|
| Cornerstone | Significance | Cross-cutting | Report |
| | | Aspect | Section |
| Initiating Events | Green | [H.12] - Avoid | 71152 |
| - | NCV 05000499/2019-02 | Complacency | Problem |
| | Closed | | Identification |
| | | | and |
| | | | Resolution |

The inspectors documented a Green self-revealed NCV for the failure to provide an adequate procedure for a Unit 2 qualified display processing system (QDPS) surveillance procedure that resulted in unnecessary troubleshooting, unnecessary replacement of properly operating circuit cards, and placing the loop 2 over-temperature delta-T, over-pressure delta-T, and low T_{avg} feedwater isolation bistables into a TRIPPED condition, a half-trip condition for the reactor. Following an investigation, the licensee discovered that incorrect biases were inputted into the QDPS surveillance procedure.

Additional Tracking Items

| Туре | Issue number | Title | Inspection Procedure | Status |
|------|----------------------|--|---------------------------------|--------|
| LER | 05000498/2017-002-00 | Unit 1 Condition Prohibited by Technical Specifications due to Inoperable Control Room Envelope Makeup Filtration System Heating Coil | 71153 Follow-up of Events | Closed |
| LER | 05000498/2018-001-00 | Unit 1 Main Steam Safety Valve As Left Settings Outside of Required Range Contrary to Technical Specifications due to Inadequate Procedure | 71153 Follow-up of Events | Closed |

PLANT STATUS

Unit 1 operated at rated thermal power for the entire inspection period.

Unit 2 began the inspection period at rated thermal power. On March 2, 2019, while performing main turbine governor valve testing at 90 percent power, a procedural error resulted in an unexpected decrease in reactor power to 86 percent power. The reactor was returned back to rated thermal power on March 3, 2019, and remained there for the remainder of the inspection period.

INSPECTION SCOPES

Inspections were conducted using the appropriate portions of the inspection procedures (IPs) in effect at the beginning of the inspection unless otherwise noted. Currently approved IPs with their attached revision histories are located on the public website at http://www.nrc.gov/reading-rm/doc-collections/insp-manual/inspection-procedure/index.html. Samples were declared complete when the IP requirements most appropriate to the inspection activity were met consistent with Inspection Manual Chapter (IMC) 2515, "Light-Water Reactor Inspection Program - Operations Phase." The inspectors performed plant status activities described in IMC 2515 Appendix D, "Plant Status," and conducted routine reviews using IP 71152, "Problem Identification and Resolution." The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel to assess licensee performance and compliance with Commission rules and regulations, license conditions, site procedures, and standards.

REACTOR SAFETY

71111.04 - Equipment Alignment

Partial Walkdown (IP Section 02.01) (5 Samples)

The inspectors evaluated system configurations during partial walkdowns of the following systems/trains:

- (1) Unit 1, train B chemical and volume control system during train A centrifugal charging pump maintenance on January 2, 2019
- (2) Unit 2, turbine driven auxiliary feedwater system with elevated unit trip risk during north bus outage on March 1, 2019
- (3) Unit 2, train C emergency core cooling system during train B emergency diesel generator maintenance on March 13, 2019
- (4) Unit 2, train A essential chilled water system during train B essential chilled water system maintenance on March 16, 2019
- (5) Unit 2, train A essential cooling water system during train C essential cooling water maintenance on March 22, 2019

71111.05Q - Fire Protection

Quarterly Inspection (IP Section 03.01) (5 Samples)

The inspectors evaluated fire protection program implementation in the following selected areas:

- (1) Unit 2, safety injection pump cubicles, Fire Area 35 on February 2, 2019
- (2) Units 1 and 2, balance of plant diesel generator rooms and turbine generator building switchgear rooms, Fire Areas 78 and 90 on February 26, 2019
- (3) Unit 1, auxiliary feedwater pump cubicles, Fire Areas 48, 49, 50, and 51 on February 27, 2019
- (4) Unit 1, train C essential cooling water intake structure, Fire Area 55 on March 22, 2019
- (5) Unit 1, train C vital switchgear room, battery room, 125 vdc distribution room, and motor generator room, Fire Areas 52 through 54 on March 26, 2019

71111.06 - Flood Protection Measures

Inspection Activities - Internal Flooding (IP Section 02.02a.) (1 Sample)

The inspectors evaluated internal flooding mitigation protections in the Unit 1, train B essential cooling water pump room on March 26, 2019.

71111.07A - Heat Sink Performance

Annual Review (IP Section 02.01) (1 Sample)

The inspectors evaluated readiness and performance of:

- (1) Unit 1, train C emergency diesel generator jacket water and lube oil heat exchangers the week of January 14, 2019
- (2) Unit 2, train B essential chilled water cooler the week of March 12, 2019

71111.11Q - Licensed Operator Requalification Program and Licensed Operator Performance

Licensed Operator Performance in the Actual Plant/Main Control Room (IP Section 03.01) (1 Sample)

The inspectors observed and evaluated licensed operator performance in the Unit 1 control room during a secondary side electro-hydraulic leak which resulted in the closure of the 13 west reheat stop valve to the low pressure turbine on January 9, 2019.

Licensed Operator Regualification Training/Examinations (IP Section 03.02) (1 Sample)

The inspectors observed and evaluated Unit 1 operations in the simulator during a loss of coolant accident followed by a loss of offsite power on February 27, 2019.

71111.12 - Maintenance Effectiveness

Routine Maintenance Effectiveness Inspection (IP Section 02.01) (2 Samples)

The inspectors evaluated the effectiveness of routine maintenance activities associated with the following equipment and/or safety significant functions:

- (1) Unit 1, turbine driven auxiliary feedwater pump low governor oil level that resulted in inoperability of the train on January 3, 2019
- (2) Unit 1, electro-hydraulic control system leak that resulted in the closure of reheat stop valve 13 on January 9, 2019

71111.13 - Maintenance Risk Assessments and Emergent Work Control

Risk Assessment and Management Sample (IP Section 03.01) (4 Samples)

The inspectors evaluated the risk assessments for the following planned and emergent work activities:

- (1) Units 1 and 2, planned north bus outage that resulted in entering the Configuration Risk Management Program on February 26, 2019
- (2) Unit 2, planned turbine driven auxiliary feedwater pump extent of condition maintenance for connecting rod engagement on January 31, 2019
- (3) Unit 1, train B essential cooling water unplanned pump replacement February 13 through 19, 2019
- (4) Unit 1, elevated risk due to unplanned entry into the Configuration Risk Management Program for exceeding the train B essential chilled water system 7 day limiting condition for operation due to maintenance activities on March 10, 2019

71111.15 - Operability Determinations and Functionality Assessments

Sample Selection (IP Section 02.01) (5 Samples)

The inspectors evaluated the following operability determinations and functionality assessments:

- (1) Unit 1, turbine driven auxiliary feedwater pump following the identification of a degraded conduit for the remote trip solenoid on January 16, 2019
- (2) Unit 1, train B control room envelope heating, ventilation, and air conditioning damper controller on February 6, 2019

- (3) Unit 2, cask loading pool leakage on February 12, 2019
- (4) Unit 1, train B emergency diesel generator shutdown when taken out of emergency mode on March 11, 2019
- (5) Unit 2, turbine driven auxiliary feedwater pump experiencing high main oil pump discharge pressure on March 15, 2019

71111.19 - Post Maintenance Testing

Post Maintenance Test Sample (IP Section 03.01) (6 Samples)

The inspectors evaluated the following post maintenance tests:

- (1) Unit 1, train C emergency diesel generator following fuel oil storage tank level transmitter replacement on January 31, 2019
- (2) Unit 2, turbine driven auxiliary feedwater pump following failure of connecting rod on January 31, 2019
- (3) Unit 1, train B essential cooling water pump following pump replacement on March 4, 2019
- (4) Unit 1, train B emergency diesel generator following replacement of shutdown air solenoid valve on March 13, 2019
- (5) Units 1 and 2, diesel fire pump number 3 following replacement of the pump impeller, diesel starter solenoid, and pump packing on March 18, 2019
- (6) Unit 2, train C residual heat removal pump following control room handswitch replacement on March 19, 2019

71111.22 - Surveillance Testing

The inspectors evaluated the following surveillance tests:

In Service Testing (IST) (IP Section 03.01) (2 Samples)

- (1) Unit 1, turbine driven auxiliary feedwater pump surveillance test on January 24, 2019
- (2) Unit 1, train B essential cooling water system surveillance test on February 14, 2019

Surveillance Testing (IP Section 03.01) (4 Samples)

- (1) Unit 2, train B emergency diesel generator surveillance test on February 12, 2019
- (2) Unit 2, train A auxiliary feedwater regulating valve dynamic pressure test on March 4, 2019
- (3) Unit 1, train B emergency diesel generator fast start surveillance on March 13, 2019

(4) Unit 1, train C emergency diesel generator fast start surveillance on March 15, 2019

RADIATION SAFETY

71124.02 - Occupational ALARA Planning and Controls

Radiological Work Planning (IP Section 02.01) (1 Sample)

The inspectors evaluated the licensee's radiological work planning by reviewing the following activities:

- 1RE21 Reactor Cavity and Head Activities
- 1RE21 Fuel Transfer Canal Activities
- 2RE19 Reactor Cavity and Head Activities
- 2RE19 Steam Generator Activities

<u>Verification of Dose Estimates and Exposure Tracking Systems (IP Section 02.02)</u> (1 Sample)

The inspectors evaluated dose estimates and exposure tracking. The inspectors reviewed the following ALARA planning documents:

- 18-276-7 ALARA Review Package: 2RE19 Non-Rapid Refuel, Revision 1
- 18-276-8 ALARA Review Package: 2RE19 Steam Generator Inspections
- 18-7926-4 ALARA Review Package: 1RE21 Non-Rapid Refuel

Additionally, the inspectors reviewed the following radiological outcome evaluations:

- 18-276-7 ALARA Close Out Review Package: 2RE19 Non-Rapid Refuel, Revision 1
- 18-276-8 ALARA Close Out Review Package: 2RE19 Steam Generator Inspections
- 18-7926-4 ALARA Close Out Review Package: 1RE21 Non-Rapid Refuel
- 18-7926-4 ALARA Close Out Review Package Supplement 1: 1RE21 Non-Rapid Refuel

71124.04 - Occupational Dose Assessment

External Dosimetry (IP Section 02.02) (1 Sample)

The inspectors evaluated the external dosimetry program implementation.

Internal Dosimetry (IP Section 02.03) (1 Sample)

The inspectors evaluated the internal dosimetry program implementation.

Three contaminated workers' whole body counts were reviewed for potential uptakes. The licensee had no positive whole body counts indicating an internal uptake of radioactive material.

The licensee had no occurrences to observe or review in-vitro internal monitoring or dose assessments performed using air sampling and DAC-hr. monitoring.

Source Term Categorization (IP Section 02.01) (1 Sample)

The inspectors evaluated the licensee's characterization of the source term and use of scaling factors for the use of hard-to-detect radionuclide activity.

Special Dosimetric Situations (IP Section 02.04) (1 Sample)

The inspectors evaluated special dosimetric situations, as detailed below.

- The inspectors reviewed approximately five declared pregnant workers' documentation from January 1, 2017, to March 21, 2019.
- The licensee did not perform any EDEX assessments from July 31, 2017, to March 21, 2019.
- The inspectors reviewed one shallow dose equivalent assessment (Condition Report 2019-1215).
- The inspectors reviewed the licensee's use of Mirion neutron thermoluminescent dosimetry and electronic alarming dose meters (Model EPDN2) for neutron dosimetry. The inspector compared radiological surveys, RWP and WAN assignments, and worker exposures to confirm the licensee is appropriately assigning neutron dose to occupational workers.

OTHER ACTIVITIES – BASELINE

71151 – Performance Indicator Verification

The inspectors verified licensee performance indicators submittals listed below. (6 Samples)

- (1) IE01: Unplanned Scrams per 7000 Critical Hours Sample (Units 1 and 2, January December 2018
- (2) IE03: Unplanned Power Changes per 7000 Critical Hours Sample (Units 1 and 2, January December 2018
- (3) IE04: Unplanned Scrams with Complications Sample (Units 1 and 2, January December 2018)

71152 - Problem Identification and Resolution

Annual Follow-up of Selected Issues (IP Section 02.03) (4 Samples)

The inspectors reviewed the licensee's implementation of its corrective action program related to the following issues:

- (1) Unit 2, pressurizer master controller card failure, Condition Report 2017-658. Inspectors reviewed the plant response to the event, operator actions, corrective actions, and interviewed licensee personnel.
- (2) Unit 1, low head safety injection breaker failure, Condition Report 2017-20444. Inspectors reviewed the apparent cause investigation, operability evaluation, and corrective actions.
- (3) Unit 2, train C steam generator main control valve failed low in automatic mode, Condition Report 2017-17659. Inspectors reviewed the plant response to the event, operator actions, maintenance and engineering troubleshooting repair of the issue, interviewed licensee personnel and corrective actions.
- (4) Unit 2, train D qualified display processing system calibration procedure that resulted in exceeding the Technical Specification allowed outage time and placed the bistables into a trip condition, Condition Reports 2016-11346 and 2016-11257. The inspectors reviewed the prompt investigation, interviewed maintenance and engineering personnel, and evaluated the corrective actions.

71153 - Follow-up of Events and Notices of Enforcement Discretion

Event Report (IP Section 03.02) (2 Samples)

The inspectors evaluated the following licensee event reports which can be accessed at https://lersearch.inl.gov/LERSearchCriteria.aspx:

- LER 05000498/2017-002-00, "Unit 1 Condition Prohibited by Technical Specifications due to Inoperable Control Room Envelope Makeup Filtration System Heating Coil," on January 22, 2018:
- (2) LER 05000498/2018-001-00, "Unit 1 Main Steam Safety Valve As Left Settings Outside of Required Range Contrary to Technical Specifications due to Inadequate Procedure," on December 4, 2018:

OTHER ACTIVITIES - TEMPORARY INSTRUCTIONS, INFREQUENT AND ABNORMAL

<u>60854 – Preoperational Testing of an Independent Spent Fuel Storage Inspection (ISFSI)</u> <u>60855 – Operation of an ISFSI at Operating Plants</u> <u>60857 – Review of 10 CFR 72.48 Evaluations</u>

Inspections of dry cask storage operations were conducted at STP on January 21-25 and on January 28 through February 2, 2019, by inspectors from NRC Regions I, III, and IV. The STP ISFSI was licensed as a general 10 CFR Part 72 license and utilized the Holtec HI-STORM FW Certificate of Compliance (COC) 1032 Amendment 2 and HI-STORM FW Final Safety Analysis Report (FSAR) Revision 5.

In prior NRC ISFSI inspections at STP (ADAMS Accession Nos. ML18221A385 and ML19032A079), the NRC staff documented the observations and evaluations of many of the required pre-operational demonstrations from License Condition No. 9 of the COC performed by STP. Those inspections included an in-depth review of the licensee's dry

cask storage program implementation into existing 10 CFR Part 50 programs to support ISFSI operations at the site. The purpose of the NRC inspections in January and February 2019 were to: (1) observe and evaluate the remaining pre-operational demonstrations and training exercises which STP was required to complete prior to commencing loading operations, and (2) observe and evaluate the licensee's first loading operations. On January 21-25, 2019, the NRC staff observed STP complete the remaining demonstrations listed in License Condition No. 9 of the COC to allow use of the Holtec HI-STORM FW storage system. South Texas Project had successfully completed all the required pre-operations activities and fully demonstrated that the procedures, programs, and training related to those dry cask storage operations had been successfully integrated into its site operations. The subsequent week, from January 28 to February 2, 2019, NRC staff observed the licensee's first canister loading operations.

The ISFSI activities specifically reviewed during the on-site inspections and during in-office review included:

- Evaluated and observed dry run demonstrations from License Condition No. 9 of the COC, which included: preparation of the canister storage system for fuel loading; loading a dummy fuel assembly into the canister with appropriate independent verification; selection and verification of the specific fuel assemblies to ensure type conformance; remote installation of the canister lid; removal of the canister from the spent fuel pool; and unloading operations that included remotely removing a lid from the canister to support fuel unloading.
- 2. Reviewed the licensee's structural and seismic calculations for dry cask storage operations which included: over-head spent fuel building crane with loaded Transfer Cask (TC); loaded TC in the spent fuel pool's loading area; loaded TC in the canister wash-down area for processing operations; loaded TC in the stack-up configuration to support downloading of a canister into the concrete over-pack; loaded over-pack on low-profile transporter; and loaded over-pack being carried by the vertical cask transporter to the ISFSI pad.
- Reviewed two 10 CFR 72.48 safety evaluations performed by the licensee for changes made to the ISFSI program since the previous NRC ISFSI inspection per Inspection Procedure 60857.
- 4. Reviewed spent fuel documentation for the first canister to verify the fuel met all Appendix B Technical Specifications requirements for storage.
- 5. Evaluated and observed fuel selection and fuel loading operations associated with dry fuel storage canister No. 1.
- 6. Evaluated and observed welding of the canister, non-destructive testing of the welds, forced helium drying, helium backfill, and heavy load movements from the spent fuel pool to the site's vertical cask transporter.
- 7. Reviewed the licensee's loading, processing, and heavy load procedures associated with their current dry fuel storage campaign.
- 8. Reviewed the licensee's corrective action program's condition reports of issues identified for resolution since the previous NRC ISFSI inspection performed in November 2018.

- 9. Evaluated and observed the licensee's radiation protection implementation during the dry run and loading operations.
- 10. Evaluated and observed the licensee's implementation of foreign material exclusion process during the dry run and loading operations.

The inspectors did not identify any issues of concerns requiring documentation.

INSPECTION RESULTS

| Failure to Impleme | nt the Procedure for Equipment Failures | | |
|--|---|----------------|----------------|
| Cornerstone | Significance | Cross-cutting | Report |
| | | Aspect | Section |
| Initiating Events | Green | [H.12] - Avoid | 71152 |
| | FIN 05000499/2019-01 | Complacency | Problem |
| | Closed | | Identification |
| | | | and |
| | | | Resolution |
| The increase of the state of th | | | |

The inspectors identified a Green finding for the licensee's failure to implement the procedure for the failure of a plant generation risk (PGR) high risk component. Specifically, the licensee failed to implement and follow Procedure WCG-0008, "Preventing Recurring Equipment Problems (PREP)," Revision 7, following the failure of the Unit 2 steam generator 2C normal feedwater regulating control valve FCV-553.

Description:

On June 19, 2017, Unit 2 reactor operators responded to control room alarms and indications for steam flow/ feed flow mismatch for steam generator 2C. Operators identified that the steam generator 2C main feedwater regulating valve had failed closed and that steam generator level was decreasing for that steam generator. Operators entered the appropriate off-normal procedure and within 28 seconds regained control of steam generator levels by manually controlling feedwater flow through the main feedwater regulating valve. As a result of the failure, reactor power lowered to approximately 97 percent, average reactor coolant system temperature (T_{avg}) reached a maximum valve of 592.9 degrees F (normally T_{avg} is 592.0), and steam generator 2C narrow range level lowered to 52.8 percent (normally 70 percent).

Following the failure, engineering and maintenance discussed and implemented changing out a suspected nuclear tracker-driver (NTD) circuit card. This type of activity in the 7300 control cabinets is a high risk evolution and required a work activity risk review to help ensure no mistakes were made and that operations prepared for the worst case outcome. South Texas Project (STP) has site specific operating experience where card calibration and card replacement activities have resulted in reactor trips. Engineering was confident that the NTD circuit card was the problem. Maintenance personnel suggested measuring voltage readings at various locations inside the panel to ensure the faulty card was identified, however these measurements were not taken due to engineering's position that the NTD card was faulty. The inspectors attended the pre-job brief and observed the field work. Maintenance performed the card replacement successfully, but the issue remained. Maintenance and engineering regrouped and decided to take voltage measurements to identify the circuit card failure. Maintenance identified the nuclear control board (NCB) as the problem and replaced the NCB without issue. STP performed the high-risk evolution twice due to inadequate troubleshooting and over-reliance on engineering assumptions.

The licensee evaluated the operators' response to the main feedwater regulating valve failure and engineering and maintenance's response to troubleshooting and repair of the failed circuit card. The inspectors interviewed engineering and maintenance and determined that the licensee should have entered and implemented Procedure WCG-0008 following the failure of the Unit 2 steam generator 2C normal feedwater regulating control valve, FCV-553. The procedure would have ensured the appropriate degree of rigor was applied when pursuing resolution of high risk equipment issues. Specifically, Step 1.3 states, in part, "The PREP process entry criteria are: Loss of Key Equipment function/ Critical Attribute." The failure of the main feedwater regulating valve was a loss of key equipment function. The PREP process would have engaged more management oversight, directed the gathering of facts through Addendum 3, "Preventing Recurring Equipment Problems (PREP) checklist," and may have led to the development of a troubleshooting plan.

Corrective Actions: The licensee replaced the failed card and developed a lessons-learned presentation for engineering to use human performance tools, validate assumptions, and challenge recommendations (use technical conscience).

Corrective Action References: Condition Reports 2017-17659 and 2019-4368

Performance Assessment:

Performance Deficiency: The failure to enter and use station Procedure WCG-0008, "Preventing Recurring Equipment Problems (PREP)," Revision 7, following the failure of the Unit 2 steam generator 2C normal feedwater regulating control valve, FCV-553, was a performance deficiency. Specifically, the licensee failed to enter WCG-0008 upon the failure of the main feedwater regulating valve, a loss of key equipment function due to the component being classified as a high PGR. The result of not implementing this procedure was an increased probability of tripping the reactor due to possible human error while in the 7300 control cabinet.

Screening: The inspectors determined the performance deficiency was more than minor because it was associated with the human performance attribute and adversely affected the Initiating Events Cornerstone objective to limit the likelihood of events that can upset plant stability during power operations and is therefore a finding. Specifically, engineering relied on past experience and did not consider entering and implementing the PREP process procedure, which would have applied more rigor to troubleshooting and resolving the issue.

Significance: The inspectors used IMC 0609, Appendix A, Exhibit 1, "Initiating Events Screening Questions," issued June 19, 2012, to determine the finding was of very low safety significance, Green. Specifically, one finding did not cause a reactor trip and the loss of mitigation equipment relied upon to transition the plant from the onset of the trip to a stable shutdown condition.

Cross-cutting Aspect: H.12 - Avoid Complacency: Individuals recognize and plan for the possibility of mistakes, latent issues, and inherent risk, even while expecting successful outcomes. Individuals implement appropriate error reduction tools.

<u>Enforcement</u>: Inspectors did not identify a violation of regulatory requirements associated with this finding.

| Failure to Provide Adequate Procedural Guidance for a Surveillance Test | | | | |
|---|----------------------|----------------|----------------|--|
| Cornerstone | Significance | Cross-cutting | Report | |
| | | Aspect | Section | |
| Initiating Events | Green | [H.12] - Avoid | 71152 | |
| - | NCV 05000499/2019-02 | Complacency | Problem | |
| | Closed | | Identification | |
| | | | and | |
| | | | Resolution | |
| The inspectors documented a Green self-revealed NCV for the failure to provide an adequate procedure for a Unit 2 qualified display processing system (QDPS) surveillance procedure | | | | |
| that resulted in unnecessary troubleshooting, unnecessary replacement of properly operating circuit cards, and placing the loop 2 over-temperature delta-T (OTDT), over-pressure | | | | |
| delta-T (OPDT), and low T_{avg} feedwater isolation bistables into a TRIPPED condition, a | | | | |
| half-trip condition for the reactor. Following an investigation, the licensee discovered that | | | | |

incorrect biases were inputted into the QDPS surveillance procedure.

<u>Description</u>: On September 15, 2016, operations declared the loop 2 OTDT, OPDT, and the low T_{avg} feedwater isolation inoperable for loop calibration surveillance testing and bypassed the channel per Technical Specifications 3.3.1, items 8 and 9, action 6, and 3.3.2, item 5F, action 20. If not restored within 72 hours, the channel must be placed into a TRIPPED condition. During the performance of Surveillance Procedure 0PSP05-RC-0420, "Delta T and T average loop 2 Set Calibration (T-0420)," Revision 53, maintenance identified an out-of-tolerance condition. Engineering recommended maintenance perform a QDPS output calibration using Procedure 0PMP08-AM-APCD2, "QDPS Train D SGWLCS/TAS Input/Output Calibration," Revision 10. During this calibration, the licensee again identified an out-of-tolerance condition which could not be resolved. The licensee performed troubleshooting and began to replace circuit boards in the train D QDPS cabinet without success. On September 18, 2016, the bistables for the OTDT, OPDT, and Low T_{avg} feedwater isolation were placed into a TRIPPED condition as required by technical specifications.

The licensee subsequently discovered that an engineering error resulted in incorrect biases being placed into the Calibration Procedures 0PSP05-RC-0420 and 0PMP08-AM-APCD2. The two procedures were corrected with the proper biases and completed satisfactorily. The manual substitution of the resistance temperature detector (RTD) biases in the two calibration procedures had never been performed before and, due to the complex nature of the QDPS system, only three people on site could perform and peer check these biases. The licensee performed a prompt investigation and a review for organizational learnings. The licensee determined that the engineer made changes to the procedure to account for the two RTD operation, but failed to get the values peer checked for accuracy. This failure led to excessive out-of-service time, unnecessary QDPS maintenance, and having to place the loop 2 protection bistables into a TRIPPED condition, i.e. half reactor trip.

Corrective Actions: The licensee immediately corrected the procedures and re-performed the calibrations and satisfactorily performed analog channel operational testing. The licensee also developed a lessons-learned document and has an outstanding action to develop an engineering guideline when either unit is in two RTD operation.

Corrective Action References: Condition Reports 2016-11346, 2016-11257, 2019-4367

Performance Assessment:

Performance Deficiency: The failure to provide adequate procedures for maintenance on safety-related equipment was a performance deficiency. Specifically, engineering supplied inaccurate information to calibration procedures for the Unit 2 loop 2 and train D QDPS that resulted in unnecessary maintenance in QDPS and TRIPPED bistables associated with OTDT, OPDT, and low T_{avg} feedwater isolation which caused Unit 2 to be in a half reactor trip.

Screening: The inspectors determined the performance deficiency was more than minor because it is associated with the Procedure Quality attribute and adversely affected the Initiating Event Cornerstone objective to limit the likelihood of events that can upset plant stability during power operations and is therefore a finding. Specifically, the loop 2 bistables associated with OTDT, OPDT, and low T_{avg} were placed into a TRIPPED condition which placed Unit 2 one spurious reactor trip signal away from a true reactor trip due to the performance deficiency.

Significance: The inspectors used IMC 0609, Appendix A, Exhibit 1, "Initiating Events Screening Questions," issued June 19, 2012, to determine the finding was of very low safety significance, Green. Specifically, one finding did not cause a reactor trip and the loss of mitigation equipment relied upon to transition the plant from the onset of the trip to a stable shutdown condition.

Cross-cutting Aspect: H.12 - Avoid Complacency: Individuals recognize and plan for the possibility of mistakes, latent issues, and inherent risk, even while expecting successful outcomes. Individuals implement appropriate error reduction tools. The inspectors determined that the finding had a crosscutting aspect in the area of human performance associated with avoiding complacency. Specifically, engineering provided inaccurate biases for the procedure changes without utilizing appropriate error reduction tools [H.12].

Enforcement:

Violation: Technical Specification 6.8.1.a requires, in part, that written procedures shall be established, implemented, and maintained in accordance with Appendix A of Regulatory Guide 1.33, Revision 2, February 1978, Section 8.b.(L) reactor protection system tests and calibrations. The licensee established Procedure 0PSP05-RC-0420, "Delta T and T average loop 2 Set Calibration (T-0420)," Revision 53 to meet the Regulatory Guide 1.33 requirement. The Unit 2 data package loop 2 set 2 (T-0420) provides appropriate biases to be used to test and calibrate the loop.

Contrary to the above, on September 15, 2016, the licensee failed to ensure that the Unit 2 data package loop 2 set 2 (T-0420) provided the appropriate biases to be used to test and calibrate the loop. Specifically, engineering failed to provide accurate biases for procedures used for surveillance and calibration of the OTDT, OPDT, and low T_{avg} feedwater isolation trip setpoints.

Enforcement Action: This violation is being treated as a Non-Cited Violation, consistent with Section 2.3.2 of the Enforcement Policy.

| Minor Violation | 71153 |
|---|--------------|
| | Follow-up |
| | of Events |
| Minor Violation: Technical Specification 3.7.7, "Control Room Makeup and Cleanu | p Filtration |
| System," states, in part, that if one Control Room Makeup and Cleanup Filtration S | ystem is |
| inoperable, it must be restored to operable in Modes 1, 2, 3, and 4 within 7 days, or | r be in at |
| least hot standby within the next 6 hours and in cold shutdown within the following | 30 hours. |
| Contrary to the above, between September 27 and November 24, 2017, the license | ee failed to |
| restore one control room makeup and cleanup filtration system to operable. Specif | ically, the |
| licensee failed to properly jumper a circuit board for the control room makeup and o | cleanup |
| filtration system heating coil. | · |
| | |
| Screening: The inspectors determined the performance deficiency was minor. The | Э |
| inspectors found this violation to be minor in accordance with IMC 0612 Appendix I | |

Screening: The inspectors determined the performance deficiency was minor. The inspectors found this violation to be minor in accordance with IMC 0612 Appendix B, "Issue Screening," issued December 13, 2017, because the violation did not satisfy any of the four More-than-Minor screening questions.

Enforcement: This failure to comply with Technical Specification 3.7.7 constitutes a minor violation that is not subject to enforcement action in accordance with the NRC's Enforcement Policy.

| Licensee-Identified Non-Cited Violation | 71153 |
|--|---|
| | Follow-up |
| | of Events |
| This violation of very low safety significance was identified by the licensee and | |
| entered into the licensee corrective action program and is being treated as a N | on-Cited |
| Violation, consistent with Section 2.3.2 of the Enforcement Policy. | |
| Violation: Technical Specification 3.7.1.1, "Safety Valves," states, in part, that if on main steam line code safety valves are inoperable, they must be restored to opera within 24 hours or reduce the Power Range Neutron Flux High Trip Setpoint or be hot standby within the next 6 hours. Contrary to the above, between October 2 an the licensee failed to restore two of the Unit 1 steam generator B main steam safet operable status within 24 hours, failed to reduce the Power Range Neutron Flux H | ble status in at least d 6, 2018, ty valves to igh Trip |
| Setpoint, and failed to be in at least hot standby within the next 6 hours. Specifica licensee failed to identify that two of the Unit 1 Steam Generator B main steam saf were left outside of their Technical Specification required lift settings following test. Significance: Green. | ety valves |

The inspectors determined the performance deficiency was more than minor because it adversely affected the equipment performance attribute of the mitigating systems cornerstone objective to ensure the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences (i.e., core damage). The inspectors assessed the significance of the finding using Exhibit 2, "Mitigating Systems Screening Questions," of IMC 0609, Appendix A, "Significance Determination Process (SDP) for Findings At-Power," issued June 19, 2012, and determined this finding did not represent an actual loss of function. Therefore, the inspectors determined the finding was of very low safety significance (Green).

Corrective Action References: Condition Reports 2018-11811 and 2019-4374

EXIT MEETINGS AND DEBRIEFS

The inspectors verified no proprietary information was retained or documented in this report.

- On April 11, 2019, the inspector presented the quarterly resident inspector inspection results to Mr. G. T. Powell, President and Chief Executive Officer, and other members of the licensee staff.
- On March 21, 2019, the inspector presented the baseline radiation safety inspection to Mr. J. Connolly, Executive Vice President and Chief Nuclear Officer, and other members of the licensee staff.
- On March 21, 2019, the inspector presented the pre-operational dry run and first loading inspection to Mr. J. Connolly, Executive Vice President and Chief Nuclear Officer, and members of the licensee staff.

DOCUMENTS REVIEWED

71111.01-Adverse Weather

| Procedures Number | Title | F | Revision |
|----------------------|---------------------|---|----------|
| 0PGP03-ZV-0001 | Severe Weather Plan | 2 | 1 |

71111.04-Partial Equipment Alignment

Condition Reports

CR-2018-2825

| Procedures Number | Title | Revision |
|----------------------|--|----------|
| 0POP02-AF-0001 | Auxiliary Feedwater | 52 |
| 0POP02-SI-0002 | Safety Injection System Initial Lineup | 45 |
| 0PSP03-CH-0001 | Essential Chilled Water Pump 11A(21A) Inservice Test | 22 |
| 0POP02-EW-0001 | Essential Cooling Water Operations | 80 |

Drawings

| Number | Title | Revision |
|---------------|---|----------|
| 5R179F05007#1 | Chemical and Volume Control System | 52 |
| 5S142F00024#1 | Auxiliary Feedwater | 13 |
| 5N129F05015#2 | Safety Injection System | 21 |
| 5V119V10001#2 | HVAC Essential Chilled Water System | 33 |
| 5R289F05038#2 | Essential Cooling Water System Train 2B | 20 |

71111.05-Fire Protection

| Procedures Number | Title | Revision |
|----------------------|---|----------|
| 0FHB35-FP-0306 | Fire Preplan Fuel Handling Building Train B SI/CSS Cubicle | 2 |
| 0FHB35-FP-0307 | Fire Preplan Fuel Handling Building Train A SI/CSS Cubicle | 2 |
| 0PGP03-ZF-0011 | STPEGS Fire Brigade | 18 |
| 0DMB99-FP-0920 | Fire Preplan for Make-Up Demineralizer Building | 2 |
| 0TGB78-FP-0703 | Fire Preplan Turbine Generator Building BOP Diesel Generator Building | 3 |
| 0TGB90-FP-0702 | Fire Preplan for Turbine Generator Building 4.16 KV and Electrical Equipment Rooms | 3 |

| Procedures Number | Title | Revision |
|----------------------|--|----------|
| 0TGB90-FP-0710 | Fire Preplan Turbine Generator Building 13.8 KV Switchgear Room and Cable Vault | 3 |
| 0IVC48-FP-0403 | Fire Preplan Isolation Valve Cubicle Pump Room Train C | 3 |
| 0IVC49-FP-0402 | Fire Preplan Isolation Valve Cubicle Pump Room Train B | 3 |
| 0IVC50-FP-0401 | Fire Preplan Isolation Valve Cubicle, Pump Room Train A | 2 |
| 0IVC51-FP-0400 | Fire Preplan Isolation Valve Cubicle, Pump Room Train D | 2 |
| 0EAB-FP-0052 | Fire Preplan Electrical Auxiliary Building ESF Switchgear Room Train C | 4 |
| 0EAB-FP-0053 | Fire Preplan Electrical Auxiliary Building, Channel IV Battery and Distribution Room | 3 |
| 0EAB-FP-0054 | Fire Preplan Electrical Auxiliary Building, Motor Generator Room | 3 |
| 1ECW55-FP-0602 | Fire Preplan Essential Cooling Water Intake Structure Pump Room Train C | 5 |

71111.07A – Annual Heat Sink

| Procedures Number | Title | Revision |
|----------------------|--|----------|
| 0PMP05-CH-0003 | York Chiller Inspection & Maintenance 300 Tons | 13 |
| 0PGP03-ZE-0080 | Essential Cooling Water System Reliability Program | 2 |

Work Authorization Numbers

443062

71111.11-Simulator/Control Room Observation

| Condition Reports | | |
|----------------------|-------------------------------------|----------|
| CR-2019-364 | CR-2019-423 | |
| Procedures Number | Title | Revision |
| 0POP02-EH-0001 | Main Turbine EHCS | 77 |
| 0POP07-MS-0003 | Main Turbine Steam Inlet Valve Test | 29 |
| P&ID Number | Title | Revision |
| | | |
| 6S109F00017#1 | P&ID Main Steam | 28 |

| P&ID Number | Title | | | Revision |
|-----------------------|-----------------------------------|-------------------------|---------------|----------|
| 7T089F10001#1 | P&ID EH Fluid System | | | 57 |
| 71111.12-Maintenand | ce Effectiveness | | | |
| Condition Reports | | | | |
| CR-2015-18885 | CR-2017-15182 | CR-2017-23544 | CR-2018-9 | 95 |
| CR-2018-8533 | CR-2018-1108 | CR-2018-12813 | CR-2018-1 | 5270 |
| CR-2018-15273 | | | | |
| Work Authorization N | umbers | | | |
| 499003 | 519391 | 521829 | 532330 | |
| 540499 | 548908 | 568084 | 603714 | |
| Procedures Number | Title | | | Revision |
| 0PMP04-AF-0002 | Auxiliary Feedwater Pum | p Turbine Maintenanc | e | 41 |
| 0PMP04-AF-0003 | Auxiliary Feedwater Turb | ine Trip Throttle Valve | Maintenance | 36 |
| 0PSP03-AF-0007 | Auxiliary Feedwater Pum | p 14(24) Inservice Te | st | 5 |
| Drawings Number | Title | | | Revision |
| 6S109F00017#1 | Piping and Instrumentation | on Diagram Main Stea | m | 28 |
| 7T089F10001#1 | Piping and Instrumentation System | on Diagram Electro Hy | draulic Fluid | 51 |
| 71111.13-Maintenand | ce Risk and Emergent Wo | <u>ork</u> | | |
| Procedures Number | Title | | | Revision |
| 0PGP03-ZA-0091 | Configuration Risk Mana | gement Program | | 14 |
| 0POP01-ZO-0006 | Risk Management Action | s (RMAs) | | 27 |
| Work Activity Risk (W | /AR) | | | |
| 2804 | | | | |
| RasCal Sequences | | | | |
| 3331 | 3336 | 3337 | | |

71111.15-Operability Determinations and Functionality Assessments

| Condition Reports | | | | |
|-------------------------|--------------------------------------|--------------------------|---------------|----------|
| CR-2019-47 | CR-2019-347 | CR-2019-1377 | 19-2777 | |
| 19-637 | | | | |
| Drawings STI. Number | Title | | Date | |
| 31390502 | Cabinet-Control (Asse | mbly Engine Control) | 02/27/197 | '8 |
| 31298485 | , | arting Sequence Control | | |
| 71111.19-Post Maint | enance Testing | | | |
| Condition Reports | | | | |
| CR-2018-7676 | CR-2018-9443 | CR-2018-14727 | CR-2019-1 | 11 |
| CR-2019-893 | CR-2019-1762 | CR-2019-2357 | CR-2019-2 | 435 |
| CR-2019-2777 | CR-2019-1020 | | | |
| Work Authorization N | lumbers | | | |
| 545649 | 565703 | 571744 | 571827 | |
| 572175 | 576480 | 602665 | 604208 | |
| 604273 | 606453 | 573948 | 605423 | |
| Procedures Number | Title | | | Revision |
| 0PSP04-DG-0004 | Standby Diesel Gener | ator Fuel Oil Storage Ta | nk Inspection | 9 |
| 0PMP08-DO-9109 | ESF Diesel Generator Calibration | Fuel Oil Storage Tank L | evel | 3 |
| 0PSP03-EW-0011 | Essential Cooling Wat Measurement | er Pump 1B(2B) Referer | nce Values | 27 |
| 0PSP03-AF-0007 | Auxiliary Feedwater P | ump 14(24) Inservice Te | est | 51 |
| 0POP07-FP-0001 | Diesel Fire Pump Test | t | | 18 |
| 0PTP03-FP-0106 | Fire Protection Water | System Functional Test | | 20 |
| 0PSP03-DG-0002 | Standby Diesel 12(22) | Operability Test | | 64 |

| Miscellaneous Documents Number | Title | Revision |
|--------------------------------------|--|----------|
| VTD-T343-0001 | Installation and Service Instructions for Tuthill Cartridge Pumps | 1 |
| VTD-P104-0011 | Patterson Operation and Maintenance Manual for Double Suction Split Case Pumps | 0 |

71111.22-Surveillances

Condition Reports

CR-2019-975 CR-2019-1762

| Procedures Number | Title | Revision |
|----------------------|--|----------|
| 0POP02-AF-0001 | Auxiliary Feedwater | 52 |
| 0PSP03-AF-0007 | Auxiliary Feedwater Pump 14(24) Inservice Test | 51 |
| 0PMP05-ZE-0425 | MOV Diagnostic Testing (VOTES) – Rising Stem Valves | 2 |
| 0PEP07-AF-0003 | Dynamic Stroke Testing of Train A Auxiliary Feed Motor Operated Feed Regulating Valve | 3 |
| 0PSP03-DG-0003 | Standby Diesel 13(23) Operability Test | 63 |
| 0PMP07-DG-0001 | Standby Diesel Recording M&TE Installation | 5 |
| 0PSP03-DG-0002 | Standby Diesel 12(22) Operability Test | 64 |
| 0PSP03-EW-0018 | Essential Cooling Water System Train B Testing | 55 |

71124.02 – Occupational ALARA Planning and Controls

| CR-2018-3840 | CR-2018-3991 | CR-2018-4050 | CR-2018-4125 |
|---------------|---------------|--------------|---------------|
| CR-2018-4555 | CR-2018-4860 | CR-2018-5849 | CR-2018-6071 |
| CR-2018-8097 | CR-2018-9179 | CR-2018-9284 | CR-2018-11217 |
| CR-2018-12339 | CR-2018-13572 | CR-2019-234 | CR-2018-1066 |

| Procedures Number | Title | Revision |
|----------------------|--|----------|
| 0PGP03-ZR-0050 | Radiation Protection Program | 14 |
| 0PGP03-ZR-0052 | ALARA Program | 18 |
| 0PRP07-ZR-0001 | ALARA Engineering and Procedure Review | 4 |
| 0PRP07-ZR-0010 | Radiation Work Permits/Radiological Work ALARA Reviews | 38 |

| Procedures Number | Title | Revision |
|----------------------|---|----------|
| 0PRP07-ZR-0033 | Radiological Briefings | 7 |
| 0PRP07-ZR-0034 | Radiological Risk Management | 5 |
| | Conduct of Operations for Radiation Protection, Chapter 18: ALARA Planning | 4 |

Audits and Self-Assessments

| Number | Title | Date |
|----------------------|--|------------|
| 18-15289-1 | Snapshot Self-Assessment using NRC 71124, Att. 2 | 02/28/2019 |
| MN-19-0-107465 | Radiation Protection Department Annual Evaluation | 02/26/2019 |
| SOER 85-3/ SOER 01-1 | Excessive Personnel Radiation Exposures; Unplanned Radiation Exposures | 12/05/2018 |

Radiation Work Permits

| Number | Title | Revision |
|-------------|--|-----------|
| 2018-1-296 | 1RE21 - Transfer Cart Repair in the FHB / RCB Fuel Transfer Canals including RP Surveys and Decontamination | 6 0 |
| 2018-1-296 | 1RE21 - Transfer Cart Repair in the FHB / RCB Fuel Transfer Canals including RP Surveys and Decontamination | 5 1 |
| 2018-2-129 | 2RE19 – Steam Generator-Primary Side Support and Equipment Setup/Tear Down (HRA) – Medium Radiological Risk | 0 |
| 2018-2-130 | 2RE19 – Steam Generator-Primary Side Manway/Inserts Removal (LHRA) – High Radiological Risk | 0 |
| 2018-2-131 | 2RE19 – Steam Generator-Primary Side Nozzle Dams (LHRA) – Hig Radiological Risk | n 0 |
| 2018-2-131 | 2RE19 – Steam Generator-Primary Side Nozzle Dams (LHRA) – Hig Radiological Risk | n 1 |
| 2018-2-132 | 2RE19 – Steam Generator-Eddy Current Testing (LHRA) – High Radiological Risk | 0 |
| 2018-2-133 | 2RE19 – Steam Generator-Re-Install Primary Side Manway (HRA) – Medium Radiological Risk | 0 |
| 2018-2-135 | 2RE19 – Steam Generator-Secondary Side Inspections (HRA) | 0 |
| ALARA In-Pr | ogress Reviews | |
| Review | | |
| Number 7 | Title D | ate |
| 240 | Stud Detensioning 1 | 0/11/2018 |

| 249 | Stud Detensioning | 10/11/2018 |
|-----|-------------------|------------|
| 250 | HP Job Coverage | 10/12/2018 |

ALARA In-Progress Reviews

| Review Number | Title | Date |
|------------------|--|------------|
| 254 | HP Job Coverage in High Radiation Areas | 10/21/2018 |
| 255 | Request PMPI to provide craft support for the removal and installation of mechanical snubbers per 0PMP04-SN-0001 in support of snubber testing | 10/22/2018 |
| 257 | Contingency for Repairs to Unit 1 Fuel Handling Building Side Fuel Transfer System | 10/25/2018 |
| 259 | Fuel Movement/Reactor Containment Building (RCB) | 10/28/2018 |

ALARA Reviews

| Number | Title | Date |
|-----------|--|------------|
| 18-276-4 | ALARA Review: 2RE19 Snubber Inspections | 03/02/2018 |
| 18-276-4 | ALARA Close Out Review: 2RE19 Snubber Inspections | 05/24/2018 |
| 18-276-8 | ALARA Review: 2RE19 Steam Generator Inspections, Revision 1 | 04/04/2018 |
| 18-276-8 | ALARA Close Out Review: 2RE19 Steam Generator Inspections | 05/24/2018 |
| 18-7926-4 | ALARA Review: 1RE21 Non-Rapid Refuel | 10/02/2018 |
| 18-7926-5 | ALARA Review: 1RE21 Flow Accelerated Corrosion Inspections – In Service Inspections | 09/12/2018 |
| 18-7926-6 | ALARA Review: 1RE21 Room 003 Activities | 09/26/218 |
| 19-234 | ALARA Review: Dry Cask Storage | 01/16/2019 |
| 19-234 | ALARA Review: Initial DCS Campaign – Dry Cask Storage Supplement 1 | 01/25/2019 |

Miscellaneous

| Documents Number | Title | Date |
|---------------------|-----------------------------------|------------|
| | Refuel Outage 1RE20: ALARA Report | 09/06/2017 |
| | Refuel Outage 2RE18: ALARA Report | 05/18/2017 |
| | Refuel Outage 2RE19: ALARA Report | 07/18/2018 |

71124.04—Occupational Dose Assessment

| CR-2017-21141 | CR-2018-2745 | CR-2018-3052 | CR-2018-4574 | CR-2018-6875 |
|---------------|---------------|---------------|---------------|---------------|
| CR-2018-8097 | CR-2018-8247 | CR-2018-10111 | CR-2018-10591 | CR-2018-10771 |
| CR-2018-14460 | CR-2018-14735 | CR-2018-15144 | CR-2019-1215 | CR-2019-1254 |

| Procedures Number | Title | Revision |
|----------------------|--|----------|
| 0PGP03-ZR-0048 | Personnel Dosimetry Program | 20 |
| 0PGP03-ZR-0050 | Radiation Protection Program | 14 |
| 0PRP02-ZR-0007 | Evaluation of Intakes | 15 |
| 0PRP02-ZR-0010 | Personnel Exposure Investigation | 11 |
| 0PRP02-ZR-0013 | Determination of Skin Dose | 10 |
| 0PRP02-ZR-0017 | Dose to the Embryo/Fetus | 3 |
| 0PRP02-ZX-0022 | Non-Routine Dosimetry Issue and Control | 12 |
| 0PTP04-ZC-0047 | Calibration of the Siemens Environmental Systems Limited / Thermo Electron Corporation Electronic Personal Dosimeter | 15 |

Audits and Self-Assessments

| Number | Title | Date |
|----------|---|------------|
| 100555-0 | Mirion Technologies (GDS), Inc. Onsite NVLAP Assessment Report | 01/09/2018 |
| | Snapshot Assessment: Dosimetry Program 2018 | 12/04/2018 |
| | Snapshot Self-Assessment using NRC Inspection Procedure 71124.04 Occupational Dose Assessment Criteria | 02/19/2019 |

Personnel Exposure Records

| 2017-07 | 2017-28 | 2017-29 | 2017-30 | 2017-49 |
|---------|---------|---------|---------|---------|
| 2018-08 | 2018-09 | 2018-10 | 2018-11 | 2018-23 |
| 2018-24 | 2018-35 | 2018-40 | 2018-41 | 2018-42 |
| 2018-43 | 2018-44 | 2018-45 | | |

71152-Issue Follow-up

| Contaition reports | | | | |
|--------------------|-------------|--------------|--------------|--|
| CR-2008-9639 | CR-2019-893 | CR-2019-1762 | CR-2019-1954 | |
| CR-2019-2357 | | | | |
| Work Authorizatior | Numbers | | | |
| 335148 | 572175 | 576480 | 604273 | |
| 606453 | 607307 | | | |
| | | | | |

| Procedures Number | Title | Revision |
|--------------------------------------|--|---------------------|
| 0PMP04-EW-0001A | Essential Cooling Water Pump Maintenance (Product- Lubricated Bearing Design) | 7 |
| 0POP02-EW-0001 | Essential Cooling Water Operations | 79 |
| Miscellaneous Documents Number | Title | Revision or Date |
| VTD-H127-0006 | 24 VSN Centrifugal Pump Installation and Operation Manual | 6 |
| DCP 06-15147-45 | Replace Essential Cooling Water Pump 2B | 02/26/2009 |

4OA5.1 Other Activities (IP 60854, IP 60855, IP 60857)

| CR-2018-14418 | CR-2018-14718 | CR-201814770 | CR-2019-540 | |
|---------------|---------------|--------------|-------------|--|
| CR-2019-630 | CR-2019-631 | CR-2019-665 | CR-2019-706 | |
| CR-2019-816 | | | | |

| Procedures Number | Title | Revision |
|----------------------|--|----------|
| 0PEP02-ZM-0012 | Fuel Selection for Dry Cask Storage | 0 |
| 0DCS03-ZO-0002 | HI-STORM and MPC Pre-Use Inspections | 1 |
| 0DCS03-ZO-0003 | MPC Loading Operations | 4 |
| 0DCS03-ZO-0004 | MPC Closure Operations | 1 |
| 0DCS03-ZO-0005 | MPC Transfer Operations | 2 |
| 0DCS03-ZO-0007 | MPC Unloading Operations | 1 |
| 0DCS03-ZO-0001 | HI-STORM Transport Operations | 2 |
| 0DCS03-ZO-0008 | DCS Abnormal Response | 1 |
| PI-OP-HLTC-H-01 | PCI Closure Welding of MPC Procedure | 3 |
| GQP – 9.2 | PCI Liquid Penetrant Procedure | 10 |
| GQP – 9.6 | PCI Visual Examination of Welds Procedure | 18 |
| 0PGP03-ZX-0002 | Condition Reporting Process | 52 |
| 0PQP01-ZA-0003 | Vendor Overview Activities (numerous) | 9 |
| 0PRP07-ZR-0036 | Radiological Controls for Dry Cask Storage | 0 |
| N/A | ALARA Review Package | 0 |
| 0DCS01-ZA-0001 | Dry Cask Storage Program Implementation | 0 |

| Procedures Number | Title | Revision |
|--|--|--|
| 0DCS02-ZN-0002 | 10CFR72.48 Screening and Evaluations | 0 |
| WPS 8 MN-GTAW | ASME Section XI Welding Procedure Specification | 7 |
| WPS 8 MC-GTAW | ASME Section XI Welding Procedure Specification | , 16 |
| PI-CNSTER-OP- HLTC-H-01 | Closure Welding of Holtec Multi-Purpose Canisters | 3 |
| 0PEP02-ZM-012 | Fuel Selection for Dry Cask Storage | 0 |
| Design Basis Documents Number | Title | Revision |
| HI-2114830 | Final Safety Analysis Report on the HI-STORM FW MPC Storage System | 5 |
| N/A | Certificate of Compliance No. 1032 | 2 |
| 72.212 | STP ISFSI 10 CFR 72.212 Report | 0 |
| Miscellaneous Documents Number | Title | Revision or Date |
| 72.48 Screen | Initial Issue of STP ISFSI 10 CFR 72.212 Report | 0 |
| 72.48 Eval | Initial Issue of STP ISFSI 10 CFR 72.212 Report | 0 |
| 72.48 Eval | Non-Mechanistic Tipover Analysis for STP | 0 |
| | Design Depart Stainless Steel Oats Cost, Channel | |
| VTI B056404 | Design Report Stainless Steel Gate Cask Channel | 0 |
| VTI B056404 58171-14-107 | Whiting Corp Seismic Analysis Derived Values for 150 ton Crane | 0 04/13/2015 |
| | Whiting Corp Seismic Analysis Derived Values for 150 ton | - |
| 58171-14-107 | Whiting Corp Seismic Analysis Derived Values for 150 ton Crane | 04/13/2015 |
| 58171-14-107 5817-14-050 | Whiting Corp Seismic Analysis Derived Values for 150 ton Crane Seismic Analysis for STP 150 ton Crane | 04/13/2015 0 |
| 58171-14-107 5817-14-050 CC09978 | Whiting Corp Seismic Analysis Derived Values for 150 ton Crane Seismic Analysis for STP 150 ton Crane FHB Crane Seismic Analysis Decoupling Evaluation | 04/13/2015 0 0 |
| 58171-14-107 5817-14-050 CC09978 B05315-0005 | Whiting Corp Seismic Analysis Derived Values for 150 ton Crane Seismic Analysis for STP 150 ton Crane FHB Crane Seismic Analysis Decoupling Evaluation Seismic Stability HI-STORM/HI-TRAC Stack-up at STP | 04/13/2015 0 0 8 |
| 58171-14-107 5817-14-050 CC09978 B05315-0005 B05315-0003 | Whiting Corp Seismic Analysis Derived Values for 150 ton Crane Seismic Analysis for STP 150 ton Crane FHB Crane Seismic Analysis Decoupling Evaluation Seismic Stability HI-STORM/HI-TRAC Stack-up at STP STP Low Profile Transporter Analysis | 04/13/2015 0 0 8 4 |
| 58171-14-107 5817-14-050 CC09978 B05315-0005 B05315-0003 B05315-00062 | Whiting Corp Seismic Analysis Derived Values for 150 ton Crane Seismic Analysis for STP 150 ton Crane FHB Crane Seismic Analysis Decoupling Evaluation Seismic Stability HI-STORM/HI-TRAC Stack-up at STP STP Low Profile Transporter Analysis Time History Generation for STP | 04/13/2015 0 0 8 4 5 |
| 58171-14-107 5817-14-050 CC09978 B05315-0005 B05315-0003 B05315-00062 B05315-00066 | Whiting Corp Seismic Analysis Derived Values for 150 ton Crane Seismic Analysis for STP 150 ton Crane FHB Crane Seismic Analysis Decoupling Evaluation Seismic Stability HI-STORM/HI-TRAC Stack-up at STP STP Low Profile Transporter Analysis Time History Generation for STP Dynamic Analysis of HI-TRAC in Cask Wash-down area | 04/13/2015 0 0 8 4 5 3 |
| 58171-14-107 5817-14-050 CC09978 B05315-0005 B05315-0003 B05315-00062 B05315-00066 B05315-00068 | Whiting Corp Seismic Analysis Derived Values for 150 ton Crane Seismic Analysis for STP 150 ton Crane FHB Crane Seismic Analysis Decoupling Evaluation Seismic Stability HI-STORM/HI-TRAC Stack-up at STP STP Low Profile Transporter Analysis Time History Generation for STP Dynamic Analysis of HI-TRAC in Cask Wash-down area Dynamic Analysis of HI-TRAC in Cask Loading Pool Structural evaluation of Cask Loading and wash-down | 04/13/2015 0 0 8 4 5 3 2 |
| 58171-14-107 5817-14-050 CC09978 B05315-0005 B05315-0003 B05315-00062 B05315-00068 B05315-00068 B05315-00069 | Whiting Corp Seismic Analysis Derived Values for 150 ton Crane Seismic Analysis for STP 150 ton Crane FHB Crane Seismic Analysis Decoupling Evaluation Seismic Stability HI-STORM/HI-TRAC Stack-up at STP STP Low Profile Transporter Analysis Time History Generation for STP Dynamic Analysis of HI-TRAC in Cask Wash-down area Dynamic Analysis of HI-TRAC in Cask Loading Pool Structural evaluation of Cask Loading and wash-down areas | 04/13/2015 0 0 8 4 5 3 2 1 |

| Miscellaneous Documents Number | Title | Revision or Date |
|--|--|---------------------|
| N/A | CK0001 – Fuel Selection for Dry Cask Storage | 08/30/2018 |
| N/A | CK0002 – Fuel Selection for Dry Cask Storage | 08/30/2018 |
| N/A | CK0003 – Fuel Selection for Dry Cask Storage | 08/30/2018 |
| N/A | CK0004 – Fuel Selection for Dry Cask Storage | 08/30/2018 |
| N/A | CK0005 – Fuel Selection for Dry Cask Storage | 08/30/2018 |
| RRTI 2319-11R0 | Response to Request for Technical Information | 02/12/2019 |
| 50.59 Screen 13- 6991-1 Supp 5 & 13- 6991-2 Supp 6 | 01-1 Supp 5 & 13- Cask Connecting Channel (CCC) Gate and Liner | |
| DCP 13-6991-1 Supp. 0 | 5 1 5 | |
| WO No. 96009469 | HI Storm Overpack #6 | 01/15/2019 |

The following items are requested for the Occupational Radiation Safety Inspection at South Texas Project

Dates of Inspection: 03/18/2019 to 03/22/2019

Integrated Report 2019001

Inspection areas are listed in the attachments below.

Please provide the requested information on or before Monday, March 04, 2019.

Please submit this information using the same lettering system as below. For example, all contacts and phone numbers for Inspection Procedure 71124.02 should be in a file/folder titled "2-A," applicable organization charts in file/folder "2-B," etc.

The information should be provided in electronic format or a secure document management service. If information is placed on *a secured document management system*, please ensure the inspection exit date entered is at least 30 days later than the onsite inspection dates, so the inspectors will have access to the information while writing the report. In addition to the corrective action document lists provided for each inspection procedure listed below, please provide updated lists of corrective action documents at the entrance meeting. The dates for these lists should range from the end dates of the original lists to the day of the

entrance meeting.

If more than one inspection procedure is to be conducted and the information requests appear to be redundant, there is no need to provide duplicate copies. Enter a note explaining in which file the information can be found.

If you have any questions or comments, please contact Bernadette Baca at 817-200-1235 or via e-mail at Bernadette.Baca@nrc.gov.

PAPERWORK REDUCTION ACT STATEMENT

This letter does not contain new or amended information collection requirements subject to the Paperwork Reduction Act of 1995 (44 U.S.C. 3501 et seq.). Existing information collection requirements were approved by the Office of Management and Budget, control number 3150-0011.

2. Occupational ALARA Planning and Controls (71124.02)

Date of Last Inspection: March 26, 2018

- A. List of contacts and telephone numbers for ALARA program personnel, as well as the Licensing/Regulatory Affairs staff. Please include area code and prefix. If work cell numbers are appropriate, then please include them as well.
- B. Applicable organization charts including position or job titles. Please include as appropriate for your site, Site Management, RP, Chemistry, Maintenance (I&C), Engineering, and Emergency Protection. (Recent pictures are appreciated.)
- C. Copies of audits, self-assessments, LARs, and LERs, written since the date of last inspection, focusing on ALARA
- D. Procedure index for ALARA Program procedures and other related disciplines.
- E. Please provide specific procedures related to the following areas noted below. Additional Specific Procedures may be requested by number after the inspector reviews the procedure indexes.
 - 1. ALARA Program
 - 2. ALARA Planning
 - 3. ALARA Reviews
 - 4. ALARA Committee
 - 5. Radiation Work Permit Preparation
- F. Please provide a list of NRC Regulatory Guides and NUREGs that you are currently committed to relative to this program. Please include the revision and/or date for the commitment and where this may be located in your current licensing basis documents.
- G. Please provide a summary list of corrective action documents (including corporate and sub-tiered systems) written since the date of last inspection, related to the ALARA program, including exceeding RWP Dose Estimates.

NOTE: These lists should include a description of the condition that provides sufficient detail that the inspectors can ascertain the regulatory impact, the <u>significance level</u> assigned to the condition, the status of the action (e.g., open, working, closed, etc.) and the <u>search criteria</u> used. Please provide in document formats which are "sortable" and "searchable" so that inspectors can quickly and efficiently determine appropriate sampling and perform word searches, as needed. (Excel spreadsheets are the preferred format.) If codes are used, please provide a legend for each column where a code is used.

H. List of work activities (RWPs) greater than 1 rem, since date of last inspection, including the original dose estimates and actual doses accrued. (Excel format preferred). Please provide all revisions/changes, as well as any related RWPs that support the work activity.

SOUTH TEXAS PROJECT ELECTRIC GENERATING STATION, UNITS 1 AND 2, NRC INTEGRATED INSPECTION REPORT 05000498/2019001; 05000499/2019001, AND INDEPENDENT SPENT FUEL STORAGE INSPECTION 07201041/2019001 – May 8, 2019

DISTRIBUTION:

SMorris, RA MShaffer, DRA AVegel, DRP MHay, DRP RLantz, DRS GMiller, DRS DCylkowski, RC MMcCoppin, RIV/OEDO VDricks, ORA JWeil, OCA EMiller, NRR AMoreno, RIV/CAO BMaier, RSLO **RKellar**, IPAT NTaylor, DRP BTharakan, DRP JMelfi, DRP ECombs. DRP ASanchez, DRP JChoate, DRP LRevna, DRP PJayroe, IPAT MHerrera, DRMA JKatanic, DNMS **TPruett**, **DNMS** R4Enforcement LHowell, DNMS JKatanic, FCDB LBrookhart, FCDB ESimpson, FCDB OMasnyk Bailey, RI REdwards, RIII MLearn. RIII MKunowski, RIII RPowell, RI WAllen, DSFM

Electronic Distribution for South Texas Project

| SUNSI Review | / ADAM | | Non-Publicly Ava | ilable ■No | on-Sensitive | Keyword: |
|--------------|------------|------------|--------------------|------------|--------------|------------|
| By: NTaylor | ■Yes | □ No ■F | Publicly Available | 🗆 S | ensitive | NRC-002 |
| OFFICE | SRI:DRP/B | RI:DRP/B | C:DRS/OB | C:DRS/IPAT | C:DRS/EB1 | C:DRS/EB2 |
| NAME | ASanchez | JChoate | GWerner | RKellar | VGaddy | JDrake |
| SIGNATURE | AAS | JMC | GEW | RLK | VGG | JFD |
| DATE | 05/08/19 | 05/03/2019 | 04/30/2019 | 04/30/2019 | 04/30/2019 | 04/29/2019 |
| OFFICE | C:DNMS/CHP | C:DRS/RCB | BC:DRP/B | | | |
| NAME | GWarnick | NMakris | NTaylor | | | |
| SIGNATURE | GXW | NJM | NHT | | | |
| DATE | 05/06/2019 | 4/29/19 | 5/8/19 | | | |

ADAMS ACCESSION NUMBER: ML19128A334

OFFICIAL RECORD COPY