



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555-0001

May 22, 2019

Mr. Mano Nazar
President and Chief Nuclear Officer
Nuclear Division
NextEra Energy Point Beach, LLC
Mail Stop: EX/JB
700 Universe Blvd
Juno Beach, FL 33408

SUBJECT: POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2 – CORRECTION LETTER
FOR AMENDMENT NOS. 264 AND 267 TO ADOPT TSTF-547,
"CLARIFICATION OF ROD POSITION REQUIREMENTS"
(EPID L-2018-LLA-0207)

Dear Mr. Nazar:

On March 27, 2019 (Agencywide Documents Access and Management System Accession (ADAMS) Accession No. ML19052A544), the U.S. Nuclear Regulatory Commission (NRC) issued Amendment Nos. 264 and 267 to Renewed Facility Operating License Nos. DPR-24 and DPR-27 for the Point Beach Nuclear Plant (PNBP) Units 1 and 2, respectively.

The amendments revised the PBNP, Units 1 and 2, technical specifications (TS) to provide time to repair rod movement failures that do not affect rod operability, correct conflicts between the TS, increase consistency between the subject TS, and improve the format and presentation. The changes are consistent with NRC-approved Technical Specifications Task Force (TSTF) Change Traveler TSTF-547, Revision 1, "Clarification of Rod Position Requirements."

Following issuance of the amendments, the NRC staff was informed by the licensee regarding the following errors in the TS pages:

1. Page 3.1.4-2 - The required action B.2.5 is incorrect. The required action was changed to B.5, and other formatting changes were made.
2. Page 3.1.6-1 - The word "overlap" is missing in the required action A.3. The required action A.3 needs to be revised to: "Restore the control bank to within the insertion sequence, and **overlap** limits specified in the COLR." In addition, other formatting changes were made.

The NRC staff determined that these errors were entirely administrative in nature, and were inadvertently introduced, and did not affect the associated notice to the public. Thus, according to the NRC's policy established by SECY-96-238 (ADAMS No. 9611250030 (Legacy Library)), these errors can be corrected by a letter. Enclosed, please find the replacement TS pages.

These corrections do not change any of the conclusions in the safety evaluation associated with the amendments. We regret any inconvenience this may have caused.

M. Nazar

- 2 -

If you have any questions regarding this matter, I may be reached at 301-415-8371.

Sincerely,

A handwritten signature in cursive script, appearing to read "Chawla".

Mahesh L. Chawla, Project Manager
Plant Licensing Branch III
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket Nos. 50-266 and 50-301

Enclosure:
Corrected TS Pages

cc: Listserv

Enclosure
Technical Specification Pages

ACTIONS (continued)

CONDITION	REQUIRED ACTION	COMPLETION TIME
<p>B. One rod not within alignment limits.</p>	<p>B.1.1 Verify SDM to be within the limits provided in the COLR.</p> <p style="text-align: center;"><u>OR</u></p>	<p>1 hour</p>
	<p>B.1.2 Initiate boration to restore SDM to within limit.</p> <p style="text-align: center;"><u>AND</u></p>	<p>1 hour</p>
	<p>B.2 Reduce THERMAL POWER to $\leq 75\%$ RTP.</p> <p style="text-align: center;"><u>AND</u></p>	<p>2 hours</p>
	<p>B.3 Verify SDM to be within the limits provided in the COLR.</p> <p style="text-align: center;"><u>AND</u></p>	<p>Once per 12 hours</p>
	<p>B.4 Perform SR 3.2.1.1, 3.2.1.2, and 3.2.2.1.</p> <p style="text-align: center;"><u>AND</u></p> <p>B.5 Re-evaluate safety analyses and confirm results remain valid for duration of operation under these conditions.</p>	<p>72 hours</p> <p>5 days</p>
<p>C. Required Action and associated Completion Time of Condition B not met.</p>	<p>C.1 Be in MODE 3.</p>	<p>6 hours</p>

(continued)

3.1 REACTIVITY CONTROL SYSTEMS

3.1.6 Control Bank Insertion Limits

LCO 3.1.6 Control banks shall be within the insertion, sequence, and overlap limits specified in the COLR.

-----NOTE-----
Not applicable to control banks inserted while performing SR 3.1.4.2.

APPLICABILITY: MODE 1,
MODE 2 with $k_{eff} \geq 1.0$.

ACTIONS

CONDITION	REQUIRED ACTION	COMPLETION TIME
A. Control bank A, B, or C inserted ≤ 10 steps beyond the insertion, sequence, or overlap limits specified in the COLR.	A.1 Verify all shutdown banks are within the insertion limits specified in the COLR.	1 hour
	<u>AND</u>	
	A.2.1 Verify SDM is within the limits specified in the COLR.	1 hour
	<u>OR</u>	
	A.2.2 Initiate boration to restore SDM to within limit.	1 hour
	<u>AND</u>	
	A.3 Restore the control bank to within the insertion, sequence, and overlap limits specified in the COLR.	24 hours

(continued)

SUBJECT: POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2 – CORRECTION LETTER
FOR AMENDMENT NOS. 264 AND 267 TO ADOPT TSTF-547,
"CLARIFICATION OF ROD POSITION REQUIREMENTS"
(EPID L-2018-LLA-0207) DATED MAY 22, 2019

DISTRIBUTION:

PUBLIC

RidsNrrDorLpl3-1Resource

RidsNrrPMPPointBeachResource

RidsOgcRp Resource

RidsAcrsAcnw_MailCTR Resource

RidsNrrDorLDprResource

RidsNrrLASRohrerResource

RidsRgn3MailCenterResource

NRR, RBeaton

NRR, RGrover

ADAMS Accession No. ML19134A284***via email**

OFFICE	DORL/LPL3-1/PM	DORL/LPL3-1/LA	DSS/SRXB/BC*
NAME	MChawla	SRohrer	JWhitman
DATE	5/22/19	5/22/19	5/16/19
OFFICE	DSS/STSB/BC(A)*	DORL/LPL3-1/BC	DORL/LPL3-1/PM
NAME	PSnyder	DWrona	MChawla
DATE	5/16/19	5/22/19	5/22/19

OFFICIAL RECORD COPY