
Repair of Doel 1 NPP Reactor Vessel Head Penetrations

International Workshop on Age-Related Degradation of Reactor Vessels and Internals, USNRC, Washington, 23-24/5/2019



PUBLIC



INTERNAL



RESTRICTED




CONFIDENTIAL

Repair Reactor Vessel Head penetrations Doel 1

Status in June 2017

- 49 adapters
- VT: no degradation reported
- UT: 25 relevant indications in 14 adapters
 - OD surface indications, considered axial, close to J-groove weld fusion line
 - Since 2016, 2 new indications and slight growth of known indications (but << to predictions)
 - Justification for Continued Operation up to outage June 2018
 - Qualification of Inside Diameter Temper Bead repair in 2017
 - June 2018: ISI of all 49 adapters, and repair of 14 affected adapters



Repair Reactor Vessel Head penetrations Doel 1

Inspection and repair in 2018

- Doel 1 – 2018: UT + repair by IDTB

- Pre-ISI PWSCC locations



- Originally scheduled (14) repair locations



- Two new indications detected by UT in 2018


- Penetration 26 : seen not reported in 2017




- Penetration 16 : not observed in 2017




- Total of 16 repaired penetrations




Repair Reactor Vessel Head penetrations Doel 1 IDTB Repair Process (1/2)




Typical Existing Configuration



Step 1
Cutting and Removal of
Thermal Sleeve




Step 2
Roll Expansion




Step 3
Adapter boring, weld
Prep Machining and
manual PT




Repair Reactor Vessel Head penetrations Doel 1 IDTB Repair Process (2/2)




Step 4
Temper Bead
Welding (GTAW)



Step 5
Machining, UT,
automated PT, rotary
peening and PT



Step 6
Thermal Sleeve
Replacement



Typical Final
Configuration



SUMO Rocky Manipulator

Repair Reactor Vessel Head penetrations Doel 1

Qualification of repair




- Demonstration of full process on dummy half-head mockup
- Qualification of welding process, welders and welding products
 - Use of several test coupons
 - ASME IX requirements + additional tests



Repair Reactor Vessel Head penetrations Doel 1

Hardness issue encountered during qualification

- Hardness value in HAZ > 380 HV₁₀



Sample	Vickers Microhardness HV10														
	Weld Metal Location					HAZ Location					Base Metal Location				
	1	2	3	4	5	1	2	3	4	5	1	2	3	4	5
IDTB02-HRD-01	200	205	229	225	228	360	321	318	296	351	271	214	218	208	215
IDTB02-HRD-02	241	221	211	248	238	434	301	298	296	320	280	194	195	195	203
IDTB02-HRD-03	205	189	228	222	239	360	307	312	312	343	242	199	206	201	205
IDTB02-HRD-04	180	187	217	216	208	367	298	354	277	314	191	195	192	203	213
Required	380 Max														

Macrography

Micrography


Repair Reactor Vessel Head penetrations Doel 1

Issues encountered during repair

- During qualification, welding parameters and sequence had to be optimized in order to have sufficient tempering and acceptable hardness values in HAZ
- During repair, breakdown of cutting tools used to cut and remove thermal sleeves
 - FRAMATOME Inc. never encountered this issue before
 - Issue may have been due to a very slight inclination of the thermal sleeves (approx. 0.5-1°)
 - Solution : tooling adaptations with tests done at Lynchburg and copied at Doel

In-Service-Inspection of repaired penetrations

- Without thermal sleeve



- With thermal sleeve

