

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

<p>1. LICENSEE/LOCATION INSPECTED:</p> <p>Integrated Science Support, Inc. 14450 N. 169 Highway Smithville, MO 64089</p> <p>REPORT NUMBER(S) 2019-001</p>	<p>2. NRC/REGIONAL OFFICE</p> <p>Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352</p>
---	---

<p>3. DOCKET NUMBER(S)</p> <p>030-38746</p>	<p>4. LICENSE NUMBER(S)</p> <p>24-35155-01</p>	<p>5. DATE(S) OF INSPECTION</p> <p style="text-align: center; font-size: 1.5em;">5/21/19</p>
---	--	--

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

\_\_\_\_\_ Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.  
(Violations and Corrective Actions)

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Kevin G. Null		5/21/19
BRANCH CHIEF	Debra T. McCann		5/31/19

**Docket File Information**  
**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:

Integrated Science Support, Inc.  
14450 N. 169 Highway  
Smithville, MO 64089

REPORT NUMBER(S) 2019001

2. NRC/REGIONAL OFFICE

Region III  
U. S. Nuclear Regulatory Commission  
2443 Warrenville Road, Suite 210  
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-38746

4. LICENSE NUMBER(S)

24-35155-01

5. DATE(S) OF INSPECTION

May 21, 2019

6. INSPECTION PROCEDURES USED

87126

7. INSPECTION FOCUS AREAS

All

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S)

3220

2. PRIORITY

5

3. LICENSEE CONTACT

Greg Sackett, RSO

4. TELEPHONE NUMBER

(816) 390-9011

- Main Office Inspection      Next Inspection Date: 05/21/2024
- Field Office Inspection \_\_\_\_\_
- Temporary Job Site Inspection \_\_\_\_\_

**PROGRAM SCOPE**

This was a routine, unannounced inspection of a licensee that was authorized to possess byproduct material with Atomic Numbers 1-83 incident to the performance of leak testing of sealed sources as a service. At the time of the inspection, the licensee had 15 nuclear medicine clients, which included 9 Agreement State licensees and 6 NRC licensees. The licensee had three full-time health physicists, and one full-time and one part-time administrative staff members.

**Performance Observations**

The inspector interviewed the radiation safety officer (RSO)/health physicist and the company president/health physicist, and toured the facility. The inspector also reviewed an inventory of sealed sources that were used by the licensee for calibrating two well counters, a random sampling of leak test results reported to three NRC-licensed customers, and well counter efficiency records. The inspector also noted the possession of two survey meters that were calibrated by an outside, NRC licensed firm. The RSO described the licensee's internal training program, and routine radiation protection audits that they also performed for their customers.

The inspector performed independent surveys of the licensee's facility. The results of the surveys were not distinguishable from background levels ranging from 0.03 - 0.05 mrem/hour.

No violations of NRC requirements were identified.