NRC FORM 591M PART 1 U.S. NUCLEAR REGULATORY COMMISSION									
10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION									
1. LICENSEE/LOCATIO	N INSPECTED:		2. NRC/REGIONAL OFFICE						
II-4 Clos4- Nicolo	. N. 4. 4								
Hot Shots Nuclea			Region III						
2296 US Hwy. 41 Marquette, MI 49			U. S. Nuclear Regulatory Commission						
Marquette, Mi 49	7633		2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352						
REPORT NUMBER(S	s) 2019001		Lisie, IL 00332-4332						
3. DOCKET NUMBER(S		4. LICENSE NUMBER	R(S) 5. DATE(S) OF INSPECTION						
030-38407		21 22912 01141	`	M? > 2010					
030-38407		21-32812-01MD		May 入入 2019					
LICENSEE:									
	n examination of the activities conduct ion (NRC) rules and regulations and the								
procedures and repre	esentative records, interviews with pers	connel, and observati	ons by the inspector. The inspec	ection findings are as fol	lows:				
1. Based on	the inspection findings, no violations v	vere identified.							
2. Previous	violation(s) closed.								
non-repet	The violations(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.								
4.00.000	Non-cited violation(s) were discuss	sed involving the follo	wing requirement(s):						
		od intolving the folio	wing rodalionicity.						
	•								
					ŧ				
During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)									
ļ ·									
Statement of Corrective Actions									
I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.									
TITLE	PRINTED NAME	Witter Witter	SIGNATURE	ou, armous specimonity re	DATE				
LICENSEE'S									
REPRESENTATIVE			/						
NRC INSPECTOR	Jason D. Draper, Health Physicis	t /	la o - yr		5/22/19				
BRANCH CHIEF	Aaron T. McCraw		1/1/1/-		6/4/19				

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION 1. LICENSEELOCATION INSPECTED. Hot Shots Nuclear Medicine 2296 US Hwy. 41 S Marquette, MI 49855 REPORT NUMBER(S) 2019001 3. DOCKET NUMBER(S) 2019001 4. LICENSE NUMBER(S) 8. DATE(S) OF INSPECTION May 22, 2019 3. DOCKET NUMBER(S) 2019001 7. INSPECTION PROCEDURES USED 7. INSPECTION INFORMATION 1. PROGRAM CODE(S) 2 PRIORITY 8. JUCINSEE CONTACT 8. THE PRIORIES NUMBER (906) 273-1306 Walson Office Inspection Next Inspection Date: 05/22/2021 Field Office Inspection Freogram Scope This was an unannounced, routine inspection of a radiopharmacy outside Marquette, Michigan that served the Upper Peninsula of Michigan. The licensee was authorized to use byproduct material to prepare radiopharmaceuticals for use by nuclear medicine licensees for medical procedures. At the time of the inspection, the radiopharmacy operated Monday through Friday starting at 12:30am with deliveries starting around 2:30am and weckend operations as needed. The licensee employed one full-time Authorized Nuclear Pharmacist who compounded approximately 60-100 doses of primarily Te-09m radiopharmaceuticals pre day, as well as perpared occasional I-131 capsules for diagnosts studies. The licensee also employed 7 drivers. The licensee's radiation safety program was reviewed quarterly by a corporate representative. PERFORMANCE OBSERVATIONS The inspector toured the radiopharmacy to observe material security, postings, and any other potential hazards to the material. The inspector also performed independent surveys of restricted and unrestricted areas and dilhot identify any contamination or dose rates that could cause members of the public to exceed regulatory limits. The inspector observed variety of activities including dose preparation, outgoing package preparation, package surveys, and delivery vehicle loading. The A	NRC FORM 591M PART 3 U.S. NUCLEAR REGULATORY COMMISSION (07-2012) Docket File Information									
1. LICENSEE/LOCATION INSPECTED: Hot Shots Nuclear Medicine 2296 US Hwy. 41 S Marquette, MI 49855 REPORT NUMBER(S) 2019001 3. DOCKET NUMBER(S) 2019001 3. DOCKET NUMBER(S) 2019001 3. DOCKET NUMBER(S) 2019001 4. LICENSE NUMBER(S) 5. DATE(S) OF INSPECTION May 22, 2019 6. INSPECTION PROCEDURES USED 7. INSPECTION FOCUS AREAS 03.01-03.07 SUPPLEMENTAL INSPECTION INFORMATION 1. PROGRAM CODE(S) 2. PRIORITY 3. LICENSE CONTACT 4. TELEPHONE NUMBER 03.01-03.07 SUPPLEMENTAL INSPECTION INFORMATION 1. PROGRAM CODE(S) 2. PRIORITY 3. LICENSE CONTACT 4. TELEPHONE NUMBER 03.01-03.07 Whain Office Inspection Next Inspection Date: 05/22/2021 Field Office Inspection Field Office Inspection PROGRAM SCOPE This was an unannounced, routine inspection of a radiopharmacy outside Marquette, Michigan that served the Upper Peninsula of Michigan. The licensee was authorized to use byproduct material to prepare radiopharmaceuticals for use by nuclear medicine licensees for medical procedures. At the time of the inspection, the radiopharmaceuticals for use by nuclear medicine licensees for medical procedures. At the time of the inspection, the radiopharmaceuticals for use by nuclear medicine licensees for medical procedures. At the time of the inspection, the radiopharmaceuticals for use by nuclear pharmacist who compounded approximately 60-100 doses of primarily Tc-99m radiopharmaceuticals per day, as well as prepared occasional 1-131 capsules for diagnostic studies. The licensee also employed 7 drivers. The licensee's radiation safety program was reviewed quarterly by a corporate representative. PERFORMANCE OBSERVATIONS The inspector toured the radiopharmacy to observe material security, postings, and any other potential hazards to the material. The inspector observed was evicently postings, and any other potential hazards to the material. The inspector reviewed a selection of records associated with dosimetry, area surveys, equipment checks and calibrations, license verification, training records, effluent monitoring reports,	10 CFR 2.201									
2296 US Hwy, 41 S Marquette, MI 49855 REPORT NUMBER(S) 2019001 3. DOCKET NUMBER(S) 2019001 4. LICENSE NUMBER(S) 5. DATE(S) OF INSPECTION May 22, 2019 6. INSPECTION PROCEDURES USED 7. INSPECTION FOCUS AREAS 03.01-03.07 SUPPLEMENTAL INSPECTION INFORMATION 1. PROGRAM CODE(S) 2 PRIORITY 2 IS LICENSE CONTACT Allen R. Doan, PharmD, RSO (906) 273-1306 Main Office Inspection Next Inspection Date: 05/22/2021 Field Office Inspection PROCEDURES or medical procedures. At the time of the inspection, the radiopharmace upticals for use by muclear medicine licensees for medical procedures. At the time of the inspection, the radiopharmace operated Monday through Friday starting at 12:30am with deliveries starting around 2:30am and weekend operations as needed. The licensee employed one full-time Authorized Nuclear Pharmacist who compounded approximately 60-100 doses of primarily Tc-99m radiopharmaceuticals per day, as well as prepared occasional 1-131 capsules for diagnostic studies. The licensee also employed 7 drivers. The licensee's radiation safety program was reviewed quarterly by a corporate representative. PERFORMANCE OBSERVATIONS The inspector toured the radiopharmacy to observe material security, postings, and any other potential hazards to the material. The inspector also performed independent surveys of restricted and unrestricted areas and did not identify any contamination or dose rates that could cause members of the public to exceed regulatory limits. The inspector observed variety of activities including dose preparation, outgoing package preparation, package surveys, and delivery vehicle loading. The ANP also described the licensee representation, training records, effluent monitoring reports, and audits, and no issues were identified.										
3. DOCKET NUMBER(S) 3. OCKET NUMBER(S) 3. OCKET NUMBER(S) 3. OCKET NUMBER(S) 4. LICENSE NUMBER(S) 3. OCKET NUMBER(S) 4. INSPECTION PROCEDURES USED 5. INSPECTION PROCEDURES USED 7. INSPECTION FOCUS AREAS 3. OCKET NUMBER(S) 7. INSPECTION INFORMATION 1. PROGRAM CODE(S) 2. PRIORITY 3. LICENSEE CONTACT Allen R. Doan, PharmD, RSO 4. TELEPHONE NUMBER (906) 273-1306 Whain Office Inspection Field Office Inspection PROGRAM SCOPE This was an unannounced, routine inspection of a radiopharmacy outside Marquette, Michigan that served the Upper Peninsula of Michigan. The licensee was authorized to use byproduct material to prepare radiopharmaceuticals for use by nuclear medicine licensees for medical procedures. At the time of the inspection, the radiopharmacy operated Monday through Friday starting at 12:30am with deliveries starting around 2:30am and weekend operations as needed. The licensee employed one full-time Authorized Nuclear Pharmacist who compounded approximately 60-100 doses of primarily Tc-99m radiopharmaceuticals per day, as well as prepared occasional 1-131 capsules for diagnostic studies. The licensee also employed 7 drivers. The licensee's radiation safety program was reviewed quarterly by a corporate representative. PERFORMANCE OBSERVATIONS The inspector toured the radiopharmacy to observe material security, postings, and any other potential hazards to the material. The inspector also performed independent surveys of restricted and unrestricted areas and did not identify any contamination or dose rates that could cause members of the public to exceed regulatory limits. The inspector observed variety of activities including dose preparation, outgoing package preparation, package surveys, and delivery vehicle loading. The ANP also described the licensees procedures for air effluent monitoring and bioassays for personnel preparing I-131 capsules. The inspector reviewed a selection of records associated with dosimetry, area surveys, equipment checks and calibrations, license verification, t	2296 US Hwy. 41 S Marquette, MI 49855			U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210						
a. INSPECTION PROCEDURES USED 87127 7. INSPECTION FOCUS AREAS 93.01-03.07 SUPPLEMENTAL INSPECTION INFORMATION 1. PROGRAM CODE(S) 2. PRIORITY 2. Allen R. Doan, PharmD, RSO PROGRAM SCOPE This was an unannounced, routine inspection □ Temporary Job Site Inspect		1	4. LICENSE NUMBER(5)	5. DATE(S) OF INSPECTION					
SUPPLEMENTAL INSPECTION INFORMATION 1. PROGRAM CODE(S) 2. PRIORITY 2. Allen R. Doan, PharmD, RSO 3. LICENSEE CONTACT Allen R. Doan, PharmD, RSO (906) 273-1306 Main Office Inspection Temporary Job Site Inspection Temporary Job Site Inspection Temporary Job Site Inspection					1					
SUPPLEMENTAL INSPECTION INFORMATION 1. PROGRAM CODE(S) 2. PRIORITY 2. Allen R. Doan, PharmD, RSO 4. TELEPHONE NUMBER (906) 273-1306 Main Office Inspection Field Office Inspection Temporary Job Site Inspection PROGRAM SCOPE This was an unannounced, routine inspection of a radiopharmacy outside Marquette, Michigan that served the Upper Peninsula of Michigan. The licensee was authorized to use byproduct material to prepare radiopharmacy operated Monday through Friday starting at 12:30am with deliveries starting around 2:30am and weekend operations as needed. The licensee employed one full-time Authorized Nuclear Pharmacist who compounded approximately 60-100 doses of primarily Tc-99m radiopharmaceuticals per day, as well as prepared occasional 1-131 capsules for diagnostic studies. The licensee also employed 7 drivers. The licensee's radiation safety program was reviewed quarterly by a corporate representative. PERFORMANCE OBSERVATIONS The inspector toured the radiopharmacy to observe material security, postings, and any other potential hazards to the material. The inspector also performed independent surveys of restricted and unrestricted areas and did not identify any contamination or dose rates that could cause members of the public to exceed regulatory limits. The inspector observed variety of activities including dose preparation, outgoing package preparation, package surveys, and delivery vehicle loading. The ANP also described the licensees procedures for air effluent monitoring and bioassays for personnel preparing 1-131 capsules. The inspector reviewed a selection of records associated with dosimetry, area surveys, equipment checks and calibrations, license verification, training records, effluent monitoring reports, and audits, and no issues were identified.	6. INSPECTION PROCEDURES USE	D	7. INSPECTION FOCUS AREAS							
1. PROGRAM CODE(S) 2. PRIORITY 2. Allen R. Doan, PharmD, RSO 3. LICENSEE CONTACT Allen R. Doan, PharmD, RSO 4. TELEPHONE NUMBER (906) 273-1306 Main Office Inspection Field Office Inspection Temporary Job Site Inspection PROGRAM SCOPE This was an unannounced, routine inspection of a radiopharmacy outside Marquette, Michigan that served the Upper Peninsula of Michigan. The licensee was authorized to use byproduct material to prepare radiopharmacy operated Monday through Friday starting at 12:30am with deliveries starting around 2:30am and weekend operations as needed. The licensee employed one full-time Authorized Nuclear Pharmacist who compounded approximately 60-100 doses of primarily Tc-99m radiopharmaceuticals per day, as well as prepared occasional 1-131 capsules for diagnostic studies. The licensee also employed 7 drivers. The licensee's radiation safety program was reviewed quarterly by a corporate representative. PERFORMANCE OBSERVATIONS The inspector toured the radiopharmacy to observe material security, postings, and any other potential hazards to the material. The inspector also performed independent surveys of restricted and unrestricted areas and did not identify any contamination or dose rates that could cause members of the public to exceed regulatory limits. The inspector observed variety of activities including dose preparation, outgoing package preparation, package surveys, and delivery vehicle loading. The ANP also described the licensees procedures for air effluent monitoring and bioassays for personnel preparing 1-131 capsules. The inspector reviewed a selection of records associated with dosimetry, area surveys, equipment checks and calibrations, license verification, training records, effluent monitoring reports, and audits, and no issues were identified.	87127		03.01-03.07							
Allen R. Doan, PharmD, RSO (906) 273-1306 Main Office Inspection Next Inspection Date: 05/22/2021 Field Office Inspection Temporary Job Site Inspection Temporary Job Site Inspection PROGRAM SCOPE	SUPPLEMENTAL INSPECTION INFORMATION									
Field Office Inspection PROGRAM SCOPE This was an unannounced, routine inspection of a radiopharmacy outside Marquette, Michigan that served the Upper Peninsula of Michigan. The licensee was authorized to use byproduct material to prepare radiopharmacy orated by nuclear medicine licensees for medical procedures. At the time of the inspection, the radiopharmacy operated Monday through Friday starting at 12:30am with deliveries starting around 2:30am and weekend operations as needed. The licensee employed one full-time Authorized Nuclear Pharmacist who compounded approximately 60-100 doses of primarily Tc-99m radiopharmaceuticals per day, as well as prepared occasional I-131 capsules for diagnostic studies. The licensee also employed 7 drivers. The licensee's radiation safety program was reviewed quarterly by a corporate representative. PERFORMANCE OBSERVATIONS The inspector toured the radiopharmacy to observe material security, postings, and any other potential hazards to the material. The inspector also performed independent surveys of restricted and unrestricted areas and did not identify any contamination or dose rates that could cause members of the public to exceed regulatory limits. The inspector observed variety of activities including dose preparation, outgoing package preparation, package surveys, and delivery vehicle loading. The ANP also described the licensees procedures for air effluent monitoring and bioassays for personnel preparing I-131 capsules. The inspector reviewed a selection of records associated with dosimetry, area surveys, equipment checks and calibrations, license verification, training records, effluent monitoring reports, and audits, and no issues were identified.										
Field Office Inspection Temporary Job Site Inspection Temporary Job Site Inspection Temporary Job Site Inspection	02500	2	Allen R. Doan, PharmD, RSO		(906) 273-1306					
This was an unannounced, routine inspection of a radiopharmacy outside Marquette, Michigan that served the Upper Peninsula of Michigan. The licensee was authorized to use byproduct material to prepare radiopharmaceuticals for use by nuclear medicine licensees for medical procedures. At the time of the inspection, the radiopharmacy operated Monday through Friday starting at 12:30am with deliveries starting around 2:30am and weekend operations as needed. The licensee employed one full-time Authorized Nuclear Pharmacist who compounded approximately 60-100 doses of primarily Tc-99m radiopharmaceuticals per day, as well as prepared occasional I-131 capsules for diagnostic studies. The licensee also employed 7 drivers. The licensee's radiation safety program was reviewed quarterly by a corporate representative. PERFORMANCE OBSERVATIONS The inspector toured the radiopharmacy to observe material security, postings, and any other potential hazards to the material. The inspector also performed independent surveys of restricted and unrestricted areas and did not identify any contamination or dose rates that could cause members of the public to exceed regulatory limits. The inspector observed variety of activities including dose preparation, outgoing package preparation, package surveys, and delivery vehicle loading. The ANP also described the licensees procedures for air effluent monitoring and bioassays for personnel preparing I-131 capsules. The inspector reviewed a selection of records associated with dosimetry, area surveys, equipment checks and calibrations, license verification, training records, effluent monitoring reports, and audits, and no issues were identified.	Field Office Inspection									
Peninsula of Michigan. The licensee was authorized to use byproduct material to prepare radiopharmaceuticals for use by nuclear medicine licensees for medical procedures. At the time of the inspection, the radiopharmacy operated Monday through Friday starting at 12:30am with deliveries starting around 2:30am and weekend operations as needed. The licensee employed one full-time Authorized Nuclear Pharmacist who compounded approximately 60-100 doses of primarily Tc-99m radiopharmaceuticals per day, as well as prepared occasional I-131 capsules for diagnostic studies. The licensee also employed 7 drivers. The licensee's radiation safety program was reviewed quarterly by a corporate representative. PERFORMANCE OBSERVATIONS The inspector toured the radiopharmacy to observe material security, postings, and any other potential hazards to the material. The inspector also performed independent surveys of restricted and unrestricted areas and did not identify any contamination or dose rates that could cause members of the public to exceed regulatory limits. The inspector observed variety of activities including dose preparation, outgoing package preparation, package surveys, and delivery vehicle loading. The ANP also described the licensees procedures for air effluent monitoring and bioassays for personnel preparing I-131 capsules. The inspector reviewed a selection of records associated with dosimetry, area surveys, equipment checks and calibrations, license verification, training records, effluent monitoring reports, and audits, and no issues were identified.	PROGRAM SCOPE									
The inspector toured the radiopharmacy to observe material security, postings, and any other potential hazards to the material. The inspector also performed independent surveys of restricted and unrestricted areas and did not identify any contamination or dose rates that could cause members of the public to exceed regulatory limits. The inspector observed variety of activities including dose preparation, outgoing package preparation, package surveys, and delivery vehicle loading. The ANP also described the licensees procedures for air effluent monitoring and bioassays for personnel preparing I-131 capsules. The inspector reviewed a selection of records associated with dosimetry, area surveys, equipment checks and calibrations, license verification, training records, effluent monitoring reports, and audits, and no issues were identified.	This was an unannounced, routine inspection of a radiopharmacy outside Marquette, Michigan that served the Upper Peninsula of Michigan. The licensee was authorized to use byproduct material to prepare radiopharmaceuticals for use by nuclear medicine licensees for medical procedures. At the time of the inspection, the radiopharmacy operated Monday through Friday starting at 12:30am with deliveries starting around 2:30am and weekend operations as needed. The licensee employed one full-time Authorized Nuclear Pharmacist who compounded approximately 60-100 doses of primarily Tc-99m radiopharmaceuticals per day, as well as prepared occasional I-131 capsules for diagnostic studies. The licensee also employed 7 drivers. The licensee's radiation safety program was reviewed quarterly by a corporate									