

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE A\* REQUIRED INFORMATION)

LICENSEE CODE 01 PAT HTI 2 7 0 0 - 1 0 1 0 1 0 1 0 1 - 1 0 1 0 3 4 1 1 1 1 4 5

REPORT SOURCE L 6 0 1 5 0 0 0 1 3 2 0 7 0 1 2 1 1 6 7 1 8 8 0 3 1 1 6 7 8 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During surveillance testing the reverse power relay actuated causing diesel generator DF-X-18 to trip. No possible adverse effect on the health and safety of the public could have resulted from this because the reverse power relay is bypassed during emergency operating mode and one diesel generator (DF-X-1A) as required while in modes 5 and 6 was operable.

SYSTEM CODE 09 E E 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE Z Z Z Z Z Z Z 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16

17 LER NO. REPORT NUMBER 7 8 EVENT YEAR 7 8 SEQUENTIAL REPORT NO. 0 0 7 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0 ACTION TAKEN Z 18 FUTURE ACTION X 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRO-4 FORM SUB. N 24 PRIME COMP. SUPPLIER Z 25 COMPONENT MANUFACTURER Z 9 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

110 The probable cause of the reverse power relay actuation was a spurious actuation of the relay. The relay was reset and the surveillance test on the diesel generator was rerun and successfully completed. No further corrective action is required.

FACILITY STATUS 15 B 23 % POWER 0 0 0 29 OTHER STATUS 30 NA METHOD OF DISCOVERY 31 B DISCOVERY DESCRIPTION 32 Operator Observation

ACTIVITY CONTENT 16 Z 33 Z 34 AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA

PERSONNEL EXPOSURES 17 0 0 0 38 TYPE Z 39 DESCRIPTION NA 39

PERSONNEL INJURIES 18 0 0 0 40 DESCRIPTION 41 NA 41

LOSS OF OR DAMAGE TO FACILITY 19 Z 42 DESCRIPTION NA 42

PUBLICITY 20 Y 43 DESCRIPTION 44 Weekly News Release

NRC USE ONLY

NAME OF PREPARED BY J. R. Stair PHONE: 215-939-3601 Ext. 118

7904200042